

The subject aircraft was involved in an incident /
accident on 7/1/2025 rendering it a Constructive Total
Loss as not repairable within its insured value. For
further details refer to insurance claim: 4600091722US.

Signed: ***Underwriters Salvage Company***

Date: **8/18/2025**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100

HELICOPTER MODEL 206 B II

SERIAL NUMBER 2122

HELICOPTER HISTORICAL SERVICE RECORD

PAGE _____ OF _____

AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS, SERVICE BULLETINS, AND SIGNIFICANT HISTORY				
DIRECTIVE OR BULLETIN NO. WHEN APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
206-93-74	9-7-93	Swashplate support insp 50 hr. C/W	335504189 Chindan	10-28-93
206-93-75	10-19-93	main transmission splines	335504189 Chindan	6-1-94
206-93-76	12-7-93	m/D/S over temp indicator tape		
206-93-77	11-17-93	m/R/ Blade rework D/N/A	335504189 Chindan	6-1-94
206-94-78	4-11-94	landing gear insp.	335504189 Chindan	11-15-94
206-93-74	9-7-93	S/plate support insp 50 hr. (100 hr. unperfected)	Chindan	6-1-94
206-92-66	5-5-92	pillow block retorquing 50 hr.	335504189	6-1-94
206-94-79	5-5-94	looseness of T/R P/C horn C/W	Chindan	9-23-94
206-94-80	8-5-94	m/R Transmission S/N for removal D/N/A	Chindan	9-26-94
206-94-81	8-17-94	replace float kit X tubes D/N/A	Chindan	9-26-94
206-94-82	9-6-94	emerg. float X tubes D/N/A	Chindan	9-26-94
206-94-83	9-6-94	light wt. emerg. float X tubes D/N/A	Chindan	9-26-94
206-95-84	7-24-95	HYD. SERVO ACTUATOR SHOULDER BOLTS N/A OVERHAUL BY STATION	REPAIR STATION	
206-95-85	9-05-96	INPUT DRIVESHAFT ATTACH HARDWARE C/W PER S.B.	FAA CRS YT2R331L WFO	
206-95-86	9-11-95	T/R DRIVESHAFT HANGER & SPRING INSP. C/W PER S.B.	06-20-96	T.T. 5821.7
206-96-87	2-26-96	SERVO SUPPORT INSP. N/A BY A/C S/N		
206-96-88	6-3-96	Fixed float Tubes N/A NOT INSTALLED		
206-97-89	5/20/97	R-134A Air con'g N/A NOT INSTALLED		
206-97-90	6-20-97	m/R Pillow Block Hardware complied with Pers. 13		2/16/97
206-97-91	10/10/97	Ceco Fuel Pump N/A BY PLW		2/16/98
206-01-96	3/30/01	Chip Detector Assy - TEDCO B3188A - C/W @ 6670.9 T.T.	Robert Mott	11/1/01
206-01-98	10/11/01	C20B Gearbox Torquemeter Gearshaft Assy N/A by T.I.S.	566483308 IN Robert Mott	11/1/01

HELICOPTER MODEL 206 B IISERIAL NUMBER 2122HELICOPTER
HISTORICAL SERVICE RECORD

PAGE _____ OF _____

AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS, SERVICE BULLETINS, AND SIGNIFICANT HISTORY				
DIRECTIVE OR BULLETIN NO. WHEN APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
206-90-52	2-23-90	T/R control tube inspection c/w.	Windway #335504189	5-26-90
" -53	5-15-90	Vor antenna not installed	Windway #335504189	9-27-90
" -54	5-31-90	Fuel valve switch guard installation c/w.	"	"
" -55	6-12-90	turbine spline adapter, replacement D/N/A.	"	"
" -56	6-21-90	sun gear S/N recall. D/N/A.	"	"
" -57	6-27-90	H/r blades (-113 or -127's) N/A per P/N & S/N's	"	"
" -58	9-18-90	H/r blades (-125 & -127's) N/A per P/N & S/N's	"	"
-91-59	1-30-91	Bearing hanger - 1 time insp. D/N/A - not installed	Windway #335504189	3-25-91
-91-60	6-28-91	Vertical fin insp. D/N/A	Windway #335504189	↑
" -61	9-13-91	D/S seal assembly replacement N/A by S/N.	Windway #335504189	12-5-91
" -62	9-19-91	restraint assy. type not installed	Windway #335504189	↓
" -63	10-10-91	Bendix fuel control D/N/A. Ceco in.		
" -64	11-21-91	horiz stab spar spares no spare D/N/A.		
206-91-65	11-26-91	Bleed valve by Aviall N/A by S/N.	Windway #335504189	4-21-92
206-89-48	9-21-89	flight control bolt insp c/w.	Windway #335504189	6-13-92
206-92-66	5-5-92	pillow block hardware replacement c/w	Windway #335504189	8-7-92
206-92-67	5-7-92	T/G/Box oil level indicator c/w	Windway #335504189	8-7-92
206-90-52RB	2-23-90	T/R Control tube insp. c/w visual	Windway #335504189	12-18-92
206-92-68	8-5-92	flap restraint -117-003	Windway #335504189	
206-92-69	9-29-92	brg support bracket 1 time		
206-92-70	12-3-92	m/r latch bolt removal	Windway #335504189	12-21-92
206-92-71	12-8-92	fuel qty probe	Windway #335504189	4-14-93
206-92-72	12-14-92	torque transducer replacement D/N/A.	Windway #335504189	8-19-93
206-93-73	6-12-93	Breene Eastern hooks		

SERIAL NUMBER 2122

HELICOPTER HISTORICAL SERVICE RECORD

PAGE _____ OF _____

AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS, SERVICE BULLETINS, AND SIGNIFICANT HISTORY

DIRECTIVE OR BULLETIN NO. WHEN APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
AD 90-13-01 R1	6-22-90	T/R Blade S/N defects: N/A by P/N & S/N'S.	P/C/W	7-18-90
AD 90-21-03	10-5-90	T/R Blade tip weight defects: N/A by P/N & S/N'S.	ulindson	3-25-91
AD 91-03-12	2-28-91	float bag malfunction N/A - not installed.	AP 33504189 IA.	"
AD 91-23-15	12-30-91	False eng out warning: D/N/A.	ulindson	4-21-92
AD 92-01-05	2-5-92	M/R/Blade failure: D/N/A.	AP 33504189 IA.	↓
AD 92-06-12	4-13-92	premature wear of sun gear: D/N/A.	ulindson	6-1-94
AD 92-09-07		Vertical fin doubler D/N/A.	AP 33504189 IA.	
AD 93-22-11	11-18-93	mast trunnion P/N 206-011-113-103 D/N/A. 206-011-120-103	ulindson	
AD 94-15-07	8-26-94	M/R Blade Rework N/A BY P/W	ROTORCRAFT SUPPORT INC. 5/5/95	
AD 94-19-02	9-28-94	Swashplate support Insp Per A.D	FAA CRS YT2R331L W/O 2/288	
AD 94-20-03	10/11/94	M/R Trunnion Insp and unaffected	ROTORCRAFT SUPPORT INC. 5/5/95	
AD 94-24-11	1/6/95	T/R Drive shaft Hangars PCW BY S.B.	FAA CRS YT2R331L W/O 2/288	
AD 94-19-02	9-28-94	Swashplate support - 109	ROTORCRAFT SUPPORT INC. 5/5/95	
AD 95-09-06	6-08-95	FUEL VALVE SWITCH GUARD PREVIOUSLY COMPLIED WITH	FAA CRS YT2R331L W/O 3200	
AD 95-11-14	6-30-95	LANDING GEAR CROSSTUBES N/A BY LANDING GEAR P/W	06-25-96	
AD 95-24-06	12-27-95	ENGINE OUT WARNING N/A BY ENGINE MODEL	T.T. 5831.7	
AD 96-06-04	4-25-96	M/R DRIVESHAFT N/A BY DRIVESHAFT P/W		

OLD RECORD

		INSTALLATION DATA			REMOVAL DATA			
COMPONENT ASSY. OR PART	SERIAL NUMBERS	TOTAL AIRCRAFT TIME (HRS)	ACCUMULATED TIME ON ASSEMBLY OR PART		TOTAL AIRCRAFT TIME (HRS)	ACCUMULATED TIME ON ASSEMBLY OR PART		SCHEDULED REMOVAL AIRCRAFT (HRS)
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: M/R Blade Assy								
NO: 206-010-200- 33	TKK-6571	0.0	0.0	0.0				
NAME: M/R Blade Assy								
NO: 206-010-200- 33	TKK-6563	0.0	0.0	0.0				
NAME: M/R Hub Assy								
NO: 206-011-100- 17	JILM-11429	0.0	0.0	0.0				
NAME: M/R Mast Assy								
NO: 206-040-002- 7	NJF-51797	0.0	0.0	0.0				
NAME: Swashplate Assy								
NO: 206-010-450- 11	JIJG-09648	0.0	0.0	0.0				
NAME: Lower Collective Tube								
NO: 206-001-194 -1	MS-639	0.0	0.0	0.0	4645.5	4645.5	TSN	4800
NAME: Transmission Assy								
NO: 206-040-002- 25	BKW-11235	0.0	0.0	0.0				
NAME: Pylon Support Link, R/H								
NO: 206-031-589- 1	M-00154	0.0	0.0	0.0				
NAME: Pylon Support Link, L/H								
NO: 206-031-589- 1	M-00193	0.0	0.0	0.0				
NAME: Input Driveshaft								
NO: 206-040-100- 13	ALF-50547	0.0	0.0	0.0				
NAME: Freewheeling Assy								
NO: 206-040-270- 3	BMB-10742	0.0	0.0	0.0				
NAME: T/R Blade Assy								
NO: 206-010-750- 7	TKM-0028	0.0	0.0	0.0				
NAME: T/R Blade Assy								
NO: 206-010-750- 7	TKM-1342	0.0	0.0	0.0				
NAME: T/R Gearbox Assy								
NO: 206-040-400- 9	ALO-11434	0.0	0.0	0.0				



HELICOPTER MODEL 206B

SERIAL NUMBER 2122

HELICOPTER HISTORICAL SERVICE RECORD

PAGE 1 OF 1

AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS, SERVICE BULLETINS, AND SIGNIFICANT HISTORY

[illegible]

Component Name BLADE,MR

Part Number 206-010-200-133

Serial Number A-8115

Page 1 Of 1



A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						Next Scheduled ☐ Insp ☐ O/H ☐ RET	REMOVAL DATA					
Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN			Date	Removed At	Component Hours / RIN		Reason For Removal	
			A/C Hours	Since New	Since O/H				A/C Hours	Since New		Since O/H
				Comp. Hrs	Comp. Hrs					Comp. Hrs		Comp. Hrs
			RIN	RIN	RIN	RIN		RIN	RIN			
18/SEP/08	856 (Bik)	AMSA	13437.2	0.0	NEW							
5/3/19	2122	SINTEK	9660	0.0	NEW	15-MAY-17	14477.8	1.040,6	New	HARD Landing		
			10184.6	1040.6								

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Complied With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date
1040.6	Inspected and repaired IAW BHT-206B3-CR&O, Chapter 62, Sec. 62-22, BHT-206A/B-Series-MM-6, Sec. 62-15, Para. 12, and RTI/ ACS approved procedures, removed and re-bonded top and bottom surface grip pad, profiled leading edge erosion, installed non-flush skin repair on top surface station 102, refinished to high visibility black and white, static balanced to nominal values, and final assembly, RTI RO# 7473 -----		RTI 9F	03/22/2019

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1)

Component Name **BLADE,MR**

Part Number **206-010-200-133**

Serial Number **A-8059**

Page **1** Of **1**



NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						Next Scheduled	REMOVAL DATA				
Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN		☐ Insp ☐ O/H ☐ RET	Date	Removed At	Component Hours / RIN		Reason For Removal
			A/C Hours	Since New	Since O/H				Since New	Since O/H	
				Comp. Hrs	Comp. Hrs				Comp. Hrs	Comp. Hrs	
				RIN	RIN				RIN	RIN	
18/SEP/08	856 (B1K)	AMSA	13437.2	0.0	NEW						
			9660	0.0	NEW						
5/3/19	2122	SIMPON	10184.6	1040.6			15-MAY-17	14477.8	1040.6	NEW	Hand Landing

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Complied With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date
1040.6	Inspected and repaired IAW BHT-206B3-CR&O, Chapter 62, Sec. 62-22, BHT-206A/B-Series-MM-6, Sec. 62-15, Para. 12, and RTI/ ACS approved procedures, removed and re-bonded top surface grip pad, profiled leading edge erosion, refinished to high visibility black and white, static balanced to nominal values, and final assembly, RTI RO# 7472		FAA Repair Station R4TR418N	03/22/2019

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1)

NOMENCLATURE MR HUB ASSY
 PART NUMBER 206-011-100-21g
 SERIAL NUMBER 102087

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						SCHEDULED REMOVAL		REMOVAL DATA					
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN				DATE	REMOVED AT	COMP HRS	COMP OH	REASON FOR REMOVAL	
				SINCE NEW	SINCE O/H								
			A/C HOURS	HRS COMP. HRS	HRS COMP. HRS					INSP. HRS	RETIR. HRS / YEARS		A/C HOURS
				RIN		O/H HRS	RETIR. RIN / DATE				RIN		
1-May-2015	N59553	SINTON	15,335..7	5620.1	0.0	N/A	/	1/7/2019	10549.6	6834	1213.9	DUE OVERHAUL	
	S/N 1458					1200.0	/					and A: P 342202SIA	
5/3/19	N16720	SINTON		6834.0	0.0		/						
	S/N 2122						/						
							/						
							/						
							/						
							/						
							/						
							/						
							/						
							/						

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.	SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
5630.1	MR HUB OH C/W IAW THE BHT COMPONENT OH MANUAL CH 62-10.			
	MR Grips (2), Trunion, Yoke, Pitch Horns (2) , Latchs (2) Blade Bolts(2) and Mast Nut			
	Overhauled by Able Eng. CRS# A1LR190N See individual component cards for W/O #'s			
	MR Hub Assembled W/ New Straps (2)(Airwolf 3 Yr), Pins (2), Fittings (2), Latch Bolts(2), and PC Trunions (2), Seals, O-Rings & Locks as required. MR Hub Assy. Serviced			
	W/ AeroShell #22 grease.			
6834.0	COMPLIED WITH A 1200 HOUR OVERHAUL INSPECTION IN ACCORDANCE WITH	<i>Reed MCB</i>	1596539 IA	1-May-2015
	206B3-CR&O-3 REVISION 5 DATED 23-NOV-2012, CHAPTER 62 MANUAL	<i>M. J. ...</i>	FAACRS YT2R331L	
	REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER		EASA. 145.5629	
				03/12/2019

WORK ORDER NO. 007921

REFER TO APPLICABLE ASB, ADS AND SECTION 4 OF THE MAINTENANCE MANUAL FOR COMPONENT AIRWORTHINESS LIMITATIONS AND RIN(Retirement Index Number)

		ACCUMULATED TIME AT INSTALLATION			SCHEDULED REMOVAL		ACCUMULATED TIME AT REMOVAL		
SUBCOMPONENT NAME	SERIAL NUMBER	COMPONENT	SUBCOMPONENT				COMPONENT	SUBCOMPONENT	
			SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H
PART NUMBER		HRS HOURS / DATE	HRS HOURS	HRS HOURS	INSP. HRS	RETIR. HRS / YEARS	HRS HOURS / DATE	HRS HOURS	HRS HOURS
			RIN		O/H HRS	RETIR. RIN / DATE		RIN	
NAME: MR YOKE	HBFS80	COND	unk	0.0	6820.1	N/A / COND	6834.6	UNK	UNK
NO.: 206-010-101-129						---	--- / ---		
NAME: TRUNION ASSY	HB3208	5620.1	565.9	0.0	6820.1	9854.2 / N/A	6834.6	1779.8	1213.9
NO.: 206-011-113-105						---	--- / ---		
NAME: MR GRIP	HBFS718	5620.1	1003.5	0.0	6820.1	9616.6 / N/A	2047.3 / 5/4/18		
NO.: 206-010-102-121A						---	--- / ---		
NAME: MR GRIP	HBFS992	5620.1	1003.5	0.0	6820.1	9616.6 / N/A	6834.6	2217.4	1213.9
NO.: 206-010-102-121A						---	--- / ---		
NAME: MR TT STRAP	BA11036	5620.1	0.0	NEW	---	6820.1 / 3	1043.8 / 5/4/18		
NO.: AA-206-011-154-105			05/01/2015			---	N/A / 5/2018		
NAME: MR TT STRAP	BA11035	5620.1	0.0	NEW	---	6820.1 / 3	1043.8 / 5/4/18		
NO.: AA-206-011-154-105			05/01/2015			---	N/A / 5/2018		
NAME: LATCH BOLT	SU10704	5620.1	0.0	NEW	---	6820.1 / N/A	6834.6	1213.9	NEW
NO.: 206-011-260-103						---	--- / ---		
NAME: LATCH BOLT	SU10667	5620.1	0.0	NEW	---	6820.1 / N/A	6834.6	1213.9	NEW
NO.: 206-011-260-103						---	--- / ---		
NAME: PIN	DI24720	5620.1	0.0	NEW	---	6820.1 / N/A	1043.8 / 5/4/18		
NO.: 206-010-123-003						---	--- / ---		
NAME: PIN	DI24924	5620.1	0.0	NEW	---	6820.1 / N/A	1043.8 / 5/4/18		
NO.: 206-010-123-003						---	--- / ---		

		ACCUMULATED TIME AT INSTALLATION			SCHEDULED REMOVAL		ACCUMULATED TIME AT REMOVAL		
SUBCOMPONENT NAME	SERIAL NUMBER	COMPONENT	SUBCOMPONENT				COMPONENT	SUBCOMPONENT	
			SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H
PART NUMBER		HRS HOURS / DATE	HRS HOURS	HRS HOURS	INSP. HRS	RETIR. HRS / YEARS	HRS HOURS / DATE	HRS HOURS	HRS HOURS
			RIN		O/H HRS	RETIR. RIN / DATE		RIN	
NAME: YOKE	HBFS80	6834.0	UNK	0.0		COND /	/		
NO.: 206-010-101-129							/		
NAME: TRUNNION	HB3208	6834.0	1779.8	0.0		9854.2	/		
NO.: 206-011-113-105							/		
NAME: PINS	DIFS25923 DIFS25927	6834.0	170.1	0.0		7863.9	/		
NO.: 206-010-123-003							/		
NAME: FITTINGS	DIFS5504 DIFS5575	6834.0	170.1	0.0		7863.9	/		
NO.: 206-011-140-001							/		
NAME: LATCH BOLTS	SUL0704 SUL0667	6834.0	1213.9	0.0		8120.1	/		
NO.: 206-011-260-103							/		
NAME: STRAPS	BAL1772 BAL1773	6834.0	170.1	NEW		7863.9 05/2021	/		
NO.: AA-206-011-154-105							/		
NAME: GRIP	HBFS992	6834.0	2217.4	0.0		9416.6	/		
NO.: 206-010-102-121A							/		
NAME: GRIP	HBFS2301	6834.0	170.1	0.0		11463.9	/		
NO.: 206-010-102-121A							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		

		ACCUMULATED TIME AT INSTALLATION			SCHEDULED REMOVAL		ACCUMULATED TIME AT REMOVAL		
SUBCOMPONENT NAME	SERIAL NUMBER	COMPONENT	SUBCOMPONENT				COMPONENT	SUBCOMPONENT	
			SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H
PART NUMBER		HRS HOURS / DATE	HRS HOURS	HRS HOURS	INSP. HRS	RETIR. HRS / YEARS	HRS HOURS / DATE	HRS HOURS	HRS HOURS
			RIN		O/H HRS	RETIR. RIN / DATE		RIN	
NAME: FITTING	FWFS1370	5620.1	0.0	NEW		6820.1 /	1043.8 / 5/4/10		
NO.: 206-011-140-001							/		
NAME: FITTING	FWFS1386	5620.1	0.0	NEW	---	6820.1 /	1043.8 / 5/4/10		
NO.: 206-011-140-001							/		
NAME: M/R GRIP	HBFS2301	6663.9	0.0	NEW		11463.9 /	6834.6	170.1	NEW
NO.: 206-010-102-121A							/		
NAME: MR TT STRAP	BA11772	6663.9	0.0	NEW		7863.9 / MAY 2021	6834.6	170.1	NEW
NO.: AA-206-011-154-105			5/4/2010				/		
NAME: MR TT STRAP	BA11773	6663.9	0.0	NEW		7863.9 / MAY 2021	6834.6	170.1	NEW
NO.: AA-206-011-154-105			5/4/2010				/		
NAME: PIN	DIFS25923	6663.9	0.0	NEW		7863.9 /	6834.6	170.1	NEW
NO.: 206-010-123-003			5/4/2010				/		
NAME: PIN	DIFS25927	6663.9	0.0	NEW		7863.9 /	6834.6	170.1	NEW
NO.: 206-010-123-003			5/4/2010				/		
NAME: FITTING	DIFS5575	6663.9				7863.9 /	6834.6	170.1	NEW
NO.: 206-011-140-001							/		
NAME: FITTING	DIFS5504	6663.9				7863.9 /	6834.6	170.1	NEW
NO.: 206-011-140-001							/		
NAME:						/	/		
NO.:						/			

COMPONENT N:
PART NUMBER
SERIAL NUMBER
PAGE 2 OF

M/R HUB ASSY
206-011-100-219
102087

COMMERCIAL HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHED. ☐ INSP ☐ O/H ☐ RET A/C HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A/C SERIAL NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
4-30-97	377KA 2187	EMDR604D	5900.6	2415.5	75.3		3-30-98	5971.2	2486.1	145.9	TRANSFER
3-30-98	802KA 1664	EMDR604D	8417.8	2486.1	145.9		12/3/01	9208.8	3277.1	936.9	Install New Straps
12/7/01	802KA 1664	Sinton	9208.8	3277.1	936.9		7/3/02	9425.0	3493.3	1153.1	O.H.
7/18/02	1664	Sinton	9425.0	3493.3	0.0		5/17/06	10,548.6	4616.9	1123.6	O.H.
7/18/06	802KA 1664	Sinton	10,656.6	4616.9	0.0		12/23/08	11,094.5	5054.8	437.9	Traction Replacement
12/23/08	802KA 1664	Sinton	11,094.5	5054.8	437.9		2/15/2013	11,660.1	5620.4	1803.5	Removed for Sudden Stop/Acceleration Insp

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY Signature affirms work performed IAW FAR Part 43.		
		SIGNATURE	CERT. NO.	DATE
2511.5	C/W T-T STRAP CHANGE IAW AD-74-15-03 M/CTT 8443.2	[Signature]	EMDR604D	7-20-99
3277.1	C/W T.T. Strap Change IAW BHT RMM M/C T.T. 9208.8 S/N LPFS 18282 & 18277	[Signature]	MLHA3308	12/7/01
3493.3	Overhauled Main rotor hub IAW Bell 206CR20. Installed new inboard fittings s/n HBFS-826, HBFS-877. Installed new clutch bolts s/n DI-13949 & 14016. Installed new pins s/n HBFS-1490 & HBFS-1641.	[Signature]		7-17-02
4616.9	OVERHAULED IAW BELL 206B CR&O MANUAL CHAPTER 62-10. REFERENCE APCS W.O. #W5099 FOR PERTINENT DETAILS.	[Signature]	WG3R344L	
3054.8	Traction S/N AS66 w/ 14724.2 TT, 1566.5 T20. Installed Traction S/N HB3208 w/ TSN 30.0, AS66	[Signature]	J80R365Y	6/27/06
		[Signature]	1596539	12/23/08

COMPONENT NO.
PART NUMBER
SERIAL NUMBER
PAGE _____ OF _____

MIR HUB ASSY
306-011-100-222-219
102087

Bell Helicopter **EXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING AN UNLIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

INSTALLATION DATA						SCH. FOR ☐ O/H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
4/4/88	806KA/ 2179	KAA 501-52	4874.6	0.0	0.0	/	3-10-89	5205.2	330.6	330.6	Transfer
3-26-89	377KA ²¹⁸⁷	KAA501-52	4161.4	330.6	330.6	/	9-14-90	5006.8	1176.0	1176.0	O/H
11-2-90	377KA ²¹⁸⁷	EMDR604D	5006.8	1176.0	0.0	/	2-19-92	5837.5	1506.7	330.7	T-TSTRAPS
				1506.7	330.7	/	7/24/92	5444.5	1616.7	440.7	Transfer
7/24/92	804KA 3315	EMDR604D	6636.2	1616.7	440.7	/	5/11/94	7018.9	1999.4	823.4	Transfer
6/6/94	803KA 2393	EMDR604D	7908.0	1999.4	823.4	/	2/21/95	8248.8	2340.2	1164.2	O/H
11-1-95	803KA 2393	EMDR604D	8248.8	2340.2	0.0	/	6-7-96	8324.1	2415.5	75.3	TTSTRAPS

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
SB 206-80-34	10-20-87	Roll up HUB ASSY FROM NEW PARTS IAW Bell MTO	KAA 501-52	10-20-89
SB 206-81-90	10-20-89	INSTALLED NEW PINS, FITTINGS, TRUNNION. WO# 1962	KAA 501-52	3-24-89
SB 206-92-66	10-1-95	INSTALLED NEW T-T STRAPS WO# 8070	EMDR 604D	2-8-90
		1/W O/H INSPECTION IAW Bell CR40 MANUAL WO# 2159	EMDR 604D	10-11-90
		REMOVED T-T STRAPS - INSTALLED NEW T-T STRAPS & GRIP SEALS	EMDR 604D	2-19-92
	Note	Installed Blade Bolts with Sunstrand grease check for corrosion	EMDR 604D	4/8/92
	NOTE -	BLADE BOLT WITH SUNSTRAND GREASE HARD TO REMOVE	EMDR 604D	5-16-94
		REMOVED T-T STRAPS - INSTALLED NEW T-T STRAPS	EMDR 604D	5-16-94
		1/W O/H INSP. RETIRE PINS, FITTINGS, LATCH BOLT - INSTALL NEW COMP.	EMDR 604D	10-6-95
		INSTALL NEW TT STRAPS WO# 2648	EMDR 604D	4-30-97

Component Name **TRUNNION ASSY**Part Number **206-011-113-105**Serial Number **HB3208**Page **1** Of **1****Bell Helicopter**A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						Next Scheduled ☐ Insp ☐ O/H ☒ RET	REMOVAL DATA						
Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN			Date	Removed At	Component Hours / RIN		Reason For Removal		
				Since New	Since O/H				Since New	Since O/H			
				A/C Hours	Comp. Hrs				Comp. Hrs	A/C Hours		Comp. Hrs	Comp. Hrs
				RIN	RIN				RIN	RIN		RIN	RIN
12/23/08	1664	Sinton	11,094.2	0.0	NEW	4806 hrs	7/24/2013	11,660.1	568.9	New	Sudden Stop/Recel		
5/1/2015	1451 59853	Sinton	15,335.7	565.9	New			N/A	N/A	N/A	Inspection		
3-12-19	102087	HUB ASSY RSI	6834.0	1779.8	0.0	9854.2	1/7/19	16549.6	1779.8	NEW	OVERHAUL		
										</			

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Complied With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date
11,094.5 Hrc	Installed on MR Hub Assy P/N 206-011-100-21G S/N 102087	Rick W. W.	1576539 DA	12/23/08
568.9	OH by Able CRS # AILR190N Installed on MR Hub P/N 206-011-100-21G, S/N 102087 @ MR Hub O.H.	Rick W. W.	1576539 DA	5/1/2015
1779.8	COMPLIED WITH A 1200 HOUR OVERHAUL INSPECTION AND INSTALLED ON HUB ASSEMBLY S/N: 102087 IN ACCORDANCE WITH 206B3-CR&O-3 REVISION 5 DATED 23-NOV-2012, CHAPTER 62 MANUAL REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 007921.	Rick W. W.		

FAA CRS YT2R331L
EASA 145 5629

03 12 2019

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1)

COMMERCIAL HISTORICAL SERVICE RECORD:

COMPONENT NAME: YOKE

PART NUMBER: 206-010-101-129

SERIAL NUMBER: HBFS80

PAGE 1 OF 1



ROTORCRAFT SUPPORT, INC.

FAA CRS YT2R331L

16425 Hart Street
Van Nuys, CA 91406

PH: 818-997-7667

FX: 818-997-1513

www.rotorcraftsupport.com

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.									
COMPONENT									

[illegible]

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)
7861 5671REV994

Component Name PIN
 Part Number 206-010-123-003
 Serial Number DIFS27848
 Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						Next Scheduled ☐ Insp ☐ O/H ☐ RET	REMOVAL DATA				
Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN			Date	Removed At	Component Hours / RIN		Reason For Removal
				Since New	Since O/H				Since New	Since O/H	
			A/C Hours	Comp. Hrs	Comp. Hrs				Comp. Hrs	A/C Hours	
RIN	RIN	RIN	RIN	RIN	RIN	RIN	RIN				
3-20-25	726	TAC	11045.0	0.0	NEW						
				0.0	NEW						

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Compiled With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)
7861 5671REV994

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)
7861 5671REV994

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)
7861 5671REV994

Component Name LATCH BOLT

Part Number 206-011-260-103

Serial Number DI31140

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA							Next Scheduled	REMOVAL DATA				
Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN		☐ Insp ☐ O/H ☒ RET	Date	Removed At	Component Hours / RIN		Reason For Removal	
				Since New	Since O/H				Since New	Since O/H		
			A/C Hours	Comp. Hrs	Comp. Hrs	Comp. Hrs			A/C Hours	Comp. Hrs		Comp. Hrs
			RIN	RIN	RIN	RIN			RIN	RIN		RIN
3-20-25	726	TAC	11,045.0	0.0	NEW							
				0.0	NEW							

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Compiled With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date

COMPONENT NAME Strap Assembly
PART NUMBER 2AA-310-004-101
SERIAL
NUMBER 23216-007
PAGE 1 OF 2



ABLE AEROSPACE SERVICES HISTORICAL SERVICE RECORD

NOTICE: When returning any limited life component to Able Aerospace Services, Inc. for any reason, it is mandatory that a valid **HISTORICAL SERVICE RECORD** accompany the component.

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES ETC.	
COMPONENT	

[illegible]

Refer to applicable regulatory agency directives and the applicable Maintenance Manual for RIN Accumulation Instructions.

AECS-044

Revision: B Dated: 9/26/2022

COMPONENT NAME Strap Assembly
 PART NUMBER 2AA-310-004-101
 SERIAL NUMBER 22266-010
 PAGE 1 OF 2



ABLE AEROSPACE SERVICES
HISTORICAL SERVICE RECORD

NOTICE: When returning any limited life component to Able Aerospace Services, Inc. for any reason, it is mandatory that a valid HISTORICAL SERVICE RECORD accompany the component.

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	REMOVAL DATA				
DATE	INSTALLED ON A/C SERIAL NO.	BY (ACTIVITY)	INSTALLED AT	COMP. HRS/CSN			DATE	REMOVED AT	COMP.HRS/CSN		REASON FOR REMOVAL
			A/C HRS.	SINCE NEW	SINCE OH				SINCE NEW	SINCE O/H	
				COMP	COMP				COMP HRS	COMP HRS	
			RIN	RIN	RIN	RIN					
3-20-25	726	TAC	11,045.0	00	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES ETC.

COMPONENT TSN	DESCRIPTION OF WORK ACCOMPLISHED	Complied with by signature affirms work performed I.A.W. FAR Part 43 or applicable data		
		SIGNATURE	CERT NO.	DATE

Refer to applicable regulatory agency directives and the applicable Maintenance Manual for RIN Accumulation Instructions.

NOMENCLATURE **GRIP ASSY**
 PART NUMBER **206-010-102-121A**
 SERIAL NUMBER **HBFS 992**
 PAGE **1** OF **1**

Bell Helicopter
 A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED					- REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN		COMP. HRS.	☐ INSP ☐ O/H ☒ RET	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL				
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H					
				HRS COMP. HRS	HRS COMP. HRS					HRS	HRS					
				A/C HOURS A/C RIN	RIN	RIN				A/C HOURS A/C RIN	RIN	RIN				
7/18/06	NB02KA S/N 1664	Sinton	10,696.6	0.0	NEW	4300 Hrs		7/14/2013	11,660.1	1003.5	New	M/R Sudden Stop/Recall Inspection				
8/1/2013	1451	Sinton	10,335.7	1003.5	0.0			1/7/19	16549.6	2217.4	1213.9	OVERHAUL				
3-12-19	102087 HUB ASSY	RSI	6834.0 HUB ASSY	2217.4	0.0	9416.6 HUB ASSY										

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
0.0	INSTALLED ON MAIN ROTOR HUB ASSY P/N 206-011-100-021G, S/N 102087 @ TSN 4616.9. REFERENCE APCS W.O. #W5099 FOR PERTINENT DETAILS.	<i>[Signature]</i>	J80R365Y	6/27/06
1003.5	Overhauled / NW BHT 206B-3 CR40-3 Rev 5 Dated 11/23/12. See 8/30-3 with Tracking number 225135 Dated 10/28/14 For Details. End	<i>[Signature]</i>	A1LR190N	10/28/14
1003.5	Installed on M/R Hub Assy P/N 206-011-100-214, S/N 102087	<i>[Signature]</i>	1596539 TX	5/1/2015
2217.4	COMPLIED WITH A 1200 HOUR OVERHAUL INSPECTION AND INSTALLED ON HUB ASSEMBLY S/N: 102087 IN ACCORDANCE WITH 206B3-CR&O-3 REVISION 5 DATED 23-NOV-2012, CHAPTER 62 MANUAL REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 007921	<i>[Signature]</i>	FAA CRS YT2R331L	

NOMENCLATURE GRIP ASSY
 PART NUMBER 206-010-102-121A
 SERIAL NUMBER HBFS2301
 PAGE 1 OF 1



NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED	- REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN		COMP. HRS.	☐ INSP	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H		☐ O/H			SINCE NEW	SINCE O/H	
			A/C HOURS	HRS COMP. HRS	HRS COMP. HRS		HRS			HRS		
			A/C RIN	RIN	RIN		RIN			RIN		
5/4/18	1451 N59553	SNTON	16379.5	0.0	NEW			1/7/19	16549.6	170.1	NEW	OVERHAUL
				0.0	NEW							
3-12-19	102087 HUB ASSY	RSI	6834.0	170.1	0.0	11463.9						
			HUB ASSY			HUB ASSY						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
0.0	INSTALLED ON M/R HUB, (P/N 206-010-100-216, S/N 102087)		34220051A	5/4/18
170.1	COMPLIED WITH A 1200 HOUR OVERHAUL INSPECTION AND INSTALLED ON HUB ASSEMBLY S/N: 102087 IN ACCORDANCE WITH 206B3-CR&O-3 REVISION 5 DATED 23-NOV-2012, CHAPTER 62 MANUAL REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 007921.		FAA CRS YT2R331L EASA.145.5629	03-12-2019

COMPONENT NAME Pylon Support Link, L/H
 PART NUMBER 206-031-589- 1
 SERIAL NUMBER M-00193
 PAGE 1 OF 1



HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHC FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA

REMOVAL DATA

DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
12/19/76	2122	BHC	0.0	0.0	0.0	3/27/95	5724.0	5724.0	NEW	OVERHAUL
4/27/95	2122	RCS	5724.0	5724.0	0.0		5821.7	5821.7	97.7	O/H HARD LANDING
6-20-96	2122	RCS	5821.7	5821.7	0.0					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		INSPECTED PER BELL 206B OVERHAUL AND HARD LANDING REQUIREMENTS. INSTALLED NEW BEARING. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER NO. 2788.	FAACRS YT2R331L	4/27/95
		INSPECTED PER BELL 206 OVERHAUL AND HARD LANDING REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC., UNDER WORK ORDER #3200.	FAACRS YT2R331L	6-20-96



BELL
HELICOPTER COMPANY
A **TEXTRON** COMPANY

NOTICE: WHEN COMPONENT IDENTIFIED
BELOW IS RETURNED TO BHC. FOR ANY
REASON IT IS MANDATORY THAT THIS SERVICE
RECORD ACCOMPANY THE COMPONENT

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

7861 56717 REV 773

COMMERCIAL HISTORICAL SERVICE RECORD

COMPONENT NAME: TRANSMISSION ASSY
 PART NUMBER: 206-040-002-025
 SERIAL NUMBER: BKW-10792
 PAGE 2 OF


Redding Air Service, Inc.

FAA CRS AUMR274C

6831 Airway Avenue
 Redding, Ca 96002
 PH: 530-221-2851
 FX: 530-221-3728
 www.reddingairservice.com

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA				
DATE	INSTALLED ON AIRCRAFT SERIAL NO. N° NUMBER	BY ACTIVITY	INSTALLED @ A/C HRS	COMP. HRS. SINCE NEW	COMP. HRS SINCE O/H	☐ INSP ☐ O/H ☐ RET	DATE	REMOVED @ A/C HRS	COMP. HRS. SINCE NEW	COMP. HRS SINCE O/H	REASON FOR REMOVAL
01/28/09	1740 N90301	RAS	11126.7	11126.7	1356.5	1500HR	12/06/13	12535.6	12535.6	1408.9	INSPECTION
12/18/13	1740 N90301	RAS	12535.6	12535.6	2765.4	1500HR	6/15/19	14115.6	14115.6	4345.4	Overhaul
6/14/20	2122 N10720	SINTEW	10258.2	14115.6	0.0						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.

COMPONENT TT	DESCRIPTION OF WORK ACCOMPLISHED	DATE	CERT NO.	SIGNATURE
11126.7	COMPLIED WITH 1500HOUR INSPECTION OF SUN GEAR. COMPONENT FOUND TO BE AIRWORTHY AND APPROVED FOR RETURN TO SERVICE, TIME CONTINUED. REF: WO# 4856	1/28/2009	CRS AUMR274C	 DAVID BURLINGAME
12535.6	COMPLIED WITH A 1500HOUR COMPONENT OPERATION INSPECTION IN ACCORDANCE WITH 206A/B SERIES 30 APR. 2013 REV 14 MAINTENANCE MANUAL CHAPTER 5-4I AND BHT-206 AB M&O, BHT 206B3-CR&O CHAPTER 63 REQUIREMENTS.	12/18/2013	CRS AUMR274C	 DAVID BURLINGAME
	(TT: 13927.8 TSO 4157.6 TSI: 1392.2) REPLACED LEAKING SEAL WITH NEW P/N A10710.V720 IN ACCORDANCE WITH BELL A/B/L SERIES CR&O MANUAL REV. 2 DATED 31-JAN-2013. DETAILS ON FILE AT REDDING AIR SERVICE, INC. UNDER WO# 5394	5/2/2018	FAA CRS AUMR274C	 PAUL THOMSEN
14115.6	COMPLIED WITH A 4500 HOUR OVERHAUL INSPECTION AND INSTALLED SERVICEABLE BEARINGS P/N: 206-040-034-105 S/N: ZV11617 AND P/N: 206-040-038-101 S/N: MB4447, OVERHAULED GEARS P/N: 206-040-146-001 S/N: B12-16887, B12-17198, B12-16849 AND B12-16635, SERVICEABLE CASE ASSEMBLY P/N: 206-040-150-029 S/N: B12-6647 AND NEW SUN GEAR P/N: 206-040-122-007 S/N: A00000513 AND CHIP DETECTOR P/N: B3188B IN ACCORDANCE WITH BHT-206B3-CR&O-3 REVISION 5 DATED 23-NOV-2012, CHAPTER 63 MANUAL REQUIREMENTS. DRAG PIN S/N: B12-3240 MODIFIED TO P/N: 206-031-509-103. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 008136.	4/2/2020	FAA CRS YT2R331L EASA.145.5629	

COMPONENT NAME Transmission Assy
 PART NUMBER 206-040-002- 25
 SERIAL NUMBER BKW-10792
 PAGE 1 OF 1



HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHC. FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
5-22-75	1740	BHC	0.0	0.0	0.0	4-1-79	960.0	960.0		1200hr insp.
4-1-79	1740	RAS	960.0	960.0		5-8-82	2400.0	2400.0		overhaul
5-8-82	1740	RAS	2400.0	2400.0	0.0	2-28-90	5311.5	5311.5	2911.5	overhaul
2-28-90	1740	RAS	5311.5	5311.5	0.0	1-05-95	6844.4	6844.4	1532.9	1500hr. inspection
1-5-95	1740	RAS	6844.4	6844.4	1532.9	2-3-00	8311.5	8311.5	3000.0	1500hr inspection
2-3-00	1740	RAS	8311.5	8311.5	3000.0	9-30-04	9673.3	9673.3	4361.8	metal generation
9-30-04	1740	RAS	9673.3	9673.3	4361.8	4-30-05	9770.2	9770.2	4458.7	4500hr overhaul
4-30-05	1740	RAS	9770.2	9770.2	0.0	1-28-09	11126.7	11126.7	1356.5	1500 hr insp

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		Perform 1200 hr inspection i/a/w Bell M&O Manual. TT 960.0	RAS	4-1-79
		Perform 2400 hr inspection/overhaul I/A/W Bell M&O Manual	RAS	5-8-82
	5311.5	Performed 3000 hr inspection/overhaul I/A/W Bell M&O Manual	CRS AUMR274C	2-28-90
	6844.4	Performed 1500hr. inspection of sun gear.	AUMR274C	1-5-95
	8311.5	Performed 1500hr. inspection of sun gear.	AUMR274C	2-3-00
	9673.3	Performed 1500 hr. component operation inspection i/a/w BHT M.M. Ch.5 and CR+D manual. Replaced vertical shaft duplex bearing. P/N 206-040-032-105 for metal generation. Sun gear spline dimensions 2.735".	AUMR274C	9-30-04
	9770.2	Performed 4500 hour component overhaul & inspection i/a/w BHT Component Repair & overhaul manual	AUMR274C	4-30-05

COMPONENT NAME MAIN ROTOR MAST Assembly
PART NUMBER 206-040-002-007
SERIAL NUMBER FAJF-10181
PAGE 1 OF 2




Phone (209) 982-4991
FAA Repair Station WG3R944L

HISTORICAL SERVICE RECORD

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	CERT. NO.	DATE
6013.3	Performed A 3000 Hour Overhaul Inspection T/A/M BHT-206A/A-Series-CR#10. Time Continued Mast pole P/N 206-010-332-121 S/N NTF-4089 TSN 2694.2. Time Continued Mast bearing P/N 206-040-036-005 S/N 1159 TSN 2694.2. Assembly TSN 6013.3 TSO 0.0.	Big Valley Aviation, Inc. FAA Repair Station No. W03R944L 		03/14/12
8542.4	MAGNETIC PARTICLE INSPECTION PERFORMED AT THE UPPER THREADS PER CUSTOMER REQUEST AND ASTM E1444/E1444M-22a DTD JULY 2022. REFERENCE APCS W.O.# W20074 DTD 12-FEB-2025 FOR PERTINENT DETAILS. TSN 8542.4 TSI 0.0.....		J80R365Y	02/22/25

COMPONENT NAME Main Rotor Mast Assy
PART NUMBER 206-040-002-7
SERIAL NUMBER FAJF-10181
PAGE 1 OF 1

Bell Helicopter **TEXTRON**

Division of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

REPRODUCTION OF ORIGINAL RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
BELOW IS RETURNED TO BHC. FOR ANY
REASON IT IS MANDATORY THAT THIS SERVICE
RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA

REMOVAL DATA

DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
7-6-79	N16726	O-H-1	2227.8	0.0		5/13/81	3207.9	980.1		Sudden Stoppage
9/11/81	XSCMD 2122	KHC TUS	3578.4	980.1	0.0	3/17/88	4152.7	1614.4	634.3	cust. conv.
3/13/88	2386	AJC	2208.5							
3/17/88	2386	AJC	2680.1	1614.4	634.3	4-28-88	2715.8	1650.1	670.0	Install in 2122
4-28-88	S/N2122	AJC	4152.7	1650.1	670.0	11-15-88	4423.1	1920.5	940.0	HARD LANDING
1-10-89	2122	CRS 205-57	4423.1	1920.5	0.0	3/27/95	5724.0	3221.4	1300.9	OVERHAUL
4/27/95	2122	RCS	5724.0	3221.4	0.0	3-96	5821.7	3319.1	97.7	O/H HARD LANDING
6-20-96	2122	RCS	5821.7	3319.1	0.0	1-11-07	7368.4	4865.8	1546.7	1500 hr Inspection
1-11-07	N16726-2122	Sinton Heli.	7368.4	4865.8	1546.7	2-29-12	8515.9	6013.3	2694.2	Overhaul

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		6/10/81 2400 hr. conditional o/h c/w i/a/w Bell 206 component o/h manual, 2400 hr o/h schedule & mandatory retirement listing Magnaflux Report No. 5213 Mast T.T. 980.1 0.0 SMOH	Keystone	
			CRS 1211	WA CRS 1211 3
		KEYSTONE W.O. 9177		
	11-15-88	MAST T.T. 1920.5 INSP. FOR HARD LANDING AND OVERHAULLED BY TEE TOOL. NO DAMAGE FOUND. SEE SOUTH AIR AVIATION W.O. 2353A. INSPECTED PER BELL 206B OVERHAUL AND HARD LANDING REQUIREMENTS. INSTALLED OVERHAULLED MAST. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER NO. 2788.	CRS 205-57	1-10-89
			R.H. Metrick	
			FAACRS YT2R331L	4/27/95
		INSPECTED PER BELL 206B OVERHAUL AND HARD LANDING REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC., UNDER WORK ORDER #3200.	FAACRS YT2R331L	6-20-96

[illegible]

COMPONENT NAME: Kaflex DriveshaftPART NUMBER: SKCP2348-5SERIAL NUMBER 1532

PAGE _____ OF _____

KAFLEX DRIVESHAFT HISTORICAL SERVICE RECORD

INSTALLATION DATA						A/C HOURS SCH. FOR O/H RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
12/12/13	N59564	RHI #10893	14647.8	UNKNOWN	0.0	6000HR O/H	2-12-25	16652.4	2004.6	2004.6	CONV
2-12-25	N16726	TAL	11,045.0	2004.6	2004.6						

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
ROT1532	03SEP2013	S/N1532 was overhauled using (1) new end fitting and (8) new flex frames. Return to service at 11982.3 hrs	K4RRS7#AI	03SEP2013

1,500 HOURS INSPECTION, 6,000 HOURS INSPECTION, AND ANY OTHER REPAIRS / MAINTENANCE PERFORMED ON THE DRIVESHAFT MUST BE RECORDED ON THIS HISTORICAL DATA CARD.

COMPONENT NAME:	FREEWHEEL ASSY		
PART NUMBER:	206-040-270-003		
SERIAL NUMBER:	BMB-12100		
PAGE	2	OF	2



67 D Street
Fillmore, CA 93015
PH: 818-997-7667
FX: 818-997-1513
www.rotorcraftsupport.com

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.

[illegible]

COMPONENT NAME FREEWHEELING ASSY.
 PART NUMBER 206-040-270-003
 SERIAL NUMBER BMB-12100
 PAGE 1 OF 1

Bell Helicopter TEXTRON

Division of Textron Inc

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHT. FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
09-10-81	3474	BHT	0.0	0.0	0.0	28-11-86	1200	1200	N/A	INSP. 1200 HRS.
19-12-86	3474	HTSA	1200	1200	N/A	10-12-92	2177.0	2177.0	TSN	Hard Landing/ Sudden Stoppage
24Dec92	3474	TU3R880L	2177:00	2177.0	0.0	2-9-95	3411.2	3411.2	1234.2	1500 Hr Inspection
24 May 95	3474	TU3R880L	3411.2	3411.2	1234.2	9-20-00	4887.6	4887.6	2710.6	Overhaul
7Feb01	3474	TU3R880L	4887.6	4887.6	0.0	9-Sep-19	7891	7891	3003.4	Overhaul

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	DATE
-----	19-12-86	Se realizó inspección y cambio de baleros por condición.	HTSA	19-12-86
		Complied with Overhaul Inspection Requirements I.A.W. BHT 206B-III CR&O.	A.S.I.	12-22-92
		Complied with TB 206-83-91 expanded inspection criteria and TB 206-83-93		
		clutch replacement. For details reference ASI W0 30,911, FAA Repair Sta-		
		tion TU3R880L.		
		Complied with 1500 Hour Inspection Requirements I.A.W. BHT 206B-III M.M. and	A.S.I.	5/4/95
		CR&O Manual. Complied with TB 206-94-147 Speedi Sleeve Installation, Ref-		
		erence ASI W.O. 31290, FAA Repair Station TU3R880L.		
	2/7/01	Complied with Overhaul, Installed new Clutch CL4225-2, S/N	A.S.I.	7Feb01
	17-120-010	FD14181 I.A.W. BHT 206 CR&O, Ref ASI W.O. 32034	TU3R880L	
	6.343.8	Se efectuó inspección de 1500 horas de componente de operación de acuerdo a IAW BHT-206A/B series MM 1 párrafo 5.22		
		rev. 5 de fecha 31 de julio del 2009 detalles en memoria de trabajo de AVIHEL OT AH10HEX-044, y como soporte el manual		
		BHT 206B-CR&O rev. 1 del 24 de agosto del 1994		

[illegible]

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

7861 5671REV994

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

7861 5671REV994

PAGE 4 OF 4



www.rotorcraftsupport.com

[illegible]

[illegible]

COMMERCIAL HISTORICAL SERVICE RECORD

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

7861 61838 REV 191

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	REMOVAL DATA		
		DATE COMPONENT HOURS	ACCUMULATED TIME ON ASSEMBLY OR PART		DATE COMPONENT HOURS	DATE	ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		AIRCRAFT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: DUPLIX BEARING	12508	4/27/95	UNK	0.0		3-96	UNK	97.7
NO.: 206-010-443-001		5724.0			COND	5821.7		
NAME: SUPPORT	EA-1072	6-20-96	1176.2	0.0		7/31/15	4764.4	✓
NO.: 206-010-452-109		5821.7			9445.5			
NAME: LEVER	TKFS-202	6-20-96	97.7	0.0				
NO.: 206-010-467-001		5821.7			10524.0			
NAME: IDLER LINK	GD-8199	6-20-96	3629.6	0.0	3/22/05	3/22/05	4799.3	1169.7
NO.: 206-010-407-001		5821.7			6992.1	6991.4		
NAME: SLEEVE	A19-01566	6-20-96	2649.5	0.0	9/11/2009	9/11/2009	4805.2	New
NO.: 206-010-454-005		5821.7			7972.2	7977.4		
NAME: DUPLIX BEARING	12508	6-20-96	UNK	97.7			UNK	2414.6
NO.: 206-010-443-001		5821.7			COND	8138.6		
NAME: Idler Link	REFS-4181	3/22/05	New	New			3649.8	NEW
NO.: 206-010-407-001		4488.8 0.0				8138.6		
NAME: Sleeve	RE 10475	9/11/2009	New	New			2663.8	NEW
NO.: 206-010-454-113		5474.8 0.0				8138.6		
NAME: SUPPORT	A-3415	7/31/15	2702.2	NEW			3933.5	NEW
NO.: 206-010-452-113		6907.3				8138.6		
NAME:								

COMPONENT NAME SWASHPLATE ASSY
PART NUMBER 206-010-450-011
SERIAL NUMBER CDJC-90189
PAGE 2 OF 2

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

NOTICE: WHEN RETURNING ANY LIMITED
LIFE COMPONENT TO BHTI FOR ANY
REASON IT IS MANDATORY THAT A VALID
HISTORICAL SERVICE RECORD ACCOMPANY
THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						A/C HOURS SCH. FOR XXX O/H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
4-28-88	2122	AJC	4152.7	1650.1	670.0	8282.7	11-3-89	4645.5	2142.9	1162.8	Support change
1-20-90	2122	HLS	4645.5	2142.9	1162.8		3/27/95	5724.0	3221.4	2241.3	OVERHAUL
4/27/95	2122	RCS	5724.0	3221.4	0.0	10524.0	3-96	5821.7	3319.1	97.7	OVERHAUL HARD LANDING
6-20-96	2122	RCS	5821.7	3319.9	0.0	10621.7					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		INSPECTED PER BELL 206B OVERHAUL AND HARD LANDING REQUIREMENTS. DETAILS		
		ON FILE AT ROTOCRAFT SUPPORT, INC. UNDER WORK ORDER NO. 2788.	FAACRS YT2R331L	4/27/95
		INSPECTED PER BELL 206 OVERHAUL AND HARD LANDING REQUIREMENTS. DETAILS		
		ON FILE AT ROTOCRAFT SUPPORT, INC. UNDER WORK ORDER #3200.	FAACRS YT2R331L	6-20-96

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	REMOVAL DATA		
		DATE COMPONENT HOURS	ACCUMULATED TIME ON ASSEMBLY OR PART		DATE COMPONENT HOURS	DATE	ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		AIRCRAFT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: Coll. Idler Link	GD-8199		1960.6			3/27/95	3531.9	NEW
NO.: 206-010-407-001		4152.7			6992.1	5724.0		
NAME: Swashplate Sleeve	A19-01566		980.5			3/27/95	2551.8	NEW
NO.: 206-010-454-005		4152.7			7972.2	5724.0		
NAME: Coll. Lever	GD-8220-9		1960.6			3/27/95	3531.9	NEW
NO.: 206-010-467-001		4152.7			6992.1	5724.0		
NAME: Duplex Bearing	3192		980.5			3/27/95	2551.8	UNK
NO.: 206-010-443-001		4152.7			Conditional	5724.0		
NAME: Swashplate Support	TR-211		2265.7			1-20-90	2758.5	
NO.: 206-010-452-005		4152.7			6687.0	4645.5		
NAME: Swashplate Support	EA-1072		0.0			3/27/95	1078.5	NEW
NO.: 206-010-452-109		4645.5			9445.5	5724.0		
NAME: IDLER LINK	GD-8199	4/27/95	3531.9	0.0		3-96	3629.6	97.7
NO.: 206-010-407-001		5724.0			6992.1	5821.7		
NAME: SLEEVE	A19-01566	4/27/95	2551.8	0.0		3-96	2649.5	97.7
NO.: 206-010-454-005		5924.0			7972.2	5821.7		
NAME: SUPPORT	EA-1072	4/27/95	1078.5	0.0		3-96	1176.2	97.7
NO.: 206-010-452-109		5724.0			9445.5	5821.7		
NAME: LEVER	TKFS202	4/27/95	0.0	NEW		3-96	97.7	NEW
206-010-467-001		5724.0			10524.0	5821.7		

NUMBER

PAGE 1 OF 1

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

REPRODUCTION OF ORIGINAL RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
BELOW IS RETURNED TO BHC. FOR ANY
REASON IT IS MANDATORY THAT THIS SERVICE
RECORD ACCOMPANY THE COMPONENT

[illegible]

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

[illegible]

COMPONENT NAME LINK ASSY
 PART NUMBER 206-010-407-001
 SERIAL NUMBER REFS 4181
 PAGE 1 OF 1

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: When returning any limited life component to BHTI for any reason, it is mandatory that a valid HISTORICAL SERVICE RECORD accompany component.

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA				
DATE	INSTALLED ON AIRCRAFT SERIAL NO.	BY (ACTIVITY)	INSTALLED AT	COMP. HRS./RIN		☐ INSP ☐ O/H ☒ RET COMP. HRS. RIN	DATE	REMOVED AT	COMP. HRS./RIN		REASON FOR REMOVAL
			A/C HRS.	SINCE NEW	SINCE O/H			A/C HRS.	SINCE NEW	SINCE O/H	
			RIN	RIN	RIN			RIN	RIN	RIN	
7/22/05	2122	Sinton Helicopters	6991.4	0.0	New	4800.0	7/25/22	10041.2	3649.8		OVERHAUL
08-05 2022	SWPLT GDLM-90189	RSI	8138.6	3649.8	0.0	9288.8 SWPLT					

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	CERT. NO.	DATE
3649.8	COMPLIED WITH AN OVERHAUL INSPECTION AND INSTALLED ON SWASHPLATE ASSY S/N: GDJF90189 IN ACCORDANCE WITH BHT-206B3-CR&O-3 REVISION 7 DATED 28-FEB-2020, CHAPTER 62 MANUAL REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 009421.		FAA CRS YT2R331L	EASA.145.5629 08-05-2022

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1.).

NOMENCLATURE SUPPORT
 PART NUMBER 206-010-452-113
 SERIAL NUMBER A-3415
 PAGE 1 OF 1

Bell Helicopter
 A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	- REMOVAL DATA				
DATE	INSTALLED ON A/C NO	BY (ACTIVITY)	INSTALLED AT	CCOMPONENT HOURS/RIN		COMP HRS.	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS				SINCE NEW HRS	SINCE O/H HRS	
			A/C HOURS A/C RIN	RIN	RIN	RIN		A/C HOURS A/C RIN	RIN	RIN	
7/23/07	N59553 S/N 1451	S.N.	12,780.7	00	NEW		7/7/15	15482.9	2702.2	NEW	CONVENIENCE
7/3/15	N16726 S/N 2122	DRA	9409.9	2702.2	NEW		2/05/22	10041.2	3933.5		OVERHAUL
08-05 2022	SWPLT GDLM90189	RSI	8138.6	3933.5	0.0	COND					
			SWPLT								

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
0.0	Installed on S/P P/N 206-010-450-011	<i>Richard M. [Signature]</i>	1596639 DA	7/23/07
2702.2	INSTALLED ON SWASHPLATE P/N 206-010-450-011 S/N GDJG-90189 C/W AD 94-19-02 IAW PARA A NEXT DUE AT 2752.2 HRS.	<i>[Signature]</i>	2702.2	7/3/15
3933.5	COMPLIED WITH AN OVERHAUL INSPECTION AND INSTALLED ON SWASHPLATE ASSY S/N: GDJF90189 IN ACCORDANCE WITH BHT-206B3-CR&O-3 REVISION 7 DATED 28-FEB-2020, CHAPTER 62 MANUAL REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 009421.	<i>[Signature]</i>	FAA CRS YT2R331L EASA.145.5629 08-05-2022	

GENERATED BY



009421
TIME SHEET OUT

206B
SWASHPLATE

DATE 08/05/22

P/N: 206-010-450-113
S/N: GDJG90189

TSN: 8138.6

TSO:

1

<u>%</u>			<u>SERIAL</u>		<u>TIME</u>	<u>REM/DUE</u>	<u>TBO/FREQ</u>	<u>INST A/C</u>	<u>ENG</u>	<u>INST PART</u>
<u>REM</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>NUMBER</u>		<u>HRS/LDG</u>	<u>REMAINING</u>	<u>HRS/CY</u>	<u>SLL</u>	<u>HRS/CY</u>	<u>HRS/CY</u>
COMPONENTS										
100%	206-010-450-113	SWASHPLATE O/I GDJG9018		HRS	0	4800	12938.6	4800	8138.6	0
24%	206-010-407-001	IDLER LINK	REFS 418	HRS	3649.8	1150.2	9288.8	4800	8138.6	3649.8
	206-010-452-113	SUPPORT	A-3415	HRS	3933.5			COND	8138.6	3933.5
82%	206-010-454-113	SLEEVE	RE10475	HRS	2663.8	11736.2	19874.8	14400	8138.6	2663.8
97%	206-010-467-105	LEVER	REFS 621	HRS	129.1	4670.9	12809.5	4800	8138.6	129.1

COMPONENT NAME: OUTER RING ASSY
 PART NUMBER: 206-010-453-009
 SERIAL NUMBER: REFS1114
 PAGE 1 OF 1



FAA CRS YT2R331L

16425 Hart Street
Van Nuys, CA 91406
PH: 818-997-7667
FX: 818-997-1513
www.rotorcraftsupport.com

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.

COMPONENT TT/RINS	DESCRIPTION OF WORK ACCOMPLISHED	DATE	CERT NO.	SIGNATURE
UNK	COMPLIED WITH AN OVERHAUL INSPECTION IN ACCORDANCE WITH BHT 206B CR&O MANUAL REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 003066.	10/2/2006	FAA CRS YT2R331L EASA. 145.5629	
UNK	COMPLIED WITH AN OVERHAUL INSPECTION AND INSTALLED ON SWASHPLATE ASSY S/N: GDJF90189 IN ACCORDANCE WITH BHT-206B3-CR&O-3 REVISION 7 DATED 28-FEB-2020, CHAPTER 62 MANUAL			
	REQUIREMENTS. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC. UNDER WORK ORDER 009421.	8/5/2022	FAA CRS YT2R331L EASA. 145.5629	

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)
7861 5671REV994

COMMERCIAL HISTORICAL SERVICE RECORD

[illegible]

COMMERCIAL HISTORICAL SERVICE RECORD

COMPONENT NAME: SERVO
 PART NUMBER: 206-076-031-013
 SERIAL NUMBER: 2204
 PAGE 1 OF 1



ROTORCRAFT SUPPORT INC.

FAA CRS YT2R33IL

16425 Hart Street
 Van Nuys, CA 91406
 PH: 818-997-7667
 FX: 818-997-1513
 www.rotorcraftsupport.com

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA				
DATE	INSTALLED ON A/C SERIAL NO.	BY ACTIVITY	INSTALLED AT A/C HRS	COMP. HRS/RIN SINCE NEW	COMP. HRS/RIN SINCE O/H	☐ INSP ☐ O/H ☐ RET	DATE	REMOVED AT A/C HRS	COMP HRS/RIN SINCE NEW	COMP HRS/RIN SINCE O/H	REASON FOR REMOVAL
			RIN	RIN	RIN	RIN		RIN	RIN	RIN	
03/28/04	1740	RAS	9485.3	UNK	0.0		01/25/07	10241.2	UNK	755.9	SEAL LEAKING
01/31/07	1740	RSI	10241.2	NK	755.9		03/25/15	13055.0	UNK	3569.7	OVERHAUL
05/3/19	2122	SINTON	10184.6	NK	0.0						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.

COMPONENT TT/RINS	DESCRIPTION OF WORK ACCOMPLISHED	DATE	CERT NO.	SIGNATURE
TT NK	Overhauled by FASCO WO# E-1418	3-24-04	YFTR947K	Brett Fortner
TT NK	Repaired & tested I.A.W. Mfg specs. WO# 50463 TSO 755.9	1-30-07	XJ2R294L	HAS 
TT NK	Overhauled & tested I.A.W. Mfg specs. WO# 62783	11-5-15	XJ2R294L	HAS 

COMMERCIAL HISTORICAL SERVICE RECORD

COMPONENT NAME: SERVO
 PART NUMBER: 206-076-031-013
 SERIAL NUMBER: 6031
 PAGE 1 OF 1

ROTORCRAFT SUPPORT INC.

FAA CRS YT2R331L

16425 Hart Street
 Van Nuys, CA 91406
 PH: 818-997-7667
 FX: 818-997-1513
 www.rotorcraftsupport.com

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA				
DATE	INSTALLED ON A/C SERIAL NO.	BY ACTIVITY	INSTALLED AT A/C HRS	COMP. HRS/RIN SINCE NEW	COMP. HRS/RIN SINCE O/H	INSP O/H RET RIN	DATE	REMOVED AT A/C HRS	COMP HRS/RIN SINCE NEW	COMP HRS/RIN SINCE O/H	REASON FOR REMOVAL
03/28/04	1740	RAS	9485.3	UNK	0.0		01/25/07	10241.2	UNK	755.9	SEAL LEAKING
01/31/07	1740	RSI	10241.2	NK	755.9		03/25/15	13055.0	UNK	3569.7	OVERHAUL
05/3/19	2122	SINTON	10184.6	NK	0.0						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.

COMPONENT TT/RINS	DESCRIPTION OF WORK ACCOMPLISHED	DATE	CERT NO.	SIGNATURE
TT NK	Overhauled By Fasco WO# E-1392	3-24-04	YFTR947K	Brett Fortner
TT NK	Repaired & tested I.A.W. Mfg specs. WO# 50462 TSO 755.9	1-30-07	XJ2R294L	HAS 
TT NK	Overhauled & tested I.A.W. Mfg specs. WO# 62782	11-5-15	XJ2R294L	HAS 

COMMERCIAL HISTORICAL SERVICE RECORD

COMPONENT NAME: TAILBOOM ASSY
 PART NUMBER: 206-031-004-115B
 SERIAL NUMBER: BCJN07190
 PAGE 1 OF 1



16425 Hart Street
 Van Nuys, CA 91406
 PH: 818-997-7667
 FX: 818-997-1513
 www.rotorcraftsupport.com

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA				
DATE	INSTALLED ON A/C SERIAL NO.	BY ACTIVITY	INSTALLED AT A/C HRS	COMP. HRS/RIN SINCE NEW	COMP. HRS/RIN SINCE O/H	☐ INSP ☐ O/H ☐ RET	DATE	REMOVED AT A/C HRS	COMP HRS/RIN SINCE NEW	COMP HRS/RIN SINCE O/H	REASON FOR REMOVAL
			RIN	RIN	RIN	RIN		RIN	RIN	RIN	
02/05/13	2122	Sinton	8767.4	8767.4	0.0 TSR	Cond.					

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETINS, SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES ETC.

COMPONENT TT/RINS	DESCRIPTION OF WORK ACCOMPLISHED	DATE	CERT NO.	SIGNATURE
0.0 TSR	INSTALLED NEW TAIL ROTOR GEAR SUPPORT CAN P/N 206-033-426-003A IN ACCORDANCE WITH CHAPTER 6-3-7 OF THE BELL 206 SERIES STRUCTURAL REPAIR MANUAL REVISION 3, DATED 18 2012			
	AND THE BELL HELICOPTER SERVICE BULLETIN 206-12-129 PART (IV). INSTALLED THREE NEW HANGAR BRACKETS IN #1, #4, & #5 POSITIONS P/N'S 206-030-407-101, 206-030-407-103, & 206-030-433-101.			
	ALIGNMENT CHECK WAS CONDUCTED AND FOUND SATISFACTORY. REPAIR WAS COMPLETED IN A BELL HELICOPTER APPROVED FIXTURE, SERIAL NUMBER 0222. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC UNDER WORK ORDER 14862.			
		1/31/2013	FAA CRS YT2R331L EASA.145.5629	
8767.4	Installed on A/C S/N 2122 following Repair	02/05/2013	AAP1596539 IN	

NOMENCLATURE T/R GEAR BOX

PART NUMBER 206-040-400-013

SERIAL NUMBER ALO-11434

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						SCHEDULED REMOVAL		REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN				DATE	REMOVED AT	COMP HRS	COMP OH	REASON FOR REMOVAL
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H	
			A/C HOURS	HRS COMP. HRS	HRS COMP. HRS					INSP. HRS	RETIR. HRS / YEARS	
		RIN		O/H HRS	RETIR. RIN / DATE		RIN					
9-May-2013	N16726	SINTON	8829.4	8829.4	3008.2	11,821.0	/					
							/					
							/					
							/					
							/					
							/					
							/					
							/					
							/					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.	SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
8829.4	Replaced damaged ring & pinion gear W/Serviceable parts. Assembled W/ new seals & O-Rings. Serviceable bearings installed. New ring gear S/N A-3507, Pinion S/N unavialable hidden by bearings.	<i>Richard M. [Signature]</i>	A&P1596539IA	9-May-2013

REFER TO APPLICABLE ASB, ADs AND SECTION 4 OF THE MAINTENANCE MANUAL FOR COMPONENT AIRWORTHINESS LIMITATIONS AND RIN(Retirement Index Number).

		ACCUMULATED TIME AT INSTALLATION			SCHEDULED REMOVAL		ACCUMULATED TIME AT REMOVAL		
SUBCOMPONENT NAME	SERIAL NUMBER	COMPONENT	SUBCOMPONENT				COMPONENT	SUBCOMPONENT	
			SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H
PART NUMBER		HRS HOURS / DATE	HRS HOURS	HRS HOURS	INSP. HRS	RETIR. HRS / YEARS	HRS HOURS / DATE	HRS HOURS	HRS HOURS
			RIN		O/H HRS	RETIR. RIN / DATE		RIN	
NAME: Gear, Ring	A-3507	8829.4	298.3	New		/	/		
NO.: 206-040-406-101							/		
NAME: Gear, Pinion		8829.4	298.3	New		/	/		
NO.: 206-040-440-103							/		
NAME: Bearing, Duplex	ZV 10660	8829.4	298.3	New		/	/		
NO.: 206-040-410-103							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		
NAME:						/	/		
NO.:							/		

16726
SN 2122

HOBBS 364.8

3/10/13

SINTON HELICOPTERS
DISCREPANCY LIST

ITEM NUMBER	DISCREPANCY	INITIAL	ACTION	PARTS USED	INITIAL
	FWD NEEDS O/H		DISASSEMBLED INSPECTED ALL PARTS IN W BHT CR+O AND MM	1 EA. 206-040-206-001 BEARING SN MB10284	
			REASSEMBLED AND INSTALLED PER CR+O AND BHT MM	1 EA 206-040-204-001 PLATE 1 EA M83248/1-141 PACKING	
			RUN UP AND TEST SATISFACTORY	1 EA. 206-340-104-101 SEAL 1 EA AM919-2D REDUCER	RAL
				1 EA. AM815-5D UNION 1 EA 206-340-204-101 SEAL	
				1 EA. 206-040-229-001 CRACKET	
				1 EA M83248/1-906 PACKING 1 EA. M83248/1-903 PACKING	
				1 EA. M83248/1-905 PACKING 1 EA. M83248/1-215 PACKING	
				1 EA. M83248/1-237 PACKING 1 EA. RR185 RETAINING 1 EA. RR268 RETAINING	

1 EA. RR204 RETAINING RING

COMPONENT NAME T/R Gearbox Assy
 PART NUMBER 206-040-400-2013
 SERIAL NUMBER ALO-11434
 PAGE 1 OF 1

HISTORICAL SERVICE RECORD

REPRODUCTION OF ORIGINAL RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHC. FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA

REMOVAL DATA

DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
12/19/76	2122	BHC	0.0	0.0	0.0	6/11/79	2227.8	2227.8		2400 hr. O/H
7/6/79	N16726	OHI	2227.8	2227.8	0.0	5/13/81	3207.9	3207.9	980.1	sudden stoppage
9/1/81	XBCMD 2122	KK TC	3518.4	3207.9	0.0	3-96	5821.7	5821.0	2613.2	O/H HARD LANDING
			73208.5							
6-20-96	2122	RCS	5821.7	5821.0	0.0	3/18/2013	8794.4	8794.4	2973.4	3000 hr. Inspection
04/01/13	2122	S.H.	8794.4	8794.4	2973.4	5/3/13	8829.2	8829.2	3008.2	Multiple Seal Failures
Continued Next Page										

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		2400 hr. O/H CRS 3145 W.O. #115	OHI	7/6/79
		6/11/81 2400 hr. conditional o/h C/W I/A/W Bell 206 component	Keystone	
		O/H manual, 2400 hr. O/H schedule & Mandatory retirement listing	CRS 1211	WA CRS 1211
		Magnaflux Report No. 5218		6/11/81
		Gearbox T.T. 3207.9 0.0 SMOH Keystone W.O. 9182		
		INSPECTED PER BELL 206, 600 HOUR OVERHAUL AND HARD LANDING REQUIREMENTS. UP-		
		GRADED TO A 206-040-400-013. DETAILS ON FILE AT ROTORCRAFT SUPPORT, INC.,		
		UNDER WORK ORDER #3200.	FAACRS YT2R3311	6-20-96
	04/01/13	3000 hr. Inspection C/W. Bearing Bore liner Repaired by Abel Engineering CRS #A1LR190N, W/O 031913-726. Unit Assembled w/ New Seals & O-Rings. Painted Comp. Gray.	Robert M. ...	04/01/13

KEYSTONE HELICOPTER CORPORATION
F.A.A. REPAIR STATION 1211

MAINTENANCE
WORK SHEET

13. Rem
CEP

able
11/11

CUSTOMER AVITEC ACFT/UNIT MAKE BELL 206 T/R GEARBOX TYPE WORK 2400 H/O OVERHAUL DATE OPENED _____
ACFT "N" XB-CMW ACFT/UNIT MODEL 206-090-900-9 TYPE INSP SUPPLEMENTAL START DATE _____
T.T. 3207.9 T.S.O. 980.1 ACFT/UNIT S/N 110-11434 FINISH DATE _____ DATE CLOSED _____

MECH/ PILOT INITIAL	ITEM NO.	ITEM	WORK ACCOMPLISHED (List p/n & s/n as req'd)	DATE	MECH. INIT.	INSP. INITIAL/ STAMP
<u>ML</u>	<u>①</u>	<u>2400 H/O ON TAIL ROTOR GEAR BOX</u>	<u>2400 H/O 1/4 C/W 1/4 H/O BELL 206 COMPONENT</u> <u>O/H MANUAL, 2400 H/O SCHEDULED</u> <u>MANDATORY RETIREMENT LISTING</u>	<u>6/1/81</u>	<u>ML</u>	<u>JM CRS 1211 10</u>
<u>ML</u>	<u>②</u>	<u>2400 H/O OVERHAUL REQUIREMENTS</u> <u>FOR SUDEN STOPPAGE</u>	<u>2400 H/O CRITERIA FOR SUDEN STOPPAGE</u> <u>1/4 H/O 206 OVERHAUL MANUAL, M/R</u> <u>CONTACTED T/R DRIVESHAFT</u>	<u>6/1/81</u>	<u>ML</u>	<u>JM CRS 1211 10</u>
<u>ML</u>	<u>③</u>	<u>OVERHAUL T/R PITCH CHANGE MECHANISM</u> <u>MANUAL REPORT #5218</u>	<u>REWORKED & OVERHAUL 1/4 H/O</u> <u>1/4 H/O NEW BEARINGS & BOLTS</u>	<u>6/1/81</u>	<u>JEM</u>	<u>WA CRS 1211</u>

THE AIRCRAFT, POWERPLANT AND/OR APPLIANCE IDENTIFIED ON
REVERSE SIDE / ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE
WITH CURRENT F.A.A. REGULATIONS AND IS APPROVED FOR RETURN
TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT
THIS REPAIR STATION UNDER WORK ORDER NO. 9182
TOTAL TIME IN SERVICE 520.1 DATE 6/1/81
AUTHORIZED SIGNATURE [Signature]
KEYSTONE HELICOPTER CORP. Airframe Class 3
1420 PHOENIXVILLE PIKE Powerplant Class 1
WEST CHESTER, PA. 19380 Powerplant Limited
F.A.A. CERT. NO. 1211 Radio Limited

COMPONENT NAME **BEARING**
 PART NUMBER **206-040-410-103**
 SERIAL NUMBER **ZV 10660**
 PAGE **1** OF **1**

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: When returning any limited life component to BHTI for any reason, it is mandatory that a valid HISTORICAL SERVICE RECORD accompany component.

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET COMP. HRS. RIN	REMOVAL DATA				
DATE	INSTALLED ON A/C SERIAL NO.	BY (ACTIVITY)	INSTALLED AT	COMP. HRS./RIN			DATE	REMOVED AT	COMP. HRS./RIN		REASON FOR REMOVAL
			A/C HRS.	SINCE NEW	SINCE O/H			A/C HRS.	SINCE NEW	SINCE O/H	
			RIN	COMP. HRS.	COMP. HRS.			RIN	COMP. HRS.	COMP. HRS.	
19 JAN 2007	C-FANC	VIH	16158.2	0.0	NEW		April 12/07	16271.2	113.0	NIZW	TRANS/RENTAL RETURN.
28 July 2007	C-FKKM	BHLP	16092.7	113.0	N/P.		28 Oct 07	16278.0	298.3	NIZW.	
05/09/2013	N16726 2122	Sinton	8829.2	298.3	3008.2						
								</			

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY Signature affirms work performed I.A.W. FAR Part 43.		
		SIGNATURE	CERT. NO.	DATE
	Received new from B.H.T. on P.O. # <u>266255-13</u> , P.S. # <u>I222254962</u> .	<i>[Signature]</i>		
0.0	Installed new on T/R Gearbox Assy P/N 206-040-400-103, S/N ALO-11531 @ TSN- 11199.2, TSO- 0.0 on	<i>[Signature]</i>		
	ACROHELIPRO Work Order 25-16159. -----	<i>[Signature]</i>		
8829.2 8829.2	Installed on TGB P/N 206-040-400-013, S/N ALO-4434	<i>[Signature]</i>	231-91 SCA C-93 DEC 20 2006	1596539 05/9/13

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1.).

HISTORICAL SERVICE RECORD

TAIL ROTOR HUB ASSY

206-011-810-153

HBFS 4669

2500 HOUR OVERHAUL

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

[illegible]

T/R Blade Assembly
2062200-301
B876

HISTORICAL RECORD

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

[illegible]

Component Name T/R Blade Assembly
Part Number 2062200-301
Serial Number B914 V-05 A

HISTORICAL RECORD

INSTALLATION DATA						NEXT SCHED. INSP O/H X RET	REMOVAL DATA				
DATE	A/C SERIAL NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			A/C HRS./DATE	DATE	REMOVED AT A/C HRS.	COMP. HRS.	
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
0-6-14	N59564 1389	RHI # 7103	14717.5	0.0	NEW	5000	4-2-15	14915.6	198.1	198.1	Removed w/6000hr 3000hr insp.
5-28-15	N59564	RHI #7177	14915.8	198.1	198.1		1-14-22				
							1-14-22	16573.6	1755.9	1755.9	TP Damage
5/3/12	N59564 1389	VERSA AIR	16573.6	1755.9			4/12/25	16,652.4	1834.7	1834.7	CONV
2/12/25	N16726	TAC	11,045.0	1834.7							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		Signature	Cert. No.	Date
0.0	The work specified has been accomplished IAW with VHR work order 22-0740. Performed visual and Computer Aided Tap Test inspection of blade IAW drawing 2062200, Rev. (J) and ICA VMM-206-301, Rev. (N/C), section 5.10 to look for damage. The outboard lower surface trailing edge corner of the abrasion strip was peeled up. Damaged skin plies and a small internal void adjacent to the peeled up abrasion strip was found. No other discrepancies found during the inspection; the blade was found to be repairable. The replacement of the abrasion strip is classified as a major repair, injection repair is minor. Removed and replaced the abrasion strip and performed an injection repair of the void and removed and replaced the data plate and paint finish (added Toughguard NHP) - all IAW VHA-206TR-CRM, Rev. (B). Static balanced B914 with B876 per dwg 2062200, Rev. (J) note 9 to make a balanced set.			
1755.9				

Justicia V7JR5024 4 March 2022

COMPONENT NAME BEARING
 PART NUMBER 206-040-410-001
 SERIAL NUMBER J-5161
 PAGE 1 OF 1

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: When returning any limited life component to BHTI for any reason, it is mandatory that a valid HISTORICAL SERVICE RECORD accompany component.

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA				
DATE	INSTALLED ON AIRCRAFT SERIAL NO.	BY (ACTIVITY)	INSTALLED AT	COMP. HRS./RIN		☐ INSP ☐ O/H ☐ RET COMP. HRS. RIN	DATE	REMOVED AT	COMP. HRS./RIN		REASON FOR REMOVAL
			A/C HRS.	SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
			RIN	COMP. HRS.	COMP. HRS.				COMP. HRS.	COMP. HRS.	
6-20-96	2122	RSI	5821.7	0.0	NEW	CONDITION					

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY Signature affirms work performed IAW FAR Part 43.		
		SIGNATURE	CERT. NO.	DATE
	INSTALLED IN TAIL ROTOR GEARBOX S/N ALO-11474. DETAILS ON FILE AT ROTORCRAFT			
	SUPPORT INC UNDER WORK ORDER NUMBER 3200.		YT2R331L	6-20-96

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1.).



**AERO
PRODUCTS**

NOMENCLATURE

STARTER GENERATOR

PART NUMBER

23032-027

SERIAL NUMBER

20039

928.537.1000

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						SCHEDULED REMOVAL		REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN				DATE	REMOVED AT	COMP HRS	COMP OH	REASON FOR REMOVAL
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H	
			A/C HOURS	HRS COMP. HRS	HRS COMP. HRS	INSP. HRS	RETIR. HRS / YEARS		A/C HOURS	HRS	HRS	
			RIN			O/H HRS	RETIR. RIN / DATE		RIN			
6/1/21	N16720 S/N 2122	SWRN	10353.1	UNK	0.0		/					
							/					
							/					
							/					
							/					
							/					
							/					
							/					
							/					
							/					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
TSO 0.0	HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC. OVERHAULED, COMPLIED WITH BRUSH SEATING AND ACCEPTANCE TESTING IAW SAFRAN 23032 SERIES CMM REV 13 DTD 8 MARCH 2017. INSTALLED SV ARMATURE P/N 23032-2111 AND SV STATOR P/N 23032-1825. REFERENCE APCG W.O. # W14925 FOR PERTINENT DETAILS. ASSY TSN UNK TSO 0.0.		J8OR365Y	17-Aug-2019

REFER TO APPLICABLE ASB, ADs AND SECTION 4 OF THE MAINTENANCE MANUAL FOR COMPONENT AIRWORTHINESS LIMITATIONS AND RIN(Retirement Index Number).