



N 5645T

Left

Right

AMERICAN PROPELLER SERVICE

20208 Charlanne Drive

Redding, California 96002, U.S.A.

PHONE NUMBER (916) 221-4470 / (800) 292-PROP (7767)

FAA REPAIR STATION #NO3R717L

PROPELLER LOGBOOK

BOOK 1

1998-

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-16-98		AMERICAN PROPELLER SERVICE REPAIR STATION No. N03R717L REDDING, CALIF. 96002	
		WORK ACCOMPLISHED <u>COMPLETE OVERHAUL</u> THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE.	
		PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER WORK ORDER # <u>27431</u>	
		INVOICE # <u>41 No 174</u> DATED <u>11-16-98</u>	
		SIGNED <u>[Signature]</u> AUTHORIZED INDIVIDUAL	

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-29-98	3007.00	Installed Prop on N5645T Torqued mount bolts Test ran good. Robt Ch Michael AP037354584	
9-2-09	3526.46	CHK OK PAINT REAR	<u>[Signature]</u> Rucker A. Tibbs 2060210 IAP
7-08-16	3528.19	Reass-paint prop	<u>[Signature]</u>
7-9-17	3538.4	Annual Insp. Golf H	APP-IA 3683010

PROPELLER MAINTENANCE RECORD

Propeller Manufacturer: McCawley

Left Engine

Right Engine

Front Engine

Rear Engine

Hub Model No. 1C172 EM 7653

Hub Serial No. E7783

Blade Model No. _____

Blade Serial No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

Low _____ High _____ Feather _____ Reverse _____

Pitch 53^{cr}

Governor Manufacturer: _____

Governor Model No. _____

Governor Serial No. _____