



The Standard

AVIONICS LOG

ASA/SA-V

Emergency Locator Transmitter

[illegible]

[illegible]

Remuneration may be subject to the rules relating to liability and other terms and/or conditions established by the Convention for the Unification of the Law Relating to the Carriage of Goods by Air (the "Warsaw Convention") and/or the Convention on the Contract for the International Carriage of Goods by Road (the "CMR Convention") and/or the Convention on the Contract for the International Carriage of Goods by Sea (the "Hague-Visby Rules") or any other applicable law. The Convention for the Unification of the Law Relating to the Carriage of Goods by Air (the "Warsaw Convention") and/or the Convention on the Contract for the International Carriage of Goods by Road (the "CMR Convention") and/or the Convention on the Contract for the International Carriage of Goods by Sea (the "Hague-Visby Rules") or any other applicable law shall apply to the extent that it is not inconsistent with the provisions of this contract. The Convention for the Unification of the Law Relating to the Carriage of Goods by Air (the "Warsaw Convention") and/or the Convention on the Contract for the International Carriage of Goods by Road (the "CMR Convention") and/or the Convention on the Contract for the International Carriage of Goods by Sea (the "Hague-Visby Rules") or any other applicable law shall apply to the extent that it is not inconsistent with the provisions of this contract.

[illegible]

© 1992 ASA

VOR Accuracy

MAKE

MODEL

SERIAL NUMBER

PART NUMBER

[illegible]

ATC TRANSPONDER TEST

The transponder tests and inspection required by FAR 91.413 were performed this date and found to comply with FAR 43, Appendix F.

Make: KING Model: KT78A S/N 7219

CUSTOM AVIONICS

CRS No. TK4R547M

418 Bartow Municipal Airport

Bartow, Florida 33830

© 1992 ASA

VOR Accuracy

MAKE

MODEL

SERIAL NUMBER

PART NUMBER _____

[illegible]

USAirports Flight Support, LLC 1295 Scottsville Road Rochester, NY 14624 UG6R0850
LOG ID# 236 10-July-2003 WO# 2090 AC TT 2720.5
N2994P S/N 956 LAKE 4-200 TACH 2230.7

Pg 1 / 1

- TROUBLESHOT TRANSPONDER MODE "C" SYSTEM. FOUND ENCODER INOP. REMOVED ACK ENCODER, P/N A-30 S/N 50157 AND INSTALLED P/N A-30, S/N 79667. PERFORMED CORRESPONDENCE CHECK. FOUND SATISFACTORY.

- ITEMS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS REPAIR STATION UNDER THE WORK ORDER MENTIONED ABOVE.

Kenneth Velez 07.10.03
KENNETH VELEZ Date

© 1992 ASA

CRAIG AVIONICS

CONCORD MUNICIPAL AIRPORT, 83 AIRPORT ROAD, P.O. BOX 865, CONCORD, NH 03301
REPAIR SATATION # RS5R182N

WORK ORDER/INVOICE

NAME Lake Aircraft
ADDRESS 50 Perimeter Rd
CITY Gilford, NH 03246

A/C TYPE	ORDER TAKEN BY	CUSTOMER'S ORDER NO.	PAYABLE UPON REC
Lake LA4-200 2994P	N JV		

AIRCRAFT WORK ORDER -- LABOR INSTRUCTIONS

100 Preliminary inspection complied with

mechanic

Inspector

Avionics Equipment

ITEM	MAKE	MODEL	PART NUMBER	SERIAL NUMBER	DATE		LOCATION STATION #	BATTERY DATES	
					INSTALLED	REMOVED		INSTALLED	REPLACE
MAR. 4, 1997	Installed	Flitecom	403 in	PANEL MOUNT	INTERCOM				
	114	Aircraft JAW	MFR'S	INSTALL	MANUAL				
CUSTOM AVIONICS									
CRS No. TK4R547M									
418 Bartow Municipal Airport									
Bartow, Florida 33830									
</									



The Standard

AVIONICS LOG



Aviation Supplies & Academics, Inc.

7005 132nd Place SE
Renton, Washington 98059-3153

Order Number ASA/SA-V

© 1992 ASA

Registration N-2994-P

Logbook Number 1

From 9/24/96

To _____

Aircraft Make Lake

Model Buc

Serial Number _____

Date of Manufacture 1979

5.) For pe
Apper
7.) When
15.) No ac
16.) When
revis
Weight and
As per FAF
All wiring
66, 67.
The above i