

Location: Hood River, OR



**UNDERWRITERS
Salvage Company**

Underside Front Fuselage



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



Canopy good shape

UNDERWRITERS
Salvage Company



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



UNDERWRITERS
Salvage Company



**UNDERWRITERS
Salvage Company**

(Trailer carpet peeling)

Horizontal Stab



UNDERWRITERS
Salvage Company




**UNDERWRITERS
Salvage Company**

Left



**UNDERWRITERS
Salvage Company**



Left Aileron damage



UNDERWRITERS
Salvage Company



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**

Underside
Left Wing



UNDERWRITERS
Salvage Company


Left wing



UNDERWRITERS
Salvage Company



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



Rt Aileron



**UNDERWRITERS
Salvage Company**

Right
Aileron



UNDERWRITERS
Salvage Company



Rt Aileron



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**

Leading
Edge
inboard
Rt.



UNDERWRITERS
Salvage Company

Rudder



UNDERWRITERS
Salvage Company

Top vertical fin



UNDERWRITERS
Salvage Company

Left
Wing



UNDERWRITERS
Salvage Company

WNR7059

Left
Wing



**UNDERWRITERS
Salvage Company**

Left
Wing
Tip



UNDERWRITERS
Salvage Company

Left Wing



**UNDERWRITERS
Salvage Company**

Right
Wing



UNDERWRITERS
Salvage Company

Right Wing
Tip



**UNDERWRITERS
Salvage Company**

Right
Wing



UNDERWRITERS
Salvage Company

Right
Wing



UNDERWRITERS
Salvage Company



**UNDERWRITERS
Salvage Company**

Wingtip wheel
in shoulder divot



UNDERWRITERS
Salvage Company



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**



**UNDERWRITERS
Salvage Company**