

**Cirrus Design Factory Service Center**

Repair Station No. YD5R855Y
4961 Airport Road
Duluth, MN 55811
Email: factoryservicecenter-duluth@cirrusaircraft.com
Phone: 218-788-3049
Fax: 218-788-3532
www.cirrusaircraft.com

Date: 06-24-2025
Reg. No.: N184AS
Quote No.: DLHQ1060-05-2025 (2024 Cirrus SF50)
A/C Serial: 0585
Airframe Total Time: 45.5
Hobbs: 58.1

Bill to: [REDACTED]

Account: [REDACTED]

Item: 1**Discrepancy**

If there will not be EBIS access at the remote location, a printed copy of the anticipated work scope is to accompany the personnel off-site.

Hours	Subtotal
[REDACTED]	[REDACTED]

Corrective Action

EBIS available.

Inspection Information

- Final Inspection: [REDACTED] (06-24-2025)
- Prelim Inspection: [REDACTED] (06-24-2025)
- Ready for Inspection: [REDACTED] (06-24-2025)

Item Summary	Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
--------------	---------------	---------------	------------------	-----------------------

Item: 2**Discrepancy**

Upon arrival, technician to determine that the location is safe and protected from the elements. Technician is to record the exact location of where the work is actually performed.

Hours	Subtotal
[REDACTED]	[REDACTED]

Corrective Action

Work performed at:
KLOZ Airfield
566 Hal Rogers Dr
London, KY 40744

Inspection Information

- Final Inspection: [REDACTED] (06-24-2025)
- Prelim Inspection: [REDACTED] (06-24-2025)
- Ready for Inspection: [REDACTED] (06-24-2025)

Item Summary	Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
--------------	---------------	---------------	------------------	-----------------------

Item: 3

Discrepancy

Personnel are required to document all equipment used during maintenance other than those already listed by Chief Inspector.

Hours	Subtotal

Corrective Action

additional equipment required.

Equipment Name: 64 element phase array probe

Equipment Type: UT probe

Manufacturer: Olympus

Equipment Name: .25" x 5MHZ probe

Equipment Type: UT probe

Manufacturer: Olympus

3" Mirror

2" Mirror

1" Mirror

Tap testing hammer

6" Scale

12" Scale

16Ft Tape measure

.25" probe extension holder

Inspection Information

- Final Inspection: (06-24-2025)
- Prelim Inspection: (06-24-2025)
- Ready for Inspection: (06-24-2025)

Item Summary	Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Item Subtotal: \$0.00
--------------	---------------	---------------	------------------	-----------------------

Item: 4

Discrepancy

Travel to KLOZ airfield
16 hrs x 2 technicians
Travel from KLOZ airfield
16 hrs x 2 technicians

Hours	Subtotal

Corrective Action

Traveled from DLH to KLOZ. Traveled from KLOZ to DLH.

Inspection Information

- Final Inspection: (06-24-2025)
- Prelim Inspection: (06-24-2025)
- Ready for Inspection: (06-24-2025)

Item Summary	Labor:	Parts: \$0.00	Shipping: \$0.00	Item Subtotal:
--------------	--------	---------------	------------------	----------------

Item: 5

Discrepancy

SF 51.30.7110002 Bondline crack: Perform damage assessment of aircraft due to hangar collapse.

Hours Subtotal

Corrective Action

Performed damage assessment inspection IAW SF50 AMM 51-10. Damage Assessment sent to Cirrus engineering for disposition.

Inspection Information

- Final Inspection: (06-24-2025)
- Prelim Inspection: (06-24-2025)
- Ready for Inspection: (06-24-2025)

Item Summary

Labor:

Parts: \$0.00

Shipping: \$0.00

Item Subtotal:

Item: 6

Discrepancy

SF 71.00.0100 Power Plant Misc: Perform Foreign Object Ingestion FJ-AAA-71-00-00-001A-420A-A/ Impact Event FJ-AAA-71-00-00-062A-420A-A inspections.

Hours Subtotal

Corrective Action

Performed Foreign Object Ingestion inspection FJ-AAA-71-00-00-001A-420A-A and Impact Event inspection FJ-AAA-71-00-00-062A-420A-A IAW WI-INT LMM 71-00-00. No engine runs performed, no visual defects noted.

Inspection Information

- Final Inspection: (06-24-2025)
- Prelim Inspection: (06-24-2025)
- Ready for Inspection: (06-24-2025)

Item Summary

Labor:

Parts: \$0.00

Shipping: \$0.00

Item Subtotal:

Shop Supplies:

Total Shop Labor:

Misc Charges Total:

Total Parts: \$0.00

- Travel Expenses - Truck fuel:

Total Shipping: \$0.00

- Travel Expenses - Truck rental:

Additional Charges:

- Travel Expenses - Lodging

Tax: \$0.00

- x 2 technicians x 3 days:

Amount Charged:

- Travel Expenses - Per Diem

Amount Paid: \$0.00

- x 2 technicians x 4 days:

Amount Due:

Important Information

*****Please send all payments to:

Cirrus Design Corp.
Accounting Department
4515 Taylor Circle
Duluth, MN 55811

I have reviewed the file on this article and the accompanying discrepancy form(s). This article was repaired/inspected in accordance with current requirements of the Federal Aviation Administration and has been determined to be unairworthy and is not approved for return to service. A list of discrepancies and unairworthy items has been provided to the owner operator. Pertinent details are on file at this Certified Repair Station No. CRS YD5R855Y under Work Order No. DLH23637-06-2025 Dated 06-24-2025

Authorized Inspector:

 6/24/25

Signature & Date