





YEAR:	REC TAC	Date 1-31-25 N8817P Tach 348.2	
DATE	TIMI	Comply with AD 2012-17-06 stabilator horn inspection, do defects noted. AD due	r
	 	again 1-30 or 848.2	-
	 	Micrichaelamburrino AP3184331 IA	-
	-	Michaellamburrino AP3184331 IA	-
	<u> </u>	Date 5-4-25 N8817P Tach 368.2	
		Remove existing DG and install used DG of same part number,	
		Michael Tamburrino AP3184331 IA	
		wellen (parles	
			_
	·		_

_

_

_





YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Tec Facility. (See back pages for other specific entries.)	chnician or Repair	YEAR: DATE	RECO TACH TIME	Lakeland Aviation of Minocqua, Inc. (715) 356-3891 N# 8817 P FAA CRS # RN7R687Y	or Repair
		Jak	Lard (Aviation of Minocqua, Inc				DISCREPANCYComplete 24 month transponder tests IAW_EAR_91.413	
s	erial numb	er 8691	ransponde 5 in existi	B-2-22 N8817P Tach 283.8 er KT78A serial number 4663 and install used KT76A ng tray. Ops check OK				CORRECTIVE ACTION Tests satisfactory-as per FAR 43 Appendix F.	
								The aircraft and/or component identified hereon was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. SIGNED DATE W.O.# 3-2-22 5007	

TE_	RECORDING TODAY'S TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technicia Facility. (See back pages for other specific entries.)	n or Rep
_			
_			
_	fakelari	Aviation of Ainocqua, Inc.	
_	Date 11-17-2		
-	appendix (d) and is considere found OK. Install new ELT bat	s been inspected IAW an annual inspection as per FAR 43 d airworthy at this time. Elt checked as per FAR 91.207 (d) teries, Batteries due again 11-23. Install 2 new 164-01900 lke pads, 4 new ms28775-218 caliper o rings. Bleed brakes	
-	Michael Tamburrino AP3184	3311A Jacko	

Iskeland Aviation of Hirocqua, Inc.

Date 11-17-21 N8817P Tach 254.8 PTSMOH 1365.9


Michael Tamburrino AP3184331IA

	TACH	FLIGHT TIME IN	YEAR		
	TIME	FLIGHT TIME IN Entring must be and and during Number of Technician or Repair		Jakeland Aviation of Hinocqua, Inc.	1 or Repair
DATE	TIME	Fakeland Aviation of Alinocqua, Inc. Date:7-11-19 N8817P Tach:207 5 AFTT 5171.5 ETSMOH 1340.0 ETT 1982.5 I certify that this airframe has been inspected IAW an annual inspection as per FAR 43 appendix (d) and is considered airworthy at this time. Installed new ELT batteries, ELT checked IAW 91.207(d) found OK. Installed new Sky Beacon ADSB out nav & strobe. Comply with AD 2012-17-06 inspection, found ok. Michael Jamburino AP3184331IA	DATE	Tach 238.9 PTSMOH 1335.0 I certify that this airframe and propeller has been inspected IAW an annual inspection as per FAR 43 appendix (d) and are considered airworthy at this time. ELT checked IAW FAR 91.207 (d), found OK. ELT batteries due 7-21. Complied with AD 77-13-121 paragraph B, install new bungee cords. Install new SSD120-30N encoder, serial# N27058. Remove altimeter and VSI, send alt in for overhaul by Kelley Instruments. Reinstall rebuilt altimeter. Install exchange VSI part # 7000 serial# OE223. Remove flap motor and transmission, disassemble and clean, repack transmission with Aeroshell 64 grease and reinstall. Run up, ops check OK	
		 			


YEAR:	Riegelman Aviation Co., LLC Mobile service to fit any schedule "serving the Midwest".	or Repair	YEAR:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations 1 Entries must be endorsed with Name, Rating and Certificate Number of Technicia. Or Repair
DATE	Ph. (715) 686-7523 FAA CRS # RN7R687Y		DATE	TIME		SERVICE	Facility. (See back pages for other specific entries.)
<u> </u>	Cell (262) 994-6706				,		LAKELAND AVIATION of MINOCQUA
	ALTIMETER, STATIC AND TRANSPONDER CERTIFICATE					D	Pate 8/17/18 N8817P Tach 191.0
	TEST ALT1 0 .5 1 1.5 2 3 4 5 6 8 10 12 14 15 16					1	Airframe TT 5155.06 PTSMOH 1287.1
	TOL 20 20 20 20 25 30 30 35 70 40 60 80 90 100 90 110						at this airframe and propeller has been inspected
	ACTUAL 15 15 15 75 90 75 30 30 10 40 20 30 30 40 20 25 40 20						nual inspection as per FAR 43 Appendix (d) and
	TEST ALT. 18 20 22 25 30 35 40 45 50 BARO. SCALE ERROR (TOL. ± 25 FT.)						ered airworthy at this time. Complied with ADs
	TOL. ± FT. 120 100 140 155 180 205 230 255 250 28.10 28.50 29.00 29.50 29.92 30.50 30.90 30.98						79-20-10, 94-13-10, 2015-19-07, all due again at
	PRICTION 30 59/0 7 6					/19	-
	HYSTERESIS (TOL. ± 75 FT.): MAX. TO MAX. TO AFTER EFFECT (TOL. 30 FT.): OK CASE LEAK! OK				N	1ichael Ta	amburrino AP 3184331 IA and the Third The amburrino
	ALTIMETER MAKE: UNITED BLIND ENCODER MAKE: NARCO TRANSPONDER MAKE: KING						-
	SIN F4993						-
	CERTIFIED ALTIMETER PER FAR 43, APP. E (b) TO						
	CERTIFIED AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM PER FAR 43, APP. E (c) TO COMPLY WITH FAB 91.411. CERTIFIED TRANSPONDER PER FAR 43, APP. F TO COMPLY WITH FAR 91.413. The alcraft and/or component identified above was repaired and inspected in accordance with current Faraget Avision Regulations.						
	and was found airworthy for return to service. Pertinent details are on file at this spectry under the toxic with current early for number. Date 15 18 Tach/Water. W.O. 2365 Signed						

DATE	TIME		SERVICE	Enures must be encorsed with iname, Hating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE	TACH TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				9.1 ETSOH 1283.6 ETT 1920.1 PTSOH 1241.1	1/29/14	158.2		Remove	BOOST PUMP and Send in FOR OVERHOUL
	I caily	That	this Are	Come has done inspected I AW mis minuse ingretion in see				ReInsta	LI BOOST PUMP after over Hour BU A-450 MOTOLS
	FAR 13 M	v(d) m	whi con	a dared neworth at this time. Bil - feller changed. Installed				LLC. I	INSTALL NEW FULL Flow Transpucer PORT
-	New M	his ford	or Gard B	mages A/W 451-359- Roberthin testal OK. Inalle New]	700900-	Lear CHECK & OPS CHECK DU
	KIGO MA	امعر <i>دا</i> ا	DO 1	Leglore 2 Ett batteres - chell is pre BAR 91.207(1) - AD.			 	mona	d Jambro AP 3184331
	com receiption	en cha	Jeef 70 0	and - She All comprisine sheet: 1/2 Centilicons					
9/11/17	TECH	1837		RAMOVE FULL SELECTOR VALUE - FEPOIR FINDICATOR		<u> </u>			
				REINSTALL VALUE - OPS CK - OK					
				muchaelyamber AP3184331		<u> </u>			
						.	<u> </u>	<u> </u>	

£									



					YEAR:	Riegelman Aviation Co., LLC	Mobile service to fit any schedule	or Repair
	RECORDING TACH TIME	FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair		"serving the Midwest".	FAA CRS # RN7R687Y	
DATE	11ME		SERVICE	Facility. (See back pages for other specific entries.)	DATE	Ph. (715) 686-7523	N#8817P	
1/10/15	TACK 78	.3	TIAF 504	2.4 ETSOH 1216.9 ETT 1853.4	- <u>- </u>	Cell (262) 994-6706	ND TRANSPONDER CERTIFICATE	
	I anh		9 this		·		2 3 4 5 6 8 10 12 14 15 16	
	samo	see &	and	is consider the worth of this time. Sof check in para		TEST ALT1 0 .5 1 1.3 2 1000 FT1 0 .5 1 1.3 2 1000 FT1 0 20 20 20 70 25 30 TEST.	70 35 76 40 60 80 90 100 80 10	
1	, , , , , , , , , , , , , , , , , , ,		_	is dea 1/17 AD compline up to Inte- see		ACTUAL FRICTION FS 0 75 75 75	20 20 16 30 C 3 30 TOL. ± 25 FT.)	
	AD com	pl. Tu	charl.	1-262. AP; 926356 IA		TEST ALT. 1B 20 22 25 30 22 25 30 20 20 20 25 30 20 20 20 20 20 20 20 20 20 20 20 20 20	35 40 45 30 250 28.10 28.50 29.00 29.50 29.92 30.50 30.90 30.99	
6/8/11	TAch 113	,, -	TAF 507	7.5 ETSOH 1251.9 ETT 1888.5 ATSOH 1290.5		TOL. 120 100 140 120 100 ACTUAL - 7 5 5 7 7		
· //#	(cert	1 16		no of some on passeller has been inspected in my	_	HYSTERESIS (TOL. ± 75 FT.): MAX.	AD% TO AFTER EFFECT (TOL. 30 FT.): OK CASE LEAK: OK AAX. TO AFTER EFFECT (TOL. 30 FT.): OK CASE LEAK: OK ACODER MAKE: NAREO TRANSPONDER MAKE: KING MODEL KT 18A	
	/ }:	< I	Z) 1	en FARY3 you(d) and is considered monthly at this time.	- 1	ALTIMETER MAKE: MAITEN	40850MODEL	
r	46	4 ° I	<i>7</i> E	10207(d) OK Batties du 1/17. Al constromo chelal		S/N	S/N	
-	to Isla	-see A	Ocomplia	nes 1:50 Ap1926356IA		CERTIFIED STATIC SYSTEM PER PAR 45, 40P. FT CERTIFIED AUTOMATIC PRESSURE ALTITUDE RE CERTIFIED TRANSPONDER PER FAR 43, APP. FT CERTIFIED TRANSPONDER PER HARNING RIDOYS WO	PORTING SYSTEM PER 1743 13. A TEMPORE TO COMPLY WITH FAR 91.413 OCOMPLY WITH FAR 91.413 or Regulation: or specific and inspected in accordance with current Fedoral XVIII work number.	
					_	The aircraft and/or component to stilling and was found airworthy for roturn to sarvice.	W.O. 1931 Signed La January	
	73 JAGE		U Complete			CERTIFIED AUTUMATION PER FAR 43, APP. F. The aircraft and/or component identified above we are the aircraft and/or component identified above we are the aircraft and was found airworthy for roturn to service. Date:	PORTING SYSTEM PER 14.43. O COMPLY WITH FAR 91.413. Is repaired and inspected in accordance with current Federal Aviation Regulations is repaired and inspected in accordance with current Federal Aviation Regulations. Pertinent details are on tile at this agency under the following work number. W.O	-



									Description of Inspections, Tests, Repairs and Alterations
YEAR:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations	YEAR:	RECORDING	TODAY'S FLIGHT	TOTAL TIME IN	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
2017	TIME		SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	_	TIME		SERVICE	Facility. (See back pages for other specific entries.)
DATE	ĹI			radiity. (See back pages for other specific entries.)	DATE		·		
12/12/12	4934	8 hrs		TTAF4934.8 hrs.	12/12/	12	el ce	utily of	this aircraft has been inspected according to a spection and was ditermined to be in air-
		Re	moved	fuel sector value P/N Hoof A 73V S/N 1264			ann	untin	spection and was determined to be in air-
		and	sent	fuel slector valve P/N Hoof A 73V S/N 1264 to Webco arieraft for repair. Reinstalled valve after repair and cheeked fuel seloctor for			wor	thy co	a el tema
		Just	selector	valve after repair and checked fuch selector for		l		0	Robert & Sehring AI1444441
		_Stax	21.		_	<u> </u>			
		_1	an seti	action test, greased gear and lubed controls.					
		U/W	A.D.68	action test, greased gear and lubed controls05-01 inspection of muffler shroud CK.OK12-06 cracks in Fin FWD spar, visual inspection					
	·	C/w	A.D. ?	5-12-06 cracks in Fin FWD span, visual inspection					
		CK.	2KC/V	VH. V.94-13-10 on loose stabilator toique lube Cho	-				
		18.0	2012-	17-06 on stobilator from assemble was e/won			<u> </u>		
		_6/	15/02.	ELT Sattery Ex. 3/20/15 Cheshed ELT I/A/W					
		FA	R9/,20	orpar(d) EKOK (cost)					
•									1.24

DATE	TACH TIME	FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See backpages for other specific entries.)	YEAR: DATE	AIRFRAME	or Repair
11/10/4		torg torg toa	ion ch ue tu certify annu	2-06 cracks in Fin FWD spar, visual in- OK. C/W A.D 94-13-10 on loose stabilator be CK.OK. this aircraft has been inspected according al inspection and was determined to be in condition.		N8817P PA24-260 ROCKFORD, ILLINOIS (815) 395-0500 3/21/2012 Installed landing gear strut tubes after they re-chromed by United Plating	
				Robit Glebring AI/44441		Works, inc. FAA repair station #FA2R813K. See UPW Order Numbers 438665 and 438916 for further details. Struts were assembled and installed with new seals and serviced with MIL-H-5606 hydraulic oil and Nitrogen. Performed gear retraction/extension checks. All checks were normal. –END-	:
						Mike Reeves 3494207A&P	

YEAR:						
RECORDING TODAY'S TOTAL TIME IN SERVICE PATE RECORDING TODAY'S FLIGHT TIME IN SERVICE TACH TIME FLIGHT SERVICE TOTAL TIME IN SERVICE Entries must be Facility. (See ba	Model ARSO s/n S4340 and system have been tested & inspected as required by FAR	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
69 10 22	91.217 in accordance with A.C. 43-6A. Pertinent	1				THE CONTROL OF THE CO
I certify that the altimeter/altitude encoder &	details are on file at this agency under	11/16	In Jack	1 W00	6 2 has	TTAF 4886.2 Jus.
static system tests required by FAR Part 91.411 in	Work Order No 11-1,3013 to 20, 00 0 ft	10	11 Juin	700	0.4.100	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
accordance with FAR 43, App. E have been	Date	-		Ron	roved &	cul strainer and fuel valve make Hoof P/N A 73V
performed. The altimeter/altitude encoder was	Signed			, ,		At to the bes aresalt for repair Reinstalled
tested by an - Sinn -	For: Superior Aviation	-	S	W/2	64 and	sent to Weber arieraft for repair Reinstalled
2 1 7 7 20 10 0	250 Riverhills Road		/	0 1	1.0	Iter server and reinstalled full strainer with
on 221-11 to 20,000 ft.	Kingsford, MI 49802		1	uee 1	new no	1 with doning and we
For: Superior Aviation United	Repair Station #9SVR935L	_		news	uspet	g screen and new quick drain valve.
250 Riverhills Road	I certify that transponder Model			.0	1-11	De la Hay Comera DG 3 1/12 3/N TO
· · · · · · · · · · · · · · · · · · ·	KT78 A s/n 4663 and system have			cln	stalled	emoved old battery cable amaster solenoid by
Repair Station #9SVR935L S/N	been tested & inspected as required by FAR 01 412	_		4/1/2	110. K	emoved old battery cable a master sounord by
7/1/19	in accordance with FAR 43, App. F. Details are on			770	1	+ + + + a landed on beginnell and installed
	file at this agency under Work Order No. 7-12013	_	1	batt	cul soo)	to starter solenoid on firewall and installed
	Date 2-21-16	-			11	a a hea
	Signed Since Later			new	Egyan	2 21 1 - 11 6 1 ELT T/A/12 EDP 0/ 207/A
	For: Superior Aviation	-		EL	T batt	my Ex 3/20/15 Checked ELT I/A/W FAR 91,207(d)
	250 Riverhills Road			1	11 11	9. And was down retraction text : CIWA. D.
	Kingsford, MI 49802	_		CK.O	K. July	Tentrols and run retraction test: C/WA.D.
	Repair Station #9SVR935L	_		10	05-01	inspection of muffler shroud & K.OK. (Cont)
	Kepan Station #324K332F			60	01011	W Contract of the contract of

					_!				
YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Responsible. Facility. (See back pages for other specific entries.)
				TTAF4801.7 Mis	0/	1 1	1		- TATUOUN 1010A
Date	10/15/09	ndicates	480/.7	hrs. on TACA Libed contrals, greased gear and	4/	NO JA	1.48	10.11	ls and run retraction test. C/W A.D. 77-13-2
l Cer	tify this l	NAME OF THE	er airfra	ne has been in sum setartion Test ClWAID 68-			Luly	conno	wand have here and the wat
specte	d accordin	g to a	00 hour /	innual inspection	i	<u> </u>	sistas	fed 2 m	ew bunger cords P/N 8097 main gear Mext
and w	ras detern	nined to	be in air	worthy condition CK.OK. E/WA.D. 25-12-06 crocks in	-		V = a	1/200	Ban and realit in son such dance senate and time
		<u>'</u>		4. FWO was sixual in a certion of KAK	-!		Y Y	Va Maria	we die Parts to have Oth, Densiales senate
				Lin F. W. D. spar, visual inspection CH.OK. C/W A.D. 94-13-10 on loose stabilator torque			<i>ከ</i> ሰ ፈ	8-05-01	in vett and mulflet sproud CI.O. C/WITTO, IS
				tube c. K.OK A.D. 27-13-2 on bunger cords due		1	4	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	EWI ARA DELLA MORIERE
				9/20/10, CK, EtT per F.A.R; 91.207(d) Bat. Ex. 3/2015.			Joan	loose	statulation torque tube CH. CK. CK ELT per FAR 91,20%(d)
				Robert Stehring AT 144441			עים על	FIT Ra	the 08x 3/2015
				The state of the s	_			' le 🔟 'v'	if a and the has been inspected according to a
			-		_		ann	wal in	nortion and uns dellemente no vector will and
-		<u> </u>			_		100	dition	Robert Jehning AI/444441
					_				

	100				
YEAR: RECORDING TACH TIME TODAY'S FLIGHT TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
I certify that the altimeter/altitude encoder & - static system tests required by FAR Part 91.411 in accordance with FAR 43, App. E have been - performed. The altimeter/altitude encoder was tested by		Date / //cg	Indica	des 4757	2 Fors. on TACh Retraction test CK. O.K. Put nitrogen
on 1/28/02 to 20,000 ft. For: Superior Aviation 250 Riverhills Road Kingsford, MI 49802 593:P-1A-63		pected acco	rding to		frame has been in- in right struct, e ju A.D 68-05-01 inspection in spection time of muffler shrond c.K.OK. e/w A.D arrivarity condition time of muffler shrond c.K.OK. e/w A.D. Spar, visual inspection 25-12-06 exacts in Fin F. W.D. Spar, visual inspection C.K.OK. e/w A.D. 94-13-10 on loose Stabilition torque table
Repair Station #9SVR935LS/W F4443					e K. O. A. D. J. J. Jon Bunger was Pero
	- 4/9	1/29			yew prop control cable p/s mcd55-252-ops chile OR.

YEAR: RECORDING TACH TIME	FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs aclity. (See back pages for other specific entries.)		TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Date 19/1/07 I Certify this spected accord and was dete	Indicates powerp ling to a amined t	s 4700.9 lant, airfr 190 hour to be in a	Firs. on TACH Installed new engine oil coalur for me has been in- me has been in- minual inspection Diagara Thermal Products LLC. P/N inworthy condition 20002 A. S/N IOT-6321-10. Removes right muffler 4 sent to Dawly as to have rebuilt Reinstalled R. A. muffler. Men Auro Dust from left muffler to Eng. intake air box. Run setraction tist. C/W A. D & 8-05-01 mispection of muf	Date Sign	rtify that the a let ACCO let ACCO e been tested of 217 in accorda ails are on file rk Order No. Acco se ACCO Superior 250 Rivet Kingsford Repair St	Aviation hills Road	d as required as r	I certify that transponder Finds and system have been tested & inspected as required by FAR 91.413 been tested with FAR 43, App. F. Details are on
			Spar, visual inspection & K.OK. C. pu B. D. 94-13- on loose Stabilitor torque table & K.OK. A.D. 97-1 on Burger cards Dace 9/2010. Robert Ashing AT 144444	0 -		adon #95	VK935L	

YEAR	Piper PA24-260 Heritage Aero, Inc. S/N 24-4273 1651 Grumman Dr. N8817P Rockford, IL 61109		to allow for in depth visual inspection of horn assembly-stabilator torque P/N 20399-02. Removed paint and primer, cleaned, performed inspection-no crack found. Applied Zinc chromate primer to bare metal. Reassembled horizontal stabilizer in accordance with	
	AIRFRAME 6/15/07 WO 1537 Tach: 4679.97		Piper maintenance manualEND	
-				
-	Replaced the landing gear wire harnesses complete with 4 new micro switches identical to the Piper P/N micro switches for the nose gear and left and right main gears in the		Jan Wind	
7	wheel well areas with new fabrication of properly marked MS22759 wire, wire terminal	ls, ——	Jeffrey WFink AP 333568922	
-	PIF-200 silicon-coated fiberglass sleeve, and installed with cushioned clamps.		1 - 2	
	Fabrication and installation as per AC 43.13-1B sections 11-66, 11-68, 11-69, 11-76, 11			
S 5	77, 11-88, 11-96, 11-97, 11-146, 11-167, 11-174 and 11-210. All work performed and using methods found with reference to the Piper Single Comanche Service Manual 753-	. —		
-	516, 9 th revision dated August 15, 1998. Weight and balance not affected. An			
	operational check was performed and found to be satisfactory. Installed 2 new Webco			
-	P/N W455-180 landing gear push-pull control cables. Disassembled horizontal stabilized	er		

-

		, ;
Craft Record General Information	24 24 26	
nufacturer _ Proex	Model <u>PA 24-260</u> Registration Number <u>N 88/7</u> P	
te of Manufacture 5 4 3	1965	
Model	IO 540- D4A5 Serial 6-5083-48	
	Model HC-C2YK-1BF	
Model - MARIZEII	C H 25893Serial	
May . E a	E 843 4 6 Serial	ŀ
Model Serial	301144	ļ
		İ
11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		



The Cardinals
3730 Trout Lake Road
Woodruff, WI 54568

FEB 99

		Al	RCRAFT LOG		Registration No				
Date	Aircra		Recorder	Maintenance	and Remarks		Signature	Certificate No.	
ENGINE MODEL: 10-540-D4A5 ENGINE SN: L-226 REG. NO: N8817P WORK ORDER: 2212-10-2006 Engine Entries Removed and replace	This Date Brought Forward 14-46 14-46 See temp control, oil cooler tent identified above was reso service. Pertinent details SiGNED Jim Jakus	Lone Mounta Repair Station No. 1 2830 N. Rancho Dr Las Vegas, NV 891 Phone: (702) 309-2 bypass valve. Engine in	Reading in Aviation, Inc. 90R473Y Suite A 30 200 un and leak check good. accordance with current regulation of the above W.O. number.	DATE: 10/10/2006 A/C TSN: ENG TT TACH: 4631.48 ons of the Federal Aviation Administration and is Work Order: 2212-10-2006 Printed by EBis 3 (datcomedia.com)	Sold To: Dan Cardinal 3730 Trout Lake Road Woodruff, WI 54568 Aircraft Number: N8817P Total Time 4,645.7 Liccroancy. 1 Action Taken: Inspected gear and found gear motor Webco. Installed repaired motor transmission Serviced tires with N2. Sublet Service Completed: 10/25/200 Motor Section: Replaced brushes, cher Replaced gear & worm in gear box, re- bearings, repacked jack shaft with new WEBCO Aircraft PO #: PON6.06170	Hobbs Time 0.0 Tach Time: 4, transmission inoperative. Removed motor transmission assembly. Performed 5 gear cycles and 1 emergency 6 Description: 4587-00-1 Dukes Gear Transmission S/ cked armature rotation, tested and returned to service. packed gear housing with new grease, replaced balls or grease, replaced barrel on jack shaft. Tested and returned	732 Opened: 10/19/2006 848 Closed: 10/28/2006 869 Opened: 10/19/2006		
Total To Carry Forward					The Authorized Sign	e articles and/or work hereon des cribed is/are certified airworthy (unless otherwise specified). Autopilots Central, Inc. FAA CRS CM2R747K			

Date	Aircr	aft Time	Recorder	Maintenance	Registration No	·	
	Brought	Total O. C	Reading		and Remarks	Signature	Certificate No.
	Forward	- Bolan	coy bro	entry NBB17P p with Aces Probalencen			e e tube
		L strul	with ni	trogen	C/WA.D. 94-13-10 CK.OK. A.D. 2006-03-08	on souse spring D/N/1	not isabled
			RL	V65838083	7	Robert & Leaning AII44	441
		<u> </u>			Piper PA24-260 S/N 24-4273	Heritage Aero, Inc. Rockford, Illinois	
Date 8/7/06 in	ikates 4608.	9 hrs. on TA	h Lus	retraction test & greased	N8817P AIRFRAME 9/15/06 WO# 1400	815-395-0500 Tach: 4619.24	
spected according and was determi	to a 100 be in a	ame has been annual inspect irworthy condit	in- gear	I new tail now bulb.	Removed horizontal stabilators to inspect fo Treated torque tube with LPS#3, and reinsta	r corrosion on the torque tube. lled stabilatorsEND-	
Shroud CK. Total To	OK. C/WA	D.75-12-a	6 cracks	in Fin FWO Spar, visual		Mike Reeves 325780366A&P	
Carry Forward		inspection of	K.OK.	(Cost)			

	Aircraf	t Time	Recorder		and Remarks	
Date	This Date	Total	Reading	Maintenance	and Kemarks	
Model AK have been 91,217 in a details are Work Orde Date 12-2 Signed For: Su 25 Kin	at the altitude encounts of the second accordance with A.C. on file at this agency of No. 132 to	and system	tem FAR nent		The Aircraft was repaired current Federal airworthy for	Garmin (Enroute, this day FAA Form airplane and/or component and inspected in eral Air Regulation
ral To					Order No. Date Signed For Superior Ford Airp	e on file at this a

Registration No.	
	Signature

Certificate No.

Log Book Entry - N 8817P

Garmin GNS430 s/n 97104855 certified for VFR/IFR Enroute, Terminal, and Non-Precision Approaches this date.

FAA Form 337 and FAA approved supplement to the airplane flight manual this date.

craft and/or component identified hereon aired and inspected in accordance with Federal Air Regulations and was found for return to service. Pertinent details of r are on file at this agency under Work

112/14/17	Aircraft	Time	Recorder	n A. Carlo
Date	This Date	Total	Reading	Maintenance
	Brought Forward			
Date 9/16/0	1 Indicates 45	5.3 hrs. on	FACh	
I Certify th	his powerplant, air	frame has been	en in- c/	N. A. D. 27-13-2 by installing
spected acco	rding to a 100 ho	ar annual ins	pertion	v A.D. 27-13-2 by installing
and was de	termined to be in	airworthy con	ndition 2 n	wmin gear bungee cords
/				linings RA main.
				ch ailson. Installed cabin
				146. Installed new left moun
				earings. I new bearing cups
	/ /			tion of muffler shroud LK. OF
1				Spar visual inspection CK.O
Carry Forward				12004)

and Remarks		Signature	Certificate
I certify that the altimeter/altitude encoder & Static system tests required by FAR Part 91.411 in accordance with FAR 43, App. E have been performed. The altimeter/altitude encoder was tested by In 12-28-05 to 2000 ft. For: Superior Aviation, Inc. 250 Riverhills Road Kingsford, MI 49802 SIN C4443 Repair Station #EATR437D	I certify that trans ST SA s/n been tested & inspin accordance with file at this agency Work Order No. Date T - 28-05 Signed Superior 250 River Kingsford	sponder K.NG 4463 and sys- pected as required by 1 FAR 43, App. F. Do under 10732 Aviation, Inc.	Model stem have by FAR 91.413

Certificate No.

Signature

		Aircraft Time	
_		Log Book Entry N8817P	
	1/25/05	Removed existing Northstar M1 Loran C w/RS08 switching assy, number one King KX170B w/Radair 240 CDI systems and installed in accordance with manufactures instructions, AC43.13-2A, AC43.13-1B and AC20-138, Garmin GNS430 w/Collins IND351 CDI system. Recomputed the acft weight & balance and revised the equipment list. FAA Form 337 this date. Note: GPS portion of GNS430 not approved for IFR at this time with placard installed so stating.	_
_		The Aircraft and/or component identified berein	_
_		was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. Pertinent details of	_
-		the repair are on file at this agency under Work Order No	r
_		For: Superior Wiation, Inc.	
-		Ford Airport Iron Mountain, MI Repair Station #EATR437D	-
Tota			

Carr

[references and expression and expression]

Date: 1-12-05	AIRFRAME LOG ENTRY N8817P

Tach: 4551.3

Serviced right hand main strut with 5606 hydraulic fluid and nitrogen in accordance with PA24-260 service manual per 2-34, 2-35. Troubleshot alternator system and found no defects. Troubleshot EDU700 GEM and found broken ground from unit. Repaired ground and performed operational check of entire system. No defects noted at this time.

The aircraft and/or components identified hereon was repaired and inspected in accordance with the current Federal Air Regulation and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under work order No. 26136

Date: 1-12-05
Signed:
Superior Aviation
250 Riverhille Park

250 Riverhills Road Kingsford, MI 49802

and Remarks

Repair Station No. EATR437D

Carry Forward

	Aircraft Time		Recorder	Maintenance
Date	This Date	Total	Reading	
7	Brought Forward		been in acc file a	tify that transponder KNG Model 18A s/n 4663 and system have tested & inspected as required by FAR 91.413 cordance with FAR 43, App. F. Details are on t this agency under c Order No. 9899 11-26-3 ed Superior Aviation, Inc. 250 Riverhills Road Kingsford, MI 49802 Repair Station #EATR437D
otal To Carry Forward				

		Signature	Certificate No
and Remarks		Signor	
certify that transponder s/n 463 and system have leen tested & inspected as required by FAR 91.413 In accordance with FAR 43, App. F. Details are on lile at this agency under Nork Order No. 925 Date 2-30-03 Signed For: Superior Aviation, Inc. 250 Riverhills Road Kingsford, MI 49802 Repair Station #EATR437D			
I certify that the altimeter/altitude encoder & static system tests required by FAR Part 91.411 in accordance with FAR 43, App. E have been performed. The altimeter/altitude encoder was tested by On 12-30-03 to 2000 ft. Superior Aviation, Inc. 250 Riverhills Road Kingsford, MI 49802 Repair Station #EATR437D	have been te 91.217 in acc details are o Work Order Date 17-30 Signed For: Sup	the altitude encoder / 3/3/3/2 s/n 3/3/3/2 s/n 3/3/2/2 sted & inspected as recordance with A.C. 43-n file at this agency un No. 9/35 to 2000 to 2000 to 2000 for Aviation, Inc. 20 Riverhills Road gsford, MI 49802 pair Station #EATR437	6A. Pertinent der conft.

-	250 Riv Kingsfé Repair 8
-	Repair S
(<u>)</u> . (
-	

Total 1 Carry Forward 4/26/02

Registration No.	
	tate No.
4/26/02 AIRFRAME LOG ENTRY N# 8817P	_
Tach: 4307 21	
Inspected instrument lights will not dim. found instrument	-
light rheostat assembly inoperative pn:22858-00. Part no longer	
procurable from Piper Aircraft. Removed rheostat assembly and	-
installed Aviation Unlimited pn: AL697-1 dimmer modute and	
rheostat kit. Dimmer modual mounted to lower surface of glove	-
boy (aft) Wards accomplished in accordance With Piper Committee	
Service manual acetion 0 figure 9-65 and AC43.13-16 Chapter 11	
and AI 607 1 mounting instructions. Removed radio light dimming	
rhoostat and in-talled Assistion Unlimited Inc. Dn. ALOJI	-
dimmon module and whoogtat kit Dimmer module mounted to Isin	
Surface of along the (first) Troubleshot Short III lauto 12800	
wining to 1 - ff 1 - ing and can in light Clicuit. Illistation	
one in the from objecting work accomplished	
on 1 AT COT 1 mounting increase for all 11010	
chapter 11. Weight and balance revised; Current empty 1927.96,	

Arm 85.86, Moment 165542.17, useful load 972.04. -----CONTINUED-----

AIRCRAI	•	

AIRFRAME LOG ENTRY N# 8817P (CONTINUED)

Tach: 4307.21

4/17/02

Repaired sheet metal on seat backs and shelf on seat. Repaired door sill by remaking old part in accordance with AC43.13-1B/2A

4-11 through 4-13.

The aircraft and/or components identified hereon was repaired and inspected in accordance with current Federal Air Regulation and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under WO No. 2/349 Date 4-17-52

SUPERIOR AVIATION, INC. 250 RIVERHILLS ROAD

KINGSFORD, MI 49802

Repair Station No. EATR437D

Tota Carry Forward

Total To Carry Forward

4/17/02 AIRFRAME LOG ENTRY N# 3817P rte No. Removed and replaced all upholstery on sidepanels, headliner and AIRFRAME LOG ENTRY N# 8817P 4/17/02 seats. Replaced foam in crew seats. Removed and replaced Tach: 4307.21 all carpet. All work done in accordance with FAR 23.853(a). Removed existing Hoskins Novastar strobe light system. Removed Necessary flame certifications attached this log. rotating beacon model WRM12 from upper fuselage. Installed Aircraft returned to service this date. Whelen wing tip strobe lights, left pn:A650-PR-14, right pn: A650-PG-14, fuselage strobelight pn:A470A-S, power supply The aircraft and/or components identified hereon was pn: A413-HDA-CF, strobe breaker switch pn: W31X2M1G10, Whelen repaired and inepacted in accordance with current Faderal Air Regulation and was found all worthy for return install kit pn: HDT3-90 and jumper switch to allow all strobe to service. Pertinent details of the repair are on file at or fuselage only operation. Routed nav. light control circuit Utils agency under WO No. ____ / 3 87 wiring through unused rotating beacon switch and replacarded switch "nav. lights". Work accomplished in accordance with STC# SA800EA, Whelen anti-collision light system installation SUPERIOR AVIATION, INC. and service manual dated Sept. 16, 1999 and AC43.13-B chapter 11. 250 RIVERHILLS ROAD KINGSFORD.)MI 49802 Removed and replaced all cabin windows with new in accordance Repair Station No. EATR437D with AC43.12-1B chapter 3 section 3 paragraph 3-26, 3-27. Removed and reinstalled left hand flap after painting in accordance with PA-24 service manual section 4 paragraph 4-9, 4-25. Weighed aircraft, empty fuel, full engine oil, with unusable fuel in accordance with PA-24 service manual section 2. New empty weight 1927.0, C.G. 85.87, moment 165842.65, useful ----CONTINUED---load 972.04.

AIRCRAFT LOG			Registration No			
certify that the altitorerafe Timeer	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.	
required by FAR 91.2 P79H90bord per wish A.C. 43-SA. Pertinent details of M959 file still is tarancy under Work Order No. 10. 22. 550 ft. Signed			Date 7/26/01 Indicates 4248.8 hrs. on TACh See A. Certify this powerplant, airframe has been in- left in Spected according to a 100-hour annual inspection and was determined to be in airworthy condition new in the condition in	D. List. Insta	bled new	
For: Superior Avalion, Inc. Ford Airpert Iron Mountain, MI Repair Station #EATR437D	I certify that the altimet static system tests requ 91.411 in accordance w have been performed. T	ired by FAR Part Hit FAR 43, App. E	spected according to a see hour annual inspection and was determined to be in airworthy condition new land	ower tail nas	bulb.	
I certify that transponder Kyo	sted by		Bun situation test & greased ges	ching AI144	4441	
Lectify that transponder	Hon Mountain, N	1nc. 5934P-14.63 11 SN F4443				
Order No. 8137 agency under Work Date Signed For: Sup or Dation, Inc.	Repail Sation #	LAINTOFE				
Iron Mountain, MI Repair Station #EATR4370						
Total To Carry Forward						

-- -

AIRCRAFT	LO

SKYCOM AVIONICS, INC. AIRCRAFT LOG ENTRY

8817P

Removed loaner transponder unit, King KT-78A S/N 4632 and installed customers repaired unit, S/N 4663. Ramp tested and found to meet MPS.

and Remarks

Certify this powerplant, airframe has been in- Cowel Chaping Material top cowel and was determined to be in airwarthy and inspection

Registration No._

Signature

Certificate No.

and was determined to be in airworthy condition Run retraction test.

rotating beacon bull

The aircraft and/or compone	ent identified above was repaired and inspe	ected in accordance with current Federal Aviation Regula	ations
	9036.0H W.O. 102148	e on file at this agency under the following work number.	
TIMMERMAN FIELD 9305 W. APPLETON AVE.	CRITES FIELD 501 BLUEMOUND RD.		

501 BLUEN WAUKESHA, WI 53188 (414) 521-8180 D F.A.A. No. NC5D062N

Total To

Carry Forward

Description of work done:

---END---

MILWAUKEE, WI 53225

(414) 463-8180

☐ F.A.A. No. NC5R062N

AIRCRAFT LOG			Registration No					
Date	Aircraft Time		Recorder	Maintenance	Signature Certificate N			
	This Date	Total	Reading	Maintenance	and Remarks	1	Signature	T armirate No.
	Brought Forward ->					SKYCOM AVIONICS, INC	C. 0017E	
6/30/99				Installed AK450 Elf Exp-7/02	Description of work done:	AIRCRAFT LOG ENTRY	N# 8817P	
I Certify this	p owerpla nt, airling to a 100 hou	rame has been rannual inspend airworthy cond	in= new tion gear	2 new bungle Cords main L. See A. D. Fist back of A/C. Fog.	Removed inoperat	ive transponder, King KT-78A S/N 478A S/N 478A S/N 4632, tested IAW FAR 43 at	663, for service. In pp FEND	nstalled
1	or hing	7	ted gea	Loor Sun retraction test.	The aircraft and/or component is and was found airworthy for and was found airworth for an arrangement of the airworth for and was found airworthy for an arrangement of the airworth for and was found airworthy for an arrangement of the airworth for a supplied to	dentified above was repaired and inspected in accordance or return to service. Pertinent details are on file at this agence w.o. 102148 Signed Signed Sol BLUEMOUND RD. WAUKESHA, WI 53188 (414) 521-8180	with current Federal Aviation R y under the following work nu	Regulations umber.

~


Date	Aircra	ft Time	Recorder	1
Date	This Date	Total	Reading	Maintenance
	Brought Forward ->			
3/20/99	3871.7	Change Ol	I life be	Ob#684509 Ad Hisk take in
		Rt wing Ti	A # A/27	Justil Engine heat and Al MILESSE
		0		
Total To Carry Forward				

1900 0		Cianatura	Certificate No
Description of work done:	SKYCOM AVIONICS, IN AIRCRAFT LOG ENTRY	IC. N# <u>88/7</u>	P
XCHANGE OVERH HECKED AS PER F	TER PN#5934P-1 SN#F4443. INS IAULED UNIT PN#5934P-1A.56 S FAR 43 APP.E(a). REPAIRED KR- 3 SN# 60276. INSTALLED LOAN	SN#M8266. RAMP -86 SN#20092.	
	END		-
he aircraft and/or component ide and was found airworthy for	entified above was repaired and inspected in accordance return to service. Pertinent details are on file at this agen	e with current Federal Aviation Regulation under the following work number.	ions
Pate: 4-13-99 Tach:		30 00	
TIMMERMAN FIELD 9305 W. APPLETON AVE. MILWAUKEE, WI 53225 (414) 463-8180 D F.A.A. No. NCSR062N	CRITES FIELD 501 BLUEMOUND RD. WAUKESHA, WI 53188 (414) 521-8180 D FAA No. NCSD062N	DANE COUNTY AIRP 3430 MILLER STREI MADISON, WI 5370 (608) 246-8180 FAA No. NC53062	ET

TEST ALT		0	.5	1	1.5	2	3	4	ISP(6	8	10	12	2 1	4 1	5
× 1000 FT				20		30	30	35	1	40	60	80	90) 10	00	90
± FT.	20	20	20	70	25	70	70		70	2.0	70	30	30	0/	2	3
ACTUAL	N 10	10	10	120	20	20	130	-20	135	50	esc.	1	5/6		-01 +	25
TEST ALT	. 18	20	22	25	30	35	40	45	50	BAF	10. S	CALE	ERR		OL. ±	
TOL.	120	130	140	155	180	205	230	255	280 250	28.10	28.50	29.00	29.50	29.92	30.50	0.90
± FT.	10	100	-	120	7	7	7		1	120	1320	960	370	0	530 8	1
FRICTIO	IN IC	140	1	50%	20	40%	25			OT (TO)	30 E	11/	5	CASE	LEAK:	CH
HYSTER	RESIS (TOL. ±	75 FT.)	: MAX.	2	MAX.			R EFFEC	31 (10	L. 30 F	SPONDER		.1	ny	
ALTIMETER M	KE:	ソルラ	10			ENCODE	R MAKE:	of ar	12		MOD		876	7	/_	_
MODEL	11/1/1	7	11-6	ے	MODE S/N	1070		434	2		S/N.		460	3	_	_
S/N	747-	> TER PE	R FAR	13. APP.	13000	10-70	ice	2	FT. 7	O COM	MPLY W	VITH FA	R 91.4	111	0.0	1 1
									PER FA	R 43, A	PP. E (c) TO C	COMPI	LY WIT	H FAR S	1.4
CERTIFIED CERTIFIED The aircra	TRANS t and/or	PONDE	R PER F	AR 43,	APP. F	TO CO	MPLY V	VITH FA	Cted in	accord	ance w	ith curr	ent Fe	deral A	viation work nu	mb
The aircra	t and/or	compor	nent ide	ntified a	servic	e. Pertir	nent det	ails are	on file	at this a	agency	under	the lot	lowing		_

	Registration No		
	and Remarks	Signature	Certificate No
-			
	Description of work done: REPAIRED KX-170B SN#55891, KX-170B SN#60276. REMOVED DO SN#46990E. REPLACED CENTRAL AIR FILTER AND INLET HOSE REINSTALLED REPAIRED RADAIR 240 SN#14138B6. REMOVED SERVICEABLE KI-208 SN#14003. WEIGHT AND BALANCE CHAN LIGHTER IN-LINE FUSE. REPLACED BEACON LAMP. REPAIRED MAGNETIC COMPASS WIRING. SWUNG MAGNETIC COMPASS. RAMP CHECKED MARKER BEACON. COMPLETED CERTIFICATI 91.413. RAMP CHECKED MENTIONED SYSTEMS. FOR N 30 60 E 120 150 STEER 2 30 60 88 117 148 FOR S 210 240 W 300 330 STEER 179 210 240 272 301 332 SKYCOM AVIONICS, INC. 12-98	G 4000C SN#54644F. INSTALLED OH E. REINSTALLED REPAIRED CLOCK RADAIR R-1 SN#0792K0. INSTALLE IGE WAS NEGLIGIBLE. REPLACED STATIC SYSTEM LEAKS. REPAIREI INSTALLED COMPASS CORRECTION	ED CIGARETTE ——
	The aircraft and/or component identified about		
	The aircraft and/or component identified above was repaired and inspected if and was found airworthy for return to service. Pertinent details are on file	n accordance with current Federal Aviation e at this agency under the following work of	Regulations
	Date: 12 12 Tach: 3 865 Wa 404393	Charles and the same of the sa	
	TIMMERMAN FIELD 9305 W. APPLETON AVE. MILWAUKEE, WI 53225 (414) 463-8180 □ F.A.A. No. NC5R062N TIMMERMAN FIELD 24151 W. BLUEMOUND RD. WAUKESHA, WI 53188 (414) 521-8180 □ F.A.A. No. NC5D062N	DANE COUN 3430 MILLE MADISON (608) 24	WI 53704

I certify this A/C has undergone an annual inspection and deemed airworthy this date. Alemand 41PTH 452119737



	Registratio	on No		
and Remarks	~ ~	Signature	Certificate No.	
12/30/96 ' PA-24-260	N8817P	Serial #24-4273)
Serviced struts. retract test - g performed test pe A/C ran up for te	& greased wheel bear: Serviced brake ca satisfactory. Repai er FAR 91.207. Repl est of fuel valve &	e per Piper Service Manus attery Box Model #STC SA ings. Serviced brake man lipers & pads. Cleaned ired nose gear door. aced "O" rings in fuel found satisfactory.	ster cylinders with M: ster cylinders with M: d & greased wheel bea Installed new ELT ba selector.	ery box and copped il Spec 5606 fluid arings. Performe ttery (Feb '97)
dertify this ai	1)	ected in accordance with	an annual inspection	and is determine

Maintenance

				Maillellation
Date	This Date	Total	Reading	Monne
Piper PA-24- TACH 3787.06	260	Seri 10/0	al #24-4273 1/95	

Recorder

Completed annual insepction this date in accordance with Piper Comanche Service Manual. Cleaned & greased wheel bearings - serviced brake master cylinders with Milspel S606 fluid - serviced main & nose gear struts with S606 fluid & nitrogen - installed Lopresti Speed Works spat. slipper & splitter bit 1.000 fluid & nitrogen - installed Lopresti Speed Works spat, slipper & splitter kits # SA328450 , # SA30 \$250 control cables - adjusted alergon six - adjusted gear doors - checked tension & lubed control cables - adjusted alerson rig - serviced battery - repaired, cleaned & painted battery box - installed new door resided battery - repaired, cleaned & painted battery box - installed new door seal on baggage compartment - repaired engine cowl & painted to match existing finish - repaired rotating beacon - repaired heated pitot tube - repaired cracked exhast - checked control rotating beacon - reparied heated pitot tube - repaired cracked exhast - checked control surfaces for proper movement & lubed same - checked ELT battery for date & proper surfaces for proper movement & repaired same checked ELT battery for date & proper operation per FAR 91.207.D - replaced air filter.

I certify this aircraft has been inspected with an annual inspection and is determined airwothy this date.

Total To Carry Forward Aircraft Time

41000	100
AIRCRAFT	100
	-00

		Α	IRCRAFT LOG		Registro	ation No		
Date	Aircra This Date	Aircraft Time Recorder This Date Total Reading		Maintenance	and Remarks		Signature	Certificate No.
	Brought ->	Total	Redding				~ ~ ~ ~	
(1)					14) 9/W AD 68-05-	-01 MUFFLER+	SHROUD IN	USP.
6,/	KESEA	LEDI	VEL STRI	AINIER,	BY VIS. INSP.	NEXT DUE 38	76. HRS.	
7.)	RESEC	UREI	LT. NAV	(STROBE,	15) 5/w AD 75-12-0	06 CRACICS IN	FIN FUD.	SPAR
8,	REPLA	TED	ALC BATT		BY UIS. INSP.			7,7,7
9.)) "			RON STATIC WICK,			2.1.2.2.2.1.1.2.1.2.1.2.1.2.1.2.1.2.1.2	0/ -10
10)	POCIS	450	ET. STRU	HON STAILE	16.) Yw AD 77-13-			
(1)	RED		1. STRU	7,	B' BY INSTALLING.	NEW BUNGEES N	EXT DUE 427	16.24 or 1
- / N)	New CA	CEDI	CH. FLEX	UBLE BRAKE	17) C/W AD 94-13-	10 LOOSE STAR	ILATOR TO	RQUE
	LINE,				TUISE, 134 INSP.	NEXT DUE, 387	76.24	
12,	REPLA	CED	EFT KIA	IN BRAKE LININGS.	TUISE, BY INSP. I HAVE INSP. THIS A/C	IN ACCORD. W/AN AND DETERMINED IT TO BE IN	AIR-	
13)	REPAR	三	57411	110.1	WORTHY CONDITION AT T	HIS TIME.	1	4 10
Forward			in a w	HICH.		ALAN C. HEINZE	1 3	C
o Forward	REPAR	lED.	STALL W	ARN.		HIS TIME.	1	

to be directly and the same and a

Date	Aircra	ft Time	Recorder		and Remarks	Signature	Certificate No.
	This Date	Total	Reading	Maintenance			
11-08-93	Brought Forward →	3736.82	3736,82		10.) RE-RIG GEAR HORN.		
	(,)	V	ED LOWE	e coul,	I HAVE INSP. THIS A/O - IN ACCO		
	2)	REPUR	CED INTAK	E FILTER	WORTHY CONDITION AT THE TIME.	Colleing.	
	3,)			AIN TIRE.	01-13-95 AZP	G. HEINZE / 1910420 I.A.	
	15)	SECURI	ED ELEV. TI	RIM ROD END.	7-73-95 ELLENTIENT DATE 1/97 3776	24 HRS. T.T.	
	5,)	REBUSH	ED SHIMMY	PAMPER PIVOT	11) CHGD. OUT E.L.T. BATT. of	VOIN ACC	ORD
	6)	RESIEA	UED FUEL	STRAINER	W/FAR 91.207 d,		-
	7.,	RE WO	AK WIRING	TO AFT MAN.	b) REPAIRED INOP. FUEL		
		41765,			3.) REPLACED AIR FILTER		
Total To	<u> </u>	REPLA	PED NOSE	TIRE & TUBE.	4) CHANGED OUT L.G. BUN		
Carry Forward	<i>- 18</i>	REPAI	RED STAIL	WARNING WIRE	S.) REPLACED INTAKE CO	OPCING BOO;	*

AIRCRAFT	LOC

Date	Aircra	ft Time	Recorder				
Daie	This Date	Total	Reading	Maintenance	and Remarks	Signature	Certificate No.
	Brought Forward				found it to be in airrigathy con	0:1:	H :c
	See 3	37 th	is dest		time . Then I ferma 1910		ins
	7) Replace	ed left	main		12-11-92 3692.82 T.T.		
	bleed	system			1.) CHANGED OUT E.L.T. BATT. NEW DA	TE JAN 95	
	8) repair	ed door	lower	hinge and instabled	L) SECURED CARGO DOOR LOCK.		
	hen a	bed went	her se	M.	3) CHANGED L.H. LANDING LITE.		
	4djus	ted gear	doors		4) REPAIRED L.G. WARN. HORN.		:
	10) Replac	J J -	r bung		5) REPLACED BURNIT POST LITTES.		
	1) Replace		t geav	overcenter assist spring	1 HAVE INSA. THIS A/CIN ACCORD. W	on surcese in	50.4
Total To Carry Forward	n n	eve in	spected		HAVE DETERMINED IT TO BE IN A	ENDRIHY CON	DITION /
,	<u> </u>	W/A A	nnval	inspection and have	AT THIS TIME Want Genge	12042014.	

Registration No._

		AIR	CRAFT LOG	· ·		Registration	No		
Date	Aircra	ft Time	Recorder	Maintenance					Certificate No.
	This Date Brought	Total	Reading	Maintenan	and Remai				1/2
/ >	Forward	A A A				I HAVE INSO.	17415 A/C 1	V ACCORD.	W AN
<u></u>		L. T. BA		EW DATE, 9-92	ANNO	IAC INSP. + H.	AVE DETER	MINES 18	1018E
4)				LAILERON.	IN A	RWORTHY CO	DNDITION	AT THIS E !	ME,
5.)		10R H1				Men	Co Henry	19104201	4
6.)	CUEANE	D COR.	ROS10N	BOTTON OF ELEV.	11/11/91	T.T. 3654.54			
7.)	"		"	AT ROTATING BEACON,		1) 76-07-17	c/w Bandix	ign. Sw ops	5 v; 0k
8.)			4	LOWER REAR VERT STA		2) 77-13-21 R	Yw L. G. le	A Prev. Gfter	- minext.
(ج	REPAIR	200 coa	KING A	THICHL BAFFLE		3) 68-05-01	Yw By in	p. exhaust	1
184	REPLA	CEO LA	NOING	41647 RT. WING.		4) 82-19-01	~	nounspier cop	5. Dyepen.
tel To		6.0	6. 000A	· · · · ·		5) 79-76-10	yw Aileva	nose r.b.	#17/2011
irry Forward	parts.	1 13074	MAI.	N STRUTS.		Ó 91-02-0	6 c/w by i	us falling kit	- 16US/G

c. 1 Registration No._ AIRCRAFT LOG Certificate No. Signature and Remarks Aircraft Time Maintenance Recorder Date This Date Reading Total AD 75-12-06 YW FWD. FIN SPAR 3527,74 3527,74 Brought 11-27-89 AD 77-13-21 R YW L.G. COLL PREK AFTER MAN. EXT 1) CHGD. ELT. BATT NEW DATE 9-91 AD 68-05-01 WW BY INSP THE EXHAUST L) SECURED NOSE STRUT FIREWALL BOLTS AD 79-20-10 FW AILERON NOSE RIB. 3) BUNGEES DUE 3RD QUARTER 1990 ED 82-19-01 YW WING MAINSPAR CAPS. DYE PEN. 4) CHED. L. H. MAIN TIRE. Man Co Hig App, 9,10420 14 5) PULLED PROP. FOR OA HAVE INSA. THIS A/C IN ACCORD. W/AN 10-22-90 3585,40 ANNUAL INSP. + HAVE DETERMINED IT TO BEIN 1) 76-07-12 GWBENDIX KON. SW OPS V, OK. AIRWORTHY CONDITION OF THIS TIME A) INSTAUED KNOTS 20 SPEED SWEED WINDSHIELD KIT/337 PORMOFTHIS DATE Menge Aup 1910420 18 Total To Carry Forward

						Signature	Certificate No.
Date	Aircraf This Date	ft Time	Recorder	Maintenance	and Remarks		
	0 1	Total	Reading		Cresilia .	syclam tests as required by	C .
7-88	Brought Forward ->	Toch Tal	inter 74	68. 4 HR. Installed	ATC Transponder Tests and Inspections as	1 100 TO TOTAL	
		- Zae	cares v	17 for	by FAR 91.172 law FAR 43,	en the things	DATE
ITOMICS E	suipment.	See Weigh	ta Bolon	ice and 337's this date for	F, have been performed.	101, MG. R. S. #2763	POLO, IL
+ Poeu	august .	1 +.		er formed using FAN AC 43.13/19,		m. dig litts No Do Wolfe	
	prou ane	1669/10M	work jo	extormed using for He	Jone BATT 10-7-88		
3.13-2 and	the manu	facturers	inst 4 4	ione os a quide.	MADIO RANCH, INC. R. S. #3763 POLO, IL.		
			rest fuel	our os a quiet			
		The gireraft and	187 Remneugab libe	niffigi alupre WAR	ar system tests and attitude reporting		
		Lougher, Spain	and inequation in	annardanna "	tests and inspections as required by		
		The state of the s	Air Regulations	the thought and the second	171 jour FAR 43. Appendix C. Turn		
		1 to 96	, has so cons. 3" (hyd oc	Lan performed. 932-10 SIN 62871		
		a regative	Heration are on fr	a at the 16 W	Clarted SIN 020		
		ון אַרביון איניין	TER 112/08 J	DATE 0-7-88	10 20,000 FT. DATE 9-30-88		
					CONED Poseel & fammer		
		Chilleson	cel 1/fas	nue	RADIO RANCH, INC. R. S. #3763 POLO, IL.		
		HADIO RANCH, I	ING. R. S. #376	POLO, M.			
otal To		8					

Registration No.__

		AIF	RCRAFT LOG		Registration No		
Date	Aircraf	t Time	Recorder			Signature	Certificate No.
	This Date	Total	Reading	Maintenance	and Remarks	olg/laters	
	Brought Forward →				06-23	-004	
	ANNUAL	INSP.	+ HAVE	DETERMINED IT	1.) REPLACED ALL FU		
	to BE	IN AIRU	ORTHY	GONDITION AT THIS	2) REPAIRED POTATO	ING BEACON.	
	TIME,	Ala	C. The	inge ASP 19104201A	3) REPLACED BOLTS +	BUSHINGS BT. MAIN TON	POUE CIN
25-87	Tail Tal		1		4) RESIECURED RT. STA		/
ectional b	100 520 G	17es 519	5. 94 HR.	Installed exchange Edo Aire		15 A/C IN ACCORD, W/	
	Parlik	Stamman	6445		ENNUAL INSP. + HAVE		EIN
			or Madio	Sanch Inc. R.S. 3763	AIRWORTHY CONDITIO		214
То	****				Munic	Hering Asp 1910420	107/
y Forward							

					· V.		
Date		oft Time	Recorder		n-1 D 1	Signature	Certificate No.
	This Date Brought	Total	Reading	Maintenance	and Remarks		
05-15-87	Forward	0065,16	TACH:		11) COPPECT SAFETY ON TRING T	URNBUCKLE.	
	REPLACE	LT. LAN	P. LITE.		12) REPLACE RT. MAIN WHEEL	OUZR.	
	REPAIR	WING L.	E, DENT		13) SECURE PT. WHEEL WELL	COUER	
4	REPLAC	E E.L.T.	BATT	NEW DATE 5-89	14) SECURE LT. TRUNION ON DE	AGLINK OF M	IOSE GEAR
•	FERMIN	ROTATIN	6 BEALD	N	15) " SHIMMY DAMPER,		1
	PEOLDS	TRUDOR	RTRIN	1 INO.	16.) REPLACED ALL SIDE WIND	ows.	,
7)	REPAIR	BILER	ON HING	BNGS, LT. PILERON	IT) TREAT + PAINT CORROS	ON AROUN	DELT.
		DAM AGA	En en		ANTENNA.		
Total To	REMOUR	- RIBO	6 FUE	Bowl,	18) SECURE WIRING HARNESS		well,
Carry Forward		(0) 0000	NEST	EROWL, ERONG UT. WING. VST. OF TRIM ROD END NEXT	19) FREE-OP STICKY ELEV. TO		1/su
	or West	FOR E	LEV.	VST. OF TRIM RODE	1 HAVE INSPITHIS ICE	Oi	FR

Date	Aircraft Tin	- K	Recorder	- ance	and Remarks	Signature	Certificate No.
	This Date		Reading	Maintenance		7.00	
	Brought Forward →				Dec. 23, 1886 Tuch Time 3340.0	o Reslave	I bolt
111 DI. 171	tests as required by		The ATC required		on fuel grund clams & clean	ed residue	from
Para. (a). SIGNED RAN	Len LAL	DATE CA	Appendix	F, have been performed.	sump eup. Infect flag tra	chee, up	look on
RADIO RANI	CH., INC. R. S. #3763 P	POLO, IL	SIGNED	Viene It look DATE 5/400	right gide, Paul Bennett A&F	395605522 -	
Aftimeter	tests required by FAR gr	11.171 law		ANCH, INC. R. S. #3763 POLO, E.			
FAR 43, ALTIMETE	мриения E, Para. (b), 1	have been perform N 6287/	ed.				
TESTED	10 2000 6 FT. DAT	5/9/86					
	RANCH, INC. R. S. #376	lock 13 POLO, IL					
To Forward						-	

_		AIRC	CRAFT LOG		Registration No:		~ ~
Date	Aircraf This Date	t Time Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
12/11/85	Brought Forward				5/20/86 Tach Time 3285,76 hour.	s Installed	A ARNAV
	Tack 3:	- COA	local geor.	beingue coul	P-20 LURAN C With preamp, Auten	ing, and Rs 08	-ol Luxay
* end	Tooled on	1	of head.		Remote transfer Reley & annunciator.	All WOLH Was ,	pertorma
	may	alson	laf1878491		95 per Manufacturers instruction	s & applicable	PARS.
					today: Dote End The aircraft and on	compressed in accordance with	35
					CHITCH Server Air	Regulations and the are and	en nem S
					airwoo's coint alton	ration are on file at this and	m/a a/e/
					OH OH	R NO. 6578 DATE	5/20/00
Total To Carry Forward		*			SIGNED LE RADIO RANCH, INC.	R. S. #3763/POLO, IL.	

AID	CRAFT	100
VIV.	CKALL	LOC

Date	Aircra This Date	ft Time Total	Recorder	Maintenance	and Remarks	Signature	Certificate No.
3-8-85		TACH: 318	Reading		- Prop overhauled by Aircraft	propeller	
				201		property	
iosai	- Cel	THA THA	THIS	S AIRFRAME HAS BEEN	gov	+	
11350	re (Fi)	IN ACCO	RDANC	E WITH AN ANNUAL	- replaced strobe timmer with no	w nwil	
		MIAI OUT		ERMINED TO BE ID	Replaced elt ballery		
mch		CODDITI	ONe		- Installed New factory (New)		ini un
3/8/85		Jamon	M. Par	el) IA. 1583532	Model # J0540 - 04A5	5/N L-226	19-98
-10 (8)	-	-all+	agel co	11s overhauled	ground runup + check ok	No oil leak	5
		by	Aviation	in fuelcells,	found		7
		= inst	alled s			10 11 1	(
Total To				r overhanded by RLB	Monde	8 Thendo	360503545
Carry Forward		- Rep	areal L	rate robrs & linnings			
		0	CI C	rake repris & lining		THE WINDS OF THE PARTY OF	La Company (Company)

Registration No.____

		AIR	CRAFT LOG		Registration No. NB 817/3		
Date	This Date	t Time Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
2/23/83		THE ATC REQUIRED DATE AND	FOIDID TO	TESTS AND INSPECTIONS WERE PERFORMED THIS	10/11/83 TACH 3110.79, REPLACED LANDING LIGHT BULB, REPLACED BOTH G AD 77-13-21 PAR B. PAR A DUE AT TAKE	EAR BUNGEES	AS POR
		REPAIR STATION UNDE	THIS INSPECTI	PECTION ARE ON FILE AT THIS DER R. O. NO. R/623	AD 79-20-10 BY REMOVING AILERONS AND DYE PENETRANT INSPECTION ACCOMPLISHED, I ACCOMPLISHED AND METAL SEAL TRIMMED TO	WSPECTION, AD 40 83-19-03 INS	82-19-1 PECTION
					SPAR INSPECTED IN ACCORDANCE WITH AD THAT THIS AIRCRAFT HAS BEEN IN		
Total To Carry Forward					AN AIR WORTHY CONDITION. Jany	FOUND TO BE	

	4	A	IRCRAFT LOG		Registration No. 8817 P				
Date		aft Time	Recorder	Maintenance	and Remarks	Signature	Certificate No.		
	This Date	Total	Reading	Maine	and Remarks ANN- CONTS				
11-4-82	Brought Forward	2928	2928						
					Total airframe time 2928 Date 11-4-82				
					in accordance with a RNNURL				
					condition. Purfaced models in airworthy				
					Pertinent details on file under repair order # 9/2				
		tool		meter and static system	TUFTS-EDGCUMBE, INC. — ELGIN, ILLINOIS F. A. A. Certificated Repair Station No. 3250				
		le Th	Altimeter was Test	have been performed. ed to 16,000	Limited: Piper all Models, Radio and Inst.				
		Aut	et on 10 - 4 - 8 6 horized Signature 7Cd	chard m. Iseb	AIRWORTHINESS DIRECTIVES CHECKED	See va	of log		
		Alti	6487	Date 11 - 4 - 82	THRU 82-2/ AND THE FOLLOWING	los AD	list -		
Total To	***************************************		TUFTS-EDG(ELGIN, ILLINOIS	C. R. S. 3250	COMPLIED WITH 75-12-6 77-13-218	0			
Carry Forward				A CONTRACTOR OF THE PROPERTY O	79-20-10, 82-19-1.	2-11-11-11-11-11-11-11-11-11-11-11-11-11			

		AI	RCRAFT LOG		Registration No. 8817 P		
Date	Aircra	ft Time Total	Recorder	Maintenance	and Remarks	Signature	Certificate No.
11-4-82	Brought	2928	Reading	ANN. CONI.			
		~ 1 ~ 0	2928	Replaced broken know	ALTIMETER SIN 62871. YN AD 75-12-6		
					WITH MAGNAFYING GLASS- C/W AD 77-		
				GEOR AND SERVERS INSPE	BOTH CORDS LOOK OK YET. S/W AD 79	-20-10 BILL	FRON NOSE
				BULKHEADS INSP- NO CRACK	FOUND ON EITHER BILERON AT BA	LANCE WEIGH	BULKHEADS,
				USING ARGUNEWING GLASS.	YW AD 82-19-1 WING SPARS IN	ISP NO CRI	ecks FOUND
-			-	211 POT OF SPARS	SKIN CUT-OUTS, OR ON TOP OF WE	RS . USING	DYE
				O THODA	NO CRACKS EQUAD ON TOP SPAR	SPLICE PLATE	
				REAR SEAT USING MAGNIT	FYING GLASS. THIS INSP. DUE EVERY	100 HR5-	
Total To Carry Forward		•			(O1/FR)		

Registration No. 8817P

Date	Aircraft	Time						
- Gal	This Date	Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.	
October 23	Broughty Earward	085/27		2 - med				
		20010 100	in and	total Hrs. Personned	11-4-82 Jack 2728 hrs. Performed annua	I annaal	inspection.	
	Maintone	ence an	d /48	nication as per liger	Cleaned + greased wheel bearings + lan	ding gen.	Retraction	
Je vice	Munaa	1- 500	20	Empliance on prevous	t 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Call wints.	Checked	
page as	of in se	er of	,	rtify that this Aircract	electrical system + lights - cleaned	Inel bout +	screen.	
			has	been inspected in accordance with	Serviced tire pressures, battery, +	brake plus	I level-	
			to b	e in an airworthy condition.		E. Replaced	narco	
			1 . 1	ENERAL AVIATION CORPORATION	Elt battery. new expiration date			
			- A-7	D 393503876	Elt tested of Replaced prop gov	emos contro	l cable +	
					adjusted. Installed new "aners	can Safety"	metal to	
Total To Carry Forward					metal bueple type seat belt	in all	reate-	
•					Replaced all brake linings.	(OVER)	

	AII	CRAFT LOG		Registration No			
Date	Aircraft Time This Date Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.	
10-20-81	Brought + TACH TIME	2851.16	INSTALLED KNOTSZU	October 23 1981 Tuch and total	1 time 285/	Hrs.	
GAT SEAL	KIT IN ACCORDA	ICE W.	STE = 1 = 31 C1 337	Changed LH main tire . Inst			
TAS	BEEN ANTEREN	. 1	1 /	Copy Greased wheel Dearings	Replaced all	brake	
WITH NEW	WEIGHT & BALANC	E SHEET.	Matthias D. Poelmer	pads and heated pitot to		301-000	
			AX 7 330-54-5809	Changed Beacon pulls O/w A		by insp	
				and due in 100 Hrs. or 5951			
				by insp. due at 2951 Tach.			
				Lea of log. Roger R. Shade	Ops 144 37366)	830	
Total To						~	
Carry Forward							

A	R	CF	A	FT	1	LO	(

		Al	RCRAFT LOG			Regist	ration No		
Date	Aircrat	ft Time Total	Recorder Reading		Maintenance	and Remarks		Signature	Certificate No.
may	Brought Forward >> 8, 1981 THE AT REQUIRED DATE AS MAKE/METAILS REPAIR	C TRANSPO ED BY FAR ND FOUND TO ODEL KIND OF THIS IN STATION UI	NDER TESTS 91.177 WERE O COMPLY V C K7-78 A SPECTION ANDER R. O. N ZEDGCUMBE,	AND INSPECTIONS PERFORMED THIS VITH FAR 43, APX F. S/N 4663 RE ON FILE AT THIS IO.R - 8953 INC.		New Empty CG New Useful Load 1. TUFTS-EDGCUMBE.	etions Performed This Equipment List evised 288-6 lb. /791.6 64.2 in. 108-4 lb. NC. — ELGIN, ILLINOIS	Leage France	CAS:3250
Total To		. 0230(16	renthen	01201 LDATE 5/12/81		Authorized Signature	Radio and Inst		-

Al	RCRAFT	LOC
AI	KCKAFI	LOC

Date	Aircra	ft Time	Recorder			
	This Date	Total	Reading	Maintenance	and Remarks	
10-22-80	Brought Forward	2696	2696	C/w AD 79-20-10 AILE	RON NOSE	BULK HEROS
				WEIGHTS, NO CRACKS FOUND.	REINSTALLED	BALANCE WI
				ENGINE FUEL +OIL HOSES		762506 HOS
	73	AIRWO	RTHINES	DIRECTIVES CHECKED	Total	2.60
		THRU .	80-20		certify	irframe time 269 that this AIRFR
		COMPL	IED WITH	14-13-3, 75-12-6, 1)	inspect	rdance with a
				11-13-21 8 19-20	- Toricit (on, Richard
8	el rear	al +0-	2	79-26-5.	TUF	TS-EDGCUMBE, INC A. Certificated Rep
Total To	***********	8 Mis	log f	AD listing-	Li	mited: Piper all Mod
Carry Forward						

Registration No. 8817 P

and Remarks	Signature	Certificate No.	
ON NOSE BULKHERDS INSP. REMOUED	AILERONS + B	ALANCE	
REINSTALLED BALANCE WEIGHTS + AILERON. INSP. P/N 762506 HOSES NOT ON T	s. C/W AD7	9-26-5	
Total airframe time 2696 Date 10-22-80 I certify that this AIRFRAME has been inspected			
in accordance with a ANNUAL			
inspection and was determined to be in airworthy condition. Ruchard m. Lieb			
TUFTS-EDGCUMBE, INC. — ELGIN, ILLINOIS			
F. A. A. Certificated Repair Station No. 3250 Limited: Piper all Models, Radio and Inst.			

Aircraft Time

Date


Registration No. 8817P Certificate No. and Remarks Signature date is 3-82- Replaced Elt antenna on linings - fateked main wheel well farrings - Replaced fuel cover reals- Replaced worm main tire + tube - C/W AD 74-13-3 STABILATOR BOLT REPLACEMENTS PLN 404-888 NUTS INSTALLED. (CORROSION RESISTANT)-FORWARD SPAR INSP. NO CRACKS FOUND - C/W AD 77-12-6 NEW PROP INSTALLED AT THIS TIME. C/W AD 77-13-21

Recorder This Date Maintenance Total Readina Brought 10-22-80 Forward -> 2696 2696 4 EA- PIN 502-329 BOLTS + 4EA-75-12-6 VERTICAL FIN Total To HARTZELL Carry Forward BUNGEE CORDS INSP- NEW CORDS INSTALLED AT THIS TIME. (OUFR)

AIRCRAFT DESCRIPTION

Registration No	88171
del: PIPER PAZY-260	Popular Name: PIPER COMANCHE
ial No.: 24-4273	Type Certificate No.:
ors: BROWN + WHITE	
gine Manufacturer. LYCO MING	Propeller Manufacturer: HARTZELL
ginal Engine Model: IO-540-04A	95 Original Propeller Model: HC-C2YK-14 181
Numbers: Single L-5083-48	Hub or Serial Number: Single AW2115
Left	Left
Right	Blade Numbers F8 467 - 7 R
	Left Right A79838 A81662
	E84390 E84385





REPLACE ELT BATTERY BY:

PIPER AIRCRAFT CORP.,

LOCK HAVEN, PA.


Date Year Mo. Day	Time in Air Hrs. Min.	Passengers Carried	NATURE OF FLIGHT	REMARKS	SIGNATURE
Tack:	-79		Replaced # 2/ 5x hours lay & PIPE WITH	10-18-79 TACH 2596 HRS. Performed Annual as left minelshield. Complied with they fol vertical fin forward spar inspection, geor system maintenance. Paragraph Total airframe time 2596 I certify that this HIRFRAME in accordance with a harm inspection and was determined condition, gentled condition, Pertinent details on file under returned time. THE SEDECUMBE, INC.— F. A. A. Certificated Repair—Limited: Piper all Models,	AD. 77-13-21 Landing B", A.D. 79-13-8 airborne Date 10-18-79 has been inspected to be in airworthy pair order # 6789 ELGIN, ILLINOIS Station No. 3250
Total Forward				to the second se	
Place of I	Last Airplane Over	haul		NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics	Act of 1938, punishable by Civil Penalty.

NOTICE:-Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LUG

					N C	AIRCRAFT LOG	
De		Time in A	Min.	Passengers Carried	NATURE OF FLIGHT	REMARKS	SIGNATURE
Year	Dy				AND THE RESERVE OF THE PERSON		
15-8	-78	TACH 2	4981	IRS. COV	APLIED WITH PIANT 91.170. INSTALLED DE-	May 30, 1979 Installed avionies	
		CENTIF	BO	ALTIME	TER + PERFORMISH STATIC SYST. TEST.	this date see Mino Alterat	
					,	hist Remsion for current a	
		1	certif	y that th	e altimeter and static system	information, Replaced Turn	+ Bank instrument
		tests	requi	ed by FAF	91.170 have been performed.	with exchange unit. Replace	d ELT Battery -
		The	Altin	eter was	Tested to 20,000	Battery replacement due Ayo-	28,1980.
		Feet	on	11-17-7	8 . 0 0 11	- Xee	rese French
		Autho	rized	Signature	Nound Ollan	THET	1
		Altim	eter :	IN 98	3 Date 12-8-78		S-EDGCUMBE
				TUFTS-	DGCUMBE, INC.		FAA 3250
		E		ILLINOIS			
Total F	orward						
Plac	e of I	ast Airplan	e Over	haul			
Dat	e of L	ast Overhau	l	this back is	a wighted	NOTICE: Making false entries in this book is a violation of the Civil Aeronautics	ict of 1938, punishable by Civil Penalty.

Da		Time in A	ir Min.	Passengers Carried	NATURE OF FLIGHT		REMARKS	SIGNATURE
Mo.	Day							834
8-1	0-7	8		Popla	cal LAK Biske Linner Robert 4/14		12-8-78 TACH 2498HES, PERFORMED ANNUAL A	PERAME INSP. REPLACED
2466	773			Brake	CVL. Battery Squiced : Terminet			MILED MOSIC CLICK MEDICALEM
				cleave	1. 160 SW Replaced A.D. 76-7-12		LANDING GEAR BUSHINGS, COMPLIED WITH T	E FOLLOWING; A.D. 77-8-1
				(Bora	ix us honger Applies	1	LANDING GEAR BUSHINGS, COMPLIED WITH THE PAIL EVEN SPAR CRACKS AS PER SIL 787 20 MI	760-919 INSTALLED,
- miles	-1	1,000			TOTAL AIRFRAME TIME Date		A.D. 75-12-6 FIN FORWARD SPAR INSP.	
					I certify that this AINCART has been Inspected		P.V. 75 10 C-70	
Sal	MBURG	AIRCRAFT MAIN	ENANCE	CENTER, SCHAU	Billig, IL 60176 in accordance with a inspection and was		Total airframe time 2498 Date 12-8-78	Delicated to the Landson
150	CENTER!	9 IRPAIR STATE	M NO. CI	3-20	repaired in accordance with current Regulations of the		certify that this AIVEREAWIZ has been inspected	
-					Federal Aviation Administration and is approved for return to service. Pertinent details on the times order		in accordance with a ANVIDEL	
					signed Signed		inspection and was determined to be in airworthy	
							condition, and and a start to 5721	
							Pertinent details on file under repair order # 562	
CUES I	20,00	CONTRACTOR SECURE	Missayth.	AOCHART MAIN	建成联系统		THE PROPERTY OF THE PROPERTY O	
Total F	rward	THE RESERVE AND ADDRESS OF THE PERSON.	STATE OF THE PARTY	MASS WARDER OF			i i i i i i i i i i i i i i i i i i i	A Table
			_				F. A. A. Certificated Repair Station and Inst. Limited: Piper all Models, Radio and Inst.	
				haul				
		ast Overhau		this book is	a violation of the Civil Aeronautics Act of 1938, nunishable by Civil Penalty.		NOTICE:-Making false entries in this book is a violation of the Civil Aeronautic	s Act of 1938, punishable by Civil Penalty.



N C	AIRCRAFT LOG			
Date Time in Air Hrs. Min. Passengers Carried NATURE OF FLIGHT		REMARKS SIGNATURE		
Detaber 8, 1976 Replaced #1 VOA 4 with	,	- Annual Inspection - CIW AD 75-27-08 by inspection,		
Lodan 240 ommi Colide slope as Minor	-S	76-19-07 by replacing tubes with PIN 28035-00 See		
alperation. No weight charge		Piper Inspection form this date for defails		
Level French		I certify that this COLOCIA To has been inspected in accordance with a ROBULL inspection and was		
AVIONOS SPECIALISTS		repaired in accordance with current Regulations of the Foderal Aviation Administration and is approved for		
10-8-76 Replaced Altimeter with PIN 13-3/0611	-1	return to service. Pertinent details on file under Order		
5/N A22/7The chimeter and static system tests required by F.A.R. Part 91.170		SCHARDONC ANCRAFT MAINTENANCE CENTER, SCHARLOUME, M. 60172 FAA CERTIFIED REPAIR STATION NO. C03-23		
have been performed. The shinister (+))	Installed Met-Co-Rive Tips PN 11050/ SN 4389 Dei		
have been tested to 20,000 it	2	SP 1022, FAR Aproval STC SA 871-WE. See 337		
on . 3-8-76	1 3	this date in Willen wordst change Pobert Clayman		
Total Forward Policy (1220- 10-8-76		\$3-503 OR ROUTAIN MARIE DE COMMUNICA AMERICA SAMUTEMANCA CENTER, SUMMINDURG, IL COLTY		
Place of Last Airplane Overhaul		FAA CERTIFIED REPAIR STATION NO. CO3-23		
Date of Last Overhaul		NOTICE:-Making false entries in this book is a violation of the Civil Aeronauties Act of 1938, punishable by Civil Penalty.		

				30 34 6 30 0 1 6 N C	AIRCRAFI LOG			
Date	Time in A	r Min.	Passengers Carried	NATURE OF FLIGHT	REMARKS SIGNATURE			
Io. Day								
				REPLACED AIR INLET THET REPLACES.	AEPAINED COCKPIT COLD AIR CONTROL, REPAIRED BT			
				NG. BERGING BEPLACEN BOLTS	WING L.E., INSTALLED NEW MAGNETIC COMPASS			
				+ SHIMMS IN BOTH TORONG LINKS	TOTAL AIRFRAME TIME 2077, 39 Date 9/28/1			
		5	and here	REPLACED ELT BATTERY DUE	I certify that this AMERAT, has been inspected			
And I was		1		JAN, 1977 BEPRIRED PROP	In accordance with a Partial inspection and was			
			3	FOTAL AIRFRAME TIME 2056-73 Date 9/11/75	repaired in accordance with current Regulations of the			
		-	1 - Y	FOTAL AIRFRAME TIME LONG Date 11111	return to service Portinent details on the under prodect			
			1	I certify that this ### has been inspected In accordance with a ###################################	No. 2701 . Signed Alle Sheeps			
				In accordance with a HANGE inspection and was repaired in accordance with current Regulations of the	SCHAUMBURG AIRPORT, INC., SCHAUMBURG, ILL. 60172			
				Federal Aviation Administration and is approved for	FAA CERTIFICATED REPAIR STATION NO. 303-13			
	1			return to service. Pertinent details on file under Order No. 2666 Signed Philippin Rental	TT 2,9983 8-676 replaced Rmain tire Polith Clayer 1961958567			
				SCHAUMBURG AIRPORT, INC., SCHAUMBURG, ILL. 60172				
				FAA CERTIFICATED REPAIR STATION NO. 303-13	the state of the s			
otal Forwar	d				The state of the s			
te of	te of Last Airplane Overhaul							

Date	Time in Air Hrs. M	tin.	Passengers Carried	NATURE OF FLIGHT	REMARKS	SIGNATURE
. Day					REMARKS	Control (Act of State)
				INSTALLED New 137 Trains Table Plan 20194-39 RMM STABLESTON BOT 760-747 Sec 337 This DATE TOTAL AIRFRAME TIME 17884 Date 1157 I certify that this Aller Time Inspection and 13 inspection and 13 repaired in accordance with a BEPUT Times treen inspected in accordance with a BEPUT	TOUCHED UP WING LEPSING FORCE C/W AD 75-12-06 ASSEM, PARAGE TO BE ACCOMP LISHED AND TO 20 8 TOTAL AIRFRAME TIME 1984 71 Bate of the second and the second	7.79 Mas Taen 1/25/75 inspected in and was inns of the peroved for the proved for
al Forward		-				THE PARTY OF THE P
						1 1000 punishable by Class D.

				N C	AIRCRAFT LOG
Date ear Mo. Day	Time in A	Min.	Passengers Carried	NATURE OF FLIGHT	REMARKS SIGNATURE
			t etc.	STRUT FILLER WITH HYDFLUID FRINGES UP WITH WITHOUT FOTAL AIRFRAME TIME 165.03 Date 1111/73 I certify that this AMERICAN has been inspected In accordance with SERRY inspection and was repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details on the under Order No. 2.46.2 Signed Market 11. 60172 FAA CERTIFICATED REPAIR STATION NO. 303-13	INSTRUCED NEW BUCK IN ROT. FECON REPUBLICANT READ LIGHT ROOMS TOTAL AIRFRAME TIME 171.97 Date 2/9/25 I certify that this AIRCART has been inspected in accordance with a Part inspection and was repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details, on file under Order No. 21. Signed AIRFORT, INC., SCHAUMBURG, ILL 20172 FAA CERTIFICATED REPAIR STATION NO. 303-13
otal Forward					
Place of La	ast Airplan ast Overha	ne Over	haul		

						AIRCRAFT BOG					
Date	Time in Air Hrs. Min.		Passengers Carried	NATURE OF FLIGHT		REMARKS SIGNATURE	SIGNATURE				
Day						AND TAKES					
			REPLA WINDO INSTA	CED REAR PROP SPINNER BLUSSIEDS CED RILLET BEAR OUTSIDER CLE PINEW O RING WHEN PROP WAS LACED I certify that this FINCHIET has been inspected In accordance with a REPART Inspection and was repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details on the under fider No. Signed Full May 11. 60172 FAA CERTIFICATED REPAIR STATION NO. 303-13	*	TOTAL AIRFRAME TIME 941.25 Date 3/2/15 I certify that this AIRFRAME inspection and was in accordance with a Airfrance inspection and was repaired in accordance with current Regulations of the repaired Aviation Administration and is approved for Federal Aviation Administration and is approved for return to service. Pertinent details on file under other No. 2425 Signed AIRFORT, INC., SCHAUMBURG, ILL. 60172 SCHAUMBURG AIRPORT, INC., SCHAUMBURG, ILL. 60172 FAA CERTIFICATED REPAIR STATION NO. 303-13					
l Forward											
lace of Last Airplane Overhaul											
ate of Last Overhaul											

Date	Time in Air Hrs. M	n. Passengers Carried	NATURE OF FLIGHT	REMARKS	SIGNATURE
Mo. Day					976 24
aug	16.19	7.4 V	Installed Hospins Novaslan	SEE WORK BRDER 2233	FOR DETRICS
	,0	asho.	aptem as minos alteration	OF WORK PERFORMED THIS L	PATE
	1	ex Mi	nor alteration & Equipment	TOTAL AIRERAME TIME 1875-67 Date 10/11/74	
	L	est R	exision this date that current	has been inspected	
	11	spiaht	+ Balanie/linformation.	inspection and was	
	U	9		repaired in accordance with current Regulations of the	
			M. D. e. Fan and	Federal Aviation Administration on file under Order	
			A CONTROL OF COLOR	return to service. Pertinent details on file under Order No. 2233 . Signed Make 1 60172	
			AVIONICS SPECIALISTS FAA COS-Z	ALLEN TO A I PROPERT INC., SCHAUMBURG, ILL.	
			FAA COS-Z	FAA CERTIFICATED REPAIR STATION NO. 303-13	
			and a service of the control of the		
Total Forward			The transfer plantage and the		
Place of I	ast Airplane O	verhaul			Drawn - Harry god to state
Date of T	ast Overhaul	on the second			AND DESCRIPTION OF THE PERSON
NOTICE:-M	laking false entrie	s in this book is	a violation of the Civil Aeronautics Act of 1922	NOTICE: Making false entries in this book is a violation of the Civil Aeronautics	Act of 1938, punishable by Civil Penalty.

SIGNATURE REMARKS REPRINED HYD LEAK UNDER INST. RIPHEL , REPLACED + REPAIRED COWL HOLD OPER ROOS, GLUEB FUEL IND RING TO COVER. AEPLACED BLEETRIC TRIM SWITCH INSTALLED NEW LEATHER BOOT FROUND GIERR EMERGER BY HAMOUR. REPLACED BULB IN #2 COMPLIED WOTH S.B. 394 TOTAL AIRFRAME TIME/8/3 Date 6/7/ I certify that this HIPCRAFT has been inspected In accordance with a PEPPIP inspection and was repaired in accordance with current Regulations of the Federal Aviation Administration and is approved return to service. Pertinent details on file under Order No 2083 Signed Chille SCHAUMBURG AIRPORT, INC., SCHAUMBURG, ILL, 60172 FAA CERTIFICATED REPAIR STATION NO. 303-13

NOTICE:-Making false entries in this book is a violation of the Civil Aeronauties Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG REMARKS NOTICE:- Washing for the Civil Account of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

AIRCRAFT LOG

REMARKS SIGNATURE

NOTICE:-Making false entries in this book is a violation of the Civil Aeronauties Act of 1938, nunishable by Civil Beauti

AIRCRAFT LOG

9-27-71-	REMARKS	1501	SIGNATURE
lat airer	all on for the	minus R	pairs.
formal.	- Cach wheel	Rewih	A Rung
Force I la	of dear of) perol	en bylly
Lyp Cth	high la temer	al ams	estrend or
The arran	off structury	AD71/1	2-5- DNA
19-3	PNA fut) 6	8-5-10	IV A. model
	I CERTIFY THAT THIS	AIRCRAFT HAS BEEN I	NSPECTED
	IN ACCORDANCE WITH	H MULA NSPECT	ION AND
	WAS DETERMINED TO	BENAIRWORTHYCO	11-291-98
	JIGINET T	CACH WAR	111/14/4
	V		

			NC8.8.17. P		44	00.45
Date	Time in Air	Passengers		_	AIRCRAFT LOG N	-8017 P
	Hrs. Min.	Carried	NATURE OF FLIGHT			
Year Mo. Day					REMARKS	SIGNATURE
		DE IPIANO	ed anguage dook lock, installed her hand-	_		V 5
20 10				-9	Frestalled new londing gear Sel	peter switch;
-	ing genr	TRANS MISS	ion Assy. Daniel A. Elmin Cirs 3250		vew landing gear Golonoid,	2 new-landing
-				-	gear assist Burgee Cords +	Retract Tests
					made OK, (Tack 1461:00	
-			Statement of the statem	_	(CM all	Q AXE 4821.
				_	Con Contraction	7-1-71
				_	Chicagoland au	fort.
				~	Installed 2 new Brake De	sca and all
				_	new brake linings. (Toch	461:00)
				_		
				_		
				_		
Total Forwar	rd			_		
Place of	Last Airplane Ov	erhaul		_		

Date of Last Owenhaul


-		T	B	8-0	AIRCRAFT LOG	
Date	Time in Air Hrs.	Min.	Passengers Carried	NATURE OF FLIGHT		
Year			1500	TALL JOHN J. Manuary	REMARKS	Charles
Mo. Day						SIGNATURE
10-7-70	TIACK 130	i biles.	COMPL	BY WITH PAYET 91-170, INSTALLED OVERLHAULT	10-72-70 TR 00 12001101 120	
	ENNIT	112	וא בו מובר	P MINSPEED PERFORMED STATIC SYSTEM	10-7-70 THON 1309 HWS. PERFORMED WINDHI HINZENAM	E WELLEN
		77.12		I certify and the altimatic and state system	- REPLACED LT. MAIN THE PERINCEN W. THE	Control State Co
	CHECK.			tests rectored by all Juli70 neve by a periorited.	MY DAMPENER DOD END, REPLACED NAV LITE DEF	MAINGS, REPLACED SHIM-
	1		0-110	07 100	AD 18-5-1 WE PER THE THEF NAV WITE THEF	LECTOR, COMPLIED WITH
				6-9-70 AM	PLEUS, NO OTHER U.D. NOTES DERIVED THE BER	DEVICES IN BURL
700				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PLENS, NO CTHEN U. NOTES HERLY WITTIME OF THIS I	MUF-
-		-		Authorized Signas South & Ethins	Total africana time 1309 Date 16-7-72	TENTECTION.
	A CONTRACTOR OF THE PARTY OF TH	1	16.	Animeter Six 673-0648 10-7-70	I mortiful thank to the second of the second	
					the state of the s	
	1			ELGIN AIRPORT CORPORATION	In accordance with a Munual	
-				ELGIN, ILLINOIS C. K. S. 3200	inspection and was determined to be a already	
					condition, and the theme	
	1 L. V.		The same	120	Pertinent details on tile under repair ord = 5065	
	1000		7		ELGIN AIRPORT CORPORATION, FLOW IN LINE	
				Charles and Comment of the Comment o	F. A. A. Certificated Repair Station of	
Total Forwar	d				Limited: Rippin all Station Mc 3 U 3	
Place of	Last Airplane	e Over	haul		Limited: Piper all Woders, Makio NJ	
NOTICE:-	Making false en	tries in	this book is	a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.		
		1	A CONTRACTOR OF THE PARTY OF TH	remaity.	NOTICE:Making to	

NC. 8.8.17. P.	AIRCRAFT LOG N-8817.P
Date Year 1969 Year Min. Passengers Carried NATURE OF FLIGHT	REMARKS (Tach 1145:00) SIGNATURE
10 31 1145 00 Tack reading + Total Time.	annual Imp. Completed. 10-31-69. aiscraft opened up & inspected as to a Piper 100 hr. check list: Jasked up aircraft, re-gressed wheel
	Learnings checked brokes OK, gressed gear retroot points, retract Tests OK serviced battery broke reservoir Verious minor repairs + object monts make as needed, AD notes (the short thru 69-21 - none applicable)
	certify that this attract has been inspected in accordance with an annual inspection and was
	determined to be in airworthy condition.
Total Forward	Obstantant disport
Place of Last Airplane Overhaul Date of Last Overhaul NOTICE:—Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.	Nome

AIRCRAFT LOG

	REMARKS	12 2011	SIGNATURE	
Replace	& brake linings Repl	aced	ailiron	
rod en	de Replaced this actua	tere 12	ocl	
end b	ofte Complied with AD	68-5-1	1.	
		1		
	Parties and the second	16		
	Total airframe time 1928 Date 9-1;	nected		
	I certify that this Authorne has been ins		300	
	inspection and was determined to be in air	worthy	24	
	condition of a new of faction		-	
	Pertinent details on file under repair order #	1101015		
	FLOIN ADDOORT CODDODATION FLOIN			
	F. A. A. Certificated Repair Station No. 3 Limited: Piper all Models, Radio and I			
110	Littlited. Fiper all Models,			

AIRCRAFT LOG REMARKS REPLACED BRAKE LINEINGS, REPLACED RIGHT MAIN TIRE, REPLACED VACUUM AIR FILTER AT REQ. REPLACED NO AD NOTES APPRICABLE AT THIS TIME BEFER TO BEM AIRCRAFT COEP. RO # 20537 FOR PERTINENT DETAILS. pection ndition, rtinent Atha Civil Association Act of 1938, punishable by Civil Penalty NOTICE ... Walter for



B & M AIRCRAFT CORP. E 039 ELGIN AIRPORT, ELGIN, ILL. 741-9100 ROSELLE AIRPORT, ROSELLE, ILL. This is to certify that the following repairs were accomplished in accordance with Current Civil Air Regulations Signed WWW WWA APCRESSON 3 NOTICE CERTIFICATION THIS TO APPROPRIATE LOG BOOK TAPE ON BACK OF FORM Date of Invoice June 24, 1967 Date Completed Piper PA21-260 Airplane Model 24-4273 Serial Number N8817P Registration No. 1-841 Tach Time Repair Order No. 20122 Amnual Airframe Inspection. 100 Hour Engine Inspection. Flat Rate Inspection Change nose and let main tire and serviced gear. Replaced brains linings. Removed and repaired gear motor assembly. ENGINE INSPECTION: Removed #6 cylinder and reinstalled. Replaced leaking nose oil seal. Replaced broken left forward baffle. Replaced broken right center baffle. Replaced broken right center baffle. Retimed both magnetos. Replaced #2 and #5 cylinder rocker cover gaskets. Adjusted propeller governor control. Replaced spinner nutplate. Additional Repairs/ A. D. NOTES No A.D. notes apply thru 67-19. No additional AD notes apply at this time. COMPRESSION #1-72 #2-74 #3-74 #4-74 #5-72 #6-56

B & M AIRCRAFT CORP. ELGIN AIRPORT, ELGIN, ILL. 741-9100 ROSELLE AIRPORT, ROSELLE, ILL. This is to certify that the following repairs were accomplished in accordance with Current Civil Aid Regulations Signed William WOM AP NOTICE ATTACH THIS CERTIFICATION TO APPROPRIATE LOG BOOK TAPE ON BACK OF FORM Date of Invoice Date Completed March 16, 1967 Airplane Model Piper PA24 "260" Serial Number 24-4273 Registration No. N 8817 P Tach Time 734.00 Repair Order No. 1812h Annual sirframe inspection. 100 Hour engine inspection. Replaced brake linings. Changed central air filter unit. Changed right main tire and stop drilled wheel cover. Replaced bad plate fut in tail cone. Replaced fuel access door gaskets.

Replaced missing rubber - left bottom rear wing root.

ENGINE


Replaced leaking "O" ring seal in propeller governor. Stop drilled cracks in baffle.

Patched crack in spinner.

A. D. NOTES

No A. D. Notes applicable at this time.

COMPRESSION #1.75. #5.7h. #6.73 #7-76_ #2-71: #3-71;



B & M AIRCRAFT CORP. E02492 ELGIN AIRPORT, ELGIN, ILL. 741-9100 ROSELLE AIRPORT, ROSELLE, ILL. This is to certify that the following repairs were accomplished in accordance with Current Civil Air Regulations. Signed Willow Well APCRS 301 ATTACH THIS CERTIFICATION TO APPROPRIATE LOG BOOK BY TAPE ON BACK OF FORM NOTICE Date of Invoice July 5, 1966 Date Completed Airplane Model Piper PA-24-260 24-4273 Serial Number N8817P Registration No. 527.67 Tach Time Repair Order No. Annual Airframe inspection 100 Hour engine inspection Replaced left main tire Replaced left landing light Replaced three (3) gas tank gaskets and repaired pilots window Installed new left wheel well line Checked #1 and #4 cylinder for reason of lower compression reading and found intake valve to be leaking. Removed #1 and #4 cylinde for overhaul and reinstall. Replaced broken front baffle support, and retimed both magnetos installed new points in left magneto to get proper timing A. D. NOTES No AD notes applicable at this time COMPRESSION TEST #1-58 #2-74 #3-76 #4-58 #5-73

The state of the s
B & M AIRCRAFT CORP. E02093
ELGIN AIRPORT, ELGIN, ILL. 741-9100
ROSELLE AIRPORT, ROSELLE, ILL.
This is to certify that the following repairs
This is to certify that the following repairs
were accomplished in accordance with
Current Civil Air Regulations
Signed to the Al
NOTICE ATTACH THIS CERTIFICATION
TO APPROPRIATE LOG BOOK
BY TAPE ON BACK OF FORM
Date of Invoice
Date Completed April 15, 1966
Airplane Model Piper PA-21-260
Serial Number 24-4273
Registration No. N 8817 P
Tach Time 423.75
Repair Order No. 16703
Kepuli Order No. 2010
100 Hour Airframe Inspection
100 Hour Engine Transcrion
100 Hour Engine Inspection
Tá chá
Replaced Turn and Eank Light
Throttle loose - retightened
Stop drilled left aliron trailing edge
orack
Trim sticks - Lubbed drum screw
nand areas left hand main tire
Removed fuel injector and reinstalled
Replaced worn starter prushes
Removed welded and reinstalled broken
Removed welded and reinstalled block
from baffle support bracket
Replaced cracked propeller spinner
A.D. Notes
77 76 A S 2 2 2 min min in a
No applicable A D Notes at this time
COMPRESSION OFFST
e de la la de la
#1 - 74 #2 - 78 #3 - 78 #4 - 60
#5 78 #6 80
175 = 10 170 = 00
B & M NORCEAST OCHECATION. ELGIN, ILLINION
F. A. A. Curtifica Conficention Ho. 2013
F. A. A. Curtifica Conficention Ho. 2013

B & M AIRCRAFT CORP. EOT ELGIN AIRPORT, ELGIN, ILL. 741-9100 ROSELLE AIRPORT, ROSELLE, ILL. This is to certify that the following repairs were accomplished in accordance with Current Civil Air Regulations. Signed William Will ATTACH THIS CERTIFICATION NOTICE TO APPROPRIATE LOG BOOK BY TAPE ON BACK OF FORM Date of Invoice January 26, 1966 Date Completed Piper PA24-260 Airplane Model Serial Number Registration No. 8817 P 321 Tach Time Repair Order No. 16403

Periodic Airframe Inspection 100 Hour Engine Inspection


Replaced brake linings
Repaired crack in close out faring in
right main gear well
Cleaned and lubricated flap tracks
Repaired broken alternator ground lead


DECEM BINE

Replaced worn propeller control swivel Replaced oil neck gasket

#1 - 74; #2 - 75; #BLF 76; #4 - 72; #5 - 75; and, #6 - 78

No A. D. Notes applicable at this time.





B & M AIRCRAFT CORP. FO742 ELGIN AIRPORT, ELGIN, ILL. 741-9100 ROSELLE AIRPORT, ROSELLE, ILL. This is to certify that the following repairs were accomplished in accordance with Current Civil Air Regulations. Signed Kenflemett APCR53063 ATTACH THIS NOTICE CERTIFICATION TO APPROPRIATE LOG BOOK TAPE ON BACK OF FORM Date of Invoice Date Completed Sept. 3, 1965 Airplane Model Piper PA2h "260" Serial Number 4273 Registration No. N 8817 P Tach Time 101,00 Repair Order No. 16001 Periodic airframe inspection. 100 hour engine inspection. Secured fuel line hose from chaffing on starter cable. Removed tar on belly and behind all wheels and struts. Replaced cabin hold open stop. A. D. NOTE No A. D. Notes applicable at this time. COMPRESSION

A

AIRCEAET LOG		
REMARKS	SIGNATURE	
I have inspected this aircraft and found is requirements of FAR 21.183. Certificate was issued. Laurance Thegas FJ, W. McNARY Piper Aircraft Corp.	by me.	

1. This log must always accompany the aircraft to which it Instructions for the Use of Log Book 5. Before departure on journey, pilot is personally to ascertain 2. No pages shall be torn from Log Book. No erasures, and that entries in log have been made are correct, and then sign 2. Original entries shall be made and signed by manufacturer or sall. certificate to the effect. 6. Special data such as manufacturers notes, test data, recondior seller. All other entries shall be made by Pilot, Chief Mechanic tioning, etc., should be affixed to stubs provided for that pur-Mechanic, or other competent person authorized to do so. 4. On journey, the pilot is responsible for carriage of Log Book and survey, the pilot is responsible for carriage of Log Book pose in the back of this book. CAA-18-1 Repair and Alteration forms listed on last page. and entries or omissions therein. Failure to do so will be considered This log book shall be available and produced, on demand of sidered a serious neglect of duty. anyone so authorized. PIPER AIRCRAFT CORP.—LOCK HAVEN, PA., U. S. A. Aircraft Name Engine Name 2.4 Model T.O. 540-D4 H. Serial No. Description of Aircraft Make of Propeller Hub Serial Hub Design No. Hub Serial Hub Serial Hub Serial Hub Design No. Blade Design No. Hub Design No. Owner Blade Serial Nos. Hub Design No. Owner Blade Serial Nos. Owner SEE NO ... 2. A. R. C.R.A.F. T. L.O.G.