# RECORD OF INSPECTIONS AND OVERHAULS



| DATE | INSPECTION OR OVERHAUL ACCOMPLISHED | ACTIVITY | MAJOR PARTS REPLACED | PRESERVATION | REMARKS | SIGNATURE |
|---|---|---|---|---|---|---|
| 2 Oct.90 | Overhauled in A/W current Factory recommendations | | | | | |
| P/N | 25202-5 Shaft Assy. Serial Number 2598 Total time is269:00 | | | | | |
| | | | THE AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER ORDER NO. 8260 DATE 2 OCT 90 SIGNED ____ FOR (SIGNATURE OF AUTHORIZED REPRESENTATIVE) MS Quad Helicopters Inc. (REPAIR STATION NAME) (CERTIFICATE NO.) Mineral Wells, Texas (ADDRESS) | | | |

**HILLER AVIATION**
Porterville, Ca. 93257

# SERVICE RECORD



**Component Part No.** 25200-3

**Model** UH-12E

**Nomenclature** Speed Decreaser

**Serial No.** 10178
**(If Blades, List All Serial Nos.)**

O/H 1200 Hrs

| INSTALLED | | | | | REMOVED | | | |
|---|---|---|---|---|---|---|---|---|
| DATE | OWNER | AIRCRAFT NUMBER | TIME ON HELICOPTER | PREVIOUS TIME ON PART | DATE | TIME ON HELICOPTER | TOTAL TIME ON PART | REASON |
| 20ct90 | | N703WA | 2750.0 | 00:00SMOH | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |