

# Status Report

208 CARAVAN -  
ANNUAL-100 HOUR  
INSPECTION

S/N 208-0245 N85WL

OWNER: WILLIS LEASE FINANCE CORPORATION  
ADDRESS: 60 E SIR FRANCIS DRAKE BLVD  
LAKE SPUR FL 94939  
OFFICE: 561-349-8972  
FAX:

OPERATOR: WILLIS LEASE FINANCE CORPORATION  
ADDRESS: 4700 LYONS TECHNOLOGY PARKWAY  
COCONUT CREEK FL 33073  
OFFICE: 561-349-8972  
FAX:

OPERATOR: PALM BEACH AIRCRAFT SERVICES, INC.  
ADDRESS: 2633 LANTANA RD.  
LATANA FL 33462  
OFFICE:  
FAX:

ANALYST: DALE WEBSTER  
EMAIL: DWEBSTER@CAMPSYSTEMS.COM

+1-316-462-2430 (DIRECT)  
+1-631-588-3200 (MAIN)  
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).

FILTER CRITERIA : ATA:00, 05, 09, 11, 12, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 44, 50, 51, 52, 53, 54, 55, 56, 57, 61, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 96, GENERAL; Spl. Reqs: INCLUDE; Task Type: PACKAGE, COMPONENT, SERVICE; PN/SN-UNKNOWN Components: INCLUDE

AIRCRAFT	SERIAL/REGNO: 208-0245/N85WL	MODEL: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION	MANUFACTURER: TEXTRON AVIATION INC.
----------	------------------------------	---	-------------------------------------

CERTIFICATION DATE: 16-NOV-1995

LAST ACTUALS:  
5607.8 A/C HRS as of 23-FEB-2024  
10628 AFL as of 23-FEB-2024

ENGINE NO. 1	SERIAL/PART: PCE-17493/3044000	MODEL: PT6A-114A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
--------------	--------------------------------	------------------	--

INSTALLED ON: 29-MAY-2020  
4924.6 ENG. HRS 5103 A/C HRS  
9660 ENC

LAST ACTUALS:  
5429.4 ENG. HRS as of 23-FEB-2024  
10287 ENC as of 23-FEB-2024

PROPELLER NO. 1	SERIAL/PART: BUA33874/HC-B3TN-3AF	MODEL: HC-B3TN-3AF	MANUFACTURER: HARTZELL PROPELLER INC.
-----------------	-----------------------------------	--------------------	---------------------------------------

INSTALLED ON: 29-JUN-2023  
1749.1 PROP HRS 5649.7 A/C HRS  
0 PRC

LAST ACTUALS:  
1855.2 PROP HRS as of 23-FEB-2024



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 00 - INFORMATION									
C208-230301	REVIEW MODEL 208, TIME LIMITS MAINTENANCE CHECKS TLMC (CHAPTER 5), POST CAB 11-5, REVISION 39, DATED MARCH 01, 2023							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF C208								
C208-230511	REVIEW AUDIT SUMMARY CHANGE FORM - DESCRIPTION CHANGE FOR 230008							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF C208								
C208-240101	REVIEW MODEL 208, TIME LIMITS MAINTENANCE CHECKS TLMC (CHAPTER 5), POST CAB 11-5, REVISION 40, DATED JANUARY 1, 2024							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF C208								
C208-240115	REVIEW AUDIT SUMMARY CHANGE FORM - CHANGE TASK 220002 (NO.1 AND NO. 2) TO 346011 (NO.1 AND NO. 2)							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	AFL								
	PROC. REF: RCF C208								
E029-181004	NO. 1 ENGINE - REVIEW SERVICE BULLETIN PT6A-72-1703 REV 13							Service	ATA:00
	MOS/MSC	18-Oct-18	-					REQUIREMENT CHANGE FORMS	
	HRS	4876.67							
	ENC	9563							
	PROC. REF: RCF E029-181004								
E029-210719	NO. 1 ENGINE - REVIEW PT6A-114/114A/135/135A EMM REV 41.0							Service	ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS	
	HRS								
	ENC								
	PROC. REF: RCF E029								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E029-210902	NO. 1 ENGINE - REVIEW SERVICE BULLETIN PT6A-72-1703 REV 14							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
					PROC. REF: RCF E029			
E029-220711	NO. 1 ENGINE - REVIEW PT6A-114/114A/135/135A EMM REV 43.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
					PROC. REF: RCF E029			
E029-230116	NO. 1 ENGINE - REVIEW PT6A-114/114A/135/135A EMM REV 44.0							Service ATA:00
	MOS/MSC	16-Mar-23	-					REQUIREMENT CHANGE FORMS
	HRS	5263						
	ENC	10089						
E029-230717	NO. 1 ENGINE - REVIEW PT6A-114/114A/135/135A EMM REV 45.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
					PROC. REF: RCF E029			
E029-230821	NO. 1 ENGINE - REVIEW PT6A-114/114A/135/135A EMM REV 46.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
					PROC. REF: RCF E029			
E029-240108	NO. 1 ENGINE - REVIEW PT6A-114/114A/135/135A EMM REV 47.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
					PROC. REF: RCF E029			

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
E029-240403	NO. 1 ENGINE - REVIEW PT6A-114/114A/116/135/135A SB PT6A-72-1803 REV 07							Service ATA:00
	MOS/MSC	EBT	-	TAC 0			NEW REQMT	REQUIREMENT CHANGE FORMS
	HRS			TAC 0				
	ENC			TAC 0				
	PROC. REF: RCF E029							
P006-230901	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL NO. 180, REVISION 41							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P006							
P006-231201	NO. 1 PROPELLER - REVIEW HARTZELL ICE PROTECTION SYSTEM MANUAL, REVISION 42							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P006							
P006-231201B	NO. 1 PROPELLER - REVIEW HARTZELL PROPELLER OWNER'S MANUAL (POM) 139 REV 21							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P006							
P006-231213	NO. 1 PROPELLER - REVIEW HARTZELL SL - PROPELLER - OVERHAUL PERIODS AND SERVICE LIFE LIMITS (SL) HC-SL-61-61Y, REV 15							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P006							
P006-240201	NO. 1 PROPELLER - REVIEW HARTZEL PROPELLER ICE PROTECTION SYSTEM MANUAL (MM) 180 REV 43							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P006							
P006-240301	NO. 1 PROPELLER - REVEIW HARTZELL PROPELLER OWNER'S MANUAL 139, REVISION 22							Service ATA:00
	MOS/MSC		-				NEW REQMT	REQUIREMENT CHANGE FORMS
	HRS							
	PROC. REF: RCF P006							

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 00 - INFORMATION									
PPPP1 <sup>U</sup>	PAINT AIRCRAFT							Service	ATA:00
	MOS/MSC	10-Jan-18	-						
	HRS	4877.4							
	AFL	9589							
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
051003 <sup>U</sup>	INSPECT LEFT A/S IND CALIBRATE							Service	ATA:05
	MOS	13-May-22	24		31-May-24		43 d		
	HRS	5268.6							
	AFL	10213							
051003 <sup>U</sup>	INSPECT RIGHT A/S IND CALIBRATE							Service	ATA:05
	MOS	13-May-22	24		31-May-24		43 d		
	HRS	5268.6							
	AFL	10213							
051009 <sup>U</sup>	INSPECT D ELT KANNAD 406AF, 6 YEAR CHECK							Service	ATA:05
	MOS	16-Mar-23	72		31-Mar-29		1808 d		
	HRS	5440.6							
	AFL	10430							
051009 <sup>U</sup>	INSPECT ELT KANNAD 406 IAW EASA SIB NO.: 2019-09R1							Service	ATA:05
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							
051250A <sup>U</sup>	INSPECT RECVRY WASH OR RINSE/O							Service	ATA:05
	MOS	19-Oct-23							
	HRS	5600.5	200		5800.5		192.7		
	AFL	10619							
051260 <sup>U</sup>	INSPECT 25 HR INSP-FLOATS							Service	ATA:05
	MOS	19-Oct-23							
	HRS	5600.5	25 (+5/-5)		5625.5	5630.5	17.7 (+5)		
	AFL	10619							

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
051265 <sup>U</sup>	INSPECT 50 HR INSP-FLOATS							Service	ATA:05
	MOS	19-Oct-23							
	HRS	5600.5	50 (+5/-5)		5650.5	5655.5	42.7 (+5)		
	AFL	10619							
051270 <sup>U</sup>	INSPECT 100 HR INSP-FLOATS							Service	ATA:05
	MOS	19-Oct-23							
	HRS	5600.5	100 (+5/-5)		5700.5	5705.5	92.7 (+5)		
	AFL	10619							
051275 <sup>U</sup>	INSPECT 200 HR & ANNUAL INSP-FLOATS							Service	ATA:05
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6	200 (+5/-5)		5640.6	5645.6	32.8 (+5)		
	AFL	10430							
051286A <sup>U</sup>	INSPECT AIRCRAFT WEIGHT CHECK							Service	ATA:05
	MOS/MSC	27-Apr-18	A/R						
	HRS	4880.4							
	AFL	9591							
051286A <sup>U</sup>	INSPECTION 1 REPORT RESULTS TO FLIGHT OPS AFTER, INSPECT AIRCRAFT WEIGH							Service	ATA:05
	MOS/MSC	27-Apr-18	A/R						
	HRS	4880.4							
	AFL	9591							
051292 <sup>U</sup>	INSPECT FIRST AID KIT INSP							Service	ATA:05
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							
052770 <sup>U</sup>	INSPECT AERO TWIN RUDDER GUST LOCK IN ACCORDING WITH ICA							Service	ATA:05
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							
053400	REPLACE PITOT AND STATIC HOSES							Service	ATA:05
	MOS	10-Nov-15	120		30-Nov-25		591 d	REPLACE	
	HRS	4454.2							
WC#: 05.010	AFL	8784							
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
053500A <sup>U</sup>	INSPECT COMPASS SWING CHECK							Service	ATA:05
	MOS	13-May-22	24		31-May-24		43 d		
	HRS	5268.6							
	AFL	10213							
053700	REPLACE VACUUM HOSES							Service	ATA:05
	MOS	10-Nov-15	120		30-Nov-25		591 d		
	HRS	4454.2							
WC#: 05.020	AFL	8784							
	PROC. REF: GENERIC NO REF								
055050 <sup>U</sup>	AIRWORTHINESS REVIEW							Service	ATA:05
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							
057005	NO. 1 ENGINE - MINOR INSPECTION							Package	ATA:05
	MOS	19-Oct-23							
	HRS	5422.1	200 (+10%/-10%)		(5622.1) 5800.5	5642.1	192.7 (+20)		
	ENC	10278							
	PROC. REF: EMM 72-00-00								
057010 <sup>U S</sup>	NO. 1 ENGINE - MINOR INSPECTION							Service	ATA:05
	MOS	19-Oct-23							
	HRS	5422.1	200 (+10%/-10%)						
	ENC	10278							
	PKG:1								
059902 <sup>U</sup>	INSPECT BOROSCOPE INSP. CAB06-9							Service	ATA:05
	MOS/MSC	27-Mar-14	N/A						
	HRS	4073.7							
	AFL	8120							
059910 <sup>U</sup>	INSPECT LIFE VEST INSPECTION							Service	ATA:05
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
5-15-0A	INSPECTION DOCUMENT 0A							Package	ATA:05
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM NO REF, TLMC 5-15-0A							PKG:141	
5-15-13	INSPECTION DOCUMENT 13							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:20000 (+25/-25)		20000	20025	14392.2 (+25)		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-13							PKG:34	
5-15-14	INSPECTION DOCUMENT 14							Package	ATA:05
	MOS	27-Feb-17							
	HRS	4756.9	2500 (+25/-25)		7256.9	7281.9	1649.1 (+25)		
	AFL	9350							
	PROC. REF: AMM NO REF, TLMC 5-15-14							PKG:35	
5-15-15	INSPECTION DOCUMENT 15							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:7500 (+25/-25)		7500	7525	1892.2 (+25)		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-15							PKG:36	
5-15-16	INSPECTION DOCUMENT 16							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:12500 (+25/-25)		12500	12525	6892.2 (+25)		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-16							PKG:37	
5-15-17	INSPECTION DOCUMENT 17							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:16500 (+25/-25)		16500	16525	10892.2 (+25)		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-17							PKG:38	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
5-15-18	INSPECTION DOCUMENT 18							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:17500 (+25/-25)		17500	17525	11892.2 (+25)		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-18							PKG:39	
5-15-19	INSPECTION DOCUMENT 19							Package	ATA:05
	MOS/MSC	16-Nov-95	N/A						
	HRS	0							
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-19							PKG:40	
5-15-25	INSPECTION DOCUMENT 25							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:20000 (+25/-25)		20000	20025	14392.2 (+25)		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-25							PKG:281	
5-15-MA	INSPECTION DOCUMENT MA							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:10000		10000		4392.2		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-MA							PKG:127	
5-15-MD	INSPECTION DOCUMENT MD							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0							
	AFL	0	T:15000		15000		4372		
	PROC. REF: AMM NO REF, TLMC 5-15-MD							PKG:49	
5-15-ME	INSPECTION DOCUMENT ME							Package	ATA:05
	MOS	27-Feb-17							
	HRS	4756.9	3600		8356.9	8356.9	2749.1		
	AFL	9350							
	PROC. REF: AMM NO REF, TLMC 5-15-ME							PKG:50	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>									
5-15-MF	INSPECTION DOCUMENT MF							Package	ATA:05
	MOS	16-Nov-95							
	HRS	0	T:20000		20000		14392.2		
	AFL	0							
	PROC. REF: AMM NO REF, TLMC 5-15-MF								PKG:51
5-15-MG	INSPECTION DOCUMENT MG							Package	ATA:05
	MOS	27-Feb-17							
	HRS	4756.9	1200		5956.9	5956.9	349.1		
	AFL	9350							
	PROC. REF: AMM NO REF, TLMC 5-15-MG								PKG:52
A052001	CHECK AIRCRAFT RECORDS							Service	ATA:05
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: TLMC 5-20-00								
A052002	INSPECTION ANNUAL/100 HOUR							Service	ATA:05
	MOS	16-Mar-23	12 (+30d)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
<b>ATA 11 - PLACARDS AND MARKINGS</b>									
A110001 <sup>S</sup>	DETAILED INSPECTION INTERIOR AND EXTERIOR PLACARD AND DECAL							Service	ATA:11
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
	PROC. REF: AMM 11-00-00								PKG:132

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 12 - SERVICING</b>									
C122101	LUBRICATION LANDING GEAR							Service	ATA:12
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 12-21-03									
C122103	LUBRICATION HARTZELL PROPELLER							Service	ATA:12
	MOS	29-Jun-23	12 (+1m/-1m)		30-Jun-24	31-Jul-24	73 d (+31)		
	HRS	5501.4							
	AFL								
PROC. REF: AMM 12-21-04									
C122106	LUBRICATION KEY LOCK							Service	ATA:12
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 12-21-07									
D121001	SERVICING BRAKE SYSTEM							Service	ATA:12
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 12-10-01									
<b>ATA 21 - AIR CONDITIONING</b>									
210201	AVIONICS FAN ASSEMBLY							Component	ATA:21
PN:C414007-0102	MOS/MSC	20-Jun-17	O/C	TSN 0					
SN:297	HRS	4795.3		TSN 0					
WC#: 21.075	AFL	9479							
PROC. REF: GENERIC NO REF									
210856	CABIN TEMP CONTROL							Component	ATA:21
PN:1H102-2	MOS/MSC	16-Nov-95	O/C						
SN:6AL41	HRS	0		TSN 0					
WC#: 21.005	AFL	0		TSN 0					
PROC. REF: AMM 21-41-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 21 - AIR CONDITIONING</b>									
210857	FLOW CONTROL VALVE							Component	ATA:21
PN:1H101-3	MOS/MSC	16-Nov-95	O/C						
SN:7AL37	HRS	0		TSN 0					
WC#: 21.010	AFL	0		TSN 0					
PROC. REF: AMM 21-41-00									
210858	PRESSURE REGULATOR							Component	ATA:21
PN:1H75-14	MOS/MSC	16-Nov-95	O/C						
SN:9AL76	HRS	0		TSN 0					
WC#: 21.010	AFL	0		TSN 0					
PROC. REF: AMM 36-10-00									
210860	MIXER MUFFLER ASSEMBLY							Component	ATA:21
PN:2613421-1	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 21.015	AFL	0		TSN 0					
PROC. REF: AMM 21-41-00									
215001	AFT EVAPORATOR							Component	ATA:21
PN:1250200-23	MOS/MSC	16-Nov-95	O/C						
SN:195	HRS	0		TSN 0					
WC#: 21.020	AFL	0		TSN 0					
PROC. REF: AMM 21-52-00, AMM 21-52-00									
215001	RIGHT EVAPORATOR							Component	ATA:21
PN:1250370	MOS/MSC	16-Nov-95	O/C						
SN:113	HRS	0		TSN 0					
WC#: 21.020	AFL	0		TSN 0					
PROC. REF: AMM 21-52-00, AMM 21-52-00									
215008	COMPRESSOR							Component	ATA:21
PN:SD5H14S6667	MOS/MSC	21-Jun-18	O/C	TSN 0					
SN:1429703880	HRS	4910.9		TSN 0					
WC#: 21.025	AFL	9661		TSN 0					
PROC. REF: AMM 21-52-00									
B212401 <sup>S</sup>	OPERATIONAL CHECK AVIONICS COOLING FAN							Service	ATA:21
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	800 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 21-24-00									

PKG:135

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 22 - AUTO FLIGHT</b>									
<b>220002</b>		<b>AUTOPILOT COMPUTER</b>							<b>Component ATA:22</b>
PN:065-0054-03	MOS/MSC	03-Aug-21	O/C	TSO 0					
SN:X31726	HRS	5197.2		TSO 0					
WC#: 22.005	AFL	10134		TSO 0					
PROC. REF: AMM 22-11-00									
<b>220004</b>		<b>TRIM SERVO</b>							<b>Component ATA:22</b>
PN:065-0061-36	MOS/MSC	16-Nov-95	O/C						
SN:46912	HRS	0		TSN 0					
WC#: 22.010	AFL	0		TSN 0					
PROC. REF: AMM 22-12-20									
<b>220005</b>		<b>PITCH SERVO</b>							<b>Component ATA:22</b>
PN:065-0059-01	MOS/MSC	03-Jul-20	O/C	TSO 2					
SN:X2260	HRS	5117.8		TSO 0					
WC#: 22.015	AFL	10019							
PROC. REF: AMM 22-12-10									
<b>220005</b>		<b>ROLL SERVO</b>							<b>Component ATA:22</b>
PN:065-0060-01	MOS/MSC	16-Nov-95	O/C						
SN:39982	HRS	0		TSN 0					
WC#: 22.015	AFL	0		TSN 0					
PROC. REF: AMM 22-12-05									
<b>220005</b>		<b>YAW SERVO</b>							<b>Component ATA:22</b>
PN:065-0060-04	MOS/MSC	26-Nov-96	O/C						
SN:UNKNOWN	HRS	323		TSO 0					
WC#: 22.015	AFL								
PROC. REF: AMM 22-12-15									
<b>220006</b>		<b>PITCH SERVO MOUNT</b>							<b>Component ATA:22</b>
PN:065-0030-00	MOS/MSC	16-Nov-95	O/C						
SN:36655	HRS	0		TSN 0					
WC#: 22.025	AFL	0		TSN 0					
PROC. REF: AMM 22-12-10, AMM 22-12-20									
<b>220006</b>		<b>ROLL SERVO MOUNT</b>							<b>Component ATA:22</b>
PN:065-0030-00	MOS/MSC	16-Nov-95	O/C						
SN:36246	HRS	0		TSN 0					
WC#: 22.020	AFL	0		TSN 0					
PROC. REF: AMM 22-12-05, AMM 22-12-20									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 22 - AUTO FLIGHT</b>									
<b>220006</b>		<b>SERVO MOUNT TRIM</b>						<b>Component</b>	<b>ATA:22</b>
PN:065-0041-00	MOS/MSC	16-Nov-95	O/C						
SN:3221	HRS	0		TSN 0					
WC#: 22.020	AFL	0		TSN 0					
PROC. REF: AMM 22-12-20									
<b>221010</b>		<b>YAW REMOTE RATE GYRO</b>						<b>Component</b>	<b>ATA:22</b>
PN:060-0024-00	MOS/MSC	26-Nov-96	O/C						
SN:UNKNOWN	HRS	323		TSO 0					
WC#: 22.035	AFL								
PROC. REF: GENERIC NO REF									
<b>221011</b>		<b>YAW YAW COMPUTER</b>						<b>Component</b>	<b>ATA:22</b>
PN:065-0036-01	MOS/MSC	26-Nov-96	O/C						
SN:UNKNOWN	HRS	323		TSO 0					
	AFL								
PROC. REF: GENERIC NO REF									
<b>B221201<sup>S</sup></b>		<b>FUNCTIONAL CHECK GARMIN AUTOPILOT (GFC 700)</b>						<b>Service</b>	<b>ATA:22</b>
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	800 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 22-12-00									
PKG:135									
<b>B221203<sup>S</sup></b>		<b>OPERATIONAL CHECK GARMIN AUTOPILOT (GFC 700) SLIP CLUTCH OVERRIDE</b>						<b>Service</b>	<b>ATA:22</b>
	MOS	13-May-22	12						
	HRS	5268.6							
	AFL	10213							
PROC. REF: AMM 22-12-00									
PKG:135									
<b>C221201</b>		<b>LUBRICATION AUTOPILOT SERVOS</b>						<b>Service</b>	<b>ATA:22</b>
	MOS	16-Mar-23	24 (+1m/-1m)		31-Mar-25	30-Apr-25	347 d (+30)		
	HRS	5440.6	800 (+25/-25)		6240.6	6265.6	632.8 (+25)		
	AFL	10430							
PROC. REF: AMM 22-12-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 23 - COMMUNICATIONS</b>									
230008	AUDIO PANEL							Component	ATA:23
PN:066-1055-70	MOS/MSC	16-Nov-95	O/C						
SN:161314	HRS	0		TSN 0					
WC#: 23.005	AFL	0		TSN 0					
PROC. REF: AMM 23-51-05									
230010	LEFT VHF ANTENNA							Component	ATA:23
PN:C598501-0202	MOS/MSC	27-May-10	O/C		TSN 0				
SN:3914	HRS	3441		TSN 0					
WC#: 23.010	AFL	6985							
PROC. REF: AMM 23-10-05									
230010	RIGHT VHF ANTENNA							Component	ATA:23
PN:C1268-60	MOS/MSC	19-Feb-16	O/C		TSN 2				
SN:505829	HRS	4550.05		TSN 0					
WC#: 23.010	AFL	8988							
PROC. REF: AMM 23-10-05									
231500 <sup>U</sup>	CREW INTERCOM							Component	ATA:23
PN:NAT AA83-001	MOS/MSC	24-May-12	O/C						
SN:UNKNOWN	HRS	3744.6							
	AFL	7575							
231501 <sup>U</sup>	PASSENGER INTERCOM							Component	ATA:23
PN:NAT AA82-060	MOS/MSC	24-May-12	O/C						
SN:UNKNOWN	HRS	3744.6							
	AFL	7575							
B236001 <sup>S</sup>	FUNCTIONAL CHECK STATIC DISCHARGE SYSTEM							Service	ATA:23
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 23-60-00									
PKG:132									
<b>ATA 24 - ELECTRICAL POWER</b>									
240000	GENERATOR CONTROL UNIT							Component	ATA:24
PN:51539-012N	MOS/MSC	16-Nov-95	O/C						
SN:95494	HRS	0		TSN 0					
WC#: 24.040	AFL	0		TSN 0					
PROC. REF: AMM 24-31-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
240003	ALT DR PULLEY ASSEMBLY							Component	ATA:24
PN:2601271-4	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 24.005	AFL	0		TSN 0					
PROC. REF: AMM 24-36-00									
240125	ALTERNATOR CONTROL ASSEMBLY							Component	ATA:24
PN:C611008-0101	MOS/MSC	16-Nov-95	O/C						
SN:5070609	HRS	0		TSN 0					
WC#: 24.010	AFL	0		TSN 0					
PROC. REF: AMM 24-36-00									
240220	OVERVOLTAGE SENSOR							Component	ATA:24
PN:C593005-0101	MOS/MSC	10-Dec-10	O/C	TSN 0					
SN:K020096	HRS	3555		TSN 0					
WC#: 24.015	AFL	7228							
PROC. REF: GENERIC NO REF									
240301	STARTER GENERATOR							Component	ATA:24
PN:200SGL153Q	MOS	27-Feb-17		TSO 0				OVERHAUL	
SN:2243XL	HRS	4756.9	2000	TSO 0	6756.9		1149.1		
WC#: 24.020	AFL	9350		TSO 0					
PROC. REF: GENERIC NO REF									
240401	ALTERNATOR							Component	ATA:24
PN:C611505-0201	MOS/MSC	16-Nov-95	O/C						
SN:1699	HRS	0		TSN 0					
WC#: 24.025	AFL	0		TSN 0					
PROC. REF: AMM 24-36-00									
240501	BATTERY							Component	ATA:24
PN:RG380E/44	MOS/MSC	08-Sep-23	O/C	TSN 0					
SN:70027699	HRS	5576.1		TSN 0					
WC#: 24.030	AFL	10609		TSN 0					
PROC. REF: GENERIC NO REF									
A243601 <sup>S</sup>	DETAILED INSPECTION STANDBY ALTERNATOR							Service	ATA:24
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 24-36-00									

PKG:133

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 24 - ELECTRICAL POWER</b>									
A245001 <sup>S</sup>	DETAILED INSPECTION POWER DISTRIBUTION BOXES							Service	ATA:24
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
	PROC. REF: AMM 24-50-00								PKG:136
B243301	FUNCTIONAL CHECK BATTERY CONCORD SEALED LEAD ACID BATTERY (CAPACITY CHECK)							Service	ATA:24
PN:RG380E/44	MOS	08-Sep-23	6 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
SN:70027699	HRS	5576.1							
	AFL	10609							
	PROC. REF: AMM 24-33-00								
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
256001	COPILOT LIFE JACKET							Component	ATA:25
PN:P0723E105P	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:2144	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
	PROC. REF: GENERIC NO REF								
256001	NO. 1 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:15060750061	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
	PROC. REF: GENERIC NO REF								
256001	NO. 2 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:15060750053	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
	PROC. REF: GENERIC NO REF								
256001	NO. 3 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:15060750025	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
	PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
256001	NO. 4 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:15060750086	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
PROC. REF: GENERIC NO REF									
256001	NO. 5 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:15060750049	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
PROC. REF: GENERIC NO REF									
256001	NO. 6 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:15060750020	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
PROC. REF: GENERIC NO REF									
256001	NO. 7 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:150607554	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
PROC. REF: GENERIC NO REF									
256001	NO. 8 LIFE JACKET							Component	ATA:25
PN:P01074-101	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:10080060198	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
PROC. REF: GENERIC NO REF									
256001	PILOT LIFE JACKET							Component	ATA:25
PN:P0723E105P	MOS	16-Mar-23	12	TSO 0	31-Mar-24		OVD		
SN:02201	HRS	5440.6		TSO 0					
	AFL	10430		TSO 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
256010	ELT TRANSMITTER							Component	ATA:25
PN:S1821502-02	MOS/MSC	22-Feb-23	O/C	TSN 94					
SN:LX1100174037	HRS								
WC#: 25.015	AFL								
PROC. REF: AMM 25-62-00, AMM 25-63-00									
256015	REPLACE ELT BATTERY							Component	ATA:25
PN:S1820506-01	MOS/MSC	06-May-21	DUE	TSN 0	31-Aug-27 (M)		1230 d		
SN:2032 0016	HRS	5164.4		TSN 0					
WC#: 25.015	AFL	10079							
			Expiry Date: : 31-Aug-27	PROC. REF: GENERIC NO REF					
256020	ELT ANTENNA							Component	ATA:25
PN:1327-82	MOS/MSC	19-May-09	O/C						
SN:3758	HRS	3269		TSN 0					
WC#: 25.015	AFL								
PROC. REF: AMM 25-62-00, AMM 25-63-00									
256021 <sup>U</sup>	ELT PROGRAMMIN DONGLE							Component	ATA:25
PN:S1820514-01	MOS/MSC	19-May-09	O/C						
SN:P1298-3185	HRS	3269		TSN 0					
	AFL								
256022 <sup>U</sup>	ELT REMOTE CTL PANEL RC200							Component	ATA:25
PN:13820513-11	MOS/MSC	19-May-09	O/C						
SN:P0921-0243	HRS	3269		TSN 0					
	AFL								
257006 <sup>U</sup>	INSPECT THE PARTITION NET, EB8-190A, FOR CONDITION AND VERIFY THAT IT IS SECURELY INSTALLED.							Service	ATA:25
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							
257007 <sup>U</sup>	INSPECT THE PARTITION NET ANCHOR PLATES FOR CONDITION AND VERIFY THAT THEY ARE SECURELY INSTALLED.							Service	ATA:25
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
257008 <sup>U</sup>	INSPECT ALL KIT PANELS FOR CONDITION AND VERIFY THAT THEY ARE SECURELY INSTALLED.							Service	ATA:25
	MOS	16-Mar-23	12		31-Mar-24		OVD		
	HRS	5440.6							
	AFL	10430							
A251000 <sup>S</sup>	GENERAL VISUAL INSPECTION SMOKE GOGGLE							Service	ATA:25
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6							
	AFL	10213							
				PROC. REF: AMM 25-10-00				PKG:128	
A251001	DETAILED INSPECTION CREW SEATS TASK							Service	ATA:25
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
				PROC. REF: AMM 25-10-00					
A251003 <sup>S</sup>	DETAILED INSPECTION PASSENGER SEATS							Service	ATA:25
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
				PROC. REF: AMM 25-21-00				PKG:136	
A255101 <sup>S</sup>	DETAILED INSPECTION CARGO NETS							Service	ATA:25
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 25-51-00				PKG:132	
A255201 <sup>S</sup>	ZONAL INSPECTION CARGO POD							Service	ATA:25
	MOS	16-Mar-23	72 (+30d)						
	HRS	5440.6							
	AFL	10430							
				PROC. REF: AMM 25-52-00				PKG:131	
B251001 <sup>S</sup>	OPERATIONAL CHECK INERTIA REEL TASK							Service	ATA:25
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 25-10-00				PKG:133	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 25 - EQUIPMENT/FURNISHINGS</b>									
B255201 <sup>S</sup>	OPERATIONAL CHECK CARGO POD DRAINS							Service	ATA:25
	MOS		13-May-22		12 (+1m/-1m)				
	HRS		5268.6		400 (+25/-25)				
	AFL		10213						
PROC. REF: AMM 25-52-00								PKG:133	
<b>ATA 26 - FIRE PROTECTION</b>									
260101	CABIN AFT FIRE EXTINGUISHER							Component	ATA:26
PN:C352TS	MOS/MSC		29-May-20	O/C	TSN 9				
SN:F-75057558	HRS		5103		TSN 0				
	AFL		9978						
PROC. REF: GENERIC NO REF									
260101	FORWARD FIRE EXTINGUISHER							Component	ATA:26
PN:C352TS	MOS/MSC		29-May-20	O/C	TSN 9				
SN:F-75057557	HRS		5103		TSN 0				
WC#: 26.005	AFL		9978						
PROC. REF: GENERIC NO REF									
260225	FIRE BOX							Component	ATA:26
PN:477-90008	MOS/MSC		16-Nov-95	O/C					
SN:9535010	HRS		0		TSN 0				
WC#: 26.010	AFL		0		TSN 0				
PROC. REF: AMM 26-10-00									
A261001 <sup>S</sup>	GENERAL VISUAL INSPECTION ENGINE FIRE DETECTION SYSTEM							Service	ATA:26
	MOS		13-May-22		12 (+1m/-1m)				
	HRS		5268.6		400 (+25/-25)				
	AFL		10213						
PROC. REF: AMM 26-10-00								PKG:133	
B262001	WEIGHT CHECK CABIN AFT FIRE EXTINGUISHER PORTABLE							Service	ATA:26
PN:C352TS	MOS		16-Mar-23		12 (+1m/-1m)	16-Mar-24	16-Apr-24	OVD	
SN:F-75057558	HRS		5440.6						
	AFL		10430						
PROC. REF: AMM 26-20-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 26 - FIRE PROTECTION</b>									
<b>B262001</b>		<b>WEIGHT CHECK FORWARD FIRE EXTINGUISHER PORTABLE</b>						Service	ATA:26
PN:C352TS	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
SN:F-75057557	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 26-20-00									
<b>B262003</b>		<b>HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER PORTABLE</b>						Service	ATA:26
PN:C352TS	MOS	13-Aug-19	144 (+1m/-1m)		31-Aug-31	30-Sep-31	2691 d (+30)		
SN:F-75057557	HRS								
	AFL								
PROC. REF: AMM 26-20-00									
<b>B262005</b>		<b>RESTORATION FORWARD FIRE EXTINGUISHER PORTABLE (INTERNAL INSPECTION)</b>						Service	ATA:26
PN:C352TS	MOS	16-Mar-23	72 (+1m/-1m)		31-Mar-29	30-Apr-29	1808 d (+30)		
SN:F-75057557	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 26-20-00									
<b>ATA 27 - FLIGHT CONTROLS</b>									
<b>270101</b>		<b>RIGHT INBOARD FORWARD FLAP BELLCRANK</b>						Component	ATA:27
PN:2622311-7	MOS	14-May-03		TSN 0				REPLACE	
SN:241	HRS	2042.8		TSN 0					
	AFL	3680	40000	TSN 0	43680		33052		
PROC. REF: GENERIC NO REF									
<b>270102</b>		<b>BOTTOM FLAP BELLCRANK BEARING</b>						Component	ATA:27
PN:MS27641-5	MOS	04-Jan-05						LIFE LIMIT	
SN:UNKNOWN	HRS	2410							
WC#: 27.010	AFL	4554	10000	TSN 0	14554		3926		
PROC. REF: GENERIC NO REF									
<b>270102</b>		<b>TOP FLAP BELLCRANK BEARING</b>						Component	ATA:27
PN:MS27641-5	MOS	04-Jan-05						LIFE LIMIT	
SN:N/A	HRS	2410							
WC#: 27.010	AFL	4554	10000	TSN 0	14554		3926		
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
270103	FLAP BELLCRANK BOLT							Component	ATA:27
PN:AN5-77	MOS	04-Jan-05						LIFE LIMIT	
SN:UNKNOWN	HRS	2410							
WC#: 27.015	AFL	4554	10000	TSN 0	14554		3926		
PROC. REF: GENERIC NO REF									
270601	AILERON TRIM ACTUATOR							Component	ATA:27
PN:2661615-1	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.020	AFL	0		TSN 0					
PROC. REF: AMM 27-10-02									
271095	FLAP TRANSITION GEAR BOX							Component	ATA:27
PN:C145-00-46	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
271401	LEFT ELEVATOR TRIM ACTUATOR							Component	ATA:27
PN:2661215-1	MOS/MSC	15-Apr-03	O/C						
SN:UNKNOWN	HRS	2024		TSN 0					
WC#: 27.025	AFL								
PROC. REF: AMM 27-30-02									
271401	RIGHT ELEVATOR TRIM ACTUATOR							Component	ATA:27
PN:2661215-1	MOS/MSC	15-Apr-03	O/C						
SN:UNKNOWN	HRS	2024		TSN 0					
WC#: 27.025	AFL								
PROC. REF: AMM 27-30-02									
271502	FLAP ACTUATOR ASSEMBLY							Component	ATA:27
PN:9910586-4	MOS/MSC	06-May-21	O/C	TSO 11					
SN:1588	HRS	5164.4		TSO 0					
WC#: 27.035	AFL	10079							
PROC. REF: AMM 27-50-01									
271508	AFT FLAP ACTUATOR MOTOR							Component	ATA:27
PN:C301002-0104	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.040	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
271508	FWD FLAP ACTUATOR MOTOR							Component	ATA:27
PN:C301002-0104	MOS/MSC	23-Sep-98	O/C						
SN:UNKNOWN	HRS	1437		TSN 0					
WC#: 27.040	AFL								
PROC. REF: GENERIC NO REF									
271700	FLAP ACT ASSY SWITCH							Component	ATA:27
PN:2662011-1	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 27.045	AFL	0		TSN 0					
PROC. REF: AMM 27-50-01									
271903	STALL WARNING LIFT TRANSDUCER							Component	ATA:27
PN:799-1	MOS/MSC	16-Nov-95	O/C						
SN:1045	HRS	0		TSN 0					
WC#: 27.050	AFL	0		TSN 0					
PROC. REF: AMM 27-31-00									
271904	STALL WARNING DETECTOR ASSEMBLY							Component	ATA:27
PN:C145-00-46	MOS/MSC	16-Nov-95	O/C		TSN 0				
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 27-31-00									
273000	AFT ELEVATOR PUSHROD							Component	ATA:27
PN:2634009-1	MOS	16-Nov-95						LIFE LIMIT	
SN:UNKNOWN	HRS	0							
	AFL	0	40000	TSN 0	40000		29372		
PROC. REF: AMM 27-30-01									
273000	FORWARD ELEVATOR PUSHROD							Component	ATA:27
PN:2613440-5	MOS	27-Feb-17							
SN:1219	HRS	4756.9							
WC#: 27.030	AFL	9350	40000	TSN 0	49350		38722		
PROC. REF: AMM 27-30-01									
A273000 <sup>S</sup>	LEFT AND RIGHT ELEVATOR TORQUE TUBE ATTACH POINTS (BORESCOPE) SPECIAL DETAILED INSPECTION							Service	ATA:27
	MOS	16-Mar-23	24						
	HRS	5440.6	1600						
	AFL	10430							
PROC. REF: AMM 27-30-00									

PKG:137

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
A275001	DETAILED INSPECTION FLAP ACTUATOR MOUNT BRACKET							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-50-00								
A275003	DETAILED INSPECTION FLAP BELLCRANK							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-50-00								
B271001 <sup>S</sup>	FUNCTIONAL CHECK SPOILER SYSTEM							Service	ATA:27
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
	PROC. REF: AMM 27-10-00							PKG:136	
B271003	FUNCTIONAL CHECK AILERON SYSTEM							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-10-00								
B271005 <sup>S</sup>	FUNCTIONAL CHECK AILERON TRIM TAB (FREE PLAY)							Service	ATA:27
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
	PROC. REF: AMM 27-10-02							PKG:133	
B272003	FUNCTIONAL CHECK RUDDER SYSTEM (FLOAT KIT INSTALLATION)							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-20-00								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
B273001	<b>FUNCTIONAL CHECK ELEVATOR SYSTEM</b>							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-30-00								
B273003 <sup>S</sup>	<b>FUNCTIONAL CHECK ELEVATOR TRIM TAB (FREE PLAY)</b>							Service	ATA:27
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
	PROC. REF: AMM 27-30-02							PKG:133	
B273101 <sup>S</sup>	<b>OPERATIONAL CHECK STALL WARNING SYSTEM</b>							Service	ATA:27
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
	PROC. REF: AMM 27-31-00							PKG:132	
B275001	<b>FUNCTIONAL CHECK FLAP SYSTEM</b>							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-50-00								
B277001 <sup>S</sup>	<b>RUDDER GUST LOCK DETAILED INSPECTION (AIRPLANES 20800237 AND ON AND AIRPLANES 208B0382 AND ON)</b>							Service	ATA:27
	MOS	16-Mar-23	24 (+1m/-1m)						
	HRS	5440.6	1600 (+25/-25)						
	AFL	10430							
	PROC. REF: AMM 27-70-01							PKG:137	
C270001	<b>LUBRICATION FLIGHT CONTROLS</b>							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-00-00								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 27 - FLIGHT CONTROLS</b>									
C271001	LUBRICATION AILERON TRIM SYSTEM							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-10-02								
C271005	LUBRICATION AILERON TRIM TAB ACTUATOR (2661615-1, 2661615- 9, OR 2661615-10)							Service	ATA:27
	MOS	19-Mar-20	60 (+1m/-1m)		31-Mar-25	30-Apr-25	347 d (+30)		
	HRS	5008.5	1600 (+25/-25)		6608.5	6633.5	1000.7 (+25)		
	AFL	9796							
	PROC. REF: AMM 27-10-02								
C272001	LUBRICATION RUDDER BAR BEARINGS AND RUDDER PEDALS							Service	ATA:27
	MOS	16-Mar-23	24 (+1m/-1m)		31-Mar-25	30-Apr-25	347 d (+30)		
	HRS	5440.6	1600 (+25/-25)		7040.6	7065.6	1432.8 (+25)		
	AFL	10430							
	PROC. REF: AMM 27-20-00								
C273003	LUBRICATION ELEVATOR TRIM TAB ACTUATOR (2661215-1 AND 2661215-9)							Service	ATA:27
	MOS	19-Mar-20	60 (+1m/-1m)		31-Mar-25	30-Apr-25	347 d (+30)		
	HRS	5008.5	1600 (+25/-25)		6608.5	6633.5	1000.7 (+25)		
	AFL	9796							
	PROC. REF: AMM 27-30-02								
C273030	ELEVATOR BELLCRANK LUBRICATION							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 12-21-02								
C275001	LUBRICATION FLAP TRACKS AND ROLLERS							Service	ATA:27
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 27-50-00								
<b>ATA 28 - FUEL</b>									
280001	LEFT FUEL QUANTITY GAUGE							Component	ATA:28
PN:C662041-0102	MOS/MSC	16-Nov-95	O/C						
SN:1647	HRS	0		TSN 0					

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
WC#: 28.005	AFL	0			TSN 0				
PROC. REF: AMM 28-41-00									
<b>280001</b>	<b>RIGHT FUEL QUANTITY GAUGE</b>							<b>Component</b>	<b>ATA:28</b>
PN:C662041-0102	MOS/MSC	16-Nov-95	O/C						
SN:1653	HRS	0			TSN 0				
WC#: 28.005	AFL	0			TSN 0				
PROC. REF: AMM 28-41-00									
<b>280347</b>	<b>FUEL PRESSURE SWITCH</b>							<b>Component</b>	<b>ATA:28</b>
PN:S2615-2	MOS/MSC	19-Oct-23	O/C						
SN:1190	HRS	5600.5							
WC#: 28.010	AFL	10619							
PROC. REF: AMM 28-22-00									
<b>280389</b>	<b>FUEL SHUTOFF VALVE</b>							<b>Component</b>	<b>ATA:28</b>
PN:72D10C	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 28.015	AFL	0			TSN 0				
PROC. REF: AMM 28-21-00									
<b>280414</b>	<b>ELEC FUEL BOOST PUMP</b>							<b>Component</b>	<b>ATA:28</b>
PN:2C6-8	MOS/MSC	16-Nov-95	O/C						
SN:8AL53	HRS	0			TSN 0				
WC#: 28.025	AFL	0			TSN 0				
PROC. REF: AMM 28-22-00									
<b>280418</b>	<b>PUMP EJECTOR</b>							<b>Component</b>	<b>ATA:28</b>
PN:68E101-14	MOS/MSC	16-Nov-95	O/C						
SN:1417	HRS	0			TSN 0				
WC#: 28.030	AFL	0			TSN 0				
PROC. REF: AMM 28-22-00									
<b>280421</b>	<b>FUEL CHECK VALVE</b>							<b>Component</b>	<b>ATA:28</b>
PN:6C172	MOS/MSC	16-Nov-95	O/C						
SN:4146	HRS	0			TSN 0				
WC#: 28.035	AFL	0			TSN 0				
PROC. REF: AMM 28-22-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
280433	LW FUEL WARN SWITCH							Component	ATA:28
PN:GF5500-82	MOS/MSC	16-Nov-95	O/C						
SN:9527965	HRS	0		TSN 0					
WC#: 28.040	AFL	0		TSN 0					
PROC. REF: AMM 28-41-00, AMM 28-42-00									
280500	FUEL TO ENGINE HOSE							Component	ATA:28
PN:AE3663726H0520	MOS	25-Apr-16	120	TSN 0	30-Apr-26		742 d		
SN:N/A	HRS	4585.1		TSN 0					
WC#: 28.045	AFL	9098							
PROC. REF: GENERIC NO REF									
280600	MOTIVE FLOW HOSE							Component	ATA:28
PN:AE3663724G0330	MOS	25-Apr-16	120	TSN 0	30-Apr-26		742 d		
SN:N/A	HRS	4585.1		TSN 0					
WC#: 28.045	AFL	9098							
PROC. REF: GENERIC NO REF									
280701	LEFT NO. 1 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1103	MOS/MSC	19-Oct-23	O/C	TSO 0					
SN:2906	HRS	5600.5		TSO 0					
WC#: 28.050	AFL	10619		TSO 0					
PROC. REF: AMM 28-10-01									
280701	LEFT NO. 2 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1107	MOS/MSC	19-Oct-23	O/C	TSO 0					
SN:3688	HRS	5600.5		TSO 0					
WC#: 28.050	AFL	10619		TSO 0					
PROC. REF: AMM 28-10-01									
280701	LEFT NO. 3 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1108	MOS/MSC	19-Oct-23	O/C	TSN 0					
SN:6475	HRS	5600.5		TSN 0					
WC#: 28.050	AFL	10619		TSN 0					
PROC. REF: AMM 28-10-01									
280701	LEFT NO. 4 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1104	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.055	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 28 - FUEL</b>									
280701	RIGHT NO. 1 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1103	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.060	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									
280701	RIGHT NO. 2 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1105	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.060	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									
280701	RIGHT NO. 3 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1106	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.060	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									
280701	RIGHT NO. 4 FUEL TRANSMITTER							Component	ATA:28
PN:C668050-1104	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 28.055	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									
280713	NO. 1 LOW FUEL LEVEL SWITCH							Component	ATA:28
PN:GF5500-81	MOS/MSC	16-Nov-95	O/C						
SN:9530862	HRS	0		TSN 0					
WC#: 28.065	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									
280713	NO. 2 LOW FUEL LEVEL SWITCH							Component	ATA:28
PN:GF5500-81	MOS/MSC	16-Nov-95	O/C						
SN:9538587	HRS	0		TSN 0					
WC#: 28.065	AFL	0		TSN 0					
PROC. REF: AMM 28-10-01									
280726	FUEL FLOW TRANSDUCER							Component	ATA:28
PN:TFF2905-13	MOS/MSC	16-Nov-95	O/C						
SN:1342	HRS	0		TSN 0					
WC#: 28.070	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 28 - FUEL									
A281001 <sup>S</sup>	DETAILED INSPECTION FUEL FILLER ASSEMBLY							Service	ATA:28
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 28-10-01				PKG:132	
A281003 <sup>S</sup>	DETAILED INSPECTION FUEL STORAGE SYSTEM							Service	ATA:28
	MOS	19-Mar-19	48 (+1m/-1m)						
	HRS	5008.5							
	AFL	9796							
				PROC. REF: AMM 28-10-01				PKG:130	
B281001 <sup>S</sup>	OPERATIONAL CHECK FUEL VENT LINE FLOAT VALVE							Service	ATA:28
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 28-10-03				PKG:132	
B282103 <sup>S</sup>	FIREWALL FUEL SHUTOFF VALVE CONTROL OPERATIONAL CHECK							Service	ATA:28
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 28-21-00				PKG:133	
B284101 <sup>S</sup>	OPERATIONAL CHECK FUEL RESERVOIR WARNING SYSTEM							Service	ATA:28
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 28-41-00				PKG:133	
B284103 <sup>S</sup>	FUNCTIONAL CHECK FUEL QUANTITY AND LOW FUEL WARNING SYSTEMS							Service	ATA:28
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
				PROC. REF: AMM 28-41-00				PKG:136	
D282101	SERVICE FIREWALL MOUNTED FUEL FILTER							Service	ATA:28
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
				PROC. REF: AMM 28-21-00					

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 30 - ICE AND RAIN PROTECTION</b>									
300523	NO. 1 PROP DE-ICE BOOT							Component	ATA:30
PN:4E2336-12	MOS/MSC	29-Jul-99	O/C						
SN:UNKNOWN	HRS			TSN 0					
WC#: 30.060	AFL								
PROC. REF: AMM 30-60-00									
300523	NO. 2 PROP DE-ICE BOOT							Component	ATA:30
PN:4E2336-12	MOS/MSC	29-Jul-99	O/C						
SN:UNKNOWN	HRS			TSN 0					
WC#: 30.060	AFL								
PROC. REF: AMM 30-60-00									
300523	NO. 3 PROP DE-ICE BOOT							Component	ATA:30
PN:4E2336-12	MOS/MSC	29-Jul-99	O/C						
SN:UNKNOWN	HRS			TSN 0					
WC#: 30.060	AFL								
PROC. REF: AMM 30-60-00									
B301001 <sup>S</sup>	FUNCTIONAL CHECK BLEED AIR PRESSURE REGULATOR (AIRPLANES WITH DE-ICE BOOTS INSTALLED)							Service	ATA:30
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 30-10-00									
B301003 <sup>S</sup>	FUNCTIONAL CHECK BLEED AIR PRESSURE REGULATOR (WITHOUT TKS AND NOT INCORPORATING CAB93-2)							Service	ATA:30
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 30-10-00									
B301101 <sup>S</sup>	FUNCTIONAL CHECK TKS ANTI-ICE SYSTEM							Service	ATA:30
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 30-11-00									
B301102 <sup>S</sup>	FUNCTIONAL CHECK INBOARD TKS WING PANEL PRESSURIZATION							Service	ATA:30
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6							
	AFL	10213							
PROC. REF: AMM 30-11-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 30 - ICE AND RAIN PROTECTION</b>									
B301105 <sup>S</sup>	FUNCTIONAL CHECK TKS SYSTEM PRESSURE AND FLOW							Service	ATA:30
	MOS	13-May-22	12						
	HRS	5268.6							
	AFL	10213							
	PROC. REF: AMM 30-11-00							PKG:133	
B304001 <sup>S</sup>	OPERATIONAL CHECK WINDSHIELD ANTI-ICE SYSTEM							Service	ATA:30
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
	PROC. REF: AMM 30-40-00							PKG:133	
<b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>									
313104	FLIGHT DATA RECORDER							Component	ATA:31
PN:PN	MOS/MSC	16-Nov-95	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
	PROC. REF: AMM 31-30-00								
313105	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							Component	ATA:31
PN:PN	MOS/MSC	16-Nov-95	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
	PROC. REF: GENERIC NO REF								
B313101 <sup>S</sup>	FUNCTIONAL CHECK FLIGHT DATA RECORDER SYSTEM							Service	ATA:31
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6							
	AFL	10213							
	PROC. REF: AMM 31-31-00							PKG:128	
B313103 <sup>S</sup>	FUNCTIONAL CHECK FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							Service	ATA:31
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
	PROC. REF: AMM 31-31-00							PKG:136	
<b>ATA 32 - LANDING GEAR</b>									
320003	AFT NOSE GEAR SPRING SUPPORT ASSEMBLY							Component	ATA:32
PN:PN	MOS	16-Nov-95			TSN 0			LIFE LIMIT	
SN:UNKNOWN	HRS	0			TSN 0				

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 32 - LANDING GEAR									
	AFL	0	40000	TSN 0	40000		29372		
PROC. REF: AMM 32-20-00									
320301F	LEFT INBOARD (FLOAT) TIRE							Component	ATA:32
PN:AA1E6	MOS/MSC	27-Apr-18	O/C	TSN 0					
SN:UNKNOWN	HRS	4880.4		TSN 0					
	AFL	9591							
PROC. REF: GENERIC NO REF									
320301F	LEFT OUTBOARD (FLOAT) TIRE							Component	ATA:32
PN:606C86-6	MOS/MSC	06-Sep-16	O/C	TSO 9					
SN:UNKNOWN	HRS	4695.7							
	AFL	9256							
PROC. REF: GENERIC NO REF									
320301F	RIGHT INBOARD (FLOAT) TIRE							Component	ATA:32
PN:AA1E6	MOS/MSC	27-Apr-18	O/C	TSN 0					
SN:UNKNOWN	HRS	4880.4		TSN 0					
	AFL	9591							
PROC. REF: GENERIC NO REF									
320301F	RIGHT OUTBOARD (FLOAT) TIRE							Component	ATA:32
PN:606C66-2	MOS/MSC	15-Aug-01	O/C						
SN:UNKNOWN	HRS	1752							
	AFL	2952		TSN 0					
PROC. REF: GENERIC NO REF									
320302F	LEFT INBOARD (FLOAT) WHEEL ASSEMBLY							Component	ATA:32
PN:40-418	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872		TSN 0					
PROC. REF: GENERIC NO REF									
320302F	LEFT OUTBOARD (FLOAT) WHEEL ASSEMBLY							Component	ATA:32
PN:8A04000-031	MOS/MSC	06-Sep-16	O/C	TSO 9					
SN:20702078	HRS	4695.7							
	AFL	9256							
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
<b>ATA 32 - LANDING GEAR</b>								
<b>320302F RIGHT INBOARD (FLOAT) WHEEL ASSEMBLY Component ATA:32</b>								
PN:40-418	MOS/MSC	14-Apr-10	O/C					
SN:NSN	HRS	3398						
	AFL	6872			TSN 0			
PROC. REF: GENERIC NO REF								
<b>320302F RIGHT OUTBOARD (FLOAT) WHEEL ASSEMBLY Component ATA:32</b>								
PN:40-418	MOS/MSC	14-Apr-10	O/C					
SN:NSN	HRS	3398						
	AFL	6872			TSN 0			
PROC. REF: GENERIC NO REF								
<b>320801F LEFT NOSE (FLOAT) WHEEL ASSEMBLY Component ATA:32</b>								
PN:1003233	MOS/MSC	14-Apr-10	O/C					
SN:NSN	HRS	3398						
	AFL	6872			TSN 0			
PROC. REF: GENERIC NO REF								
<b>320801F RIGHT NOSE (FLOAT) WHEEL ASSEMBLY Component ATA:32</b>								
PN:D-30500-1	MOS/MSC	31-Jan-96	O/C					
SN:UNKNOWN	HRS	11						
	AFL	13			TSN 0			
PROC. REF: GENERIC NO REF								
<b>320802F LEFT NOSE (FLOAT) TIRE Component ATA:32</b>								
PN:505C01-2	MOS/MSC	16-Mar-23	O/C		TSN 0			
SN:20660472	HRS	5440.6			TSN 0			
	AFL	10430			TSN 0			
PROC. REF: GENERIC NO REF								
<b>320802F RIGHT NOSE (FLOAT) TIRE Component ATA:32</b>								
PN:505C06-1	MOS/MSC	28-Aug-97	O/C					
SN:UNKNOWN	HRS	782						
	AFL	1216			TSN 0			
PROC. REF: GENERIC NO REF								
<b>321000F<sup>U</sup> HYDRAULIC ASSY Component ATA:32</b>								
PN:34-24524022-5	MOS/MSC	31-Jan-96	O/C					
SN:UNKNOWN	HRS	11						
	AFL	13			TSN 0			

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
321001	LEFT AMPHIBIOUS FLOAT ASSEMBLY							Component	ATA:32
PN:6R1-2001-1	MOS/MSC	28-Aug-97	O/C						
SN:80077	HRS	782							
	AFL	1216			TSO 0				
PROC. REF: GENERIC NO REF									
321001	RIGHT AMPHIBIOUS FLOAT ASSEMBLY							Component	ATA:32
PN:6R1-2001-1	MOS/MSC	28-Aug-97	O/C						
SN:80078	HRS	782							
	AFL	1216			TSO 0				
PROC. REF: GENERIC NO REF									
321086	LEFT MLG AXLE							Component	ATA:32
PN:8A04000-021	MOS	02-Apr-13			TSN 0			LIFE LIMIT	
SN:UNKNOWN	HRS	3865.7			TSN 0				
WC#: 32.065	AFL	7769	10000		TSN 0	17769	7141		
PROC. REF: AMM 32-40-00									
321086F	LEFT MAIN LANDING GEAR AXLE FLOATS							Component	ATA:32
PN:8A04000-021	MOS/MSC	28-Aug-97	O/C						
SN:-	HRS	782							
	AFL	1216			TSO 0				
PROC. REF: GENERIC NO REF									
321086F	RIGHT MAIN LANDING GEAR AXLE FLOATS							Component	ATA:32
PN:8A04000-021	MOS/MSC	27-Apr-18	O/C		TSN 0				
SN:NOT APPLICABLE	HRS	4880.4			TSN 0				
	AFL	9591							
PROC. REF: GENERIC NO REF									
321101	LEFT INBOARD (FLOAT) BRAKE ASSEMBLY							Component	ATA:32
PN:30-241	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
WC#: 32.070	AFL	6872			TSN 0				
PROC. REF: GENERIC NO REF									
321101	LEFT OUTBOARD (FLOAT) BRAKE ASSEMBLY							Component	ATA:32
PN:30-241	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
WC#: 32.070	AFL	6872			TSN 0				
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
321101	RIGHT INBOARD (FLOAT) BRAKE ASSEMBLY							Component	ATA:32
PN:30-241	MOS/MSC	19-Oct-23	O/C						
SN:NSN	HRS	5600.5							
WC#: 32.075	AFL	10619							
					PROC. REF: GENERIC NO REF				
321101	RIGHT OUTBOARD (FLOAT) BRAKE ASSEMBLY							Component	ATA:32
PN:30-241	MOS/MSC	19-Oct-23	O/C						
SN:NSN	HRS	5600.5							
WC#: 32.075	AFL	10619							
					PROC. REF: GENERIC NO REF				
321106F	LEFT INBOARD BRAKE PRESS PLATE							Component	ATA:32
PN:073-04200	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
					PROC. REF: GENERIC NO REF				
321106F	LEFT OUTBOARD BRAKE PRESS PLATE							Component	ATA:32
PN:073-04200	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
					PROC. REF: GENERIC NO REF				
321106F	RIGHT INBOARD BRAKE PRESS PLATE							Component	ATA:32
PN:073-04200	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
					PROC. REF: GENERIC NO REF				
321106F	RIGHT OUTBOARD BRAKE PRESS PLATE							Component	ATA:32
PN:073-04200	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
					PROC. REF: GENERIC NO REF				
321107F	LEFT INBOARD BRAKE PADS							Component	ATA:32
PN:066-30026	MOS/MSC	26-Apr-04	O/C						
SN:UNKNOWN	HRS	2197							
	AFL	4007			TSN 0				
					PROC. REF: GENERIC NO REF				

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
321107F	LEFT OUTBOARD BRAKE PADS							Component	ATA:32
PN:066-30026	MOS/MSC	26-Apr-04	O/C						
SN:UNKNOWN	HRS	2197							
	AFL	4007			TSN 0				
	PROC. REF: GENERIC NO REF								
321107F	RIGHT INBOARD BRAKE PADS							Component	ATA:32
PN:066-10500	MOS/MSC	19-Oct-23	O/C		TSN 0				
SN:UNKNOWN	HRS	5600.5			TSN 0				
	AFL	10619			TSN 0				
	PROC. REF: GENERIC NO REF								
321107F	RIGHT OUTBOARD BRAKE PADS							Component	ATA:32
PN:066-10500	MOS/MSC	19-Oct-23	O/C		TSN 0				
SN:UNKNOWN	HRS	5600.5			TSN 0				
	AFL	10619			TSN 0				
	PROC. REF: GENERIC NO REF								
321108F	LEFT INBOARD BRAKE DISC							Component	ATA:32
PN:164-24501	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321108F	LEFT OUTBOARD BRAKE DISC							Component	ATA:32
PN:164-24501	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321108F	RIGHT INBOARD BRAKE DISC							Component	ATA:32
PN:164-24501	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321108F	RIGHT OUTBOARD BRAKE DISC							Component	ATA:32
PN:164-24501	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
321110F	LEFT INBOARD BRAKE BACK PLATE							Component	ATA:32
PN:074-02900	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321110F	LEFT OUTBOARD BRAKE BACK PLATE							Component	ATA:32
PN:074-02900	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321110F	RIGHT INBOARD BRAKE BACK PLATE							Component	ATA:32
PN:074-02900	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321110F	RIGHT OUTBOARD BRAKE BACK PLATE							Component	ATA:32
PN:074-02900	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321118F	LEFT INBOARD TORQUE PLATE							Component	ATA:32
PN:075-20700	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321118F	LEFT OUTBOARD TORQUE PLATE							Component	ATA:32
PN:075-20700	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								
321118F	RIGHT INBOARD TORQUE PLATE							Component	ATA:32
PN:075-20700	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872			TSN 0				
	PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
321118F	RIGHT OUTBOARD TORQUE PLATE							Component	ATA:32
PN:075-20700	MOS/MSC	14-Apr-10	O/C						
SN:NSN	HRS	3398							
	AFL	6872		TSN 0					
PROC. REF: GENERIC NO REF									
321201	PARKING BRAKE CONTROL ASSEMBLY							Component	ATA:32
PN:S1779-3	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 32.110	AFL	0		TSN 0					
PROC. REF: AMM 32-42-00									
A321001	DETAILED INSPECTION MAIN LANDING GEAR TASK							Service	ATA:32
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 32-10-00									
A321003 <sup>S</sup>	SPECIAL DETAILED INSPECTION CENTER-SPRING AND MAIN GEAR-SPRING INTERFACE AREA (CORROSION INSPECTION AND REPAIR)							Service	ATA:32
	MOS	19-Mar-19	48 (+1m/-1m)						
	HRS	5008.5							
	AFL	9796							
PROC. REF: AMM 32-10-00									
A322002 <sup>S</sup>	GENERAL VISUAL INSPECTION DRAG LINK FORWARD SUPPORT SEAL (AIRCRAFT 20800553 AND ON AND 208B5076 AND ON)							Service	ATA:32
	MOS	13-May-22	12 (+30d)						
	HRS	5268.6							
	AFL	10213							
PROC. REF: AMM 32-20-00									
A322003 <sup>S</sup>	GENERAL VISUAL INSPECTION DRAG LINK FORWARD SUPPORT (AIRCRAFT 20800553 AND ON AND 208B5076 AND ON)							Service	ATA:32
	MOS	19-Mar-19	48 (+30d)						
	HRS	5008.5							
	AFL	9796							
PROC. REF: AMM 32-20-00									
A324001	DETAILED INSPECTION BRAKES							Service	ATA:32
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 32-40-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 32 - LANDING GEAR</b>									
A324005	DETAILED INSPECTION MAIN LANDING GEAR WHEELS AND TIRES							Service	ATA:32
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 32-40-00								
A324009	DETAILED INSPECTION NOSE LANDING GEAR WHEEL AND TIRE							Service	ATA:32
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 32-40-00								
B322001 <sup>S</sup>	FUNCTIONAL CHECK SHIMMY DAMPER							Service	ATA:32
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
	PROC. REF: AMM 32-20-02								
	PKG:132								
B324001 <sup>S</sup>	OPERATIONAL CHECK BRAKES							Service	ATA:32
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
	PROC. REF: AMM 32-40-00								
	PKG:136								
<b>ATA 33 - LIGHTS</b>									
330124	ANNUNCIATOR							Component	ATA:33
PN:2670104-802	MOS/MSC	16-Nov-95	O/C						
SN:843	HRS	0		TSN 0					
WC#: 33.040	AFL	0		TSN 0					
	PROC. REF: GENERIC NO REF								
330312	GRAPHIC SIGN							Component	ATA:33
PN:9002-03	MOS/MSC	16-Nov-95	O/C						
SN:35G26	HRS	0		TSN 0					
WC#: 33.005	AFL	0		TSN 0					
	PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 33 - LIGHTS</b>									
330701	LEFT LANDING LIGHT							Component	ATA:33
PN:4553	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 33.010	AFL	0			TSN 0				
PROC. REF: AMM 33-40-10									
330701	RIGHT LANDING LIGHT							Component	ATA:33
PN:4553	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 33.010	AFL	0			TSN 0				
PROC. REF: AMM 33-40-10									
330702	LEFT TAXI LIGHT							Component	ATA:33
PN:4626	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 33.015	AFL	0			TSN 0				
PROC. REF: AMM 33-40-10									
330702	RIGHT TAXI LIGHT							Component	ATA:33
PN:4626	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0			TSN 0				
WC#: 33.015	AFL	0			TSN 0				
PROC. REF: AMM 33-40-10									
330813	FLASHER ASSEMBLY BEACON							Component	ATA:33
PN:C594502-0102	MOS/MSC	16-Nov-95	O/C						
SN:95060746	HRS	0			TSN 0				
WC#: 33.020	AFL	0			TSN 0				
PROC. REF: AMM 33-43-00									
330901	LEFT STROBE LIGHT ASSEMBLY							Component	ATA:33
PN:C622010-0101	MOS/MSC	07-Nov-07	O/C						
SN:H07041129	HRS	2956			TSN 0				
WC#: 33.025	AFL								
PROC. REF: AMM 33-42-00									
330901	RIGHT STROBE LIGHT ASSEMBLY							Component	ATA:33
PN:C622010-0102	MOS/MSC	16-Nov-95	O/C						
SN:95060016	HRS	0			TSN 0				
WC#: 33.025	AFL	0			TSN 0				
PROC. REF: AMM 33-42-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 33 - LIGHTS</b>									
<b>330903</b>		<b>LEFT STROBE LIGHT POWER SUPPLY</b>					<b>Component</b>	<b>ATA:33</b>	
PN:152-0024	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 33-42-00									
<b>330903</b>		<b>RIGHT STROBE LIGHT POWER SUPPLY</b>					<b>Component</b>	<b>ATA:33</b>	
PN:152-0024	MOS/MSC	25-Aug-03	O/C						
SN:G03088164	HRS	2145		TSO 0					
	AFL								
PROC. REF: AMM 33-42-00									
<b>B332001<sup>S</sup></b>		<b>OPERATIONAL CHECK PASSENGER/CARGO COMPARTMENT LIGHTING</b>					<b>Service</b>	<b>ATA:33</b>	
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
PROC. REF: AMM 33-20-00									
PKG:136									
<b>ATA 34 - NAVIGATION</b>									
<b>340004</b>		<b>LEFT TURN COORDINATOR</b>					<b>Component</b>	<b>ATA:34</b>	
PN:C661003-0506	MOS/MSC	16-Nov-95	O/C						
SN:9508153	HRS	0		TSN 0					
WC#: 34.015	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
<b>340005</b>		<b>RIGHT TURN &amp; BANK INDICATOR</b>					<b>Component</b>	<b>ATA:34</b>	
PN:C661030-0301	MOS/MSC	16-Nov-95	O/C						
SN:9508240	HRS	0		TSN 0					
WC#: 34.020	AFL	0		TSN 0					
PROC. REF: AMM 34-22-00									
<b>340006</b>		<b>NO. 1 ENCODING ALTIMETER</b>					<b>Component</b>	<b>ATA:34</b>	
PN:5035P-P45P45	MOS/MSC	13-Jun-07	O/C						
SN:05B574	HRS	2837		TSO 0					
WC#: 34.005	AFL								
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340006	NO. 2 ENCODING ALTIMETER							Component	ATA:34
PN:C661014-0101	MOS/MSC	16-Nov-95	O/C						
SN:3K507	HRS	0		TSN 0					
WC#: 34.010	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340007	ALTIMETER RADAR							Component	ATA:34
PN:066-1061-03	MOS/MSC	16-Nov-95	O/C						
SN:16247	HRS	0		TSN 0					
WC#: 34.025	AFL	0		TSN 0					
PROC. REF: AMM 34-17-05									
340013	HSI GYRO							Component	ATA:34
PN:066-3046-07	MOS/MSC	05-Nov-98	O/C						
SN:83555	HRS	1444		TSO 28					
WC#: 34.040	AFL								
PROC. REF: AMM 34-23-00									
340014	DIRECTIONAL GYRO							Component	ATA:34
PN:060-0015-00	MOS/MSC	16-Nov-95	O/C						
SN:38484	HRS	0		TSN 0					
WC#: 34.040	AFL	0		TSN 0					
PROC. REF: AMM 34-23-00									
340015	SLAVING ACCESSORY							Component	ATA:34
PN:071-1242-06	MOS/MSC	16-Nov-95	O/C						
SN:22601	HRS	0		TSN 0					
WC#: 34.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340016	FLUX DETECTOR							Component	ATA:34
PN:071-1052-00	MOS/MSC	16-Nov-95	O/C						
SN:47848	HRS	0		TSN 0					
WC#: 34.045	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340017	MODE ANNUN REMOTE							Component	ATA:34
PN:065-0058-03	MOS/MSC	16-Nov-95	O/C						
SN:3280	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340019	RADAR RECEIVER/TRANSMITTER							Component	ATA:34
PN:071-1378-00	MOS/MSC	02-Apr-13	O/C		TSO 0				
SN:4056	HRS	3865.7			TSO 0				
WC#: 34.050	AFL	7769			TSO 0				
PROC. REF: GENERIC NO REF									
340019A	AFT RADAR ANTENNA							Component	ATA:34
PN:071-1316-00	MOS/MSC	14-Sep-98	O/C						
SN:UNKNOWN	HRS	1416			TSO 1405				
WC#: 34.050	AFL								
PROC. REF: GENERIC NO REF									
340021	LEFT AIRSPEED INDICATOR							Component	ATA:34
PN:C661065-0237	MOS/MSC	16-Nov-95	O/C						
SN:T35097	HRS	0			TSN 0				
WC#: 34.060	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
340021	RIGHT AIRSPEED INDICATOR							Component	ATA:34
PN:C661064-0237	MOS/MSC	04-Nov-11	O/C		TSN 0				
SN:T26032	HRS	3702.7			TSN 0				
WC#: 34.060	AFL	7498							
PROC. REF: GENERIC NO REF									
340022	RIGHT ATTITUDE GYRO							Component	ATA:34
PN:C661051-0201	MOS/MSC	16-Nov-95	O/C						
SN:25025	HRS	0			TSN 0				
WC#: 34.065	AFL	0			TSN 0				
PROC. REF: AMM 34-23-00									
340023 <sup>U</sup>	NO. 1 DIRECTION GYRO							Component	ATA:34
PN:C661053-0101	MOS/MSC	16-Nov-95	O/C						
SN:T42367E	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 34-23-00									
340023	RIGHT DIR GYRO INDICATOR							Component	ATA:34
PN:1U262-001-7	MOS/MSC	04-May-98	O/C						
SN:T42367E	HRS	1203			TSN 0				
WC#: 34.065	AFL								
PROC. REF: AMM 34-23-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340025	NO. 1 ADF RECEIVER							Component	ATA:34
PN:066-1072-00	MOS/MSC	16-Nov-95	O/C						
SN:63743	HRS	0		TSN 0					
WC#: 34.070	AFL	0		TSN 0					
PROC. REF: AMM 34-59-05									
340026	LEFT ADF ANTENNA							Component	ATA:34
PN:071-1234-00	MOS/MSC	28-Mar-02	O/C						
SN:67665	HRS	1829		TSN 0					
WC#: 34.075	AFL								
PROC. REF: AMM 34-59-10									
340027	RMI INDICATOR							Component	ATA:34
PN:066-3038-00	MOS/MSC	16-Nov-95	O/C						
SN:7775	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340028	DME RECEIVER							Component	ATA:34
PN:066-1070-01	MOS/MSC	16-Nov-95	O/C						
SN:12376	HRS	0		TSN 0					
WC#: 34.080	AFL	0		TSN 0					
PROC. REF: AMM 34-58-05									
340029	DME INDICATOR							Component	ATA:34
PN:066-1069-00	MOS/MSC	16-Nov-95	O/C						
SN:14753	HRS	0		TSN 0					
WC#: 34.080	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340030	BOTTOM NAV COMPUTER							Component	ATA:34
PN:069-01033-0201	MOS/MSC	11-Oct-17	O/C		TSN 4				
SN:14189	HRS	4851.6			TSN 0				
WC#: 34.280	AFL	9570							
PROC. REF: GENERIC NO REF									
340030	TOP NAV COMPUTER							Component	ATA:34
PN:06901033-0201	MOS/MSC	11-Oct-17	O/C		TSN 4				
SN:14205	HRS	4851.6			TSN 0				
WC#: 34.280	AFL	9570							
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
<b>340032</b>	<b>NAV INDICATOR</b>							<b>Component</b>	<b>ATA:34</b>
PN:066-3034-04	MOS/MSC	16-Nov-95	O/C						
SN:65696	HRS	0		TSN 0					
WC#: 34.085	AFL	0		TSN 0					
PROC. REF: AMM 34-51-00									
<b>340033</b>	<b>RADAR ALT INDICATOR</b>							<b>Component</b>	<b>ATA:34</b>
PN:066-3054-01	MOS/MSC	16-Nov-95	O/C						
SN:9240	HRS	0		TSN 0					
WC#: 34.285	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
<b>340035</b>	<b>NO. 1 TRANSPONDER</b>							<b>Component</b>	<b>ATA:34</b>
PN:PN-UNKNOWN	MOS/MSC	15-Jul-22	O/C						
SN:2867	HRS	5310							
WC#: 34.090	AFL								
PROC. REF: AMM 34-52-00									
<b>340040</b>	<b>LEFT VERTICAL SPEED INDICATOR</b>							<b>Component</b>	<b>ATA:34</b>
PN:C661035-0101	MOS/MSC	16-Nov-95	O/C						
SN:8F250	HRS	0		TSN 0					
WC#: 34.105	AFL	0		TSN 0					
PROC. REF: AMM 34-13-00									
<b>340040</b>	<b>RIGHT VERTICAL SPEED INDICATOR</b>							<b>Component</b>	<b>ATA:34</b>
PN:C661035-0101	MOS/MSC	16-Nov-95	O/C						
SN:8F489	HRS	0		TSN 0					
WC#: 34.105	AFL	0		TSN 0					
PROC. REF: AMM 34-13-00									
<b>340047</b>	<b>NO. 1 TRANSPONDER ANTENNA</b>							<b>Component</b>	<b>ATA:34</b>
PN:C1105	MOS/MSC	16-Mar-23	O/C		TSN 0				
SN:105837	HRS	5440.6			TSN 0				
WC#: 34.120	AFL	10430			TSN 0				
PROC. REF: AMM 34-52-10									
<b>340048A</b>	<b>NO. 1 DME ANTENNA</b>							<b>Component</b>	<b>ATA:34</b>
PN:C1105-16	MOS/MSC	05-Mar-14	O/C		TSN 0				
SN:29933	HRS	4069			TSN 0				
WC#: 34.125	AFL	8112							
PROC. REF: AMM 34-58-10									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340053	RADAR INDICATOR							Component	ATA:34
PN:066-3114-01	MOS/MSC	14-Sep-98	O/C						
SN:13670	HRS	1416		TSO 1405					
WC#: 34.145	AFL								
PROC. REF: GENERIC NO REF									
340055 <sup>U</sup>	GRAPHICS INTERFACE							Component	ATA:34
PN:050-2354-00	MOS/MSC	26-Nov-96	O/C						
SN:UNKNOWN	HRS	323		TSN 0					
	AFL								
340056	RADAR ALTIMETER ANTENNA							Component	ATA:34
PN:071-1114-01	MOS/MSC	04-Oct-19	O/C		TSO 6				
SN:13210	HRS	5082.6		TSO 0					
WC#: 34.155	AFL	9955							
PROC. REF: AMM 34-17-10									
340057 <sup>U</sup>	RNAV UNIT							Component	ATA:34
PN:066-04031-0122	MOS/MSC	03-Jan-11	O/C						
SN:M20814	HRS	3555							
	AFL	7228							
340058	BOTTOM COUPLER							Component	ATA:34
PN:C598506-0101	MOS/MSC	16-Nov-95	O/C						
SN:1570	HRS	0		TSN 0					
WC#: 34.160	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340058	TOP COUPLER							Component	ATA:34
PN:C598506-0101	MOS/MSC	16-Nov-95	O/C						
SN:1564	HRS	0		TSN 0					
WC#: 34.160	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340060	MARKER BEACON ANT							Component	ATA:34
PN:C1102	MOS/MSC	24-Oct-97	O/C						
SN:1365	HRS	834		TSN 0					
WC#: 34.165	AFL								
PROC. REF: AMM 34-35-05									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340061	MARKER BEACON							Component	ATA:34
PN:066-1021-01	MOS/MSC	16-Nov-95	O/C						
SN:10820	HRS	0		TSN 0					
WC#: 34.290	AFL	0		TSN 0					
PROC. REF: AMM 34-35-05									
340071	LEFT NAV BAL LOOP ANT							Component	ATA:34
PN:C598505-0303	MOS/MSC	16-Nov-95	O/C						
SN:1898	HRS	0		TSN 0					
WC#: 34.170	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340071	RIGHT NAV BAL LOOP ANT							Component	ATA:34
PN:C598505-0303	MOS/MSC	16-Nov-95	O/C						
SN:1895	HRS	0		TSN 0					
WC#: 34.170	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340079 <sup>U</sup>	DATA BASE CARTRIDGE							Component	ATA:34
PN:071-01523-0302	MOS/MSC	16-Feb-96	O/C						
SN:UNKNOWN	HRS	36		TSN 0					
	AFL								
340080	FLT COMMAND INDICATOR							Component	ATA:34
PN:060-0020-01	MOS/MSC	16-Nov-95	O/C						
SN:12982	HRS	0		TSN 0					
WC#: 34.175	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340083	LEFT GPS ANTENNA							Component	ATA:34
PN:071-01553-0200	MOS/MSC	20-Jan-12	O/C		TSN 0				
SN:22824	HRS	3703.2		TSN 0					
WC#: 34.180	AFL	7499							
PROC. REF: AMM 34-57-05									
340085	PHASING COUPLER							Component	ATA:34
PN:C598505-0304	MOS/MSC	16-Nov-95	O/C						
SN:993	HRS	0		TSN 0					
WC#: 34.185	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
340098 <sup>U</sup>	GRAY CODE CONVERTER							Component	ATA:34
PN:9000T	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
340106 <sup>U</sup>	GPS-NAVIGATOR							Component	ATA:34
PN:80821-00-0212	MOS/MSC	16-Nov-95	O/C						
SN:5263303	HRS	0		TSN 0					
	AFL	0		TSN 0					
340110	A/S WARNING PRESSURE SWITCH							Component	ATA:34
PN:251500-0141	MOS/MSC	30-Apr-98	O/C						
SN:269961	HRS			TSO 0					
WC#: 34.210	AFL								
PROC. REF: GENERIC NO REF									
340424	VACCUUM REGULATOR							Component	ATA:34
PN:C482001-0402	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.235	AFL	0		TSN 0					
PROC. REF: GENERIC NO REF									
340501	COMPASS ASSEMBLY							Component	ATA:34
PN:C660501-0102	MOS/MSC	17-Mar-08	O/C						
SN:CE-07684	HRS	2990		TSN 0					
WC#: 34.240	AFL								
PROC. REF: AMM 34-21-00									
340607	OAT GAGE							Component	ATA:34
PN:C668507-0105	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 34.255	AFL	0		TSN 0					
PROC. REF: AMM 34-12-00									
B341101 <sup>S</sup>	OPERATIONAL CHECK PITOT TUBE HEATERS							Service	ATA:34
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 34-11-00									

PKG:132

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 34 - NAVIGATION</b>									
B341103	CALIBRATION TEST NO. 1 ENCODING ALTIMETER (FAR 91.411)							Service	ATA:34
PN:5035P-P45P45	MOS	16-Mar-23	24		01-Nov-24 (M)		197 d		
SN:05B574	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 34-11-00									
B341103	FUNCTION CHECK LEFT HAND PITOT/STATIC SYSTEM (91.411)							Service	ATA:34
	MOS	16-Mar-23	24		01-Nov-24 (M)		197 d		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 34-11-00									
B341103	FUNCTION CHECK RIGHT HAND PITOT/STATIC SYSTEM (91.411)							Service	ATA:34
	MOS	16-Mar-23	24		31-Mar-25		347 d		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 34-11-00									
B341104 <sup>S</sup>	FUNCTIONAL TEST LOW AIRSPEED AWARENESS SYSTEM (AIRPLANES WITH TKS ANTI-ICE)							Service	ATA:34
	MOS	06-May-21	24 (+30d)						
	HRS	5164.4							
	AFL	10079							
PROC. REF: AMM 34-11-01									
B341105 <sup>S</sup>	FUNCTIONAL TEST DE-ICING LOW AIRSPEED AWARENESS SYSTEM (AIRPLANES WITH PNEUMATIC DE-ICING)							Service	ATA:34
	MOS	06-May-21	24 (+30d)						
	HRS	5164.4							
	AFL	10079							
PROC. REF: AMM 34-11-02									
B345001	CALIBRATION TEST NO. 1 TRANSPONDER (FAR 91.413)							Service	ATA:34
PN:PN-UNKNOWN	MOS	16-Mar-23	24		01-Nov-24 (M)		197 d		
SN:2867	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 34-50-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 35 - OXYGEN</b>									
B350101 <sup>S</sup>	OPERATIONAL CHECK OXYGEN SYSTEM							Service	ATA:35
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6							
	AFL	10213							
PROC. REF: AMM 35-01-00								PKG:128	
<b>ATA 37 - VACUUM</b>									
370102	VACUUM SYSTEM CENTRAL AIR FILTER DISCARD							Component	ATA:37
PN:AAD9-18-1	MOS	16-Mar-23	12	TSN 0	31-Mar-24		OVD		
SN:UNKNOWN	HRS	5440.6		TSN 0					
	AFL	10430		TSN 0					
PROC. REF: AMM 37-10-00									
370103	VACUUM RELIEF VALVE FILTER DISCARD							Component	ATA:37
PN:ARB3-5-1	MOS	16-Mar-23	12	TSN 0	31-Mar-24		OVD		
SN:UNKNOWN	HRS	5440.6		TSN 0					
	AFL	10430		TSN 0					
PROC. REF: AMM 37-10-00									
370110	AIR EJECTOR							Component	ATA:37
PN:19E32-2A	MOS/MSC	16-Nov-95	O/C						
SN:RF770	HRS	0		TSN 0					
WC#: 37.005	AFL	0		TSN 0					
PROC. REF: AMM 37-10-00									
<b>ATA 52 - DOORS</b>									
A520001 <sup>S</sup>	DETAILED INSPECTION CREW DOORS							Service	ATA:52
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
PROC. REF: AMM 52-00-00								PKG:136	
A520003 <sup>S</sup>	DETAILED INSPECTION PASSENGER/CARGO DOORS AND DOOR FRAMES							Service	ATA:52
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
PROC. REF: AMM 52-00-00								PKG:136	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
A531001	ZONAL INSPECTION EXTERNAL FUSELAGE							Service	ATA:53
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 53-10-00								
A531003	ZONAL INSPECTION INTERNAL COCKPIT							Service	ATA:53
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 53-10-00								
A531004	ZONAL INSPECTION INTERNAL CABIN							Service	ATA:53
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 53-10-00								
A531006	SPECIAL DETAILED INSPECTION FUSELAGE TO STRUT ATTACH FITTING LUGS (NOMINAL STANDARD BOLT SIZE) (SEVERE INSPECTION COMPLIANCE) (SID 53-20-07)							Service	ATA:53
	MOS	27-Feb-17							
	HRS	4756.9	1200		5956.9		349.1		
	AFL	9350							
	PROC. REF: AMM 53-20-07								
	PKG:52								
A531007	ZONAL INSPECTION INTERNAL TAIL CONE							Service	ATA:53
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 53-10-00								
A531008 <sup>S</sup>	SPECIAL DETAILED INSPECTION FUSELAGE ENGINE MOUNT FITTINGS (SID 53-10-01)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00								
	PKG:34								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 53 - FUSELAGE</b>									
A531009 <sup>S</sup>	DETAILED INSPECTION SEAT RAILS AND ATTACHMENT STRUCTURE (SID 53-10-07)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:7500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-25-00							PKG:36	
A531013	ZONAL INSPECTION EMPENNAGE AND HORIZONTAL STABILIZER							Service	ATA:53
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 53-10-00								
A531014	HORIZONTAL AND VERTICAL STABILIZER ATTACH BOLTS DETAILED INSPECTION AND LUBRICATION TASK 53-10-00-226							Service	ATA:53
	MOS	16-Mar-23	72 (+1m/-1m)		16-Mar-29	16-Apr-29	1793 d (+31)		
	HRS	5440.6							
	AFL	10430							
	PROC. REF: AMM 53-10-00								
A532003 <sup>S</sup>	SPECIAL DETAILED INSPECTION CARGO AND PASSENGER DOOR DOUBLERS (SID 53-20-01)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:7500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:36	
A532004 <sup>S</sup>	SPECIAL DETAILED INSPECTION LOWER FORWARD CARRY-THRU BULKHEAD (SID 53-20-03)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:12500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:37	
A532006 <sup>S</sup>	SPECIAL DETAILED INSPECTION MAIN LANDING GEAR ATTACH FITTINGS AND AFT CARRY-THRU BULKHEAD (SID 53-20-05)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:12500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:37	
A532007 <sup>S</sup>	SPECIAL DETAILED INSPECTION FUSELAGE TO WING ATTACH FITTING LUGS (SID 53-20-02)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 53 - FUSELAGE</b>									
A532008 <sup>S</sup>	DETAILED INSPECTION FIREWALL BRACE AND DOUBLER ASSEMBLIES (SID 53-20-11)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	
A532009 <sup>S</sup>	DETAILED INSPECTION CARRY-THROUGH ROOT RIB (SID 53-20-08)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	
A532011 <sup>S</sup>	DETAILED INSPECTION CREW DOOR FRAMES (SID 53-20-09)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	
A532012 <sup>S</sup>	DETAILED INSPECTION PASSENGER AND CARGO DOOR FRAMES (SID 53-20-10)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	
A532013 <sup>S</sup>	DETAILED INSPECTION BULKHEADS AND STIFFENERS BELOW THE SEAT RAIL ATTACHMENTS AT FS 143.00 AND FS 158.00 (SID 53-20-12)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:7500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-25-00							PKG:36	
A532014 <sup>S</sup>	DETAILED INSPECTION STRINGERS AT INTERSECTIONS WITH FORWARD AND AFT CARRY - THRU BULKHEADS (SID 53-20-13)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:12500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:37	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 53 - FUSELAGE									
A532015 <sup>S</sup>	DETAILED INSPECTION FUSELAGE SKIN DOUBLER AT MAIN LANDING GEAR CUTOUT (SID 53-20-14)							Service	ATA:53
	MOS	27-Feb-17							
	HRS	4756.9	2500 (+25/-25)						
	AFL	9350							
	PROC. REF: AMM 53-10-00							PKG:35	
A532016 <sup>S</sup>	SPECIAL DETAILED INSPECTION FUSELAGE TO WING CARRY-THRU ATTACH FITTING AND BULKHEAD (SID 53-20-06)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:12500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:37	
A535001 <sup>S</sup>	SPECIAL DETAILED INSPECTION FUSELAGE TO HORIZONTAL STABILIZER ATTACH FITTINGS (SID 53-50-01)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	
A535002 <sup>S</sup>	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER ATTACH POINTS (TYPICAL INSPECTION COMPLIANCE) (SID 53-50-02)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:34	
A535003 <sup>S</sup>	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER ATTACH POINTS (SEVERE INSPECTION COMPLIANCE) (SID 53-50-02)							Service	ATA:53
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:16500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 53-10-00							PKG:38	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 55 - STABILIZERS</b>									
A551003 <sup>S</sup>	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER FORWARD AND AFT ATTACH POINTS (SID 55-10-01)							Service	ATA:55
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 55-10-00								PKG:34
A551005 <sup>S</sup>	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER SPARS (SEVERE INSPECTION COMPLIANCE) (SID 55-10-02)							Service	ATA:55
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:17500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 55-10-00								PKG:39
A553001 <sup>S</sup>	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER SPARS (TYPICAL INSPECTION COMPLIANCE) (SID 55-30-01)							Service	ATA:55
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 55-30-00								PKG:34
A553002 <sup>S</sup>	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER SPARS (SEVERE INSPECTION COMPLIANCE) (SID 55-30-01)							Service	ATA:55
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:16500 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 55-30-00								PKG:38
A553004 <sup>S</sup>	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER SPARS (TYPICAL INSPECTION COMPLIANCE) (SID 55-10-02)							Service	ATA:55
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 55-10-00								PKG:34

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 56 - WINDOWS</b>									
560203	LEFT WINDSHIELD ASSY, (LH)							Component	ATA:56
PN:2613088-1	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 56.005	AFL	0		TSN 0					
PROC. REF: AMM 56-10-00									
560203	RIGHT WINDSHIELD ASSY, (RH)							Component	ATA:56
PN:2613088-2	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 56.005	AFL	0		TSN 0					
PROC. REF: AMM 56-10-00									
A564002	DETAILED INSPECTION WINDSHIELD AND ATTACHMENT STRUCTURE (SID 56-30-01)							Service	ATA:56
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 56-00-01									
<b>ATA 57 - WINGS</b>									
570000 <sup>S</sup>	LEFT WING STRUT							Component	ATA:57
PN:PN	MOS/MSC	16-Nov-95	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
570000	RIGHT WING STRUT							Component	ATA:57
PN:PN	MOS/MSC	16-Nov-95	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: GENERIC NO REF									
A570008	SPECIAL DETAILED INSPECTION LEFT WING STRUT FITTINGS (TYPICAL INSPECTION COMPLIANCE) (SID 57-60-01)							Service	ATA:57
	MOS	16-Nov-95			TAC 0				
	HRS	0	T:10000		10000		4392.2		
	AFL	0			TAC 0				
PROC. REF: AMM 57-10-01									
								PKG:127	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
A570008	SPECIAL DETAILED INSPECTION RIGHT WING STRUT FITTINGS (TYPICAL INSPECTION COMPLIANCE) (SID 57-60-01)							Service	ATA:57
PN:PN	MOS	16-Nov-95		TAC 0					
SN:UNKNOWN	HRS	0	T:10000		10000		4392.2		
	AFL	0		TAC 0					
PROC. REF: AMM 57-10-01								PKG:127	
A570009	SPECIAL DETAILED INSPECTION LEFT WING STRUT FITTINGS (SEVERE INSPECTION COMPLIANCE) (SID 57-60-01)							Service	ATA:57
	MOS	27-Feb-17							
	HRS	4756.9	3600		8356.9	8356.9	2749.1		
	AFL	9350							
PROC. REF: AMM 57-10-01								PKG:50	
A570009 <sup>S</sup>	SPECIAL DETAILED INSPECTION RIGHT WING STRUT FITTINGS (SEVERE INSPECTION COMPLIANCE) (SID 57-60-01)							Service	ATA:57
PN:PN	MOS	27-Feb-17		TAC 0					
SN:UNKNOWN	HRS	4756.9	3600	TAC 0					
	AFL	9350		TAC 0					
PROC. REF: AMM 57-10-01								PKG:50	
A570010	SPECIAL DETAILED INSPECTION FRONT SPAR LOWER CAP INBOARD WS 141.20 (SID 57-20-02)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000		20000		14392.2		
	AFL	0		TAC 0					
PROC. REF: AMM 57-10-00								PKG:51	
A570011	SPECIAL DETAILED INSPECTION REAR SPAR LOWER CAP INBOARD WS 141.20 (SID 57-20-03)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000		20000		14392.2		
	AFL	0		TAC 0					
PROC. REF: AMM 57-10-00								PKG:51	
A570012 <sup>S</sup>	SPECIAL DETAILED INSPECTION RIGHT RIGHT WING STRUT ATTACHMENT TO FRONT SPAR (NOMINAL/STANDARD BOLT SIZE) (TYPICAL INSPECTION COMPLIANCE) (SID 57-60-02)							Service	ATA:57
PN:PN	MOS	16-Nov-95		TAC 0					
SN:UNKNOWN	HRS	0	T:20000	TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 57-10-01								PKG:51	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 57 - WINGS									
A570013	SPECIAL DETAILED INSPECTION WING TO CARRY - THRU FRONT SPAR ATTACHMENT FITTINGS (SID 57-20-01)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000		20000		14392.2		
	AFL	0		TAC 0					
	PROC. REF: AMM 57-10-00								PKG:51
A570014	SPECIAL DETAILED INSPECTION WING TO CARRY - THRU REAR SPAR ATTACHMENT FITTINGS (SID 57-20-01)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000		20000		14392.2		
	AFL	0		TAC 0					
	PROC. REF: AMM 57-10-00								PKG:51
A570015 <sup>S</sup>	SPECIAL DETAILED INSPECTION RIGHT WING STRUT ATTACHMENT TO FRONT SPAR (NOMINAL/STANDARD BOLT SIZE) (SEVERE INSPECTION COMPLIANCE) (SID 57-60-02)							Service	ATA:57
PN:PN	MOS	16-Nov-95		TAC 0					
SN:UNKNOWN	HRS	0	T:20000	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 57-10-01								PKG:51
A570015	SPECIAL DETAILED INSPECTION WING STRUT LEFT WING STRUT ATTACHMENT TO FRONT SPAR (NOMINAL/STANDARD BOLT SIZE) (SEVERE INSPECTION COMPLIANCE) (SID 57-60-02)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000		20000		14392.2		
	AFL	0		TAC 0					
	PROC. REF: AMM 57-10-01								PKG:51
A570016 <sup>S</sup>	SPECIAL DETAILED INSPECTION RIGHT WING STRUT ATTACHMENT TO FRONT SPAR (1/64 INCH OVERSIZE BOLT SIZE) (SEVERE INSPECTION COMPLIANCE) (SID 57-60-02)							Service	ATA:57
PN:PN	MOS	16-Nov-95		TAC 0					
SN:UNKNOWN	HRS	0	T:20000	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 57-10-01								PKG:56
A570017 <sup>S</sup>	SPECIAL DETAILED INSPECTION RIGHT WING STRUT ATTACHMENT TO FRONT SPAR (1/32 INCH OVERSIZE BOLT SIZE) (SEVERE INSPECTION COMPLIANCE) (SID 57-60-02)							Service	ATA:57
PN:PN	MOS	16-Nov-95		TAC 0					
SN:UNKNOWN	HRS	0	T:20000	TAC 0					
	AFL	0		TAC 0					
	PROC. REF: AMM 57-10-01								PKG:57

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 57 - WINGS</b>									
A571001	ZONAL INSPECTION WING TASK							Service	ATA:57
	MOS	23-May-23	48 (+1m/-1m)		31-May-27	30-Jun-27	1138 d (+30)		
	HRS	5440.8							
	AFL	10431							
PROC. REF: AMM 57-10-00									
A575002	SPECIAL DETAILED INSPECTION CENTER FLAP TRACK AND INBOARD FLAP TRACK (SID 57-50-01)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0		TAC 0					
	AFL	0	T:15000		15000		4372		
PROC. REF: AMM 57-10-00									
A575003	SPECIAL DETAILED INSPECTION OUTBOARD FLAP TRACK (SID 57-50-01)							Service	ATA:57
	MOS	16-Nov-95		TAC 0					
	HRS	0		TAC 0					
	AFL	0	T:15000		15000		4372		
PROC. REF: AMM 57-10-00									
<b>ATA 61 - PROPELLERS/PROPULSORS</b>									
610000	NO. 1 PROPELLER - OVERHAUL							Service	ATA:61
	MOS	29-Jun-23	60		30-Jun-28		1534 d	OVERHAUL	
	HRS	1749.1	3000		(4749.1) 8501.7		2893.9		
PROC. REF: POM 61-00-39									
610002	PROPELLER GOVERNOR							Component	ATA:61
PN:8210-002-01	MOS	31-Dec-19		TSO 0				OVERHAUL	
SN:14006725	HRS	4924.6	4500	TSO 339.5	9085.1		3477.3		
WC#: 61.010	AFL			TSO 0					
PROC. REF: AMM 61-20-00									
610005	PROPELLER OVERSPEED GOVERNOR							Component	ATA:61
PN:A210507	MOS	08-Aug-19						OVERHAUL	
SN:13175265	HRS	5042.7	6500	TSO 0	11542.7		5934.9		
WC#: 61.020	AFL	9885							
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 61 - PROPELLERS/PROPULSORS</b>									
611010	NO. 1 PROPELLER - PERIODIC INSPECTION							Service	ATA:61
	MOS	29-Jun-23	12		30-Jun-24		73 d		
	HRS	1749.1	400		(2149.1) 5901.7		293.9		
PROC. REF: GENERIC CUSTOM, POM 61-00-39									
611020	NO. 1 PROPELLER - LUBRICATE							Service	ATA:61
	MOS	29-Jun-23	12		30-Jun-24		73 d		
	HRS	1749.1	400		(2149.1) 5901.7		293.9		
PROC. REF: POM 61-00-39									
611025	NO. 1 PROPELLER - APPLY CORROSION INHIBITOR TO STEEL COUNTERWEIGHTS							Service	ATA:61
	MOS/MSC	29-Jun-23	A/R					CPCP	
	HRS								
PROC. REF: POM 61-00-39									
611101	NO. 1 PROPELLER - NO. 1 PROPELLER BLADE							Component	ATA:61
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
611102	NO. 1 PROPELLER - NO. 2 PROPELLER BLADE							Component	ATA:61
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
611103	NO. 1 PROPELLER - NO. 3 PROPELLER BLADE							Component	ATA:61
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
611220	NO. 1 PROPELLER - PROPELLER SLIP RING							Component	ATA:61
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
PROC. REF: GENERIC CUSTOM									
611230 <sup>S</sup>	NO. 1 PROPELLER - DEICE SYSTEM 200 HOUR INSPECTION							Service	ATA:61
	MOS/MSC	29-Jun-23	N/A						
	HRS	1749.1							
PROC. REF: MM 30-61-80									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 61 - PROPELLERS/PROPULSORS									
611240 <sup>S</sup>	NO. 1 PROPELLER - ANITICE SYSTEM 200 HOUR INSPECTION							Service	ATA:61
	MOS/MSC	29-Jun-23	N/A						
	HRS	1749.1							
				PROC. REF: MM 30-61-80					
611280	NO. 1 PROPELLER - FEEDBACK COLLAR							Component	ATA:61
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
				PROC. REF: GENERIC CUSTOM					
611290	NO. 1 PROPELLER - FEEDBACK BEARING							Component	ATA:61
PN:PN	MOS/MSC		O/C						
SN:UNKNOWN	HRS								
				PROC. REF: GENERIC CUSTOM					
614010	NO. 1 PROPELLER - INSPECT TACHOMETER							Service	ATA:61
	MOS/MSC		A/R						
	HRS								
				PROC. REF: GENERIC CUSTOM					
616010	NO. 1 PROPELLER - DAMPER ASSEMBLY							Component	ATA:61
PN:PN	MOS	29-Jun-23	72	TSN 0	30-Jun-29		1899 d	OVERHAUL	
SN:UNKNOWN	HRS	1749.1	2400	TSN 0	(4149.1) 7901.7		2293.9		
				PROC. REF: GENERIC CUSTOM					
619000	NO. 1 PROPELLER - PRE-FLIGHT CHECKS							Service	ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK	
	HRS								
				PROC. REF: POM 61-00-39					
619010	NO. 1 PROPELLER - OPERATIONAL CHECKS							Service	ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK	
	HRS								
				PROC. REF: POM 61-00-39					

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 61 - PROPELLERS/PROPULSORS								
619020	NO. 1 PROPELLER - OVERSPEED/OVERTORQUE							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: POM 61-00-39			
619030	NO. 1 PROPELLER - LIGHTNING STRIKE							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: MM 30-61-80, POM 61-00-39			
619040	NO. 1 PROPELLER - FOREIGN OBJECT STRIKE/GROUND STRIKE							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: MM 30-61-80, POM 61-00-39			
619050	NO. 1 PROPELLER - FIRE/HEAT DAMAGE							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: MM 30-61-80, POM 61-00-39			
619060	NO. 1 PROPELLER - SUDDEN STOPPAGE							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: POM 61-00-39			
619070	NO. 1 PROPELLER - ENGINE OIL CONTAMINATION							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: POM 61-00-39			
619080	NO. 1 PROPELLER - LONG TERM STORAGE							Service ATA:61
	MOS/MSC		A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS							
					PROC. REF: POM 61-00-39			

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 61 - PROPELLERS/PROPULSORS</b>									
61PR1	NO. 1 PROPELLER							Component	ATA:61
PN:HC-B3TN-3AF	MOS/MSC	29-Jun-23	PP/C						
SN:BUA33874	HRS	5501.4		TSN 1749.1					
WC#: 61.PR1	AFL								
PROC. REF: AMM 61-10-00, AMM 61-11-00									
B611002	FUNCTION CHECK HARTZELL ALUMINUM PROPELLER							Service	ATA:61
	MOS	29-Jun-23	12 (+1m/-1m)		30-Jun-24	31-Jul-24	73 d (+31)		
	HRS								
	AFL								
PROC. REF: AMM 61-10-00									
<b>ATA 71 - POWER PLANT</b>									
710002	ENGINE MOUNT ASSEMBLY							Component	ATA:71
PN:2651023-19	MOS/MSC	16-Nov-95	O/C						
SN:743	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 71-00-01, AMM 71-00-05, AMM 71-20-00									
710010	NO. 1 ENGINE - OVERHAUL ENGINE							Service	ATA:71
	MOS	15-May-11						OVERHAUL	
	HRS	3445.1	3600		(7045.1) 8703		1615.7		
	ENC	7009							
PROC. REF: GENERIC NO REF									
710015 <sup>S</sup>	NO. 1 ENGINE - INSPECT ACCESSORIES ATTACHMENTS AND LINKAGES, AIR, OIL, AND FUEL LINES							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-07									
710020	NO. 1 ENGINE - INSPECT HOT SECTION							Service	ATA:71
	MOS	16-Mar-23							
	HRS	5263	1800 (+50)		(7063) 7241.4	7113	1633.6 (+50)		
	ENC	10089							
PROC. REF: EMM 72-00-00, EMM 72-00-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 71 - POWER PLANT</b>									
710030	NO. 1 ENGINE - BORESCOPE INSPECT HOT SECTION							Service	ATA:71
	MOS	16-Mar-23							
	HRS	5263	400 (+10%)		(5663) 5841.4	5703	233.6 (+40)		
	ENC	10089							
PROC. REF: EMM 72-00-00, EMM 72-00-00									
710030 <sup>U</sup>	NO. 1 ENGINE - S EXCITER-IGNITION							Component	ATA:71
PN:10-381550-4	MOS/MSC	18-Mar-96	O/C						
SN:96018073	HRS	0		TSN 0					
	ENC								
710033	NO. 1 ENGINE - T5 TRIM STICK							Component	ATA:71
PN:3031417CL45	MOS/MSC	31-Dec-19	O/C	TSN 0					
SN:UNKNOWN	HRS	4925.4		TSN 0					
	ENC	9665		TSN 0					
PROC. REF: GENERIC NO REF									
710035 <sup>S</sup>	NO. 1 ENGINE - VISUAL INSPECT FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROROR A BORESCOPE							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200 (+20/-20)						
	ENC	10278							
PROC. REF: EMM 72-00-00									
710050	NO. 1 ENGINE - PERFORM DESALINATION WASH							Service	ATA:71
	MOS/MSC	19-Oct-23	A/R						
	HRS	5422.1							
	ENC	10278							
PROC. REF: EMM 71-00-00									
710055	NO. 1 ENGINE - PERFORM PERFORMANCE RECOVERY WASH							Service	ATA:71
	MOS/MSC		A/R	TAC 0					
	HRS			TAC 0					
	ENC			TAC 0					
PROC. REF: EMM 71-00-00									

PKG:1

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 71 - POWER PLANT</b>									
710080 <sup>S</sup>	NO. 1 ENGINE - INSPECT STARTER-GENERATOR GEARSHAFT SPLINESFOR WEAR (AT STARTER-GENERATORREMOVAL/REPLACEMENT ONLY)							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
					PROC. REF: EMM 72-60-00			PKG:1	
710512	NO. 1 ENGINE - ENGINE COLLAR							Component	ATA:71
PN:2651022-15	MOS/MSC	16-Nov-95	O/C						
SN:835	HRS	0		TSN 3					
	ENC								
					PROC. REF: GENERIC NO REF				
712031	LEFT ENGINE MOUNT							Component	ATA:71
PN:LM600-9	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
WC#: 71.005	AFL	0							
					PROC. REF: AMM 71-00-01, AMM 71-00-05, AMM 71-20-00				
712031	RIGHT ENGINE MOUNT							Component	ATA:71
PN:LM600-9	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0							
					PROC. REF: AMM 71-00-01, AMM 71-00-05, AMM 71-20-00				
713015 <sup>S</sup>	NO. 1 ENGINE - INSPECT FIRE SEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
					PROC. REF: EMM 72-30-01			PKG:1	
714010 <sup>S</sup>	NO. 1 ENGINE - INSPECT ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
					PROC. REF: EMM 70-00-00			PKG:1	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 71 - POWER PLANT</b>									
714020 <sup>S</sup>	NO. 1 ENGINE - INSPECT TUBING, WIRING, CONTROL LINKAGES, AND HOSE ASSEMBLIES FOR WEAR CHAFING CRACKS AND CORROSION							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 70-00-00								PKG:1	
716015 <sup>S</sup>	NO. 1 ENGINE - INSPECT AIR INLET SCREEN FOR CLEANLINESS							Service	ATA:71
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 72-20-00								PKG:1	
71EN1	NO. 1 ENGINE							Component	ATA:71
PN:3044000	MOS/MSC	29-May-20	E/C						
SN:PCE-17493	HRS	5103		TSN 4924.6, TSO 1479.5					
WC#: 71.EN1	AFL	9978		TSN 9660, TSO 2651					
PROC. REF: AMM 71-00-01, AMM 71-00-05									
A710001	ZONAL INSPECTION ENGINE COMPARTMENT							Service	ATA:71
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 71-00-01									
A712001	DETAILED INSPECTION ENGINE MOUNTS AND FIREWALL TASK							Service	ATA:71
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 71-20-00									
A712003 <sup>S</sup>	SPECIAL DETAILED INSPECTION ENGINE TRUSS AND RING ASSEMBLY (SID 71-20-01)							Service	ATA:71
	MOS	16-Nov-95		TAC 0					
	HRS	0	T:20000 (+25/-25)	TAC 0					
	AFL	0		TAC 0					
PROC. REF: AMM 71-20-00								PKG:281	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 71 - POWER PLANT</b>									
A714101 <sup>S</sup>	DETAILED INSPECTION ENGINE WASH RING, AIR PLENUM, AND THERMOCOUPLE (T1)							Service	ATA:71
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6							
	AFL	10213							
				PROC. REF: AMM 71-41-00				PKG:128	
A716001 <sup>S</sup>	DETAILED INSPECTION INERTIAL AIR SEPARATOR							Service	ATA:71
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	400 (+25/-25)						
	AFL	10213							
				PROC. REF: AMM 71-60-00				PKG:133	
<b>ATA 72 - ENGINE</b>									
720010	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE							Service	ATA:72
	MOS/MSC	19-Oct-23	A/R						
	HRS	5422.1							
	ENC	10278							
				PROC. REF: EMM 72-00-00					
723010	NO. 1 ENGINE - COMPRESSOR 1ST STAGE HUB							Component	ATA:72
PN:3013111	MOS	12-May-11						LIFE LIMIT	
SN:8R613	HRS	3445.1		TSN 6581.6					
	ENC	7009		TSN 2787	(23222) 23563 (M)		12935		
	ACCCYC	0	19000	TSN 2787					
				PROC. REF: GENERIC NO REF					
723015 <sup>S</sup>	NO. 1 ENGINE - INSPECT GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION AND CORROSION							Service	ATA:72
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
				PROC. REF: EMM 72-30-04				PKG:1	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
723030	NO. 1 ENGINE - COMPRESSOR 2ND STAGE DISC							Component	ATA:72
PN:3013712	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:A001KP6F	HRS	3445.1		TSN 3599.7					
	ENC	7009		TSN 12645	(18364) 18705 (M)		8077		
	ACCCYC	0	24000	TSN 12645					
PROC. REF: GENERIC NO REF									
723040	NO. 1 ENGINE - COMPRESSOR 3RD STAGE DISC							Component	ATA:72
PN:3011713	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:98A377	HRS	3445.1		TSN 3445.1					
	ENC	7009		TSN 7009	(25000) 25341 (M)		14713		
	ACCCYC	0	25000	TSN 7009					
PROC. REF: GENERIC NO REF									
723060	NO. 1 ENGINE - IMPELLER							Component	ATA:72
PN:3027798	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:4F603	HRS	3445.1		TSN 3363.4					
	ENC	7009		TSN 6884	(19125) 19466 (M)		8838		
	ACCCYC	0	19000	TSN 6884					
PROC. REF: GENERIC NO REF									
725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISC							Component	ATA:72
PN:3102421-01	MOS	09-Mar-23						LIFE LIMIT	
SN:97A381	HRS	5263							
	ENC	10089		TSN 10089	(16000) 16341 (M)		5713		
	ACCCYC	0	16000	TSN 10089					
PROC. REF: GENERIC NO REF									
725015	NO. 1 ENGINE - INSPECT COMPRESSOR TURBINE DISC BLADES							Service	ATA:72
PN:3102421-01	MOS	09-Mar-23							
SN:97A381	HRS	5263	3000		(8263) 8441.4		2833.6		
	ENC	10089							
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725017	NO. 1 ENGINE - BORESCOPE INSPECTION OF COMPRESSOR TURBINE BLADE TRAILING EDGE							Service	ATA:72
	MOS/MSC	05-Apr-16	-						
	HRS	4456.38							
	ENC	8820							
PROC. REF: GENERIC NO REF									
725020-1	NO. 1 ENGINE - NO. 1 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y14	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-10	NO. 1 ENGINE - NO. 10 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H68	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-11	NO. 1 ENGINE - NO. 11 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y13	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-12	NO. 1 ENGINE - NO. 12 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W42	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-13	NO. 1 ENGINE - NO. 13 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H75	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-14	NO. 1 ENGINE - NO. 14 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9N80	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-15	NO. 1 ENGINE - NO. 15 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9B93	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-16	NO. 1 ENGINE - NO. 16 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8H95	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-17	NO. 1 ENGINE - NO. 17 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W57	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-18	NO. 1 ENGINE - NO. 18 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H56	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
<b>725020-19</b>		<b>NO. 1 ENGINE - NO. 19 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9D17	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-2</b>		<b>NO. 1 ENGINE - NO. 2 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8R35	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-20</b>		<b>NO. 1 ENGINE - NO. 20 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8K13	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-21</b>		<b>NO. 1 ENGINE - NO. 21 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9C16	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-22</b>		<b>NO. 1 ENGINE - NO. 22 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9C76	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-23	NO. 1 ENGINE - NO. 23 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9A91	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-24	NO. 1 ENGINE - NO. 24 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W29	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-25	NO. 1 ENGINE - NO. 25 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8R68	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-26	NO. 1 ENGINE - NO. 26 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H88	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-27	NO. 1 ENGINE - NO. 27 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H85	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-28	NO. 1 ENGINE - NO. 28 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H47	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-29	NO. 1 ENGINE - NO. 29 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9C66	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-3	NO. 1 ENGINE - NO. 3 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8H96	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-30	NO. 1 ENGINE - NO. 30 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9A38	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-31	NO. 1 ENGINE - NO. 31 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9E20	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-32	NO. 1 ENGINE - NO. 32 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9R59	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-33	NO. 1 ENGINE - NO. 33 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W78	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-34	NO. 1 ENGINE - NO. 34 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y62	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-35	NO. 1 ENGINE - NO. 35 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y60	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-36	NO. 1 ENGINE - NO. 36 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y81	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-37	NO. 1 ENGINE - NO. 37 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W35	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-38	NO. 1 ENGINE - NO. 38 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8K06	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-39	NO. 1 ENGINE - NO. 39 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9D73	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-4	NO. 1 ENGINE - NO. 4 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9E17	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-40	NO. 1 ENGINE - NO. 40 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y64	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-41	NO. 1 ENGINE - NO. 41 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W83	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-42	NO. 1 ENGINE - NO. 42 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y76	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-43	NO. 1 ENGINE - NO. 43 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9B58	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-44	NO. 1 ENGINE - NO. 44 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y11	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-45	NO. 1 ENGINE - NO. 45 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9D06	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-46	NO. 1 ENGINE - NO. 46 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9L99	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-47	NO. 1 ENGINE - NO. 47 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H25	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-48	NO. 1 ENGINE - NO. 48 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y84	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-49	NO. 1 ENGINE - NO. 49 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8K24	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-5	NO. 1 ENGINE - NO. 5 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9K28	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725020-50	NO. 1 ENGINE - NO. 50 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9H18	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-51	NO. 1 ENGINE - NO. 51 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9E14	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-52	NO. 1 ENGINE - NO. 52 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8Y25	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-53	NO. 1 ENGINE - NO. 53 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8R16	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
725020-54	NO. 1 ENGINE - NO. 54 COMPRESSOR TURBINE BLADE							Component	ATA:72
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9D11	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
<b>725020-55</b>		<b>NO. 1 ENGINE - NO. 55 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9N45	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-56</b>		<b>NO. 1 ENGINE - NO. 56 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW9D77	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-57</b>		<b>NO. 1 ENGINE - NO. 57 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8R47	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-58</b>		<b>NO. 1 ENGINE - NO. 58 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W28	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-6</b>		<b>NO. 1 ENGINE - NO. 6 COMPRESSOR TURBINE BLADE</b>					<b>Component</b>	<b>ATA:72</b>	
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8R81	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
<b>725020-7</b>		<b>NO. 1 ENGINE - NO. 7 COMPRESSOR TURBINE BLADE</b>						<b>Component</b>	<b>ATA:72</b>
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8W70	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-8</b>		<b>NO. 1 ENGINE - NO. 8 COMPRESSOR TURBINE BLADE</b>						<b>Component</b>	<b>ATA:72</b>
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8N95	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725020-9</b>		<b>NO. 1 ENGINE - NO. 9 COMPRESSOR TURBINE BLADE</b>						<b>Component</b>	<b>ATA:72</b>
PN:3072791-01	MOS	12-May-11		TSN 0				LIFE LIMIT	
SN:HW8M60	HRS	3445.1	10000	TSN 0	(13445.1) 13623.5		8015.7		
	ENC	7009		TSN 0					
PROC. REF: GENERIC NO REF									
<b>725030</b>		<b>NO. 1 ENGINE - POWER TURBINE DISC</b>						<b>Component</b>	<b>ATA:72</b>
PN:3026812	MOS	12-May-11						LIFE LIMIT	
SN:14B450	HRS	3445.1		TSN 3445.1					
	ENC	7009		TSN 7009	(20000) 20341 (M)		9713		
	ACCCYC	0	20000	TSN 7009					
PROC. REF: GENERIC NO REF									
<b>725040</b>		<b>NO. 1 ENGINE - INSPECT EXHAUST DUCT</b>						<b>Service</b>	<b>ATA:72</b>
	MOS/MSC	07-Jul-22	A/R						
	HRS	5133							
	ENC								
PROC. REF: EMM 72-50-05									
<b>725050</b>		<b>NO. 1 ENGINE - INSPECT EXHAUST DUCT WELDS</b>						<b>Service</b>	<b>ATA:72</b>
	MOS/MSC	16-Mar-23	O/C						
	HRS	5263							
	ENC	10089							
PROC. REF: EMM 72-50-05									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 72 - ENGINE</b>									
725075 <sup>S</sup>	NO. 1 ENGINE - T5 THERMOCOUPLE ASSEMBLY BUS BAR							Component	ATA:72
PN:3027629	MOS/MSC	31-Dec-19	O/C	TSN 0					
SN:UNKNOWN	HRS	4925.4		TSN 0					
	ENC	9665		TSN 0					
PROC. REF: EMM 77-20-01									
725085	NO. 1 ENGINE - COMPRESSOR TURBINE VANE RING							Component	ATA:72
PN:3126891CL03	MOS/MSC	16-Mar-23	O/C	TSO 0					
SN:HLAAC159	HRS	5263		TSO 0					
	ENC	10089		TSO 0					
PROC. REF: EMM 72-50-01									
725095	NO. 1 ENGINE - NO. 2 FLANGE 1.5748 X2.6772 X.5906 ROLLER BEARING							Component	ATA:72
PN:PN	MOS/MSC	24-May-96	O/C	TSN 0					
SN:UNKNOWN	HRS	0		TSN 0					
	ENC	0		TSN 0					
PROC. REF: GENERIC NO REF									
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
730001	NO. 1 ENGINE - FUEL FLOW INDICATOR							Component	ATA:73
PN:DSFF1785-1	MOS/MSC	16-Nov-95	O/C						
SN:9530108	HRS	0		TSN 3					
	ENC								
PROC. REF: GENERIC NO REF									
731010	NO. 1 ENGINE - FUEL PUMP							Component	ATA:73
PN:702801-5	MOS/MSC	29-May-20	O/C	TSO 5					
SN:002080	HRS	4924.6		TSO 0					
	ENC	9660		TSO 0					
PROC. REF: EMM 73-10-02									
731015 <sup>S</sup>	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-02									
								PKG:1	

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
731025	NO. 1 ENGINE - CLEAN/LEAK/FUNCTIONAL TEST FUEL MANIFOLD AND NOZZLES							Service	ATA:73
	MOS	09-Mar-23							
	HRS	5263	400 (+10%)		(5663) 5841.4	5703	233.6 (+40)		
	ENC	10089							
PROC. REF: EMM 73-10-05, EMM 73-10-05									
731030	NO. 1 ENGINE - REPLACE FUEL PUMP OUTLET FILTER							Service	ATA:73
PN:702801-5	MOS	16-Mar-23							
SN:002080	HRS	5263	600 (+10%)		(5863) 6040.6	5923	433.6 (+60)		
	ENC	10089							
PROC. REF: EMM 73-10-02									
731035 <sup>S</sup>	NO. 1 ENGINE - INSPECT FUEL FILTER FOR FOREIGN MATERIAL OR DISTORTION							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-02									
731040	NO. 1 ENGINE - CHECK/CLEAN/REPLACE FUEL PUMP INLET SCREEN							Service	ATA:73
PN:702801-5	MOS	16-Mar-23							
SN:002080	HRS	5263	600 (+10%)		(5863) 6040.6	5923	433.6 (+60)		
	ENC	10089							
PROC. REF: EMM 73-10-02									
731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION							Service	ATA:73
	MOS	13-May-22							
	HRS	5091	600 (+10%)		(5691) 5868.6	5751	261.6 (+60)		
	ENC	9900							
PROC. REF: EMM 73-10-02									
731055	NO. 1 ENGINE - REMOVE/INSPECT FUEL PUMP DRIVE COUPLING AND COVER							Service	ATA:73
	MOS	13-May-22							
	HRS	5091	1800 (+100)		(6891) 7068.6	6991	1461.6 (+100)		
	ENC	9900							
PROC. REF: EMM 73-10-02									

PKG:1

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
731060	NO. 1 ENGINE - OIL TO FUEL HEATER							Component	ATA:73
PN:10552E	MOS/MSC	29-May-20	O/C	TSN 5, TSO 0					
SN:WA58333	HRS	4924.6		TSO 0					
	ENC	9660		TSO 0					
PROC. REF: EMM 73-10-01									
731065 <sup>S</sup>	NO. 1 ENGINE - INSPECT OIL TO FUEL HEATER INSTALLATION							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-01									
731070	NO. 1 ENGINE - FLOW DIVIDER AND FUEL DUMP VALVE							Component	ATA:73
PN:3019906	MOS/MSC	29-May-20	O/C						
SN:18903	HRS	4924.6		TSN 4924.6, TSO 1479.5					
	ENC	9660		TSN 9660, TSO 2651					
PROC. REF: EMM 73-10-04									
731080 <sup>S</sup>	NO. 1 ENGINE - INSPECT STARTING FLOW CONTROL/ FLOW DIVIDER FOR INSTALLATION AND LEAKS							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-04									
731090	NO. 1 ENGINE - FUEL CONTROL UNIT							Component	ATA:73
PN:3244897-4	MOS	13-May-22		TSO 5				OVERHAUL	
SN:C66719	HRS	5091	4100	TSO 0		(9191) 9368.6	3761.6		
	ENC	9900		TSO 0					
PROC. REF: EMM 73-20-00									
731091 <sup>S</sup>	NO. 1 ENGINE - INSPECT FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC TUBES							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-20-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
731095	NO. 1 ENGINE - INSPECT FUEL CONTROL UNIT BODY/BEARING							Service	ATA:73
PN:3244897-4	MOS	13-May-22							
SN:C66719	HRS	5091	3600 (+100)		(8691) 8869.4	8791	3261.6 (+100)		
	ENC	9900							
PROC. REF: GENERIC NO REF									
731100	NO. 1 ENGINE - OPERATIONAL CHECK FUEL CONTROL UNIT MANUAL OVERRIDE STATIC SYSTEM							Service	ATA:73
PN:3244897-4	MOS	19-Oct-23							
SN:C66719	HRS	5422.1	200 (+10%)		(5622.1) 5800.5	5642.1	192.7 (+20)		
	ENC	10278							
PROC. REF: EMM 71-00-00									
731105	NO. 1 ENGINE - PERFORM DECELERATION CHECK							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	150 (+10%)		(5572.1) 5750.5	5587.1	142.7 (+15)		
	ENC	10278							
PROC. REF: EMM 71-00-00									
731150 <sup>S</sup>	NO. 1 ENGINE - EXAMINE THE FCU FOR WASHOUT							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: GENERIC NO REF									
732011 <sup>S</sup>	NO. 1 ENGINE - INSPECT FUEL DRAIN VALVE FOR INSTALLATION AND LEAK							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-06									
733010	NO. 1 ENGINE - CLEAN/REPLACE /INSPECT PNEUMATIC P3 FILTER/HOUSING							Service	ATA:73
	MOS	19-Oct-23							
	HRS	5422.1	100 (+10%)		(5522.1) 5700.5	5532.1	92.7 (+10)		
	ENC	10278							
PROC. REF: EMM 73-10-07, EMM 73-10-07									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 73 - ENGINE FUEL AND CONTROL</b>									
733020	NO. 1 ENGINE - REPLACE PNEUMATIC P3 FILTER							Service	ATA:73
	MOS	30-Aug-18							
	HRS	4854.27	1000 (+100)		(5854.27) 6032.67	5954.27	424.9 (+100)		
	ENC	9529							
PROC. REF: EMM 73-10-07									
<b>ATA 74 - IGNITION</b>									
740010	NO. 1 ENGINE - IGNITION EXCITER							Component	ATA:74
PN:10-381550-1M	MOS/MSC	24-May-96	O/C						
SN:NN95111981	HRS	17		TSN 0					
	ENC	0							
PROC. REF: EMM 74-10-00									
740015	NO. 1 ENGINE - SYSTEMS - IGNITION SYSTEM - EXAMINE THE IGNITION EXCITER/CURRENT REGULATOR FOR INSTALLATION AND CONDITION							Service	ATA:74
	MOS	16-Mar-23							
	HRS	5263	400 (+10%/-10%)		(5663) 5841.4	5703	233.6 (+40)		
	ENC	10089							
PROC. REF: EMM 74-10-00									
741020	NO. 1 ENGINE - OUTBOARD SPARK IGNITER							Component	ATA:74
PN:CH34055	MOS/MSC	27-Apr-18	O/C						
SN:N/A	HRS	4762.87							
	ENC	9371							
PROC. REF: EMM 74-20-00									
741025	NO. 1 ENGINE - SYSTEMS - IGNITION SYSTEM - EXAMINE THE OUTBOARD SPARK IGNITER FOR CLEANLINESS AND EROSION. DO A FUNCTIONAL CHECK							Service	ATA:74
PN:CH34055	MOS	16-Mar-23							
SN:N/A	HRS	5263	400 (+10%/-10%)		(5663) 5841.4	5703	233.6 (+40)		
	ENC	10089							
PROC. REF: EMM 74-20-00, EMM 74-20-00									
741030	NO. 1 ENGINE - INBOARD SPARK IGNITER							Component	ATA:74
PN:CH34055	MOS/MSC	27-Apr-18	O/C						
SN:N/A	HRS	4762.87							
	ENC	9371							
PROC. REF: EMM 74-20-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 74 - IGNITION									
741035	NO. 1 ENGINE - SYSTEMS - IGNITION SYSTEM - EXAMINE THE INBOARD SPARK IGNITER FOR CLEANLINESS AND EROSION. DO A FUNCTIONAL CHECK							Service	ATA:74
PN:CH34055	MOS	16-Mar-23							
SN:N/A	HRS	5263	400 (+10%/-10%)		(5663) 5841.4	5703	233.6 (+40)		
	ENC	10089							
PROC. REF: EMM 74-20-00, EMM 74-20-00									
741040	NO. 1 ENGINE - SYSTEMS - IGNITION SYSTEM - EXAMINE THE IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION							Service	ATA:74
	MOS	16-Mar-23							
	HRS	5263	400 (+10%/-10%)		(5663) 5841.4	5703	233.6 (+40)		
	ENC	10089							
PROC. REF: EMM 74-20-00									
741045 <sup>U S</sup>	NO. 1 ENGINE - INSPECT SPARK IGNITER/GLOW PLUGS FOR CLEANLINESS AND EROSION. CHECK FUNCTION							Service	ATA:74
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							

PKG:1

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 75 - AIR									
750010	NO. 1 ENGINE - BLEED VALVE							Component	ATA:75
PN:540-1407-4	MOS	12-May-11		TSO 0				OVERHAUL	
SN:GA1276	HRS	3445.1	4100	TSN 1896.1, TSO 0	(7545.1) 7723.5		2115.7		
	ENC	7009		TSO 0					
PROC. REF: EMM 75-30-00									
750020	NO. 1 ENGINE - INSPECT/CHECK BLEED VALVE							Service	ATA:75
	MOS	13-May-22							
	HRS	5091	600		(5691) 5869.4		261.6		
	ENC	9900							
PROC. REF: EMM 75-30-00									
750030 <sup>S</sup>	NO. 1 ENGINE - INSPECT P3 FILTER FOR INSTALLATION							Service	ATA:75
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-07									
750040 <sup>S</sup>	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS							Service	ATA:75
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
PROC. REF: EMM 73-10-07									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 76 - ENGINE CONTROLS</b>									
760200	ENGINE CONTROL QUAD ASSEMBLY							Component	ATA:76
PN:C299514-0101	MOS/MSC	16-Nov-95	O/C						
SN:163	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 76-10-01									
761010 <sup>S</sup>	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES							Service	ATA:76
	MOS	19-Oct-23							
	HRS	5422.1	200 (+10%)						
	ENC	10278							
PROC. REF: EMM 76-10-00									
B761001	FUNCTIONAL CHECK ENGINE CONTROLS							Service	ATA:76
	MOS	16-Mar-23	12 (+1m/-1m)		31-Mar-24	30-Apr-24	TOL (+12 d)		
	HRS	5440.6							
	AFL	10430							
PROC. REF: AMM 76-10-00									
B761003 <sup>S</sup>	OPERATIONAL CHECK EMERGENCY POWER LEVER ANNUNCIATOR LIGHT (EPL)							Service	ATA:76
	MOS	13-May-22	12 (+1m/-1m)						
	HRS	5268.6	200 (+25/-25)						
	AFL	10213							
PROC. REF: AMM 76-10-01									
<b>ATA 77 - ENGINE INDICATING</b>									
770001	NO. 1 ENGINE - TORQUE INDICATOR							Component	ATA:77
PN:2606011-3RX	MOS/MSC	04-Oct-15	O/C	TSO 2					
SN:E07-1165	HRS	4329.4		TSO 0					
	ENC	8543							
PROC. REF: GENERIC NO REF									
770002	NO. 1 ENGINE - RPM PROP INDICATOR							Component	ATA:77
PN:2606014-1	MOS/MSC	25-Aug-03	O/C						
SN:52C0014	HRS	2052		TSO 0					
	ENC								
PROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 77 - ENGINE INDICATING</b>									
770003	NO. 1 ENGINE - ITT INDICATOR							Component	ATA:77
PN:2606012-1	MOS/MSC	14-Apr-98	O/C						
SN:37J13C	HRS	1078		TSN 0					
	ENC								
	PROC. REF: GENERIC NO REF								
770004	NO. 1 ENGINE - RPM INDICATOR							Component	ATA:77
PN:2606013-1	MOS/MSC	16-Nov-95	O/C						
SN:900164	HRS	0		TSN 3					
	ENC								
	PROC. REF: GENERIC NO REF								
770010	NO. 1 ENGINE - AFT TACH GENERATOR							Component	ATA:77
PN:22A703	MOS/MSC	16-Nov-95	O/C						
SN:72284	HRS	0		TSN 3					
	ENC								
	PROC. REF: GENERIC NO REF								
770011	NO. 1 TORQUE VENT & PRESSURE HOSE							Component	ATA:77
PN:AE3663161E0113	MOS	06-May-21	120	TSN 48	31-May-27		1138 d	REPLACE	
SN:N/A	HRS	5164.4							
WC#: 77.005	AFL	10079							
	PROC. REF: GENERIC NO REF								
770015	NO. 1 ENGINE - FORWARD TACH GENERATOR							Component	ATA:77
PN:22A703	MOS/MSC	16-Nov-95	O/C						
SN:72299	HRS	0		TSN 3					
	ENC								
	PROC. REF: GENERIC NO REF								
770030	NO. 1 ENGINE - TURBINE INLET TEMPERATURE HARNESS							Component	ATA:77
PN:3117924-01	MOS/MSC	28-Oct-22	O/C	TSO 0					
SN:NRA33549	HRS			TSO 0					
	ENC			TSO 0					
	PROC. REF: GENERIC NO REF								
770100	OIL PRESSURE HOSE							Component	ATA:77
PN:AE3663163E0230	MOS	25-Apr-16	120	TSN 0	30-Apr-26		742 d	REPLACE	
SN:N/A	HRS	4585.1		TSN 0					
WC#: 77.010	AFL	9098							
	PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 78 - EXHAUST</b>									
780015 <sup>S</sup>	NO. 1 ENGINE - INSPECT EXHAUST DUCT FOR CRACKS AND DISTORTION							Service	ATA:78
	MOS	19-Oct-23							
	HRS	5422.1	200						
	ENC	10278							
				PROC. REF: EMM 72-50-05				PKG:1	
780116	PRIMARY EXHAUST DUCT ASSEMBLY							Component	ATA:78
PN:2654008-205	MOS/MSC	18-Sep-08	O/C						
SN:N/A	HRS	3210		TSN 0					
WC#: 78.005	AFL								
				PROC. REF: AMM 78-10-00					
780201	SECONDARY EXHAUST DUCT ASSEMBLY							Component	ATA:78
PN:2654008-833	MOS/MSC	16-Nov-95	O/C						
SN:68	HRS	0		TSN 0					
WC#: 78.010	AFL	0		TSN 0					
				PROC. REF: AMM 78-10-00					
A781001 <sup>S</sup>	GENERAL VISUAL INSPECTION PRIMARY AND SECONDARY EXHAUST DUCT							Service	ATA:78
	MOS	06-May-21	24 (+1m/-1m)						
	HRS	5164.4	800 (+25/-25)						
	AFL	10079							
				PROC. REF: AMM 78-10-00				PKG:136	
<b>ATA 79 - OIL</b>									
790001	NO. 1 ENGINE - OIL COOLER							Component	ATA:79
PN:10751B	MOS/MSC	16-Nov-95	O/C						
SN:758	HRS	0		TSN 3					
	ENC								
				PROC. REF: GENERIC NO REF					
790004A <sup>U</sup>	VALVE-VERNATHERM							Component	ATA:79
PN:723655	MOS/MSC	16-Nov-95	O/C						
SN:UNKNOWN	HRS	0		TSN 0					
	AFL	0		TSN 0					
790020	NO. 1 ENGINE - CHIP DETECTOR							Component	ATA:79
PN:3045951-02	MOS/MSC	31-Dec-19	O/C		TSN 0				
SN:UNKNOWN	HRS	4925.4			TSN 0				
	ENC	9665			TSN 0				
				PROC. REF: GENERIC NO REF					

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 79 - OIL</b>									
790030	NO. 1 ENGINE - CONTINUITY CHECK CHIP DETECTOR							Service	ATA:79
PN:3045951-02	MOS	19-Oct-23							
SN:UNKNOWN	HRS	5422.1	100 (+10%)		(5522.1) 5700.5	5532.1	92.7 (+10)		
	ENC	10278							
PROC. REF: EMM 79-20-02									
790040	NO. 1 ENGINE - BRIDGE CHECK CHIP DETECTOR							Service	ATA:79
PN:3045951-02	MOS	16-Mar-23	12 (+30d)		31-Mar-24	30-Apr-24	TOL (+12 d)		
SN:UNKNOWN	HRS	5263	600 (+10%)		(5863) 6041.4	5923	433.6 (+60)		
	ENC	10089							
PROC. REF: EMM 79-20-02									
790045	NO. 1 ENGINE - OIL SYSTEM SERVICING							Service	ATA:79
	MOS/MSC	24-May-96	A/R	TAC 0					
	HRS	0		TAC 0					
	ENC	0		TAC 0					
PROC. REF: EMM 79-20-02									
790050	NO. 1 ENGINE - CLEAN/REPLACE OIL FILTER							Service	ATA:79
	MOS	29-May-20							
	HRS	4924.6	1000		(5924.6) 6103		495.2		
	ENC	9660							
PROC. REF: EMM 79-20-02									
790051 <sup>U</sup>	CHANGE OIL							Service	ATA:79
	MOS	09-Mar-23	12		31-Mar-24		OVD		
	HRS								
	AFL								
790060 <sup>S</sup>	NO. 1 ENGINE - INSPECT OIL FILTER ELEMENT AND SECONDARY SCREEN							Service	ATA:79
	MOS	19-Oct-23							
	HRS	5422.1	200 (+10%)						
	ENC	10278							
PROC. REF: EMM 79-20-02									

PKG:1

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
<b>ATA 79 - OIL</b>									
790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN							Service	ATA:79
	MOS	29-May-20							
	HRS	4924.6	1000 (+100)		(5924.6) 6103	6024.6	495.2 (+100)		
	ENC	9660							
PROC. REF: EMM 72-60-00									
791000	OIL COOLER RETURN HOSE							Component	ATA:79
PN:AE3663161K0600	MOS	25-Apr-16	120	TSN 0	30-Apr-26		742 d	REPLACE	
SN:N/A	HRS	4585.1		TSN 0					
WC#: 79.005	AFL	9098							
PROC. REF: GENERIC NO REF									
791020	ENGINE OIL BREATHER VENT HOSE							Component	ATA:79
PN:R221520	MOS	16-Mar-23	120	TSN 0	31-Mar-33		3269 d	REPLACE	
SN:UNKNOWN	HRS	5440.6	3600	TSN 0	9040.6		3432.8		
	AFL	10430		TSN 0					
PROC. REF: GENERIC NO REF									
792000	OIL COOLER SUPPLY HOSE							Component	ATA:79
PN:AE3663163K0600	MOS	25-Apr-16	120	TSN 0	30-Apr-26		742 d	REPLACE	
SN:N/A	HRS	4585.1		TSN 0					
WC#: 79.005	AFL	9098							
PROC. REF: GENERIC NO REF									
792003	OIL PRESSURE SWITCH ASSEMBLY							Component	ATA:79
PN:1103P-65-16	MOS/MSC	16-Nov-95	O/C						
SN:2795	HRS	0		TSN 0					
WC#: 79.035	AFL	0		TSN 0					
PROC. REF: AMM 79-30-00									
792005	OIL TEMPERATURE/PRESSURE INDICATOR							Component	ATA:79
PN:2606015-3	MOS/MSC	01-Sep-14	O/C	TSO 0					
SN:M2317	HRS	4216.2		TSO 0					
	AFL	8360		TSO 0					
PROC. REF: AMM 79-30-00									

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: 208 CARAVAN - ANNUAL-100 HOUR INSPECTION Serial: 208-0245 RegNo: N85WL HRS: 5607.8 AFL: 10628 As Of: 23-Feb-2024

18-Apr-2024 10:32 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
792026 <sup>S</sup>			NO. 1 ENGINE - SYSTEMS - OIL SYSTEM - EXAMINE THE FORWARD OIL TRANSFER ELBOW INSTALLATION ON THE FLANGE A. MAKE SURE THAT THE BOLTS TIGHTEN CORRECTLY					Service ATA:79
	MOS	19-Oct-23						
	HRS	5422.1	200 (+10%/-10%)					
	ENC	10278						
			PROC. REF: GENERIC NO REF					PKG:1
ATA 80 - STARTING								
A801001 <sup>S</sup>			DETAILED INSPECTION STARTER-GENERATOR (PART NUMBER 23081 SERIES ONLY)					Service ATA:80
	MOS	13-May-22	12 (+1m/-1m)					
	HRS	5268.6	400 (+25/-25)					
	AFL	10213						
			PROC. REF: AMM 80-10-00					PKG:133

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task