

Discrepancy: 13.7 Install new upper cowl verify if fit . If fit check good send to paint .  
\*If trimming required additional time will be needed.

Resolution:

	<u>Time &amp; Materials</u>	<u>Flat Rate</u>	<u>Total</u>
Labor:	0.00 USD	1,788.00 USD	1,788.00 USD
Parts:	184,758.59 USD	---	184,758.59 USD
Services:	<u>6,350.57 USD</u>	<u>---</u>	<u>6,350.57 USD</u>
<b>Total:</b>	<b>191,109.16 USD</b>	<b>1,788.00 USD</b>	<b>192,897.16 USD</b>