

HARTZELL

PROPELLER LOGBOOK

f Propeller Model: HC-B5MP-3C / M10876ANS

f Propeller S/N: EVA3734

LOGBOOK # _____

The subject aircraft was involved in an incident / accident on 6/5/2024 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: 1163097201US.

Signed: ***Underwriters Salvage Company***

Date: **8/22/2025**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100

Model Number HC-B5MP-3C/M10876ANS

Ass'y Ser No. EVA3734 Hydr Unit No. NA Bulkhead No. 2100046 Valve No. NA

Blade 1: M10954	Blade 2: M10960	Blade 3: M10961	Blade 4: M10962	Blade 5: M10963	Blade 6:
Clamp 1: F38448	Clamp 2: F38449	Clamp 3: F38451	Clamp 4: F38453	Clamp 5: F38454	

Reverse	Start Lock	Low Pitch	High Pitch	Feather	Position	Orient.	Qty:Al	St	Scrw	A-2424-1	Washer
-11.0	NA	16.5	NA	79.0	5	F	0	8	0	0	0
Ref Radius (inches) for angles: 42					5	C	0	2	0	0	0
Comments: Deice Kit: NA					1	F	0	0	0	0	2

Packing Certified By: T. J. [Signature] Date: 1-8-21

Inspected By: BL

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.
The propeller covered by this certificate has passed a functional test as required by 14 CFR Part 21.137(e)(2).

PROPELLER MAINTENANCE RECORD

Position Centerline

PITCH RANGE

Propeller Model HC-B5MP-3C

High / Feather NA / 79.0

Propeller S/N EVA3734

Start Lock NA

Blade Design M10876ANS

Low 16.5

Blade S/N's

Reverse -11.0

No. 1 M10954

No. 2 M10960

No. 3 M10961

No. 4 M10962

No. 5 M10963

Aircraft Manufacture Air Tractor, Inc.

Aircraft Model AT-602

Aircraft S/N 602-1319

Registration N602AW

Spinner Assembly Part No. _____