

PROPELLER LOG BOOK

FOR SENSENICH 70CM SERIES
FIXED PITCH METAL PROPELLER



SENSENICH PROPELLER MFG. CO.


Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

WARNING!


**AVOID ALL OPERATION ABOVE
2600 RPM**

THIS LOG BOOK IS TO BE KEPT WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED
WORK WILL NOT BE PERFORMED ON ANY PROPELLER WITHOUT A LOG BOOK

Make: Vans
Model: RV-6
S/N: 60209
N644K
Tach: 210.7
AFTT: 364.7
PROP LOG
I certify this propeller has been inspected IAW an annual condition inspection and was determined to be in an airworthy condition.
1. Performed annual condition inspection IAW Vans inspection checklist.
This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.
Dan Webre Jr
AP3501544IA 


DW Aircraft Service
1000 Airport Blvd
Hillsboro, TX 76645
254-715-0240

12/10/2020
Sensenich 70GM759-0-79
S/N: 33162R
Prop TSNEW: 364.7

Make: Vans
Model: RV-6
S/N: 60209
N644K
Tach: 243.5
AFTT: 397.5
PROP LOG
I certify this propeller has been inspected IAW an annual condition inspection and was determined to be in an airworthy condition.
1. Performed annual condition inspection IAW Vans inspection checklist.
This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.
Dan Webre Jr
AP3501544IA 


DW Aircraft Service
1000 Airport Blvd
Hillsboro, TX 76645
254-715-0240

1/4/2022
Sensenich 70GM759-0-79
S/N: 33162R
Prop TSNEW: 397.5

Make: Vans
Model: RV-6
S/N: 60209
N644K
Tach: 280.0
AFTT: 434.0
PROP LOG
I certify this propeller has been inspected IAW an annual condition inspection and was determined to be in an airworthy condition.
2. Performed annual condition inspection IAW Vans inspection checklist.
This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.
Dan Webre Jr
AP3501544IA 

DW Aircraft Service
1000 Airport Blvd
Hillsboro, TX 76645
254-715-0240

2/1/2023
Sensenich 70GM759-0-79
S/N: 33162R
Prop TSNEW: 434.0

Make: Vans
Model: RV-6
S/N: 60209
N644K
Tach: 302.6
AFTT: 456.6
PROP LOG
I certify this propeller has been inspected IAW an annual condition inspection and was determined to be in an airworthy condition.
1. Performed annual condition inspection IAW Vans inspection checklist.
This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.
Dan Webre Jr
AP3501544IA 

DW Aircraft Service
1000 Airport Blvd
Hillsboro, TX 76645
254-715-0240

3/14/2024
Sensenich 70GM759-0-79
S/N: 33162R
Prop TSNEW: 456.6

PROPELLER MAINTENANCE RECORD

PROPELLER MODEL 70GM759-0-79

PROPELLER SERIAL NUMBER 33162R

TABLE OF PROPELLER ATTACHING BOLT WRENCH TORQUE
Sensenich Metal Propellers (the proper torque is also shown on Blade Information Decal)

| PROPELLER SERIES** | BOLT DIA. (inches) | RECOMMENDED WRENCH TORQUE | | |
|---|--------------------|---------------------------|---------|-------|
| | | in.-lb. | ft.-lb. | n.-m. |
| 69CK, M69CK (6 bolts) 72CK (6 bolts) 74CK, M74CK (6 bolts) 76AK, M76AK (6 bolts) 76AM6, M76AM (6 bolts) 74DM6, M74DM (6 bolts) *74DR, M74DR (8 bolts) | 3/8 (0.375) | 280-300 | 23-25 | 32-34 |
| 74DM7 (6 bolts) | 7/16 (0.4375) | 480-540 | 40-45 | 54-61 |
| 72CC (6 bolts) 74DC, M74DC (6 bolts) 76EM8, M76EMM (6 bolts) *80BM8, M80BMM (6 bolts) | 1/2 (0.500) | 720-780 | 60-65 | 81-88 |

*Not in production

**These are the basic propeller models. Spacer addition does not affect recommended wrench torque.

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

| DATE | TACH TIME | DESCRIPTION OF WORK | SIGNATURE |
|--------|-----------|-------------------------------|--------------------|
| 5/5/01 | 37.52 | retorqued bolts (500" lbs) | <i>[Signature]</i> |

Make: Vans
Model: RV-6
S/N: 60209
N644K
Tach: 154.6
AFTT: 308.6
PROP LOG

DW Aircraft Service
1000 Airport Blvd
Hillsboro, TX 76645
254-715-0240

11/15/2019
Sensenich 70GM759-0-79
S/N: 33162R
Prop TSNEW: 308.6

I certify this propeller has been inspected IAW an annual condition inspection and was determined to be in an airworthy condition.

1. Performed annual condition inspection IAW Vans inspection checklist.

This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.

Dan Webre Jr
AP3501544IA

[Signature]