

	Total Time in Service	Description			
lns	wo: WO_1171		AVIATION SERVICES	Propeller ⋅ page 1 of	
		Altman Aviation Services LLC	222 Airport Dr · Lockhart, TX 78644 ·	830-800-2067	
=	N611KH HOBBS: 138.6	TACH: 3222.2	PTSN: 3222.2	August 08, 2024	
ms (Performed an annual inspection following the scope and details of FAR 43. Appendix D and using Altman Aviation Services checklist. Visually inspected this propeller no defects noted.				
	I certify this PROPELLER has been inspected IAW an ANNUAL Inspection and was determined to be in an airworthy condition.				
= \ [With respect to the work performed, this PROPELLER is approved for return to service. Details of work performed are on file with Altman Aviation Services LLC. under work order: WO_1171.				
-	David Altman A&P	IA 3770040			
_ [

ropeller Record General Information ropeller Manufacturer Mc(au/e) lodel IAIOI/HCM6948	
	Type
lub Series #	
Make/Model Aircraft Installed On: <u>Cessna/i50L</u>	Serial #