





**HARTZELL**



# PROPELLER LOGBOOK

PROPELLER MODEL HC-E3YR-1RF/F7392

PROPELLER S/N FM1570B

LOGBOOK # \_\_\_\_\_

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
	wo: WO_721			Propeller - page 1 of 1
 <b>BK AIRCRAFT SERVICES, LLC</b> BK Aircraft Services · 503 McKeever Rd · Arcola, TX 77583 · (832) 595-5008				
	<b>N1346J</b>	<b>HARTZELL, HC-E3YR-1RF/F7392, S/N: FM1570B</b>		<b>April 03, 2023</b>
	HOBBS: 781.1	TACH: 326.8		SNEW: 500.9
	<ol style="list-style-type: none"> <li>1. PERFORMED ANNUAL INSPECTION IAW 14 CFR APPENDIX D AND MANUFACTURERS CHECK-LIST.</li> <li>2. REMOVED SPINNER, INSPECTED PROP SPINNER AND BULKHEADS.</li> <li>3. REDRESSED PROP REINSTALLED SPINNER.</li> <li>4. ALL AD'S HAVE BEEN COMPLIED WITH TO THIS DATE.</li> <li>5. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHINESS CONDITION.</li> </ol>			
	With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with BK Aircraft Services under work order: WO_721.			
	Brian Isbell A&P 3402213IA 			

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
	wo: WO_1124			Propeller - page 1 of 1
 <b>BK AIRCRAFT SERVICES, LLC</b> BK Aircraft Services · 503 McKeever Rd · Arcola, TX 77583 · (832) 595-5008				
	<b>N1346J</b>	<b>HARTZELL, HC-E3YR-1RF/F7392, S/N: FM1570B</b>		<b>August 09, 2024</b>
	TACH: 337.0	SNEW: 511.1		
	<ol style="list-style-type: none"> <li>1. PERFORMED ANNUAL INSPECTION IAW 14 CFR AND MANUFACTURERS CHECKLIST.</li> <li>2. REMOVED SPINNER, INSPECTED PROP SPINNER AND BULKHEADS, REINSTALLED SPINNER.</li> <li>3. ADJUSTED PROP CONTROL CABLE TO HIT STOPS FUNCTIONED OPS GOOD PROP GOVERNER WORKS AS DESCRIBED.</li> <li>4. ALL AD'S HAVE BEEN COMPLIED WITH TO THIS DATE.</li> <li>5. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHINESS CONDITION.</li> </ol>			
	With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with BK Aircraft Services under work order: WO_1124.			
	Brian Isbell A&P 3402213IA 			

Make: Aero Commander	DW Aircraft Service	1/24/2019
Model: 112	1000 Airport Blvd	Hartzell HC-E3YR-1RF
S/N: 346	Hillsboro, TX 76645	S/N: FM1570B
N1346J	254-715-0240	Prop TT: 371.2
Tach: 197.1		
AFTT: 2593.7		
PROP LOG		
I certify this propeller has been inspected IAW a 100 hour inspection and was determined to be in an airworthy condition. AD research completed through this date. See separate AD list for details.		
1. Performed a 100 hour inspection IAW FAR 43 Appendix D.		
This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.		
	Dan Webre Jr	<i>[Signature]</i>
	425015441A	
	N1346J	
	MARCH 2, 2020	TACH: 257.9
	PERFORMED 100HR/ANNUAL INSPECTION IAW FAR 43 APPENDIX D AND MANUFACTURERS CHECKLIST, REMOVED SPINNER INSPECTED PROP SPINNER AND BULKHEADS, DRESSED PROP, REINSTALLED SPINNER, ALL AD'S HAVE BEEN COMPLIED WITH TO THIS DATE, I CERTIFY THAT THIS PROPELLOR HAS BEEN INSPECTED IN ACCORDANCE WITH AN 100HR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHINESS CONDITION, BRIAN ISBELL A&P 3402213IA	
	<i>[Signature]</i>	

wo: WO\_320

Propeller - page 1 of 1



**BK AIRCRAFT SERVICES, LLC**

BK Aircraft Services - 503 McKeever Rd - Arcola, TX 77583 - (832) 595-5008

**N1346J**  
TACH: 315.0



**HARTZELL, HC-E3YR-1RF/F7392, S/N: FM1570B**


**February 08, 2022**

1. PERFORMED ANNUAL INSPECTION IAW 14 CFR APPENDIX D AND MANUFACTURERS CHECKLIST.
2. REMOVED SPINNER, INSPECTED PROP SPINNER AND BULKHEADS.
3. REDRESSED PROP REINSTALLED SPINNER.
4. ALL AD'S HAVE BEEN COMPLIED WITH TO THIS DATE.
5. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHINESS CONDITION.

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with BK Aircraft Services under work order: WO\_320.

Brian Isbell A&P 3402213IA *[Signature]*

Date	Propeller TSN . TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<p>September 25, 2014 Tach/TT/ AF 2371.1 Engine TT: 2371.1 TTProp: 183.52            Performed an Annual Inspection. I certify this engine/airframe/propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.</p> <p>Signed <u></u>            Talladega Aircraft Maintenance            Randal W. Durley            A/P3476652I/A</p>
			<p>October 1, 2015 Tach: 41.6 AFTT 2438.2 Engine TT: 2438.2 TTProp: 215.2            Performed an annual inspection. I certify this propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.</p> <p>Signed <u></u>            Durley Air Service            Randal W. Durley            A/P3476652I/A</p>

			<p>October 1, 2016 Tach: 97.2 AFTT 2493.8 Engine TT: 2493.8 TTProp: 270.8            Performed an annual inspection. I certify this propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.</p> <p>Signed <u></u>            Durley Air Service            Randal W. Durley            A/P3476652I/A</p>
--	--	--	---

Make: Aero Commander  
 Model: 112  
 S/N: 346  
 N1346J  
 Tach: 128.7  
 AFTT: 2525.3  
 PROP LOG

DW Aircraft Service  
 13506 WCR 178  
 Odessa, TX 79766  
 254-715-0240


11/3/2017  
 Hartzell HC-E3YR-1RF/F7392  
 S/N: FM1570B  
 Prop TT: 302.8

I certify this propeller has been inspected IAW a 100 hour inspection and was determined to be in an airworthy condition. AD research completed through this date.

1. Performed a 100 hour inspection IAW FAR 43 Appendix D.
2. Dressed prop blades as needed.

This propeller was inspected IAW current Federal Aviation Regulations and is approved for return to service.

Dan Webre Jr  
 AP3501544IA



Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<p>PROP MODEL: HC-E3YR-1RF/F7392            COMPASS AVIATION MAINTENANCE, LLC.            830 College Ave., Hangar C            Shelby, NC 28152            Phone: 704-669-5935</p> <p>DATE: 7/28/2010            A/C TSN: 2187.58            PROP TT: 0            TACH: 2187.58</p> <p><b>Prop Entries</b>            INSTALLED HARTZELL PROPELLER, HC-E3YR-1RF/F7392, S/N FM1570B USING NEW O-RING AND MOUNTING HARDWARE, TORQUED TO MANUFACTURERS SPECS. INSPECTED PROPELLER IAW FAR 43 APPENDIX D USING COMPASS 21, INC. CHECKLIST. NO DEFECTS NOTED. REASSEMBLE AND RETURN TO SERVICE... A/D COMPLIANCE THROUGH ATP CONTENT REVISION DISC DATED 9/10/2010... PER FAR 43.9 PARA. (a), (3): ADDITIONAL TECHNICIANS PERFORMING WORK RELATED TO THIS WORK ORDER ARE AS FOLLOWS: JOHN R. WATT AND JAMIN R. PECK</p> <p>I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION</p> <p>DATE: 7/28/2010 SIGNED: <i>John M. Edmonds</i> Work Order: 468-01-2007            John M. Edmonds, A&amp;P: 2678565 IA Printed by EBIS 3 (datcomedia.com)</p>
7/22/11	7AC 2247+		<p>ANNUAL INSP C/W LUBED PROP            DRESSED BLADES            Airframe Int 3404585</p>

			<p>August 22, 2012 Tach/TT/ AF 2277.16 Engine TT: 2277.16 TTProp: 89.58            Performed an annual inspection. I certify this propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.</p> <p>Signed <i>Randal W. Durley</i>            Durley Air Service            Randal W. Durley            A/P34766521/A</p>
			<p>August 5-2013 Tach/TT/ AF 2318.12 Engine TT: 2318.12 TTProp: 130.54            Performed an annual inspection. I certify this propeller has been inspected in accordance with an annual inspection and determined to be in airworthy condition.</p> <p>Signed <i>Randal W. Durley</i>            Talladega Aircraft Maintenance            Randal W. Durley            A/P34766521/A</p>

# PROPELLER MAINTENANCE RECORD

Position N/A

Propeller Model HC-E3YR-1RF/F2392

Propeller S/N EM1520B

Blade Design \_\_\_\_\_

Blade S/N's

No. 1 K50270

No. 2 K50267

No. 3 K50276

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

PITCH RANGE

High/Feather 30.0

Start Lock N/A

Low 11.2

Reverse N/A

Aircraft Manufacturer Rockwell

Aircraft Model 112

S/N 346

Registration N1346J