

PROPELLER MAINTENANCE LOG BOOK

COURTESY OF .




PALM BEACH AIRCRAFT PROPELLER, INC.


F.A.A. Approved Repair Station #LU4R349M J.A.A. Acceptance Certificate JAA.5271

2633 Lantana Road, Suite 23, Bldg 1501, Lantana, FL 33462 1-800-965-7767 / FAX 561-965-7933 / www.pbapi.com

**EXPLANATION OF ALL MAINTENANCE
PERTAINING TO AIR WORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
MINOR ADJUSTMENTS & MAJOR OVERHAULS.**

DATE	T.T.	T.S.O.	DESCRIPTION OF WORK	SIGNATURE
10/4/06	3689.75	-0-	Installed propeller on N6921P after OVERHAUL. HC-92ZK-8D, S/N 806L	
			Thru PMalikub AIP 375605708	
			Tach same total 3689.75	
Date: 10/29/2007 Registration #: N6921P Make: Piper Model: PA-24 Serial #: 24-2055 Prop Make: Hartzell Prop Model: HC-92ZK-8D Prop Serial #: 806L Tach. Time: 661.96 Prop Total Time: Unknown Prop TSOH: 68.79 I certify that this propeller has been inspected in accordance with a 100 hour/annual inspection and is approved for return to service.  Stephen M. Crumpler, Jr. 28014331A Woods Aviation, Inc.				

**EXPLANATION OF ALL MAINTENANCE
PERTAINING TO AIR WORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
MINOR ADJUSTMENTS & MAJOR OVERHAULS.**

DATE	T.T.	T.S.O.	DESCRIPTION OF WORK	SIGNATURE
1 Aug 08			Overhauled propeller m/w HC-92ZK-8D S/N 806L, C/W SB 136E, 137A, 202, 5L61-61XR1 177, 229, 258R1, 5F 169, AD (05-18-12) (95-11-08) greased, painted and balanced by H & H Propeller Service also under DO# 16493.7	
			H & H PROPELLER SERVICE, INC. 	
			3439 SOUTH AVIATION DRIVE	
			BURLINGTON MUNICIPAL AIRPORT	
			BURLINGTON, N. C. 27215	
			FAA REPAIR STATION PS4R451M	
			1-800-334-6437	

INSTALLATION ■ OPERATION ■ SERVICE

Hartzell

propeller owner's
manual
& log book

For Propeller Models HC-82X, HC-A2(), HC-A3(), HC-B4(),
HC-92Z, HC-B3(), HC-92W,
HC-83X, HC-93Z, HC-B5MP Series

Constant Speed and Feathering Two, Three, Four, and Five Blade

JUSTIN "JACK" B. COX
1220 HURON COURT
OSHKOSH, WI 54901
PIPER PA-24-180
N6921P

D.O.A. -
F.A.A.
APPROVED
MANUAL
106J

HARTZELL PROPELLER, INC. - PIQUA, OHIO

PIPER PA-24-180
LYCOMING O-360-A1A (SER. L-3141-36)

PROPELLER MAINTENANCE RECORD

~~LEFT~~ ENGINE

Hub Model HC92ZK-1D

Blade Design 8447A-12A

Diameter 72"

Hub Ser. No. 806L

Blade Ser. Nos. _____

No. 1 B29535

No. 2 B29533

No. 3 _____

PITCH RANGE

High 27° Low 13°

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____