

The subject aircraft was involved in an incident / accident on <u>9/4/2025</u> rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: <u>0655945168US</u>.

Date: **10/14/2025**AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100
Atlanta, GA 30326

Signed: Underwriters Salvage Company

Installed new Sensonich Propellor (customer supplied) Model: W72GK-44, S/N AM1999. Re-torque safety wire prop bolts twice. With respect to the work performed, this propeller is approved for return to service. Details of work formed are on file with Aircraft Service & Parts Corp. under work order: 3266. Bob Baker A&P 1639399 Total Time in Service Description Description	ır:	wo: 3266	ARCRAFT	Propeller - page 1 of 1	
N92041 Sensonich, W72GK-44, S/N: AM1999 August 28, 20 ACTT: 4611.2 Installed new Sensonich Propellor (customer supplied) Model: W72GK-44, S/N AM1999. Re-torque safety wire prop bolts twice. With respect to the work performed, this propeller is approved for return to service. Details of work formed are on file with Aircraft Service & Parts Corp. under work order: 3266. Bob Baker A&P 1639399 Total Time in Service Description Description		Aircraft Service & Parts Corp., 410 E. Bloom Book, DAVEDONIELD, CALLED DAVE CORP.			
With respect to the work performed, this propeller is approved for return to service. Details of work formed are on file with Aircraft Service & Parts Corp. under work order: 3266. Bob Baker A&P 1639399 Total Time in Service Description Description		N92041 Sensonich, W72GK-44, S/N; AM1999		August 28, 2025	
Bob Baker A&P 1639399 Total Time in Service Bescription Description	r:	Installed new Sensonich Propellor (customer supplied) Model: W72GK-44, S/N AM1999. Re-torque and safety wire prop bolts twice.			
Bob Baker A&P 1639399 Total Time in Service Because Bob Baker A&P 1639399 Description	ct Insp	With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Aircraft Service & Parts Corp. under work order: 3266.			
e: in Service	:	Bob Baker A&P 1639399 Bally Baker			
	r:		Description	văto, s	
	e:				
t inspection Time Since	t Inspec				

Propeller Record General Information Propeller Manufacturer SENSENICH	The second second second
odel 72 GK 44 (AM) 999) ub Series #	
te of Manufacture 2025	
	Serial #
Make/Model rcraft Installed On: PIPER J3 Cuß (8)	[18/25] 16474 N92041