

N85WL 5-10-2V PT6A-114A SN PCE 17493

HOBBS 5719.6

1. DRAIN OIL AND FUEL SYSTEM DISCONNECTION
LINES, FOUND CHIP DETECTOR BROKEN AT CASE
AND GEARBOX FULL OF SAND, COULD NOT
FULLY PRESERVE.

TERRY LOE HIGDON
/ m 24 12

ATP 2713082 IA