

# PROPELLER LOG BOOK




*SENSENICH PROPELLER MFG. CO.*  
Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

THIS LOG BOOK IS TO BE KEPT  
WITH THE PROPELLER  
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		 <p>Date: August 12, 2025            Propeller Model: 74DM6-0-58 SN# A65240 – Repitched factory new propeller from 60" to 58". This was the only work done. See form 8130-3 for details.</p> <p><b>MAINTENANCE RELEASE:</b> The component identified above was repaired and inspected in accordance with regulations of the FAA and was found airworthy for return to service for the work performed. Pertinent details of the repair are on file at this agency under work order number: ER-16771</p> <p>Approved by:             Shawn M. Young, 2747920 Repairman For:</p> <p>East Coast Propeller Service, Inc.            2079 Main Street            Lititz, PA 17543 Phone: 1-800-875-6377            email: <a href="mailto:ecps1998@gmail.com">ecps1998@gmail.com</a>            FAA Repair Station E65R064Y</p>	



Date: August 12, 2025

Propeller Model: 74DM6-0-58 SN# A65240 – Repitched factory new propeller from 60" to 58". This was the only work done. See form 8130-3 for details.

**MAINTENANCE RELEASE:** The component identified above was repaired and inspected in accordance with regulations of the FAA and was found airworthy for return to service for the work performed. Pertinent details of the repair are on file at this agency under work order number: ER-16771

Approved by

Shawn M. Young, 2747920 Repairman For:

East Coast Propeller Service, Inc.  
2079 Main Street  
Lititz, PA 17543 Phone: 1-800-875-6377  
email: [ecps1998@gmail.com](mailto:ecps1998@gmail.com)  
FAA Repair Station E65R064Y