

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL HC-E4N-30/E8501B-3.5

PROPELLER S/N HH 5147

LOGBOOK # \_\_\_\_\_



Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
11/24/15	-0-		INSTALLED THIS PROP ON PA46-SOUP SIN 4697018 N 388TW.
HR MTR	1247.0		INSTALLED NEW SPINNER. GROUND RUN UP CHECKED NORMAL.
			AP45096612 <i>S. Well</i>
			TEMMEL AIRCRAFT SERVICES LLC
6-4-2016			VISUALLY INSPECTED PROP, HUB AND BULKHEADS -OK. ICEIC BOGT OPERATION
HR MTR	1310.6		CHECKED -OK.
TT	63.6		
			AP45096612 <i>S. Well</i>
			TEMMEL AIRCRAFT SERVICES LLC

5-26-2017			PROP, SPINNER AND BULKHEADS VISUALLY INSPECTED -OK. ICEIC HUBS
HR MTR	1389.7		CHECKED PROP ICEIC OPERATION -OK.
TT	142.7		
			AP45096612 <i>S. Well</i>
			TEMMEL AIRCRAFT SERVICES LLC
4-6-2018			VISUALLY INSPECT PROP, SPINNER AND BULKHEADS. REPAIRED BETA RING BLOCK
HR MTR	1447.8		(A3026). ICEIC OPERATION CHECKED - FOUND DEFECTIVE TIME. REPAIRED TIME
TT	200.8		WITH NEW. OPERATION CHECKED NORMAL.
			AP45096612 <i>S. Well</i>
			TEMMEL AIRCRAFT SERVICES LLC