

New ENGINE Log Book



*The Standard*

**ENGINE LOG**

ASA-SE-2

The subject aircraft was involved in an incident / accident on  
1 / 1 rendering it a Constructive Total Loss as  
not repairable within its insured value. For further details  
refer to insurance claim:

613168123045

Signed USC

Date 10,20,23

AIG Aerospace Adjustment Services, Inc.

3500 Lenox Road, Suite 1100

Atlanta, GA. 30326

YEAR  
20 \_\_\_\_\_  
DATE

RECORDING  
TACH  
TIME

TODAY'S  
FLIGHT

TOTAL  
TIME IN  
SERVICE

**Description of Inspections, Tests, Repairs and Alterations**  
Entries must be endorsed with Name, Rating and Certificate Number of  
Technician or Repair Facility. (See back pages for other specific entries.)


Date 05-05-23 Tach 3519.0 SMOH 0.0 TTE 3549.1

Make Continental Model O-200- A-4-8

Serial #250030

Removed Engine sent out for overhaul.05-05-2023 re-  
installed Engine that was removed (see log book) Zero time  
since Major overhaul engine Serial# 250030. Installed  
Overhauled Alternator P# DOFF10300F. Ser# H-X02045.  
Magnetos 500 inspection completed Slick 4201 Ser#  
90090001 & 89030142.

I certify that this aircraft has been inspected in accordance  
with FAR 43, 13 appx D ANNUAL inspection and was  
determined to be in an air worthy condition as of this date.

  
Luther S. Turner A&P #3212114 IA