



#1 Ron

COMPONENT LOG CARD

PART NO. 76900-01802-106

NOMENCLATURE

ROLL ACTUATOR #1 FWD

SERIAL NO.

92020718

L/H
FWD

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]



UNITED TECHNOLOGIES
LIBRARY
AIRCRAFT

अ० १७१

COMPONENT LOCATION CARD

PART NO.	76900-01802-106
----------	-----------------

NOMENCLATURE AFCS ACTUATOR

SERIAL NO. 810759C

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]



COMPONENT LOG CARD

PART NO. 76900-01802-106

NOMENCLATURE Actuator, AFCS

SERIAL NO. 95040043

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]



SERIAL NO. : 0221046

OVERHAUL INTERVAL	
RETIREMENT TIME	

[illegible]



PART NO.	76900-01802-106
----------	-----------------

NOMENCLATURE #2 YAW Actuator

SERIAL NO.	95090118
------------	----------

[illegible]OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]

COMPONENT LOG CARD

Page 1 of 3

PART NO: 76361-04007-042

NOMENCLATURE: DRIVE SHAFT BEARING SUPPORT SERIAL NO: A348-00522

[illegible]

OVERHAUL INTERVAL: 5YR/3000HR

RETIREMENT TIME:

Helicopter Support Inc.

Services Division

ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT

Page 3 of 3

[illegible]

COMPONENT LOG CARD

PART NO: 76361-04007-042

NOMENCLATURE: T/D/S BEARING SUPPORT

SERIAL NO: A348-00451

[illegible]

OVERHAUL INTERVAL:

RETIREMENT TIME:

COMPONENT LOG CARD

PART NO: 76361-04007-042

NOMENCLATURE: T/D/S BEARING SUPPORT

SERIAL NO: A348-00450

[illegible]

OVERHAUL INTERVAL:

RETIREMENT TIME:

Helicopter Support Inc.

Services Division

ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT

Page 3 of 3

[illegible]



PART NO. 76107-08100-243

NOMENCLATURE M/R Lower 3P Bifilar

SERIAL NO. A173-00153

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME



PART NO.

76107-08100-042

NOMENCLATURE

5P
BIFILAR ASSEMBLY

SERIAL NO.

NONE

[illegible]

1. MAJOR COMPONENT

BIFILAR ASSEMBLY

2. PART NUMBER

76107-08100-042

3. SERIAL NUMBER Page

NONE

[illegible]

COMPONENT LOG CARD

PART NO.

VCT 1518C

NOMENCLATURE

Oil Cooler Fan

SERIAL NO.

60

[illegible]

OVERHAUL INTERVAL



SERIAL NO.	1612
------------	------

OVERHAUL INTERVAL

RETIREMENT TIME



SERIAL NO. 1577

RETIREMENT TIME





Page 1 of 2

76358-05600-042

NOMENCLATURE

TAIL GEAR BOX

SERIAL NO.

A239-00022

RETIREMENT TIME

COMPONENT MAINTENANCE RECORD

SIKORSKY AIRCRAFT

ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT LC Page 2 of 2

Page 2 of 2

[illegible]


Air Methods

HISTORICAL SERVICE RECORD

LIFE LIMIT OF COMPONENT	OVERHAUL	HRS_1000	RIN	N/A	MONTHS	N/A	RETIRE	HRS.	RIN	N/A	MONTHS	N/A
--------------------------------	-----------------	-----------------	------------	------------	---------------	------------	---------------	-------------	------------	------------	---------------	------------

“COMPONENT HISTORY”

[illegible]

STARTER GENERATOR

23081-043

Y0327

1

1

 $\#_2 E_N$ 

COMPONENT
LEVEL

HISTORICAL SERVICE RECORD

LIFE LIMIT OF COMPONENT	OVERHAUL	HRS. _____ RIN _____ N/A _____ MONTHS _____ N/A _____	RETIRE	HRS. _____ RIN _____ N/A _____ MONTHS _____ N/A _____
-------------------------	----------	---	--------	---

[illegible]

"COMPONENT HISTORY"

[illegible]

COMPONENT LOG CARD

Serial No. | A231-00130

<u>OVERHAUL INTERVAL</u>	3250 HRS.
--------------------------	-----------

RETIREMENT TIME

231-91
SCA
C-86

VA-HSNA #548 (0608)



76070-35012-045



Page 1 of 2

PART NO.

76351-09600-044

NOMENCLATURE

MAIN GEAR BOX

SERIAL NO.

A231-00130

SA 7343-9 REV A.

OVERHAUL INTERVAL

RETIREMENT TIME

DATE	REPAIRS OR OVERHAULS	SIGNATURE	CERTIFICATE NO.
28MAY02	OVERHAULED AT TT: 3258.3 HRS. I/A/W MANUAL SA4047-76-7-8 REV. 6 AND S.O. #E3591-001. "FULL LOAD TESTED" AND ACCEPTED I/A/W ATP 23118. COMPLIED WITH THE FOLLOWING DIRECTIVES: ASB 76-66-29 REV. A, AD 2001-10-06 AMD. 39-12232 ASB #76-66-32 A(319),	<i>[Signature]</i> SIKORSKY 224	SIKORSKY A/C OVERHAUL DEPT. CERTIFIED REPAIR STATION A1R004K
9 Sep. 02	Remove Left and Right Hand lower Jaws replaced O' Rings, Snap rings & Y3 CAULK.	<i>[Signature]</i>	002533779
30 Sept 2005	CSN 76-205- Main Gearbox Unused Accessory drive unit removal of. (customer option) Complied with @ A/C 7534.5hrs MGB TSN 5006.9/ TSO 1748.6	<i>[Signature]</i> J. Samuels	AAG WO#2296 CRS#-AYPR340S
15 Nov 2005	Re-installed Accessory Drive as required @ A/C tt 7538.0hrs	<i>[Signature]</i>	AYPR340S
20 JAN 2006	REPAIRED, UPPER & LOWER BULL GEAR SUPPORT BEARINGS (323W15-103/103) REPLACED IAW SA4047-76-7-8, CHG 8-30 SEPCT, SE76-66-40, SE76-66-41, SE76-66-42, CSN 76-24A COMPLIED WITH FULL LOAD TEST, SEALANT & PAINT REQUIRED PRIOR TO RETURN TO SERVICE. ALL ABOVE WORK PERFORMED ON HELICOPTER N104513787 AT TT: 5010.4 HRS. REQUIRES FWA INT. RESTORATION SCHEDULE. NEXT O/H AUL.	<i>[Signature]</i> COMP-3 82-00	AMO 82-00
10 FEB 06	REPAIR CONSISTED OF PREP FOR TEST & POST TEST MAINT. ONLY. NO OTHER WORK PERFORMED. ALL MAINT. PERFORMED IAW SIK S76 OVH MAN SA4047-76-7-8 CHG 8 DTD 30 SEPT 04 & SIK ATP PROCEDURES. FULL LOAD TEST PERFORMED BY SIK ACFT IAW ATP 23118 REV N REF MO FY751-002 DTD 01 FEB 06. ACOUSTIC TEST PERFORMED AND ACCEPTED BY SIK ACFT. W/O 24313 TT: 5010.4, TSO: 1752.1, TSR: 0.0	<i>[Signature]</i>	TT5R235N
2/27/2007	REP CONSISTED OF REMOVAL & REPLACEMENT OF LOWER MAST SEAL, PREP FOR TEST & POST TEST MAINTENANCE IAW SIK S76 OVH MAN SA4047-76-7-8, CHG 9 DTD 3/31/2006. LEAK CHECK PERFORMED BY SIK ACFT IAW ATP 23118 REV P, ON 2/25/07. COMPLIED WITH ASB 76-66-43, ASB 76-66-44A, ASB 76-66-45. W/O 29378. TT: 5372.3 TSO: 2114.0, TSR: 0.00.	<i>[Signature]</i>	TT5R235N

ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONE

3. SERIAL NUMBER

76351-09600-044

A231-00130

[illegible]

1. MAJOR COMPONENT		2. PART NUMBER		3. SERIAL NUMBER		4. REASON FOR REMOVAL	
MAIN GEAR BOX		76351-09600-044		A231-00130			
PART NAME A.	PART NUMBER B.	SERIAL NUMBER C.	DATE D.	PERFORM. ORGAN- IZATION E.	TIME SINCE NEW ON ITEM SHOWN IN BLOCK 1	TIME SINCE NEW ON LIFE LIMITED ITEMS SHOWN IN COLUMN A. INSTALLED	REMOVED
Quill Shaft	76351-09628-101	A212-00113	3-08-93	Sikorsky	NEW	NEW	
Spline Shaft	76351-09626-101	A211-00124	"	"	"	"	
Upper Housing	76351-09002-053	A001-00215	"	"	"	"	
Main Shaft	76351-09630-041	C213-00087	"	"	"	"	
Swashplate Guide	76351-09029-101	A028-00203	"	"	"	"	
Closed							



Page 1 of 2

A231-00130

closed



Sikorsky
A United Technologies Company

COMPONENT LOG CARD

PART NO. 76209-03001-058

NOMENCLATURE

MAIN GEAR BOX SUPPORT STRUCTURE FITTING R/H

SERIAL NO.

F021-00033

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME



PART NO. 76209-03001-057

NOMENCLATURE

MAIN GEAR BOX SUPPORT
STRUCTURE FITTING L/H

SERIAL NO.	C021-00808
------------	------------

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME



Sikorsky

A United Technologies Company

COMPONENT G CARD

Page 1 of 2

PART NO.

76250-02500-101

NOMENCLATURE

L/H
MAIN LANDING GEAR

SERIAL NO.

T-9134

[illegible]

SA 7343-9 REV A.

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]

[illegible]



2071-235

NOMENCLATURE

ROD END

УА

SERIAL NO.

CPT 0291 BIC

[illegible]

COMPONENT MAINTENANCE RECORD

[illegible]



PART NO.

1945G200-01

NOMENCLATURE

L/H
MAIN LANDING GEAR ACTUATOR

SERIAL NO.

CPT1297JK

[illegible]

SA 7343-9 REV A.

OVERHAUL INTERVAL

RETIREMENT TIME

ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENTS Page 2 of 2

[illegible]

SERIAL NO. T-9153

SA 7343-9 REV A.

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]



PART NO. 76103-08010-049 NOMENCLATURE MAIN ROTOR HUB SERIAL NO. A027-01022

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME



PART NO.

76000-09500-046

NOMENCLATURE

MAIN ROTOR HEAD AND
MAIN TRANSMISSION
QUICK CHANGE UNIT

SERIAL NO.

76COMMON-00020

RETIREMENT TIME

M. L. G. ACTIVATOR

COMPONENT HISTORICAL RECORD

REPLACEMENT CHR

[illegible]

SUB-COMPONENT HISTORICAL RECORD

[illegible]

P/N

1945-6200-4

W/S

CPC 0391 7K

COMPONENT	MLC	ALLOCATION	AMT

[illegible]



MAJOR COMPONENT:

NOSE LANDING GEAR

2. PART NUMBER:

76250-01700-043

3. SERIAL NUMBER:

T-9121

[illegible]

[illegible]



PART NO.

2070A200

NOMENCLATURE

NOSE LANDING GEAR ACTUATOR

SERIAL NO.

CPT0658ADE

SA 7343-9 REV A.

OVERHAUL INTERVAL

RETIREMENT TIME

)

PART NO. 2070A200

NOMENCLATURE NOSE LANDING GEAR ACTUATOR

SERIAL NO. CPT0658ADE

[illegible]

SA 7343-9 REV A.

OVERHAUL INTERVAL

RETIREMENT TIME



AS4

782500-1

NOMENCLATURE

PRIMARY SERVO - ~~FORWARD~~

SERIAL NO.

B345-00279

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]

Overhaul : _____

Component Log Card

Part Number : 76400-00034-056

Nomenclature : Servo Input Tube

Serial No. : 760477-1

[illegible]

Component Maintenance Record

[illegible]

Overhaul : _____

Component Log Card

Part Number : 76400-00034-056

Nomenclature : Servo Input Tube

Serial No. : 760477-2

[illegible]

Component Maintenance Record

[illegible]

Overhaul : _____

Component Log Card

Part Number : 76400-00034-056

Nomenclature : Servo Input Tube

Serial No. : 760477-3

[illegible]

Component Maintenance Record

[illegible]

B346-00150

RETIREMENT TIME

COMPONENT MAINTENANCE RECORD

[illegible]



~~SECT~~ 12

PAGE:
Page 1 of 2

PART NO: 76102-08000-061 Blue NOMENCLATURE: SPINDLE ASSY. SERIAL NO: N/A

[illegible]

REPAIR INTERVAL

OVERHAUL INTERVAL

RETIREMENT TIME



ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT

[illegible]



ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT

SECTION:

PAGE:

Page 2 of 2

1. MAJOR COMPONENT: SPINDLE ASSY.			2. PART NUMBER: 76102-08000-061			3. SERIAL NUMBER: N/A		
PART NAME A	PART NUMBER B	SERIAL NUMBER C	DATE D	PERFORM. ORGAN- IZATION E	TIME SINCE NEW ON ITEM SHOWN IN BLOCK 1	TIME SINCE NEW ON LIFE LIMITED ITEMS SHOW IN COLUMN A.		REASON FOR REMOVAL
						INSTALLED	REMOVED	
NOTES:								



SERIAL NO: N/A

DATE	REPAIRS OR OVERHAULS	SIGNATURE	CERTIFICATE NO.
10/14/09	1250 hour Insp	Fawad Money	AP 3221311

TECHNICAL DIRECTIVES

[illegible]



SECTION:

PAGE:

Page 1 of 2

PART NO: 76102-08000-061 Yellow

NOMENCLATURE: SPINDLE ASSY.

SERIAL NO: N/A

[illegible]

REPAIR INTERVAL

OVERHAUL INTERVAL

RETIREMENT TIME



1. MAJOR COMPONENT: SPINDLE ASSY.			2. PART NUMBER: 76102-08000-061			3. SERIAL NUMBER: N/A		
PART NAME A	PART NUMBER B	SERIAL NUMBER C	DATE D	PERFORM. ORGAN- IZATION E	TIME SINCE NEW ON ITEM SHOWN IN BLOCK 1	TIME SINCE NEW ON LIFE LIMITED ITEMS SHOW IN COLUMN A.		REASON FOR REMOVAL
						INSTALLED	REMOVED	
NOTES:								



Sik sky

A United Technologies Company

COMPONENT MAINTENANCE RECORD

PART NO: 76102-08000-061

NOMENCLATURE: SPINDLE ASSY.

SERIAL NO: N/A

DATE	REPAIRS OR OVERHAULS	SIGNATURE	CERTIFICATE NO.
10/14/09	1250 hr Insp	Jared Money	HP 3221311

TECHNICAL DIRECTIVES

[illegible]



SECRET

PAGE:
Page 1 of 2

SERIAL NO: N/A

DATE:10/18/05

RETIREMENT TIME

2. PART NUMBER:

3. SERIAL NUMBER:

76102-08000-061

N/A

[illegible]



ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT

SECTION:

1. MAJOR COMPONENT:			2. PART NUMBER:			3. SERIAL NUMBER:		
SPINDLE ASSY.			76102-08000-061			N/A		
PART NAME A	PART NUMBER B	SERIAL NUMBER C	DATE D	PERFORM. ORGAN- IZATION E	TIME SINCE NEW ON ITEM SHOWN IN BLOCK 1	TIME SINCE NEW ON LIFE LIMITED ITEMS SHOW IN COLUMN A.		REASON FOR REMOVAL
						INSTALLED	REMOVED	
NOTES:								

SERIAL NO: N/A

DATE	REPAIRS OR OVERHAULS	SIGNATURE	CERTIFICATE NO.
10/14/09	1250 hour Insp	Jared Money	AP 3221311

TECHNICAL DIRECTIVES

[illegible]

PART NO: 76102-08000-061

Red

NOMENCLATURE: SPINDLE ASSY.

SERIAL NO: N/A

[illegible]

REPAIR INTERVAL

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]



SECTION:

PAGE:
Page 2 of 2

[illegible]

SERIAL NO: N/A

[illegible]

TECHNICAL DIRECTIVES

[illegible]



SERIAL NO.	A253-00191
------------	------------

OVERHAUL INTERVAL

RETIREMENT TIME

[illegible]



**UNITED
TECHNOLOGIES
SIKORSKY
AIRCRAFT**



COMPONENT LOG CARD

PART NO.	76209-24004-043
----------	-----------------

NOMENCLATURE

STABILIZER SUPPORT FITTING

SERIAL NO. A317-00159

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME

SIKORSKY HELICOPTER LOG

MODEL NO. S-76C

REGISTRATION NO. N176AE

SERIAL NO. 760477



Sikorsky

A United Technologies Company

Stratford, Connecticut U.S.A.



PART NO. 76102-05001-047

NOMENCLATURE

TAIL ROTOR OUTBOARD RETAINING PLATE

SERIAL NO.

A131-00557

[illegible]

OVERHAUL INTERVAL

RETIRED TIME

PART NO. 76101-05501-042

I/B
NOMENCLATURE

TAIL ROTOR BLADE

SERIAL NO. A245-00396

[illegible]

OVERHAUL INTERVAL

RETIREMENT TIME

To: 13056972480

9-2007 1:12 From:

DATE	REPAIRS OR OVERHAULS	SIGNATURE	CERTIFICATE NO.
	Manufacture Date of Tail Rotor Blade #1: 4-23-97 #2: 5-13-97		
	Manufacture Date of Spar: 12-09-96		
	Manufacture Date of T/R Blade Assy.: 8-13-97		
19 August 1997	A.S.B. 76-65-46 - Tail Rotor Blade, One Time Inspection of	<i>Natalie Williams</i>	SIKORSKY AIRCRAFT QUALITY ASSURANCE
	A.D. 89-07-12, Amd. 39-6171 - To Prevent Possible Failure of the T/R Horn (TIME COMPLIANCE REFER TO AD)		
11/19/01	Inspected I.A.W. SA 4047-76-2-1 900 Hour inspection Checklist, item 2, 1500 Hour Inspection Checklist Zone 3, item 4, and CMM SA 4047-76-5. X-rayed both paddles for water with no defects indicated. Replace the spar plug per IAC-8110-0393, repaired paddle B trailing edge per CMM procedure no. 18, replaced both poly strips per IAC-8110-0326, repaired paddle B fairing per CMM procedure no. 2, installed supplemental polyurethane abrasion strips per IAC-8110-0518, reassembled center hardware per MM 65-21-00, replaced both fairing boots per MM 65-21-00, refinished the paint per 8110-IAC-S76T-003, static balanced per 8110-IAC-S76T-002. T.T.S.N. 27409 IAC Ltd. Co. YIVR004J 11/19/2001 Jay Stichter		
7/28/06	7/28/06 W.O. 35820 X-rayed per MIL-STD-453, ultrasonic inspected per QATI 3098, performed all scheduled inspections up to and including 1500 hr. inspection in accordance with composite MM 4047-76-5 rev. 12 table 3-2 and MM 4047-76-2 rev. 35, 65-21-00 and 65-21-01, complied with AD 94-14-20 & 89-07-12 and ASB 76-65-40, 76-65-43, 76-65-46 & 76-65-60. Replaced both secondary polystrips per SA 4047-76-5 section 4-16 rev. 12; Replaced spar plug per RS-022L-II. Replaced and reassembled center hardware per MM SA 4047-76-2 rev. 35 section 65-21-01. Refinished paint per drwg. 76101-05020. Static balanced per drwg. 76101-11528 amdt. 20 and drwg. 76101-11529 rev. C @ T.T. 5056.0		

7. MAJOR COMPONENT

2. PAR NUMBER

3. SERIAL NUMBER

TAIL ROTOR BLADE

76101-05501-042

A245-00396

[illegible]

To: 130560

11:12 From:

I/B

Page 1 of 3

SERIAL NO: A245-00394

1

RETIREMENT TIME: 20,000

PART NO: 76101-05501-042

NOMENCLATURE: Tail Rotor Blade

SERIAL NO: A245-00394

Page 2 of 3

[illegible]

ASSOCIATE LIFE LIMITED EQUIPMENT TO MAJOR COMPONENT

[illegible]



Page 1 of 2

SERIAL NO. A245-00394

FOR READING ONLY

OVERHAUL INTERVAL RETIREMENT TIME



Sikorsky

A United Technologies Company

[illegible]



PART NO.

76101-05501-042

o/B
NOMENCLATURE

TAIL ROTOR BLADE

SERIAL NO.

A245-00395

RETIREMENT TIME

COMPONENT MAINTENANCE RECORD

DATE	REPAIRS OR OVERHAULS	SIGNATURE	CERTIFICATE NO.
	Manufacture Date of Tail Rotor Blade #1: 4-22-97 #2: 5-29-97		
	Manufacture Date of Spar: 3-18-97 Manufacture Date of T/R Blade Assy.: 7-30-97		
1 August 1997	A.S.B. 76-65-46 - Tail Rotor Blade, One Time Inspection of	Natalie Williams	SIKORSKY AIRCRAFT QUALITY ASSURANCE
	A.D. 89-07-12, Amd. 39-6171 - To Prevent Possible Failure of the T/R Horn (TIME COMPLIANCE REFER TO AD)		
2/12/2002	Inspected I.A.W. SA 4047-76C-2-1 - 900 Hour Inspection Checklist, item 2, 1500 Hour Inspection Checklist Zone 3, item 4, and CMM SA 4047-76-5. X-rayed both paddles for water with no defects indicated. Reinstalled both fairings and reinstalled all four pivot bearings and reassembled center hardware per MM 65-21-00, replaced both fairing boots per MM 65-21-01, installed supplemental poly strips per IAC-8110-0518, refinished the paint per 8110-IAC-S76T-003, static balanced per 8110-IAC-S76T-002 W.O 5065 IAC Ltd. Co. YTVR004J 02/12/2002 Jay Stichter	IAC Ltd., Co. YIVR004J	
	8-6-07 W/O 35819 X-rayed per MIL-STD-453, ultrasonic inspected per QATI 3098 & 3261, performed all scheduled inspections up to and including 1500 hr. inspection in accordance with composite MM 4047-76-5 rev. 12 table 3-2 and MM 4047-76-2 rev. 35, 65-21-00 and 65-21-01, complied with AD 94-14-20 R-1 & 89-07-12, ASB 76-65-35, 76-65-40A, 76-65-43B, 76-65-46 & 76-65-60; Replaced both secondary poly strips per SA 4047-76-5 section 4-16 rev. 12; Replaced spar with S/N A293-03276 and removed & reinstalled both paddles per RS-022L-III; Repaired 1 ea fairing per RS-044-I; Replaced both primary poly strips per RS-018M-I; Replaced and reassembled center hardware, 4 ea pivot bearings and 1 ea fairings per MM SA 4047-76-2 rev. 35 section 65-21-01; Refinished paint per drwg. 76101-05020; Static balanced per drwg. 76101-11528 amdt. 20 and drwg. 76101-11529 rev. C @ T.T. 5208.4		CTI RWIR467K

[illegible]



12/20/41

Page 1 of 2

PART NO.

76101-05501-042

NOMENCLATURE

TAIL ROTOR BLADE

SERIAL NO.

A245-00217

O/B

SA 7343-9 REV A

✓✓✓✓

[illegible]