



H

Year: PROP MODEL: 2A34C203-C/ 90DCA-8
PROP S/N: 080070
Date: REG NO: N182VE
WORK ORDER: HND1821-01-2023




Lone Mountain Aviation, Inc.
Repair Station No. L90D473Y
1456 Jet Stream Drive
Henderson, NV 89052

DATE: 4/1/2023
A/C TSN: 8151.76
PROP TT: 908.86
TACH: 4628.76

Next Due: Prop Entries

I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

Year: DATE: 4/1/2023
Date: SIGNED:  Work Order: HND1821-01-2023
Next Due: Jamila Aarab Certified Repair Station No. L90D473Y Printed by EBis 3 (datcomedia.com)

		Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

ALTER

MAKE: Cessna
MODEL: 182L
S/N: 18258911
REG. NO: N182VE
PROP MAKE: MCCAULEY
PROP MODEL: 2A34C203-C/
90DCA-8
ENGINE SN: 834225-R



Lone Mountain Aviation, Inc.
FAA Cert: L90D473Y
1456 Jet Stream Drive
Henderson, NV 89052

W/O #: HND2477-11-2023
DATE: 07-10-2024
A/C TT: 8164.1
Tach: 4641.1
Propeller TT: 921.2

Propeller Entries

I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above WO number.

DATE: 07-10-2024
Date: SIGNED:  WORK ORDER: HND2477-11-2023
Jamila Aarab Certified Repair Station No. L90D473Y Printed by EBIS (EBISCloud.com)

		Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

REPAIRS AND ALTERATIONS



Boulder City Airport
Boulder City, NV

Date 12/1/2017
Manufacturer McCauley
Model 2A34C203-C
TSMO

N182VE
S/N 080070
Tach 4562.3
Prop TT 816.2

Propeller Log Book

Performed a 100 hour inspection IAW Cessna and McCauley service and maintenance manual. Performed all service and lube items due. Dressed leading edge of propeller. Repainted the face of the blades with flat propeller epoxy. All ADs as of this date have been complied with. See AD compliance sheet. I certify that this propeller has been inspected IAW a 100 hour inspection and is found to be in an airworthy condition.

Paul Schulz AP / IA 3417346



Boulder City Airport
Boulder City, NV

Date 11/7/2016
Manufacturer McCauley
Model 2A34C203-C
TSMO

Propeller Log Book

Performed a 100 hour inspection IAW Cessna and McCauley service and maintenance manual. Performed all service and lube items due. Dressed leading edge of propeller. Repainted the face of the blades with flat propeller epoxy. All ADs as of this date have been complied with. See AD compliance sheet. I certify that this propeller has been inspected IAW a 100 hour inspection and is found to be in an airworthy condition.

Paul Schulz AP / IA 3417346

HUB & BLADE INSPECTIONS SERVICE AND MAINTENANCE

Year: _____

Date: _____

Next Inspect Due: _____

N182VE
S/N 080070
Tach 4536.1
Prop TT 816.2

Swiss

Year: _____

Date: _____

Next Inspect Due: _____

Year: _____

Date: _____

Next Inspect Due: _____

Propeller Record General Information

Propeller Manufacturer MCCAULEY

Model 7A34C203-C Type _____

Hub Series # 080070 Blade # _____

Date of Manufacture _____

Make/Model

Serial #

Aircraft Installed On: N182VF @ 37199 TACH 9/24/10

18258911

