



*The Standard*

# PROPELLER LOG

ASA-SP-L

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**


CHASAERO LLC. 19299 AIRPORT LANE WARSAW, MO 65355  
(660) 641-4506

**PROPELLER LOGBOOK ENTRY 21134C**

REG: N2040X MAKE: MCCAULEY MODEL: 2S34C S/N: 750872  
DATE: 07/14/2022 TACH: 4115.8 SPOH:

1. COMPLIED WITH 100HR INSPECTION LAW FAR 43 APPENDIX D

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED LAW FAR 43 APPENDIX D FOR A 100 HOUR INSPECTION AND FOUND TO BE AIRWORTHY.

 Date: 07/14/2022  
Chas L. Perkins 3097271 A&P


CHASAERO LLC. 19299 AIRPORT LANE WARSAW, MO 65355  
(660) 641-4506

**PROPELLER LOGBOOK ENTRY**

REG: N2040X MAKE: MCCAULEY MODEL: 2S34C S/N: 750872  
DATE: 08/11/2025 TACH: 4238.22 SPOH:

1. COMPLIED WITH 100HR INSPECTION LAW FAR 43 APPENDIX D

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED LAW FAR 43 APPENDIX D FOR A 100 HOUR INSPECTION AND FOUND TO BE AIRWORTHY.

 Date: 08/11/2025  
Chas L. Perkins 3097271 A&P

**Mech. Cert. # or Repair Station #**

CHASAERO LLC. 19299 AIRPORT LANE WARSAW, MO 65355  
(660) 641-4506


**AND ALTERATIONS**

**PROPELLER LOGBOOK ENTRY**

REG: N2040X MAKE: MCCAULEY MODEL: 2S34C S/N: 750872  
DATE: 07/25/2024 TACH: 4240.87 SPOH:

1. COMPLIED WITH 100HR INSPECTION LAW FAR 43 APPENDIX D

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED LAW FAR 43 APPENDIX D FOR A 100 HOUR INSPECTION AND FOUND TO BE AIRWORTHY.

 Date: 07/25/2024  
Chas L. Perkins 3097271 A&P

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____