

THE **adlog**TM AIRCRAFT
MAINTENANCE
RECORDKEEPING
SYSTEM

~~N33180~~ N7199K

5/4/2018-

**PROPELLER
MAINTENANCE
RECORDS**

The subject aircraft was involved in an incident / accident on 9/3/2023 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: .

Signed: ***Underwriters Salvage Company***

Date: **12/15/2023**

AIG Aerospace Adjustment Services, Inc.

3500 Lenox Road, Suite 1100

Atlanta, GA 30326

N7199K

PROPELLER

Tach: 6458.1

McCauley 1A200/FA8236

PSMOH: 989.6

PROP TT: 5,069.2

AUG 08, 2023

S/N ACC46509A


Page No. _____

DESCRIPTION OF WORK PERFORMED—
IDENTIFICATION NO. OF PERSON PERFORMING WORK

from previous page

Inspected propeller for nicks, cuts, and general condition. Checked prop bolts and mount bushings for evidence of wear and cracks, none found. Verified safety wire installed and secure, dressed and painted propeller as required.

I certify that this propeller was inspected in reference to VAN WAGNER AERIAL MEDIA checklist, FAR Part 43 Appendix D, and McCauley installation instructions, 100 hour inspection and was determined to be in an airworthy condition.


Juan Arevalo A&P 3285120 IA

SUB-TOTALS this page


Van Wagner Aerial Media, LLC
1600 East Airport Road
Hollywood, FL 33023
954-989-2086
Propeller

Aircraft: Piper PA18 Reg #: N7199K Serial #: 18-222
Prop Model: McCauley 1A200/FA8236 S/N#: ACC46509A

Date: 04/26/2023 Tach: 6280.9 PropTT: 4892 TSMOH: 812.4
Inspected propeller for nicks, cuts, and general condition. Checked prop bolts and mount bushings for evidence of wear and cracks--None found. Verified safety wire installed and secure, dressed and painted propeller as required.

I Certify that this propeller was inspected in reference to VAN WAGNER AERIAL MEDIA checklist, FAR 43 Appendix D, and McCauley installation instructions annual inspection and was determined to be in airworthy condition.

Name: Juan Arevalo
A&P: 3285120 IA



N7199K

PROPELLER

Tach: 6357.2

McCauley 1A200/FA8236

PSMOH: 888.7

PROP TT: 4,968.3

S/N ACC46509A


JUNE 29, 2023

Inspected propeller for nicks, cuts, and general condition. Checked prop bolts and mount bushings for evidence of wear and cracks, none found. Verified safety wire installed and secure, dressed and painted propeller as required.

I certify that this propeller was inspected in reference to VAN WAGNER AERIAL MEDIA checklist, FAR Part 43 Appendix D, and McCauley installation instructions, 100 hour inspection and was determined to be in an airworthy condition.



Juan Arevalo A&P 3285120 IA

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
				<div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">VAN WAGNER AERIAL MEDIA LLC. 1600 EAST AIRPORT ROAD HOLLYWOOD FL 33023 954-989-2086</p> <p>Model: J5 Registration: N-33180 S/N# 5-456 PROPELLER Propeller Model: McCauley: 1A200/FA8236 S/N: ACC46509A Date: 05/04/18 Tach: 4834.7 Prop TT: 3907.7 TTSOH: 3907.7</p> <p>I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW FAR 43 APPENDIX D AND VAN WAGNER 100 HR. INSPECTION CHECKLIST AND WAS DETERMINED TO BE AIRWORTHY-END-</p> <p><i>ANDREW TOKICH</i> A&P 3831050 <i>Andrew Tokich</i></p> </div>
6/1/18	3929.5	3929.5	4856.5	S/N ACC46509A REMOVED + ROUTED FOR OVERHAUL. <i>for 591261081A P</i>
8/02/18				<div style="border: 1px solid black; padding: 5px; text-align: center;">  <p>AVIATION PROPELLERS, INC. PROPELLER LOG BOOK ENTRY STICKER</p> <p>August 2, 2018 Fixpitch Propeller serial number ACC46509A was Overhauled IAW McCauley Propeller manuals: 730720R6, SPM100R6. AD Notes: N/A. Service Bulletins: N/A. A copy of the work order issued. Original FAA Form 8130-3 and propeller log book entry sticker issued. Propeller model number 1A200/FA8236</p> <p>Propeller times are: TTSN: 3929.5 TSO 0.0 Work accomplished by Aviation Propellers, Inc, 12970 Port Said Road, Opa Locka, Florida, 33054, Repair Station ME4R359M, under Work Order Number 44879A.</p> <p style="text-align: right;"><i>Jason H. Gato</i> Chief Inspector</p> </div>
8/22/18	3929.5	0.0		<p>08/22/2018 N7199K Eng S/N L-15353-36A Tach 5318.4</p> <p>Removed propeller 1A200/FA8236 for O/H ser# AAJ46003 Installed O/H propeller 1A200FA8236 ser# ACC46509A</p> <p>Test flew ; no noticeable vibration. Returned to service.</p> <p>Douglas Libby <i>Douglas Libby</i> A&P 3492594 IA</p>
				SUB-TOTALS this page
				TOTALS -Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
08/29/2018				<p style="text-align: right;">PTSMOH: 28.4 PTT: 34679 Tach 5356.8</p> <p style="text-align: center;">N7199K PSN: ACC46509A</p> <p>I certify that this propeller has been inspected IAW a 100 hour inspection as per VWAM Inspection Checklist and was determined to be in an airworthy condition</p> <p style="text-align: right;"><i>Douglas Libby</i> Douglas Libby A&P 3492594 IA</p>
				<div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">VAN WAGNER AERIAL MEDIA LLC. 1600 EAST AIRPORT ROAD HOLLYWOOD FL 33023 954-989-2086</p> <p>Aircraft: N-7199K Serial Number: 18-222</p> <p>Engine Model: O-0360-C2A S/N: L-15353-36A Prop Model: 1A200/FA8236 PS/N: ACC46509A</p> <p>Date: 12/20/18 Tach: 5468.50 ETT: 11121.9 ETSMOH: 1925.7 AFTT: 9695.5 PTT: 4079.6 PTSMOH: 150.1</p> <p>REMOVED ENGINE AND PROPELLER FOR COMPANY COVENIENCE. -END-</p> <p><i>ANDREW TOKICH</i> A&P 3831050 <i>Andrew Tokich</i></p> </div>
04/12/2021				<p>MCCAULEY 1A200/8236 S/N ACC46509A INSTALLED ON N7199K</p> <p>TACH 5468.5 TT 4079.6 TTSOH 150.1</p> <p>THIS PROPELLER WAS REMOVED AND REINSTALLED ON THIS AIRCRAFT USING MCCAULEY INSTALLATION DOCUMENTS. I HAVE INSPECTED THIS PROPELLER USING VAN WAGNER AERIAL MEDIA CHECKLIST, FAR 43 APPENDIX D ANNUAL INSPECTION AND FIND IT AIRWORTHY. 591261081A. <i>John</i></p>
				<p style="text-align: center;">Van Wagner Aerial Media, LLC 1600 East Airport Road Hollywood, FL 33023 954-989-2086</p> <p style="text-align: center;">Propeller</p> <p>Aircraft: Piper PA18 Reg #: N7199K Serial #: 18-222 Prop Model: McCauley 1A200/FA8236 S/N#: ACC46509A <i>248.3</i> Date: 07/24/2021 Tach: 5566.7 Prop TT: <i>4177.8</i> TSMOH: <i>00002</i></p> <p>Inspected propeller for nicks, cuts, and general condition. Checked prop bolts and mount bushings for evidence of ware and cracks--None found. Verified safety wire installed and secure. dressed and painted propeller as required.</p> <p>I certify that this propeller was inspected IAW FAR 43 Appendix D 100Hr Inspection and was determined to be in airworthy condition.</p> <p style="text-align: right;">-END- <i>Ruben Sandoval</i> Name: Ruben Sandoval A&P: 3676074 IA</p>



PROPELLER MAINTENANCE RECORDS

Log No. _____

Aircraft Registration No. N33180

Propeller Manufacturer MCCAULEY

Hub Model 1A200

Blade Design No. FAB236

Hub Serial No. ACC46509A

Blade Serial No's.

- 1. _____
- 2. _____
- 3. _____
- 4. _____

Pitch Range:

High _____ Low _____

Feather _____ Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

Date installed on aircraft _____

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

- Right Left
- Front Rear

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

www.adlog.com

P.O. Box 1359 / Southold, NY 11971-0965

(631) 765-9375

1-800-235-6444

FAX: (631) 765-9359