



EAST COAST PROPELLER SERVICE INC.

# PROPELLER LOGBOOK

PROPELLER MODEL B3D32C412-C

PROPELLER S/N 992582

LOG BOOK # \_\_\_\_\_



Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	----------------------	------------	---



Date: March 17, 2022

Propeller Model B3D32C412-C/G-82NDA-5 Serial Number 992582 was overhauled this date. See form 8130-3 for details.

**MAINTENANCE RELEASE:** The component identified above was repaired and inspected in accordance with regulations of the FAA and was found airworthy for return to service for the work performed. Pertinent details of the repair are on file at this agency under work order number: ER-15007

Approved by: \_\_\_\_\_

Shawn M. Young 2747920 Repairman for:

East Coast Propeller Service, Inc.  
2079 Main Street  
Lititz, PA 17543 Phone: 1-800-875-6377  
email: [eastcoastprop@dejazzd.com](mailto:eastcoastprop@dejazzd.com)  
FAA Repair Station E65R064Y

--	--	--	--	--

--	--	--	--	--

Somerset Air Service, Inc.  
150 Airport Rd Bedminster, NJ 07921 Tel: (908) 722-8251 somersetshop@gmail.com

8/3/2022 N6359P TACH 3059 AFTT 3059 McCAULEY B3D32C412-C/G-82NDA-5 S/N 992582

REMOVE PROPELLER AND SEND TO EAST COAST PROPELLER SERVICE FOR OVERHAUL.  
INSTALL PROPELLER AFTER OVERHAUL.  
McCAULEY PROPELLER GOVERNOR M/N DC290D1-K/T34 S/N 991378 WAS SENT TO H&H TRIAD FOR OVERHAUL. INSTALL OVERHAULED PROP GOVERNOR.

I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

John Bartley AP 3117495 IA John Bartley AP3117495 IA

Somerset Air Service, Inc. 150 Airport Rd Bedminster, NJ 07921  
Tel. (908) 722-8251 somersetshop@gmail.com

12/13/2023 N6359P TACH 3085 PTSOH: 26.0 McCAULEY B3D32C412-C/G-82NDA-5 S/N 992582

Inspect, file and paint prop. Inspect hub for leaks / defects

I certify that this ame has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition

John Bartley AP 3117495 IA John Bartley AP3117495 IA

# PROPELLER MAINTENANCE RECORD

Position \_\_\_\_\_

Propeller Model B3D32C412-C

Propeller S/N 992582

Blade Design G-82NDA-5

Blade S/N's

No. 1 TC 314

No. 2 TC 343

No. 3 TC 353

No. 4 —

No. 5 —

No. 6 —

Spinner Assembly Part No. \_\_\_\_\_

## PITCH RANGE

High Feather 33.5°

Start Lock N/A

Low 13.5°

Reverse N/A

Aircraft Manufacturer \_\_\_\_\_

Aircraft Model \_\_\_\_\_

S/N \_\_\_\_\_

Registration \_\_\_\_\_




**McCAULEY™**

**PROPELLER LOGBOOK**



# MAINTENANCE & SERVICE HISTORY


Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
11-21-05		- 0 -	McCAULEY PROPELLER MODEL B3D32C41Z-C, SN: 99258Z WAS COMPLETELY OVERHAULED THIS DATE. SEE YELLOW TAG FOR DETAILS.	
<b>MAINTENANCE RELEASE</b>				
The component identified above was repaired and inspected in I.A.W. regulations of the FAA and was returned airworthy for return to service for work performed. Pertinent details of the repair are on file at this agency under work order # <u>ER-5213</u>			 <b>EAST COAST PROPELLER SERVICE, INC.</b> 2079 MAIN ST. LITITZ, PA 17543 FAA REPAIR STATION # 655004Y	

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

SOMERSET AIR SERVICE, Inc.  
 P.O. BOX 1007 Bedminster, NJ 07921  
 Tel: (908) 722-8251 Fax: (908) 722-1359

Date: 11-28-05 Tach: 2764 A/C: Piper PA-24-250 #: 6395P

Removed and reinstalled prop after overhaul. Installed using new o-ring. Run-up and leak check okay at this time.

  
 Authorized Signature

Authorized Signature

# SERVICE HISTORY

Description of Work	Authorized Signatures Repairman and Station Certificate Numbers

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Owner Name \_\_\_\_\_

Address \_\_\_\_\_

Propeller Model R3D32C412-2

Blade Model G-82 NDA-5

Hub Serial No. 992582

Blade Serial No. 1 TC 314

2 TC 343

3 TC 353

4 \_\_\_\_\_

# INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
OCT 25 1999	PROPELLER WAS MANUFACTURED AT McCAULEY PROPELLER SYSTEMS, INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE.	(M) 36.
29 NOV 99	Installed Propeller on PA 24-250 SN 24-1505 Engine SN 2-486-40 ops check good & JL 1931910	Tach 2491.3
12-22-99	Reinstall Propeller check TRACK ANGLES + BALANCE Walker B Watter Repair Station #QV9R191N	