

ENGINE LOG BOOK



The subject aircraft was involved in an incident /
accident on 6/1/2024 rendering it a Constructive Total
Loss as not repairable within its insured value. For
further details refer to insurance claim: 6684408418US.

Signed: *Underwriters Salvage Company*

Date: **7/23/2024**

AIIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100
Atlanta, GA 30326



Engine Log & Maintenance Record

LOG #: 1

RECORD OF Lycoming Y10-540-EXP86 EL-36997-48E
(MAKE) (MODEL) (SERIAL)
same as 10-540-D4A5

AIRCRAFT REGISTRATION NUMBER: N90VT

FROM 9/15/19 2019 TO _____ 20____

DETAILING TIME FROM 4 TO _____
(HOURS) (HOURS)

If used on a multi-engine aircraft: ___Right ___Left ___Front ___Rear

*installed in N90VT
in service 4/1/19*

Reciprocating Engine Certificate of Conformance

This is to certify that the engine as described hereinafter has been manufactured / ground operation tested as prescribed by Lycoming drawing(s), specification(s) and/or other documents detailed within the bills of material. All applicable requirements including Lycoming Service Publications have been complied with at time of manufacture. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

LYCOMING

Part Number ATC-RT0274
Serial Number EL-36997-48E
Engine Model Y10-540-EXP86
Work Order ATC698736
Total Time 0

Charles Hess 3/1/18
Authorized Representative Date

Cage Code 1XP50 AS9100 Registered

652 Oliver Street Williamsport, PA 17701 U.S.A.
Lycoming Engines is a division of Avco Corporation

Form 2700 Rev. 05/13