FLIGHTCRAFT

PROPELLER SHOP PORTLAND, OREGON ARS 4126 503-281-3300

AIRCRAFT PROPELLER/ROTOR LOG

9570	MM
370	
	JUU U

Propeller Log N30JW

Tach, 31.7

Prop SMOH 102.6

MA

Performed annual inspection per FAR 43 Appendix D, using in-house inspection checklist as a guide. Researched and complied with all applicable ADs using current AD Toolbox search engine, see AD compliance report for details.

Performed ground run, no defects noted.

Dat		e. I certify that this Propeller v	ecordance with current regulations of the Fec was inspected in accordance with an Annual I	deral Aviation Administration and is Inspection and has been determined	tures tation pers
	David Miller ProAv Aircraft Serv	vices Ous	AMCa	AP32680941A Date 4/2/2024	
					-
NOTE	Enter Compliance W	/ith All Applicable FA	 A A.D. & Factory Service Bulleti	ns On Pages 11-16	

8

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
5-191		-0-	DATE 5/7 JACH 26 4. IJ. A	1 France 17 15320
0111			Propelles IN ACCORDANCE WITH AN	
			ANNUAL INSPECTION AND FOUND IT AIRWORTHY.	Tanger Commencer III
			MICHAEL WITTE I.A. 485524735 PHONE: (503)643-0639 OR (208)362-1931	- 103°
des (Gard Core	(110.5)		mut with	Here and the second sec
2-27-09	TAL 340:00	16:00	Performed a /cohr. Inapaction	1/2/C AN 1556123
6-9-21	TAC 391.7	·	PORTORMED LOOKE INSP	Kendferthen 1602+23
			FOUND TO BE IN AIRWORTHY	CONDITION
1	'a '			
Lucy			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
NOTE: En	ter Compliance W	ith All Applicable FA	A A.D. & Factory Service Bulletins On	Pages 11-16

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers	
Inspec	cted Propeller in acc	Propeller Mo 394.9 PTSO: 70.9 PTT ordance with Far Part 43 has been inspected in acc	SAFE AVIATION, LLC N30JW del: 1A170-DM7359 S/N: 60659 ': Unknown B Appendix D. Researched AD's through b cordance with an Annual Inspection and war		
NOTE: Er	nter Compliance V	l Vith All Applicable FA	A A.D. & Factory Service Bulletins On	Pages 11-16	

PROPELLER/ROTOR HISTORY

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
LATIONS AT DATE	AFT AND OR COMPONER AFT AND OR COMPONER CURRENT FEDERAL AV DAPPROVED FOR RETUR 2 9 - 90 SIGNED FT. INC./PORTLAND FCP VERNATIONAL AIRPORT	NTOSERVICE.	Peronditioned Peap Peop. O.K. Dressed for Cut poth tips from cut Polane Pantal Pup.	Penetrant inspected. measured Clades. 74" aladnie Prop. and balance
		This pro-	to pinion thispure Installed on Glob	2. Pap at close at 33' Islaton Swift by
NOTE: E	nter Compliance V	Vith All Applicable FA	A A.D. & Factory Service Bulletins On	Pages 11-16

PROPELLER/ROTOR LOGBOOK

PROPELLER MODEL 14170 - DM 735 HUB SERIAL # 60659
MANUFACTURER ME Con ley BLADE SERIAL #
DATE OF MANUFACTURE
LOW HIGH
FEATHER REVERSE
OWNER NAME
ADDRESS