☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

PROPELLER LOGBOOK ENTRY

Reg No: N9246F February 16, 2024 ACTT:18478.8 PTT:11594.3
PSOH: 4475.3 Make: Sensenich Model: M74D S/N: A53733
Completed 100hr inspection.
Inspected propeller hub, spinner, blades and bulkhead. I certify this propeller has been
Name: Christopher Holloway **Cert:** A&P 4560851
Sign: _____
I certify this propeller has been inspected in accordance with an Annual Inspection
And was determined to be in an airworthy condition.
Clyde Hogate: _____
A&P 3495015 IA

Year: _____	**Total Time in Service**	**Description**
Date:		
Next Inspection Due:	**Time Since Overhaul**	
		Mech. Cert. # or Repair Station #

☐ HUB

Year:

Date:

Next Insp Due:

PROPELLER LOGBOOK ENTRY

Reg. no: N9246F May 04,, 2023 Tach: 4630.1 PTT: 11203.0 SOH: 4183.3
Inspect propeller hub, spinner, blades and bulkhead.
I certify this propeller has been inspected in accordance with a 100 hour
Inspection and was determined to be in an airworthy condition.
Work performed by Simon Whittaker.
Clyde Hogate
A&P 3495015

Year:

Date:

Next I Due:

Date: 07/16/2023 Hours: ACTT: 18186.8 MX Hobbs:
Tail#: N9246F PTT: 11302.3 PSOH: 4282.6
Make: Sensenich Model: M74D S/N: A53733

I certify this propeller has been inspected in accordance with an 100hr inspection as per Piper PA28-161 100-hour checklist and was determined to be in airworthy condition. All ADs complied with and checked thru 2023-18

Name: Richard Maloney Cert: A&P 3367799
Co: Symmetry Aviation llc Sign:

Year:

Date:

Next I Due:

INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Date: 10/01/2023 Hours: ACTT: 18282.3 TACH: 4824.9 PTT: 11397.8
Tail#: N9246F PSOH : 4278.8
Make: Sensenich Model: M74D S/N: A53733
I certify this propeller has been inspected IAW a 100hr inspection and was determined to be in an airworthy condition.

Name: Richard Maloney Cert: A&P 3367799
Co: Symmetry Aviation llc Sign:

Date: 12/01/2023 Hours: ACTT: 18379.7 TACH: 4922.3 PTT: 11495.2
Tail#: N9246F PSOH : 4376.2
Make: Sensenich Model: M74D S/N: A53733
I certify this propeller has been inspected IAW a 100hr inspection and was determined to be in an airworthy condition.

Name: Richard Maloney Cert: A&P 3367799
Co: Symmetry Aviation llc Sign:

Date: 10/12/2022 Hours: ACTT: 17856.3 Tach: 4399.0
Tail#: N9246F PTT: 10971.8 PSOH: 3952.1
Make: Sensenich Model: M74D S/N: A53733

This Propellor has switched over to Engine tachometer time for ACTT and maintenance tracking. ACTT at this entry is 17856.3 with Tach 4399.0.
PTT: 10971.8 PSOH: 3952.1

Name: Rich Maloney Cert: A&P 3367799
Co: Sign:

Next Inspection Due:	Time Since Overhaul

Mech. Cert. # or Repair Station #

PROPELLER LOGBOOK ENTRY

Reg. no: N9246F Nov 21, 2022 Tach: 4467.6 PTT: 11040.5 SOH: 4020.8
Inspect propeller hub, spinner, blades and bulkhead.
I certify this propeller has been inspected in accordance with a 100 hour Inspection and was determined to be in an airworthy condition.
Work performed by Simon Whittaker.
Clyde Hogate
A&P 3495015

PROPELLER LOGBOOK ENTRY

Reg. No: N9246F February 13, 2023 Tach: 4530.6 PTT: 11103.5 SOH: 4083.8
Inspect propeller hub, blades, spinner, and spinner bulkhead.
I certify this propeller has been inspected in accordance with an annual Inspection and was determined to be in an airworthy condition.
Clyde Hogate
A&P 3495015 IA

PROPELLER LOGBOOK ENTRY

Reg. no: N9246F January 12, 2022 MX Hobbs: 2631.5 PTT: 10760.5 SOH: 3740.8
Inspect propeller, spinner, and bulkhead. Dressed and painted front and backside of propellor.
I certify this propeller has been inspected in accordance with an annual
Inspection and was determined to be in an airworthy condition.
Work performed by Simon Whittaker.
Clyde Hogate
A&P 3495015 IA

PROPELLER LOGBOOK ENTRY

Reg. no: N9246F April 7, 2022 MX Hobbs: 2724.4 PTT: 10853.4 SOH: 3833.7
Inspect propeller hub, spinner, blades and bulkhead.
I certify this propeller has been inspected in accordance with a 100 hour
Inspection and was determined to be in an airworthy condition.
Work performed by Simon Whittaker.
Clyde Hogate
A&P 3495015

INSPECTIONS, REPAIRS AND ALTERATIONS

Date: 10/02/2022 **Hours:** ACTT: 17835.2 MX Hobbs:12821.7
Tail#: N9246F PTT: 10950.7 PSOH: 3931.0
Make: Sensenich **Model:** M74D **S/N:** A53733

I certify this propellor has been inspected in accordance with an 100hr inspection as per Piper PA28-161 100-hour checklist and was determined to be in airworthy condition. All ADs complied with and checked thru 2022-20.

Name: Richard Maloney **Cert:** A&P 3367799
Co: **Sign:**

Next Inspection Due:	Time Since Overhaul

Mech. Cert. # or Repair Station #

N9246F

Propeller Record General Information

Propeller Manufacturer Sensenich

Model M74D

Type

Hub Series #

Blade # A53733

Date of Manufacture

	Make/Model	Serial #
Aircraft Installed On:	PA28-161	2841257