

1

# Propeller Logbook

**Also in Ohio**

**Aircraft Propeller Service of Ohio, Inc.**  
3530 Lightner Drive • Vandalia, Ohio 45377  
(800) 878-3999      CRS # O05R870Y

- Hartzell
- McCauley
- Dowty
- Sensenich
- Hamilton Standard
- 



# AIRCRAFT PROPELLER SERVICE, INC.

---

**INSTALLING AGENCY PLEASE NOTE:**  
Recording of Propeller Total Time Since New (TTSN)  
is Required Per F.A.R. 91.417



# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
3/7/13	UNK	79.5	Annual Inspection IAW Piper Service Manual PIN: 753-586 dated: 1/31/08. AD's CK'd thru 2013-04. Ops CK OK. I certify that this Propeller has been inspected IAW an Annual Inspection & was determined to be in an Airworthy condition.	Paul Fahey 2789585 IA
Tach	5021.9			
3/28/14	UNK	164.8	Annual Inspection IAW FAR 43.91 & Piper Service Manual PIN: 753-586 dated: 1/31/08- 1 Dressed prop. 2 Painted prop face. 3 Removed prop to replace starter ring gear. Reinst prop torqued 64 Ft. lbs & safetied 4 AD's CK'd thru 2014-06. Ops CK OK. I certify that this Propeller has been inspected IAW an Annual Inspection & was determined to be in an Airworthy condition.	Paul Fahey 2789585 IA
Tach	5107.2			
N2167T PA28-180 S/N: 28-7205017 McCauley 1A170/BMS7660M1 S/N: 0A088				
Date: 4/8/15	Tach: 5181.9	AFTT: 5181.9	PTT: Unkwn	PSMOH: 239.5
Annual Inspection IAW FAR 43 Appendix D & 91. Dressed leading edges. I certify that this Propeller has been inspected IAW an Annual Inspection & was determined to be in an airworthy condition. AD's CK'd thru 2015-07. PF				
Total Aircraft				Paul Fahey 2789585 IA
20 Lindbergh Dr.				<i>Paul Fahey</i>
Hartford, CT. 06114				

N2167T PA28-180 S/N: 28-7205017 McCauley 1A170/BMS7660M1 S/N: 0A088

Date: 4/1/16 Tach: 5259.1 AFTT: 5259.1 PTT: Unkwn PSMOH: 316.7

Annual Inspection IAW FAR 43 Appendix D & 91. Dressed leading edges. AD's checked thru 2016-07. I certify that this Propeller has been inspected IAW an Annual Inspection & was determined to be in an airworthy condition.

Total Aircraft  
20 Lindbergh Dr.  
Hartford, CT. 06114

Paul Fahey 2789585 IA

*Paul Fahey*

N2167T PA28-180 S/N: 28-7205017 McCauley 1A170/BMS7660M1 S/N: 0A088

Date: 2/17/17 Tach: 5314.1 AFTT: 5314.1 PTT: Unkwn PSMOH: 371.7

Annual Inspection IAW FAR 43 Appendix D & 91. Dressed leading edges. AD's checked thru 2017-03. I certify that this Propeller has been inspected IAW an Annual Inspection & was determined to be in an airworthy condition.

Total Aircraft  
20 Lindbergh Dr.  
Hartford, CT. 06114

Paul Fahey 2789585 IA

*Paul Fahey*

**N2167T PA28-180 S/N: 28-7205017 McCauley 1A170/BMS7660M1 S/N: 0A088**

Date: 2/27/18 Tach: 5391.1 AFTT: 5391.1 PTT: Unkwn PSMOH: 448.7

Annual Inspection IAW FAR 43 Appendix D & 91. Dressed leading edges. AD's checked thru 2018-04. I certify that this Propeller has been inspected IAW an Annual Inspection & was determined to be in an airworthy condition.

Total Aircraft 20 Lindbergh Dr. Hartford, CT. 06114 Paul Fahey 2789585 IA

*Paul Fahey*

N2167T  
TTAF: 5444.5

28-7205017  
TTE: 5444.5

February 25, 2019  
SMOH: 1927.5

TACH: 5444.5  
SPOH: 502.1

Inspect propeller in accordance with Piper Cherokee 180 checklist FAR 43 appendix D. All AD's complied with at this time. This propeller has been inspected in accordance with an Annual Inspection and has been found to be in airworthy condition.

Christopher S Carman AP28582361A

*Christopher S Carman*

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
6/11/11	Unk	684.3	Annual Inspection IAW FAR 43.91 & Piper Service Manual PIN: 753-586 dated: 1/31/08. Dressed prop & primed & painted prop face & back tips. AD's CK thru 2011-12.	
Tech	4878.8		I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy Condition.	Paul Feilby 2789585 IA
2/27/12	Unk	747.9	IAW Piper Service Manual PIN: 753-586 dated: 1/1/08 - Removed Propeller, McCawley	
Tech	4942.4		1A170/BMS7660M1 SIN: OA-088, For Overhaul. — End —	Paul Feilby 2789585 A&P
<del>_____</del>				

Total Aircraft  
20 Lindbergh Drive  
Brainard Airport  
Hartford, CT 06114

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
3/7/12	UNKNOWN	00.00	1A170/BMS7660M1	S/NOA088
			MAJOR OVERHAUL. BLADES REFINISHED. PROPELLER FLORESCENT PENETRANT INSPECTED. CHECKED ANGLES, TRACKED, BALANCED, ALOINED AND PAINTED.	
			AUTHORIZED BY	W/o # CR-38724
			For NEW ENGLAND PROPELLER SERVICE, INC.	
			EAST HADDAM, CT	
			FAA REPAIR STATION # RC2R130L	
			1-800-878-6377	
3/20/12	Unk	0.0	IAW Piper Service Manual PIN: 753-586 dated: 1/1/08 - Reinstalled Propeller, McCawley	
Tech	4942.4		1A170/BMS7660M1 SIN: OA-088, after overhaul. Torqued 65 Ft-lbs & safetied with .041 wire	Paul Feilby 2789585 A&P
3/20/12	Unk	0.0	Annual Inspection IAW FAR 43.91 & Piper Service Manual PIN: 753-586 dated: 1/31/08. AD's CK'd thru 2012-05. Ops CK OK. I certify that this Propeller has been inspected IAW an Annual inspection & was determined to be in an Airworthy Condition.	Paul Feilby 2789585 IA

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
4/24/06 TACH	UNK 4389.8	195.3	Annual inspection per FAR Part 43.91 & Piper Service Manual. AD's checked them 06-03, check ok. Meadow Aviation	
<p>I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>Annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. <u>R. J. [Signature]</u>            DATE <u>4/24/06</u> TOTAL AIRCRAFT TIME <u>4389.8</u>            A &amp; P <u>223045 JA</u></p>				
4/23/07 TI	UNK 4480.2	285.7	Annual inspection per FAR Part 43.91 & Piper Service Manual. AD's checked them 07-06, check ok. Meadow Aviation	
<p>I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>Annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. <u>R. J. [Signature]</u>            DATE <u>4/23/07</u> TOTAL AIRCRAFT TIME <u>4480.2</u>            A &amp; P <u>223045 JA</u></p>				

# SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures
4/23/08 TACH	UNK 4576.4	381.9	Annual inspection per FAR Part 43.91 & Piper Service Manual. AD's checked them 08-07, check ok. Meadow Aviation	
<p>I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>Annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. <u>R. J. [Signature]</u>            DATE <u>4/23/08</u> TOTAL AIRCRAFT TIME <u>4576.4</u>            A &amp; P <u>223045 JA</u></p>				
5/12/09 TACH	UNK 4692.9	498.4	Annual insp. - I.A.N. FAR Part 43.91 & Piper Service Manual. AD's checked them 2009-08, check ok.	
<p>I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>Annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. <u>R. J. [Signature]</u>            DATE <u>5/12/09</u> TOTAL AIRCRAFT TIME <u>4692.9</u>            A &amp; P <u>3373314 JA</u></p>				



Propeller Model 1A170 / BMS 7660 m1

Blade Model \_\_\_\_\_

Hub Serial No. OA 008

Blade Serial No. 1 \_\_\_\_\_

2 \_\_\_\_\_

3 \_\_\_\_\_

4 \_\_\_\_\_

5 \_\_\_\_\_

6 \_\_\_\_\_